

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 395U**AAD1901-122***Not Authored
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 395U

VF1ABL15AUC283295

RENAULT

LATITUDE

13.1.2019

AIG

30/9/2016

PART**LIST**

1	DOOR PANEL REAR RH	\$	<i>B</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>n</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>n</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>n</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10 ?
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75 ?
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43 X
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31 X
1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>na</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i> 6.91
1	DOOR CASING REAR RH	\$	<i>Sn</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>Sn</i> 30.39
1	DOOR CASING CLIP	\$	<i>na</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>na</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>na</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Sn</i> 210.96

Trans-cab Auto Services Pte Ltd**AAD1901-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 395U

1	DOOR BLIND REAR RH	\$	741.80	X
1	DOOR WHEATHESTRIP REAR RH	\$	410.66	X
1	DOOR SEAL REAR RH	\$	162.02	X
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31	X
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	X
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64	X
1	FENDER PANEL REAR RH	\$	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	671.45	X
1	WHEELARCH REAR RH	\$	543.47	X
1	ROCKER PANEL INNER GARNISH RH	\$	466.51	X
1	ROCKER PANEL INNER RH	\$	1,024.79	X
1	ROCKER PANEL CENTER RH	\$	990.25	X

	\$	18,918.30
10%	\$	1,891.83
	\$	17,026.47

Specical Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	X
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	X
1	REAR DOOR STICKER '6555-3333'	\$	80.00	6555
1	DOOR CHECK BOLT	\$	22.69	} X
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	DOOR CATCH SCREW L70Y	\$	10.06	

TOTAL \$ 311.63**TOTAL PARTS \$ 17,338.10****LABOUR**

Trans-cab Auto Services Pte Ltd**AAD1901-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 395U

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800/
Putty and spray painting of the affected portion.	\$	4,200.00	660/
To rust-proofing of the affected areas.	\$	170.00	60/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100/
To check steering geometry and computer wheel alignment	\$	220.00	60/
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60/
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Towing Fees.	\$	~ 120.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 395U

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$

nn 380.00 *X*

TOTAL	\$	12,590.00
--------------	-----------	------------------

Over All Total	\$	29,928.10
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**15 DAYS***5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: