



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKR2372M

Estimation No. : E19010015

Make & Model : VOLKSWAGEN, JETTA 1.4 TSI A/T ABS D/AIRBAG DOA
2WD, WVVZZZ16ZEM068579

: 15/01/2021

Year of Manufacture : 2014

No	Description	Qty	U/P	Amt
Section: List Items				
1	REAR BUMPER	1.00	0.00	0.00 CRU ✓
2	REAR BUMPER UNDER COVER	1.00	0.00	0.00 TN ✓
3	REAR BUMPER SIDE CORE (LH+RH)	2.00	0.00	0.00 NEC ✓
4	REAR BUMPER CENTRE BRACKET	1.00	0.00	0.00 BR ✓
5	REAR BUMPER SPONGE	1.00	0.00	0.00 NN ✓
6	REAR BUMPER REINFORCEMENT	1.00	0.00	0.00 BT ✓
7	REAR BUMPER REINFORCEMENT BRACKET (LH+RH)	2.00	0.00	0.00 NN ✓
8	REAR BUMPER REFLECTOR (LH+RH)	2.00	0.00	0.00 BR ✓
9	REAR BUMPER LOWER GARNISH	1.00	0.00	0.00 CU ✓
10	BOOT LID	1.00	0.00	0.00 BT ✓
11	BOOT LID LOCK	1.00	0.00	0.00 BR ✓
12	BOOT LID LOCK CATCH	1.00	0.00	0.00 NN ✓
13	BOOT LID LOCK SENSOR	1.00	0.00	0.00 NN ✓
14	BOOT LID LOCK SWITCH	1.00	0.00	0.00 CR ✓
15	BOOT LID EMBLEM - LOGO	1.00	0.00	0.00
16	BOOT LID EMBLEM - JETTA	1.00	0.00	0.00
17	BOOT LID EMBLEM - TSI	1.00	0.00	0.00
18	BOOT LID LAMP (LH+RH)	2.00	0.00	0.00 BR ✓
19	LICENSE LAMP (LH+RH)	2.00	0.00	0.00 NN ✓
20	BOOT LID INSULATOR	1.00	0.00	0.00 NN ✓
21	BOOT LID HINGES	2.00	0.00	0.00 NN ✓
22	BOOT LID HINGE GARNISH	2.00	0.00	0.00 NN ✓
23	BOOT LID RUBBER BEADING	1.00	0.00	0.00 CU ✓
24	TAIL LAMP (LH+RH)	2.00	0.00	0.00 CR ✓

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT**Vehicle No** : SKR2372M**Estimation No.** : E19010015**Make & Model** : VOLKSWAGEN, JETTA 1.4 TSI A/T ABS D/AIRBAG DOA
2WD, WVWZZZ16ZEM068579

: 15/01/2021

**Year of
Manufacture** : 2014

No	Description	Qty	U/P	Amt
25	TAIL LAMP GASKET (LH+RH)	2.00	0.00	0.00 NNx
26	TAIL LAMP INNER PANEL (LH)	1.00	0.00	0.00 DDV
27	REAR END PANEL	1.00	0.00	0.00 DDV
28	REAR END PANEL TOP GARNISH	1.00	0.00	0.00 BR ✓
29	SPARE TYRE TOP BOARD	1.00	0.00	0.00 NNx
30	SPARE TYRE PANEL	1.00	0.00	0.00 NNx
31	REAR FENDER (LH)	1.00	0.00	0.00 R x
32	REAR FENDER INNER SHIELD (LH)	1.00	0.00	0.00 TN ✓
33	REAR WINDSCREEN	1.00	0.00	0.00 NN
34	REAR EXHAUST MUFFLER	1.00	0.00	0.00 BT ✓
35	REAR EXHAUST MID PIPE	1.00	0.00	0.00 NNx
				Amt S\$ 0.00
				Discount (10.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

36	REVERSE SENSOR SET	1.00	250.00	200.00 250.00
37	REAR NUMBER PLATE & CASING	1.00	45.00	45.00 NNx
38	REAR BUMPER CLIP SET	1.00	50.00	50.00 NEC
39	BOOT LID INSULATOR CLIP SET	1.00	50.00	50.00 } NEC ✓
40	REAR END PANEL TOP GARNISH CLIP SET	1.00	50.00	50.00 } NEC ✓
41	REAR BUMPER UNDERCOVER CLIP SET	1.00	40.00	40.00 NEC ✓
42	REAR FENDER INNER SHIELD CLIP SET	1.00	50.00	50.00 NEC ✓
43	EXHAUST MOUNTING SET	1.00	160.00	160.00 NEC ✓
44	REAR END PANEL SEALANT	1.00	50.00	50.00 NN NEC
45	REAR WINDSCREEN SEALANT	1.00	50.00	50.00 NNx

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKR2372M
Make & Model : VOLKSWAGEN, JETTA 1.4 TSI A/T ABS D/AIRBAG 2WD, WVWZZZ16ZEM068579
Year of Manufacture : 2014
Estimation No. : E19010015
DOA : 15/01/2021

No	Description	Qty	U/P	Amt
46	REAR WINDSCREEN TINTED	1.00	250.00	250.00 N N X
47	SPARE TYRE PANEL INSULATOR MATT	1.00	250.00	250.00 N N X
				Amt S\$ 1,295.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,295.00

Section: Labour Items

48	TO R&R REAR BUMPER REVERSE SENSOR	1.00	80.00	80.00 60.00 ✓
49	TO SUPPLY & RESPRAY UNDERCOATING/PUTTY ON PARTS REPLACED	1.00	80.00	80.00 60.00 ✓
50	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	1.00	60.00	60.00 ✓
51	TO CHECK WIRING & LIGHTING SYSTEM	1.00	80.00	80.00 ✓
52	TO R&R REAR TRIMS, GARNISH ASSY	1.00	200.00	200.00 100.00
53	TO R&R REAR EXHAUST ASSY	1.00	280.00	280.00 150.00
54	TO R&R REAR WINDSCREEN	1.00	260.00	260.00 N N X
55	TO R&R FUEL TANK TO CUT & WELD	1.00	300.00	300.00 N N X
56	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	1.00	1,500.00	1,500.00 700.00
57	TO SPRAY PAINTING ON AFFECTED AREAS	1.00	1,200.00	1,200.00 800.00
58	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	1.00	150.00	150.00 60.00
59	SUNDRIES	1.00	50.00	50.00 NECV ✓

Amt S\$ 4,240.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 4,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey 16/1/19
 1500 hr
 TGLim
 Lump Sum Repair

List Items Subtotal S\$ 0.00
Special Nett Items S\$
Subtotal 1,295.00
Labour Items Subtotal S\$
Total 4,240.00
Total S\$
Total 5,535.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SKR2372M

Estimation No. : E19010017

Make & Model : VOLKSWAGEN, JETTA 1.4 TSI A/T ABS D/AIRBAG
2WD, VVVZZZ16ZEM068579

DOA : 15/01/2019

Year of Manufacture : 2014

No	Description	Qty	U/P	Amt
Section: List Items				
1	Tail lamp bracket (RH+LH)	1.00	0.00	0.00 <i>NECV</i>
2	<i>Exhaust Heat shield</i>			
			Amt	S\$ 0.00
			Discount (10.00%)	S\$ 0.00
			Subtotal	S\$ 0.00
Section: Labour Items				
2	To R&R rear undercarriage to replace rear exhaust muffler	1.00	400.00	<i>150.00</i> 400.00
3	To conduct 4 wheel alignment	1.00	100.00	100.00 <i>60.00</i>
			Amt	S\$ 500.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 500.00

? Photograph

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey

17/1/19

1345

TG Lim

Days of repair 7

List Items Subtotal S\$ 0.00
Labour Items Subtotal S\$ 500.00
Total S\$ 500.00