

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBG1695C

No.	Qty	List Items	
1	1	Front bumper	\$ Bu 452.10 ✓
2	2	Front bumper side retainer	NIS DR \$ 382.60 ✓
3	1	Front bumper inner reinforcement	\$ B 364.40 ✓
4	1 set	Front bumper clips	\$ M 40.00 ✓
5	2	Headlamp	mtjck \$ 4,966.80 ✓
6	1	Front grille assy	\$ CM 580.80 ✓
7	1	Front bonnet	\$ B 756.60 ✓
8	1	Front bonnet centre "TOYOTA" logo	\$ M 66.10 ✓
9	1	Front bonnet lock	\$ H 77.50 X
10	1	Front support panel	\$ Bu 332.70 ✓
11	1	Air con condenser	\$ P 1,216.10 ✓
12	1	Radiator	\$ P 1,990.90 ✓
13	1	Radiator fan assy	\$ M 3,812.70 ✓
14	1	Rear bumper	\$ B 517.20 ✓
15	2	Rear bumper side clips	\$ CM 60.00 ✓
16	4	Rear bumper inner bracket	\$ B 154.00 ✓
17	1	Rear bumper inner reinforcement	\$ B 382.00 ✓
18	1 set	Rear bumper clips	\$ M 40.00 ✓
19	2	Taillamp	NIS CM 1,154.40 ✓
20	2	Taillamp lower garnish	NIS B 189.60 ✓
21	2	Taillamp panel	NIS DR \$ 682.00 ✓
22	1	Rear tailgate	\$ B 1,855.30 ✓
23	1	Rear tailgate outer black handle	\$ S 201.40 X
24	1	Rear tailgate centre "TOYOTA" logo	\$ M 66.20 ✓
25	1	Rear tailgate "HIACE" emblem	\$ M 39.00 ✓
26	1	Rear tailgate top lock	\$ T 289.70 ✓
27	1	Rear tailgate central lock	\$ T 260.10 ✓
28	1	Rear tailgate lower lock catch	\$ B 85.00 ✓
29	1	Rear tailgate weatherstrip	\$ CM 391.20 ✓
30	1	Rear tailgate inner trim board	\$ CM 186.70 ✓
31	1 set	Rear tailgate inner board clips	\$ M 50.00 ✓
32	1	Rear end panel inner	\$ B 475.10 ✓
33	1	Rear end panel outer	\$ B 580.10 ✓
34	1	Rear LH body panel	\$ Bu 1,118.00 ✓
35	1	Rear LH body panel sliding door Rail	\$ S 466.50 X
36	1	Rear LH body panel sliding door Rail end garnish	\$ S 42.40 X
37	1	Rear LH body inner panel	\$ B 988.70 ✓
38	1	Rear floor panel	Bt/Bu \$ 1,888.50 ✓
39	1	Rear floor panel top beam	\$ B 270.70 ✓
40	1	Rear lower spare tyre carrier	\$ D/T 247.80 ✓
41	1	Rear exhaust silencer	\$ B 971.20 ✓
42	2	Rear exhaust silencer mounting	\$ S 76.00 X
			\$ 28,768.10
Less 25%			\$ 7,192.03
Total :			\$ 21,576.08

Not Authorised
6/1 Sep @ 21,850/-
Resuming After Repair

24 days

Special Nett Items

43	1	Front number plate	\$	CMA	50.00	451m
44	1 set	Reverse sensors	\$	AW	250.00	2005m
45	1	Rear number plate	\$	SCA	50.00	451m
46	1 set	Rear windscreen sealant	\$	MA	80.00	405m
47	1 set	Rear LH body panel glass sealant	\$	MA	50.00	405m
48	1 set	Rear end panel sealant	\$	MA	80.00	305m
49	1	Rear tailgate "5pax" sticker	\$	MA	15.00	—
50	1	Rear tailgate "70km/h" sticker	\$	MA	15.00	—
51	1	Rear lower spare tyre	\$	SM	160.00	X
Total :			\$		750.00	

Labour

1		Tower charges.	\$		80.00	601
2		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$		2,600.00	22001
3		To putty and spray Spray Paintings charges.	\$		2,400.00	18001
4		To remove, refit A/c condenser, radiator and etc..	\$		150.00	1001
5		To remove, refit rear windscreen glass.	\$		140.00	1201
6		To remove, refit rear LH body panel glass.	\$		140.00	1201
7		To check wirings and lightings for front & rear portion.	\$		60.00	401
8		To remove, refit reverses sensors.	\$		80.00	501
9		To remove, refit rear tailgate fittings.	\$		80.00	601
10		To remove, refit rear upholstery and attachments.	\$		150.00	1001
11		To remove, refit rear exhaust silencer.	\$		80.00	601
12		To supply and apply anti rust treatment	\$		120.00	✓
Total :			\$		6,080.00	

Total Parts and Labour : \$ 28,406.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600L

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

GBG1695C SUPPLEMENTARY PARTS

GBG1695C

No. Qty

List Items

1	1	Rear lower spare tyre carrier holder hook	\$	10.00	✓
2	1	Rear LH body panel air duct	\$	36.00	✓
3	1	Front intercooler	\$	1,745.20	✓
			\$	1,791.20	
Less 25%			\$	447.80	
Total:			\$	1,343.40	

Special Netts Items

4	1	Rear floor panel top wooden board	P.T	\$	380.00	✓ 250m
---	---	-----------------------------------	-----	----	--------	--------

Total Supplementary Parts: \$ 1,723.40