

INS. CASE OWNER:

CC

4, MG 1900 0980, Kkazy

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

16/1/19

Date / Time:

15/01/19

Registered in Merimen:

16/01/19

Pre-assign / CCU / FTE

GEP 8238 Z



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBE 4796K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

18/1/19

GBE 4796K - X ; GBE 8238 Z - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Ot:

After call ltr to Ot:

22/4/19 + phone call

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to Ot:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ 8,600

(14 days) Reduction: 25 %

Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 14/1/2020 Confirm with June

Email ☒ Call ☐

Final Liability: % 100 / (Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lin:

Repair Cost: S\$ 4,202

(OI REAR END TP)

Loss of Rental (LOR): S\$ - (- days)

Loss of Use (LOU): S\$ 960 (560 x 16 days)

Loss of Income (LOI): S\$ - (5 - x - days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 8

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

Total: S\$ 10,170

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 10,170

Name 1: CHENG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.) S\$ -

Name 2:

Payee 3: (Strike if N.A.) S\$ -

Name 3:

COPY SENT

REF:

AIG

ORIGINATE

Form

Date: 16/1

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE4796K

at Workshop m/s: Cheng Hoe

at: Yichun.

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

845K

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

14 days

Res: Yes or No

Lump Sum:

1-B.1%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

GBE4796K

Vt Regn:

12 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S NV200

1461

Colour:

Red

A/C Insured / Std / NI / NA

Sp Reading:

56054

TiRatio: Insured / Std / NI / NA

Eng/No:

C/No:

VSKYB Am 2070116589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: In / S/Rim / STD A/Rim or

Tyre Size

F:

R:

175/70R14

BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

14/1/19.

D.O.I:

16/1/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

14/1 15h pos. to Car

(415 \$8,600 / Red \$2,817.16 / 25%.)

14 days + 2 Sundays = 16 days

Date/Time: File Pass to:

☐

Prel. Report

By:

☐

Final Report

Date/Time: File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. 2 x 100

2. 100

3. 100

Total:

Report Format:

Lump Sum / L.B. 1: 15

Add Fee:

☐

Site Insp: 15

☐

Interview: 15

☐

Tech. Insp: 15

☐

Weekend: 15

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBE4796K
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991052/WS

Date: 16 Jan 2019

Policy No: 5091499236-01

Veh Reg No: GBE4796K

Make/Model: NISSAN NISSAN NV200
1.5MT ABS AIRBAG
2WD

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 14/01/2019

TP Veh Reg No: GBF8238Z

Chassis No: VSKYBAM20Z0116569

Engine No: K9KC400D054984

Reg. Date: 15/12/2015

Not Authorized

Resurvey By point

14 days

Estimate Repair Cost to Vehicle No :GBE4796K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	624.80	1 PC	624.80	✓
2 REAR BUMPER SPONGE	84.00	1 PC	84.00	7x n
3 REAR BUMPER SIDE RETAINER LH	33.30	1 PC	33.30	✓
4 REAR BUMPER CLIP	5.00	6 PC	30.00	✓
5 REAR BUMPER REFLECTOR LH	55.00	1 PC	55.00	✓
6 REAR LH TAILGATE	1,409.50	1 PCS	1,409.50	✓
7 TAILGATE EMBLEM - NV200	87.00	1 PC	87.00	✓
8 TAILGATE LOGO	59.70	1 PC	59.70	✓
9 TAILGATE OUTER GARNISH	336.00	1 PC	336.00	✓
10 TAILGATE INNER LOCK (BOTTOM)	125.00	1 PC	125.00	✓
11 TAILGATE INNER TRIM BOARD	75.00	1 PC	75.00	✓
12 TAILGATE INNER TRIM BOARD CLIP	5.00	1 PC	5.00	✓
13 TAILGATE INNER LOCK TOP	155.00	1 PC	155.00	7x n
14 TAILGATE LOWER HINGE	99.10	1 PCS	99.10	7x n
15 REAR END PANEL OUTER	217.60	1 PC	217.60	✓
16 REAR END PANEL INNER TOP GARNISH	69.60	1 PC	69.60	✓
17 REAR FLOOR BOARD CARPET	742.60	1 PCS	742.60	✓
18 REAR TAILGATE RH	1,056.90	1 PC	1,056.90	✓
19 REAR RH TAILGATE EMBLEM - dci	73.60	1 PC	73.60	✓
20 RH TAILGATE INNER RUBBER	83.90	1 PC	83.90	508 n
21 RH TAILGATE INNER LOCK (BOTTOM)	125.90	1 PC	125.90	7x n
22 REAR TAILGATE FRAME RUBBER	69.90	1 PC	69.90	7x n
23 LH TAILLAMP <i>finder</i>	258.70	1 PC	258.70	✓
24 REAR SIDE SPONGE LH	1,554.30	1 PC	1,554.30	✓
25 REAR LH TAILLAMP PANEL	616.50	1 PC	616.50	✓
26 REAR WIPER LINKAGE WITH MOTOR	204.50	1 PC	204.50	7x n
			8,252.40	
Less 10%			825.24	7,427.16
Special Net				
27 REVERSE SENSOR	200.00	1 PC	200.00	✓
28 TAILGATE GLASS GUM	30.00	2 PC	60.00	✓
29 REAR TAILGATE STICKER - 70KM/H	10.00	1 PCS	10.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES1991052/WS
Date: 16 Jan 2019
Policy No: 5091499236-01
Veh Reg No: GBE4796K
Make/Model: NISSAN NISSAN NV200
1.5MT ABS AIRBAG
2WD
Chassis No: VSKYBAM20Z0116569
Engine No: K9KC400D054984
Reg. Date: 15/12/2015

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 14/01/2019
TP Veh Reg No: GBF8238Z

Estimate Repair Cost to Vehicle No :GBE4796K

Description	U/Price	Quantity	List Price	Amount
30 REAR TAILGATE STICKER - 6 PAX	10.00	1 PC	SS 10.00	SS
31 REAR LH SIDE PANEL GLASS GUM	30.00	1 PC	SS 30.00	SS
32 REVERSE CAMERA	350.00	1 PC	350.00	TX nn
			660.00	660.00
Labour				
33 TO REMOVE AND REFIX TAILGATE BOTH GLASS	80.00	2 LA	160.00	1200
34 TO REMOVE AND REFIX REAR LH SIDE PANEL GLASS	80.00	1 LA	80.00	600
35 TO REMOVE AND REFIX RR BUMPER ASSY, TAILGATES, RR WIPER ASSY, TAILLAMP, 3RD BRAKE LIGHT; CUT, WELD & RENEW RR PANEL OUTER, RR LH SIDE PANEL, LH TAILLAMP PANEL; STRAIGHTEN, KNOCK & REPAIR RR FLOOR BOARD PANEL, RR LH FENDER INNER PANEL AND RE-ALIGN TO SAME	1,600.00	1 LA	1,600.00	15000
36 REMOVE AND REFIX RR FLOOR BOARD CARPET, GARNISH, TOP ROOF LINING ETC	120.00	1 LA	120.00	1000
37 PUTTY AND RESPRAY ON RR LH SIDE PANEL, BOTH TAILGATES, RR PANEL, RR END PANEL, RR FLOOR BOARD PANEL	1,300.00	1 LA	1,300.00	12000
38 RUSTPROOFING	90.00	1 LA	90.00	✓
39 REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	60.00	1 LA	60.00	✓
			3,410.00	3,410.00
			Total	SS 11,497.16
			Add GST @ 7%	804.80
			Total Amount Payable	SS 12,301.96

I KK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire Vehicle & Owner Information (Vehicle No. GBF8238Z As At 14 Jan 2019 / 08:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-GBE4796

Current Owner Details

Owner ID Type: Company

Owner ID: 201132450R

Owner Name: INGERSOLL-RAND SINGAPORE ENTERPRISES PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 42

Registered Street Name: BENOI ROAD

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 629903

Current Vehicle Details

Vehicle No.: GBF8238Z

Make Description/Model: NISSAN / NV350 PANEL VAN 2.5 SMT 5DR EURO V

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5868Z
Vehicle Details	
Vehicle No.:	GBE4796K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	K9KC400D054984
Chassis No.:	VSKYBAM20Z0116569
Maximum Power Output:	-
Open Market Value:	\$19,981.00
Original Registration Date:	15 Dec 2015
First Registration Date:	15 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$1,000.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,044.00
COE Rebate Amount:	\$24,238.00
Total Rebate Amount:	\$24,238.00

The information contained herein is correct as at 14 Jan 2019

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Jan 2019 15:26	Clim Veh Model Changed	(204951) NISSAN NV200 1.5 (A).	[A] HOW MEI KWAN
2	16 Jan 2019 15:26	Clim Created	Reg No: GBE4796K. Acct Date: 2019/01/14. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Cheng Hoe Motor Pte Ltd (Yishun)	[A] HOW MEI KWAN
3	16 Jan 2019 15:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	16 Jan 2019 15:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/25	[A] HOW MEI KWAN
5	16 Jan 2019 15:26	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	16 Jan 2019 15:26	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[T] Merimen Administrator
7	16 Jan 2019 15:27	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
8	16 Jan 2019 15:27	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
9	10 Dec 2019 16:54	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
10	10 Dec 2019 16:54	Clim Dtl Modified	JPJ Reg. Date: -> 2015/12/15.	[A] JOANNE LEE KHANG MIN
11	10 Dec 2019 16:54	Clim Details Notified		[A] JOANNE LEE KHANG MIN
12	02 Jan 2020 17:17	Adj Mandate Request	Cur.Req:10170.00:BOLA 27 head to rear end collision. liability is down against Insured.	[A] Khanchna Pothura

Date From



Date To



Audit Type None



Go

ACTIVITY

[22/04/2019 15:32] Khanchna Pothuraj:

22/4/2019 @ 3.08PM - Spoken to OI (Co rep:Ms.Vasa -6861 1555) She confirmed the mva.

Informed OI on TP claim, agreed to settle and aware of NCD will be affected if applicable.Sent letter to OI.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Insurer	Acc Insurer (Branch)	Ref C	Ref T	Amount
2372930	10 Dec 2019 16:54:24	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBE4796K	GBF8238Z	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 14 January 2020 2:05 PM
To: junephua@singnet.com.sg
Cc: Admin A
Subject: CONFIRM SETTLEMENT - Accident between GBE 4796K & GBF 8238Z [AIG] on 14/01/2019

Tracking:	Recipient	Delivery
	junehua@singnet.com.sg	
	Admin A	
	olivialau@lkkauto.com	Delivered: 14/1/2020 2:05 PM
	Meikwan@lkkauto.com	Delivered: 14/1/2020 2:05 PM

WITHOUT PREJUDICE

Dear June,

We refer to the above matter.

We confirm settlement as per your LOD (below):

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	GBF8238Z
Claimant Vehicle No.	GBE4796K
Date of Accident	14/01/2019
Traffic Accident involving vehicle's No.	NEO TIEW ROAD

BREAKDOWN OF PAYMENT/S

S/No.	Items	Amount	Remark
1	Repair cost	\$ 9,202.00	
2	Loss of Use	\$ 960.00	(\$60 x 16 days)
3	LTA Search	\$ 8.00	
TOTAL		\$ 10,170.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd

Service Adviser : LKK
Contact No. 6256 3581

We will proceed to do the necessary accordingly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

"In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."



"Wishing you a Happy and Prosperous Lunar New Year"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***GBE4796K (2031880814SG)
[GBF8238Z]**

TP

TAKAGI RAMEN PTE LTD

Jan 14 2019 8:00AM

[INGERSOLL-RAND SOUTH EAST ASIA]

Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/01/2020 13:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10170.00) - GBE4796K - Claim Handler: Loh, Chee-Heng

Approved:10170.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019 Edit Reg		15 Jan 2019 00:00 Edit Adj Rpt	\$58,600.00 Edit Estimates	\$58,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	INGERSOLL-RAND SOUTH EAST ASIA (PTE) LTD, Co. Reg. No.: 196400122D								
Main Claimant:	TAKAGI RAMEN PTE LTD, Co. Reg. No.: 201525868Z								
Vehicle Reg. No.:	GBE4796K	Date of Loss:	14/01/2019 08:00 - :59 [36 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2031880814SG	Policy/Cover Note No.:	0999994610 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF8238Z	Policy No. (Claimant):	5091499236-01						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (03/01/2020): Alert - Adj Mandate Approved (\$510170.00) - GBE4796K - Claim Handler: Loh, Chee-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE4796K (2031880814SG)
[GBF8238Z]

TP

TAKAGI RAMEN PTE LTD

Jan 14 2019 8:00AM

[INGERSOLL-RAND SOUTH EAST ASIA (PTE) LTD]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Thumbnail v ☒ Edit v
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	02/01/20 17:09	General View		Load JPG ☒ Thumbnail v ☒
2	02/01/20 17:09	General View		Load JPG ☒
3	02/01/20 17:09	General View		Load JPG ☒
4	02/01/20 17:09	General View		Load JPG ☒
5	02/01/20 17:09	General View		Load JPG ☒
6	02/01/20 17:09	General View		Load JPG ☒
7	02/01/20 17:09	General View		Load JPG ☒
8	02/01/20 17:09	General View		Load JPG ☒
9	02/01/20 17:09	General View		Load JPG ☒
10	02/01/20 17:09	General View		Load JPG ☒
11	02/01/20 17:09	General View		Load JPG ☒
12	02/01/20 17:09	General View		Load JPG ☒
13	02/01/20 17:09	General View		Load JPG ☒
14	02/01/20 17:09	General View		Load JPG ☒
15	02/01/20 17:09	General View		Load JPG ☒
16	02/01/20 17:09	General View		Load JPG ☒
17	02/01/20 17:09	General View		Load JPG ☒
18	02/01/20 17:09	General View		Load JPG ☒
19	02/01/20 17:09	General View		Load JPG ☒
20	02/01/20 17:09	General View		Load JPG ☒
21	02/01/20 17:09	General View		Load JPG ☒
22	02/01/20 17:09	General View		Load JPG ☒
23	02/01/20 17:09	General View		Load JPG ☒
24	02/01/20 17:09	General View		Load JPG ☒
25	02/01/20 17:09	General View		Load JPG ☒
26	02/01/20 17:09	General View		Load JPG ☒
27	02/01/20 17:09	General View		Load JPG ☒
28	02/01/20 17:09	General View		Load JPG ☒
29	02/01/20 17:09	General View		Load JPG ☒
30	02/01/20 17:09	General View		Load JPG ☒
31	02/01/20 17:09	General View		Load JPG ☒
32	02/01/20 17:09	General View		Load JPG ☒
33	02/01/20 17:09	General View		Load JPG ☒
34	02/01/20 17:09	General View		Load JPG ☒
35	02/01/20 17:09	General View		Load JPG ☒
36	02/01/20 17:09	General View		Load JPG ☒
37	02/01/20 17:09	General View		Load JPG ☒
38	02/01/20 17:09	General View		Load JPG ☒
39	02/01/20 17:09	General View		Load JPG ☒
40	02/01/20 17:09	General View		Load JPG ☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	02/01/20 17:09	General View		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/01/19 15:27	ACKNOWLEDGEMENT EMAIL TO AIG DD 15.01.2019		☐
2	16/01/19 15:27	EMAIL FROM AIG DD 15.01.19		☐
3	16/01/19 15:27	TP GIA REPORT		☐
4	18/01/19 09:12	TP ESTIMATE - MARKED		☐
5	22/04/19 15:33	LETTER TO OI		☐
6	02/01/20 13:57	LTA SEARCH		☐
7	02/01/20 13:57	LOD		☐
8	30/01/20 10:38	WORKSHOP INVOICE		☐
9	30/01/20 10:38	AUTHORISATION TO ACT FORM		☐
10	30/01/20 10:38	Release Voucher		☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/01/19 13:53	OI GIA REPORT		☐
2	18/01/19 09:28	TP GIA		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBF8238Z (Insd veh)	Model:	NISSAN NV200 1.5 (A)
	GBE4796K (TP veh)		
Date of Accident:	14/01/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	12,301.96
Final Repair Cost	:	\$	9,202.00
Loss of Use	:	\$	960.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,170.00

16.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ — BOLA Scenario No: _____
27

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 10,170.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

30 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19000980/KKA3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994610
Claimant
Vehicle No : GBE4796K **Insured Vehicle No :** GBF8238Z
Date of Loss: 14/01/2019 **Nature of Claim:** TP **Claim No:** 2031880814SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE4796K
 Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D054984
 Reg. Date: 15/12/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0116569
 Colour: Red Odometer: 56054 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,087.16	7,039.04	1,048.12	12.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	3,130.00	280.00	8.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,497.16	10,169.04	1,328.12	11.55
Approved Total (Overridden) (S\$)		8,600.00		
(S\$)	11,497.16	8,600.00	2,897.16	25.20
+ GST 7.00/7.00% (S\$)	804.80	602.00	202.80	25.20
Nett Amount (S\$)	12,301.96	9,202.00	3,099.96	25.20
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		10,170.00		

INSPECTION

Date of Assignment: 15/01/2019
 Date Inspected: 16/01/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	624.80 FN	*624.80 FN
2	1		*REAR BUMPER SPONGE	Not Necessary	84.00 FN	*- FN
3	1		*REAR BUMPER SIDE RETAINER LH	Distorted	33.30 FN	*33.30 FN
4	6		*REAR BUMPER CLIP	Necessary	30.00 FN	*30.00 FN
5	1		*REAR BUMPER REFLECTOR LH	Mtg Distorted	55.00 FN	*55.00 FN
6	1		*REAR LH TAILGATE	Bent	1,409.50 FN	*1,409.50 FN
7	1		*TAILGATE EMBLEM -NV200	Necessary	87.00 FN	*87.00 FN
8	1		*TAILGATE LOGO	Necessary	59.70 FN	*59.70 FN
9	1		*TAILGATE OUTER GARNISH	Warped	336.00 FN	*336.00 FN
10	1		*TAILGATE INNER LOCK (BOTTOM)	Dented	125.00 FN	*125.00 FN
11	1		*TAILGATE INNER TRIM BOARD	Buckled	75.00 FN	*75.00 FN
12	1		*TAILGATE INNER TRIM BOARD CLIP	Necessary	5.00 FN	*5.00 FN
13	1		*TAILGATE INNER LOCK TOP	Not Necessary	155.00 FN	*- FN
14	1		*TAILGATE LOWER HINGE	Not Necessary	99.10 FN	*- FN
15	1		*REAR END PANEL OUTER	Bent	217.60 FN	*217.60 FN
16	1		*REAR END PANEL INNER TOP GARNISH	Buckled	69.60 FN	*69.60 FN
17	1		*REAR FLOOR BOARD CARPET	Necessary	742.60 FN	*742.60 FN
18	1		*REAR TAILGATE RH	Bent	1,056.90 FN	*1,056.90 FN
19	1		*REAR RH TAILGATE EMBLEM -DCI	Necessary	73.60 FN	*73.60 FN
20	1		*RH TAILGATE INNER RUBBER (50%)	Dented / Cut	75.51 FS	*41.95 FS
21	1		*RH TAILGATE INNER LOCK(BOTTOM)	Not Necessary	125.90 FN	*- FN
22	1		*REAR TAILGATE FRAME RUBBER	Not Necessary	69.90 FN	*- FN
23	1		*LH TAILLAMP	Scratched	258.70 FN	*258.70 FN
24	1		*REAR SIDE FENDER LH	Buckled	1,554.30 FN	*1,554.30 FN
25	1		*REAR LH TAILLAMP PANEL	Bent	616.50 FN	*616.50 FN
26	1		*REAR WIPER LINKAGE WITH MOTOR	Not Necessary	204.50 FN	*- FN
27	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
28	2		*TAILGATE GLASS GUM	Necessary	60.00 FS	*60.00 FS
29	1		*REAR TAILGATE STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
30	1		*REAR TAILGATE STICKER -6 PAX	Necessary	10.00 FS	*10.00 FS
31	1		*REAR LH SIDE PANEL GLASS GUM	Necessary	30.00 FS	*30.00 FS
32	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NetItemDisc.

Sub Total (\$\$)	8,904.01	7,782.05
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	816.85	743.01
Total Parts (\$\$)	8,087.16	7,039.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT TAILGATE BOTH GLASS	New	160.00	120.00
2	TO REMOVE AND REFIX REAR LH SIDE PANEL GLASS	New	80.00	60.00
3	TO REMOVE AND REFIX RR BUMPER ASSY ,TAILGATE ,RR WIPER ASSY ,TAILLAMPS ,3RD BRAKE LIGHT ,CUT ,WELD & RENEW RR PANEL OUTER ,RR LH SIDE PANEL ,LH TAILLAMP PANEL ,STRAIGHTEN ,KNOCK & REPAIR RR FLOOR BOARD PANEL ,RR LH FENDER INNER PANEL AND RE-ALIGN TO SAME	New	1,600.00	1,500.00
4	REMOVE AND REFIX RR FLOOR BOARD CARPET ,GARNISH ,TOP ROOF LINING ETC	New	120.00	100.00
5	PUTTY AND RESPRAY ON RR LH SIDE PANEL,BOTH TAILGATE ,RR PANEL,RR END PANEL ,RR FLOOR BOARD PANEL	New	1,300.00	1,200.00
6	RUSTPROOFING	New	90.00	90.00
7	REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	New	60.00	60.00
Gross Labour Cost (S\$)			3,410.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >