

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBE4796K
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991052/WS

Date: 16 Jan 2019

Policy No: 5091499236-01

Veh Reg No: GBE4796K

Make/Model: NISSAN NISSAN NV200
 1.5MT ABS AIRBAG
 2WD

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 14/01/2019

TP Veh Reg No: GBF8238Z

Chassis No: VSKYBAM20Z0116569

Engine No: K9KC400D054984

Reg. Date: 15/12/2015

Not Authorised

Repair By paint

14 days

Estimate Repair Cost to Vehicle No :GBE4796K

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER	624.80	1 PC	624.80	✓
2 REAR BUMPER SPONGE	84.00	1 PC	84.00	✓
3 REAR BUMPER SIDE RETAINER LH	33.30	1 PC	33.30	✓
4 REAR BUMPER CLIP	5.00	6 PC	30.00	✓
5 REAR BUMPER REFLECTOR LH	55.00	1 PC	55.00	✓
6 REAR LH TAILGATE	1,409.50	1 PCS	1,409.50	✓
7 TAILGATE EMBLEM - NV200	87.00	1 PC	87.00	✓
8 TAILGATE LOGO	59.70	1 PC	59.70	✓
9 TAILGATE OUTER GARNISH	336.00	1 PC	336.00	✓
10 TAILGATE INNER LOCK (BOTTOM)	125.00	1 PC	125.00	✓
11 TAILGATE INNER TRIM BOARD	75.00	1 PC	75.00	✓
12 TAILGATE INNER TRIM BOARD CLIP	5.00	1 PC	5.00	✓
13 TAILGATE INNER LOCK TOP	155.00	1 PC	155.00	✓
14 TAILGATE LOWER HINGE	99.10	1 PCS	99.10	✓
15 REAR END PANEL OUTER	217.60	1 PC	217.60	✓
16 REAR END PANEL INNER TOP GARNISH	69.60	1 PC	69.60	✓
17 REAR FLOOR BOARD CARPET	742.60	1 PCS	742.60	✓
18 REAR TAILGATE RH	1,056.90	1 PC	1,056.90	✓
19 REAR RH TAILGATE EMBLEM - dc	73.60	1 PC	73.60	✓
20 RH TAILGATE INNER RUBBER	83.90	1 PC	83.90	50% off
21 RH TAILGATE INNER LOCK (BOTTOM)	125.90	1 PC	125.90	✓
22 REAR TAILGATE FRAME RUBBER	69.90	1 PC	69.90	✓
23 LH TAILLAMP	258.70	1 PC	258.70	✓
24 REAR SIDE SPONGE LH	1,554.30	1 PC	1,554.30	✓
25 REAR LH TAILLAMP PANEL	616.50	1 PC	616.50	✓
26 REAR WIPER LINKAGE WITH MOTOR	204.50	1 PC	204.50	✓
			8,252.40	
Less 10%			825.24	7,427.16
Special Net				
27 REVERSE SENSOR	200.00	1 PC	200.00	✓
28 TAILGATE GLASS GUM	30.00	2 PC	60.00	✓
29 REAR TAILGATE STICKER - 70KM/H	10.00	1 PCS	10.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES1991052/WS
Date: 16 Jan 2019
Policy No: 5091499236-01
Veh Reg No: GBE4796K
Make/Model: NISSAN NISSAN NV200
 1.5MT ABS AIRBAG
 2WD
Chassis No: VSKYBAM20Z0116569
Engine No: K9KC400D054984
Reg. Date: 15/12/2015

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 14/01/2019
TP Veh Reg No: GBF8238Z

Estimate Repair Cost to Vehicle No :GBE4796K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
30 REAR TAILGATE STICKER - 6 PAX	10.00	1 PC	10.00	
31 REAR LH SIDE PANEL GLASS GUM	30.00	1 PC	30.00	
32 REVERSE CAMERA	350.00	1 PC	350.00	
			660.00	660.00
Labour				
33 TO REMOVE AND REFIX TAILGATE BOTH GLASS	80.00	2 LA	160.00	1200
34 TO REMOVE AND REFIX REAR LH SIDE PANEL GLASS	80.00	1 LA	80.00	600
35 TO REMOVE AND REFIX RR BUMPER ASSY, TAILGATES, RR WIPER ASSY, TAILLAMPS, 3RD BRAKE LIGHT; CUT, WELD & RENEW RR PANEL OUTER, RR LH SIDE PANEL, LH TAILLAMP PANEL; STRAIGHTEN, KNOCK & REPAIR RR FLOOR BOARD PANEL, RR LH FENDER INNER PANEL AND RE-ALIGN TO SAME	1,600.00	1 LA	1,600.00	15000
36 REMOVE AND REFIX RR FLOOR BOARD CARPET, GARNISH, TOP ROOF LINING ETC	120.00	1 LA	120.00	1000
37 PUTTY AND RESPRAY ON RR LH SIDE PANEL, BOTH TAILGATES, RR PANEL, RR END PANEL, RR FLOOR BOARD PANEL	1,300.00	1 LA	1,300.00	12000
38 RUSTPROOFING	90.00	1 LA	90.00	✓
39 REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	60.00	1 LA	60.00	✓
			3,410.00	3,410.00
			Total	S\$ 11,497.16
			Add GST @ 7%	804.80
			Total Amount Payable	S\$ 12,301.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE