

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0021290
Nguyen Thi Thiet Cheryl

Page : 1 of 3
Your ref. : TP-SLG 14G India
Job No. : 70157
Our ref : 19.01.18
Payment :
Date : 15/1/2019

Attn :

Vehicle No : SLL 7887G
Vehicle Model : Subaru Outback 2.5
Accident on : 13/1/2019

Not withash
Running B4 part

11 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear tailgate	1,072.80		<i>B1</i> 1,072.80 ✓
1.00	Pc	Rear tailgate Subaru AWD emblem	72.00		<i>na</i> 72.00 ✓
1.00	Pc	Rear tailgate Outback emblem	50.40		<i>na</i> 50.40 ✓
1.00	Set	Rear windscreen mouldings	40.50		<i>na</i> 40.50 ✓
1.00	Pc	Rear bumper	694.00		<i>B1</i> 694.00 ✓
1.00	Pc	Rear bumper tow hook cover	10.80		<i>na</i> 10.80 ✓
1.00	Pc	Rear bumper diffuser cover	180.00		<i>B1</i> 180.00 ✓
1.00	Pc	Rear bumper reflector LH	61.20		<i>B1</i> 61.20 ✓
1.00	Pc	Rear bumper top protector cover	280.00		<i>na</i> 280.00 ✓
1.00	Pc	Rear bumper reinforcement	496.00		496.00 ✓
8.00	Pcs	Rear bumper clips	3.50		<i>na</i> 28.00 ✓
1.00	Pc	Rear bumper side inner retainer LH	46.00		<i>na</i> 46.00 ✓
1.00	Pc	Rear bumper corner clip LH	3.50		<i>na</i> 3.50 ✓
1.00	Pc	Rear end panel	359.20		<i>B1</i> 359.20 ✓
1.00	Pc	Rear exhaust box	640.00		640.00 ✓
1.00	Pc	Rear exhaust box heat shield	64.00		64.00 ✓
1.00	Pc	Rear exhaust centre pipe	820.00		820.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021290
Nguyen Thi Thiet Cheryl

Page 2 of 3
Your ref TP-SLG 14G India
Job No. 70157
Our ref 19.01.18
Payment
Date 15/1/2019

Attn

Vehicle No SLL 7887G
Vehicle Model : Subaru Outback 2.5
Accident on ... 13/1/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		<i>200</i> 200.00 ✓
Labour & Misc:					
1.00		To dismantle and refix rear windscreen	160.00		160.00 <i>120</i>
1.00		To supply sealant	40.00		40.00 ✓
1.00		To dismantle and refix rear fender inner trim garnish (x2)	200.00		200.00 <i>150</i>
1.00		To dismantle and renew rear exhaust box + centre pipe, etc	140.00		140.00 ?
1.00		To apply underbody undercoating (tuff coat)	280.00		280.00 ?
1.00		To check/erase fault codes	60.00		60.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021290
Nguyen Thi Thiet Cheryl

Page 3 of 3
Your ref. TP-SLG 14G India
Job No 70157
Our ref 19.01.18
Payment
Date 15/1/2019

Attn

Vehicle No SLL 7887G
Vehicle Model : Subaru Outback 2.5
Accident on ... 13/1/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel and renew of parts	1,500.00		1,500.00 135
1.00		To spray paint (Pearl white)	1,600.00		1,600.00 1400

Sub-Total 9,098.40
GST 7.00% 636.89
Total S\$ 9,735.29

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."