

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

15-04-19

Accident Date : 12-01-2019

OUR REF : SGF 8259D/T/19

POH KIM HUAT

Blk 149 Rivervale Crescent

#09-60

Singapore 540149

ESTIMATE BILL ON VEH. NO. : SGF 8259D

MODEL : TOYOTA VIOS

CHASSIS NO : MR053HY4204181215

LIST ITEM

Rear Bumper Fascia	DP	381.75	/
Rear Bumper Side Retainer - RH	Bar	43.10	/
Rear Bumper Side Attachment - RH	Bar	69.90	/
Rear Bumper Clips	8pcs @ 12.90	103.20	/
Rear End Panel	3/4 (2)	689.40	/
Tail Lamp - RH	17	182.25	X
Tail Lamp Sealant	17	50.00	X
		1,519.60	
		Less Discount 25%:	379.90
			1,139.70

SPECIAL NETT ITEM

Rear Bumper Protector (Acc)	17	50.00	X
Reverse Sensor with Control Unit.	17	380.00	X
		50.00	30
		180.00	50
		120.00	50
		750.00	600
		650.00	✓

To Check Wiring System.		
To Tuff Coat Affected Areas.		
To Remove & Refix Reverse Sensor		
To Respray Affected Areas.		
To Renew Damaged Parts, Straighten & Repair Rear RH Fender & Aligned All Parts.		
		3,319.70
		232.38
		3,552.08

111 A

Not Admin /
2/5 \$1800
6dy.

Marcus

Date in/out : 12/01/19 to 24/01/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No other condition is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: