

INS. CASE OWNER: Peter | CC 4 ASM / AXA1900 0988, 6/11/19 | LKK: ab IDAC: 6/11/19

Surveyor: XGD | DOI: 12/1/19 | Date/Time: 16/1/19 | Registered in Meritum: \_\_\_\_\_

Pre-assign / CCU / FTE

Insured Vehicle No.: Sbx 8789 G | Claim No.: SAMOLAHU (an 820)  
 Name of Insured: Took peng Haw. | Policy No.: LPMP 8561710  
 Insured Tel No.: \_\_\_\_\_ | HP: \_\_\_\_\_ | Make / Model: Hyundai  
 Excess Sec II :SS \_\_\_\_\_ | D.O.A.: 11/1/19 | Place of Accident: MARYMOUNT RD.  
 Is driver the owner? ( YES / NO ) | Nature of Accident: \_\_\_\_\_  
 If NO, Driver Name / Age: Lim Hamster Tan Sion H | OI GIA REPORT: ( YES / NO ) | TP GIA REPORT: ( YES / NO )  
 Driver Tel No.: \_\_\_\_\_ | ( VL: YES / NO ) | Insured Liability: Final ? Yes / No

MH 65967 → Sbx 8789 G → Saw 97516

INSRS: WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_  
 INSRS: WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: 01  
 INSRS: WSP: MH | Tel: Lim | Liability: \_\_\_\_\_ | RMKS: TP  
 INSRS: WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE/PIC
<u>16/1/19</u>	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	<u>2045-3-19</u>
	After call Itr to OI	
	Documentation Check List:	Handler   Typist
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Authorization To Act	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Car Rental Invoice	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	LTA / GIA	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Medical Bill	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	PIR	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Mandate/Reject Instruction	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/>   <input type="checkbox"/>
	Post-Repair Photos	<input checked="" type="checkbox"/>   <input type="checkbox"/>
	Others	<input checked="" type="checkbox"/>   <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: Lim Hamster  
 Repair Cost: 46 \$S 1050.00 ( 3 days) Reduction: 529.79 \$S  
 Email  Call

FINAL SETTLEMENT Date/Time: 5/9/2020 Confirm with: Mai Hong Email  Call   
 Final Liability: 100 \$S (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 0  
 Repair Cost: 1158.00 \$S  
 Loss of Rental (LOR): 300.00 \$S ( 3 days) x 100  
 Loss of Use (LOU): - \$S ( 5 x days)  
 Loss of Income (LOI): - \$S ( 5 x days)  
 LOR only  LOU only  LOR + LOU  LOR + LOI  (Tick only one)  
 GIATA Search 2.00 \$S  
 Medical: - \$S  
 Disbursement: - \$S (e.g. Tow/Independent)  
 Legal Cost: 47.00 \$S  
 Total: 1467.50 \$S - Global Sum SS:  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: 3VC  
 3) Survey fee: 012ND

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call   
 Payee 1: 1467.50 \$S Name 1: MH Lim Motor Company  
 Payee 2: (Strike if N.A.) \$S Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) \$S Name 3: \_\_\_\_\_

✓ an  
 \* KIA company chof  
 no clerv. CTP)





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000988/Gjb3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 16-01-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDX 8789G	Veh. Inspected	SGW 9751C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/01/2019

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	11/01/2019	Inspection Date	17/01/2019
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

Insurer Reference:  
 Repairer Reference: **SGW9751C**  
 Date calculated: **29/08/2019 3:04 PM**

Full Report  
 Registration: **SGW9751C**  
 Printed: **29/08/2019 3:04 PM**

Code	Description	WU	Price SGD
NO NUMBER	PREPARATION TIME	2.0	9.00
514221 10	R + R REAR BUMPER	7.0	31.50
514210 10)	REAR BUMPER (REMOVED) RENEW INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT	1.0	4.50
NO NUMBER	R + R REAR BUMPER REINFORCEMENT	2.0	9.00
153510 10)	R + R MAIN EXHAUST SECTION	5.0	22.50
2711	REAR PANEL REPAIR	40.0*	180.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>5.70</b>	<b>57.0</b>
<b>Total of Labour</b>			<b>256.50</b>

**Paint**

Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR COVER BUMPER NEW PART PAINT K1R	16.0	
	REAR PANEL REPAIR PAINTING >50%	17.0	
	BOOTLID SURFACE PAINT	8.0	

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR COVER BUMPER NEW PART PAINT K1R	80.69
2711	REAR PANEL REPAIR PAINTING >50%	16.59
2931	BOOTLID SURFACE PAINT	23.66

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		41.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>71.0</b>	<b>319.50</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

Insurer Reference:  
 Repairer Reference: **SGW9751C**  
 Date calculated: **29/08/2019 3:04 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

<b>Material Cost - Paint</b>		<b>Price SGD</b>
New Part Painting - Plastic K1R		80.69
Repair Painting		16.59
Surface-/Blend Paint		23.66
Material-constant Metal Preparation		28.60
Material-constant Plastic		9.00
<b>Total</b>		<b>158.54</b>

**Spare Parts**

				prices as at 2015-06-01	
<b>Code</b>	<b>Description</b>	<b>Part Number</b>	<b>Supplier</b>		<b>Price SGD</b>
2583	REAR COVER BUMPER	6410B220WA			300.00
2644	REAR BUMPER SUPPORT	6410B929			120.00
8834	EXH PIPE ORNAMENTAL	1570A700			70.00
1000	RR BUMPER TOW CVR	1			15.00
1001	RR BUMPER CLIPS (20)	1			30.00
f: OEM Parts	<b>Savings</b>				<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>				<b>535.00</b>
u: Used parts	<b>Addition(+15.00%)</b>				<b>80.25</b>
	<b>Total</b>				<b>615.25</b>

**Final Calculation**

		<b>SGD</b>	<b>SGD</b>
<b>Parts</b>		535.00	
Addition(+15.00%)		80.25	
<b>Total Parts</b>			<b>615.25</b>
<b>Labour Time Base 10 WU/h</b>			
Total 57.0 WU X 45.00 SGD/h		256.50	
<b>Total of Labour</b>			<b>256.50</b>
<b>Paint Work Time Base 10 WU/h</b>			
Labour Cost 71.0 WU X 45.00 SGD/h		319.50	
Material Cost		158.54	
<b>Total Paint Including Material</b>			<b>478.04</b>
<b>Repair Cost Excludes GST</b>			<b>1,349.79</b>
GST (+7.0%)			94.49
<b>Repair Cost Included GST</b>			<b>1,444.28</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

**Insurer Reference:**  
**Repairer Reference: SGW9751C**  
**Date calculated: 29/08/2019 3:04 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

---

**No assessment notes entered.**

ce cilia

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

**Insurer Reference:**  
**Repairer Reference: SGW9751C**  
**Date calculated: 29/08/2019 3:04 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	11/01/19
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	MITSUBISHI
Model:	LANCER (CY,CX)
Sub Model:	GLS
Model Sheet Number:	32 39 09
Registration:	SGW9751C
VIN number:	JMYSTCY4A8U000563
Odometer:	

**Model Specs**

2.0 LTR 110-118KW	4-DOOR SALOON	TWO COAT METALLIC	PREPARE OFF VEHICLE
-------------------	---------------	-------------------	---------------------


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

All   
Underbody



**Labour**

Time Base 10 WU/h

Price = 45.00 SGD/h

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

Insurer Reference:  
 Repairer Reference: **SGW9751C**  
 Date calculated: **29/08/2019 3:04 PM**

**Full Report**  
 Registration: **SGW9751C**  
 Printed: **29/08/2019 3:04 PM**

Code	Description	WU	Price SGD
NO NUMBER	PREPARATION TIME	2.0	9.00
514221 10	R + R REAR BUMPER	7.0	31.50
514210 10)	REAR BUMPER (REMOVED) RENEW INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT	1.0	4.50
NO NUMBER	R + R REAR BUMPER REINFORCEMENT	2.0	9.00
153510 10)	R + R MAIN EXHAUST SECTION	5.0	22.50
2711	REAR PANEL REPAIR	40.0*	180.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>5.70</b>	<b>57.0</b>
<b>Total of Labour</b>			<b>256.50</b>

**Paint**

Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR COVER BUMPER NEW PART PAINT K1R	16.0	
	REAR PANEL REPAIR PAINTING >50%	17.0	
	BOOTLID SURFACE PAINT	8.0	

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR COVER BUMPER NEW PART PAINT K1R	80.69
2711	REAR PANEL REPAIR PAINTING >50%	16.59
2931	BOOTLID SURFACE PAINT	23.66

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		41.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>71.0</b>	<b>319.50</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

Insurer Reference:  
 Repairer Reference: **SGW9751C**  
 Date calculated: **29/08/2019 3:04 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

<b>Material Cost - Paint</b>		<b>Price SGD</b>
New Part Painting - Plastic K1R		80.69
Repair Painting		16.59
Surface-/Blend Paint		23.66
Material-constant Metal Preparation		28.60
Material-constant Plastic		9.00
<b>Total</b>		<b>158.54</b>

**Spare Parts**

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR COVER BUMPER	6410B220WA		300.00
2644	REAR BUMPER SUPPORT	6410B929		120.00
8834	EXH PIPE ORNAMENTAL	1570A700		70.00
1000	RR BUMPER TOW CVR	1		15.00
1001	RR BUMPER CLIPS (20)	1		30.00
f: OEM Parts				<b>Savings</b>
n: Non-OEM Parts				<b>Subtotal</b>
u: Used parts				<b>Addition(+15.00%)</b>
<b>Total</b>				<b>615.25</b>

**Final Calculation**

		SGD	SGD
<b>Parts</b>		535.00	
Addition(+15.00%)		80.25	
<b>Total Parts</b>			<b>615.25</b>
<b>Labour Time Base 10 WU/h</b>			
Total 57.0 WU X 45.00 SGD/h		256.50	
<b>Total of Labour</b>			<b>256.50</b>
<b>Paint Work Time Base 10 WU/h</b>			
Labour Cost 71.0 WU X 45.00 SGD/h		319.50	
Material Cost		158.54	
<b>Total Paint Including Material</b>			<b>478.04</b>
<b>Repair Cost Excludes GST</b>			<b>1,349.79</b>
GST (+7.0%)			<b>94.49</b>
<b>Repair Cost Included GST</b>			<b>1,444.28</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

**Insurer Reference:**  
**Repairer Reference: SGW9751C**  
**Date calculated: 29/08/2019 3:04 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

---

**No assessment notes entered.**

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimco@singnet.com.sg  
GST:M9-0009639-E RCB NO-06470300B

DRAFT

M/S : XIE YAO QUAN  
11 SIN MIN WALK  
#05-02 THOMSON GRAND  
SINGAPORE 575579

Claim No: MCS1900004  
Ref No: MFS1900159  
Date: 29 Aug 2019  
Policy No: PNPV2017-00005683-01  
Veh Reg No: SGW9751C  
Make/Model: MITSUBISHI LANCER  
2.0L

ATTN:

Your Ref No: SGW9751C  
Claim Type: Third Party  
Accident Date: 11/01/2019

## Repair Cost to Vehicle No (For Finalization):SGW9751C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<b>SPARE PARTS</b>				
1 REAR BUMPER		1 PC	300.00	
2 REAR BUMPER REINFORCEMENT		1 PC	120.00	
3 REAR TOWING COVER		1 PC	15.00	
4 EXHAUST MUFFLER TIP		1 PC	70.00	
5 REAR BUMPER CLIPS		20 PC	30.00	
			535.00	
	Add 15%		80.25	615.25
<b>LABOUR</b>				
6 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR TAIL END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	256.50	
7 TO SPRAY REAR BUMPER, TAILLAMP PANEL		1 PC	478.04	
				734.54

Total	S\$ 1,349.79
Lump Sum Less 20%	-269.96
Amount Before Excess	S\$ 1,079.83
Less Rounding	-29.83
Amount Before Excess	S\$ 1,050.00
Less Excess	S\$ 0.00
Amount Before GST	S\$ 1,050.00
Add GST @ 7%	73.50
Total Amount payable	S\$ 1,123.50

TOTAL: SINGAPORE DOLLAR ONE THOUSAND ONE HUNDRED TWENTY THREE AND CENTS FIFTY ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 17/01/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY  
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint  
AUTHORISED SIGNATURE  
Tel: 6483 1244 Fax: 6483 6170

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**  
**Assessment number: SGW9751C**  
**Version: 1712**  
**Date calculated: 01/15/2019 02:09 PM**

(TP)  
FWD Liberty  
SURVEYOR COPY

Liability  
Clean

**Full Report**  
**Registration: SGW9751C**  
**Printed: 01/15/2019 2:09 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mul Hong	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-11
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	MITSUBISHI	
Model:	LANCER (CY,CX)	
Sub Model:	GLS	
Model Sheet Number:	32 39 09	
Registration:	SGW9751C	
VIN number:	JMYSTEY4A8U000563	
Odometer:		
<b>Model Specs</b>		
2.0 LTR 110-118KW	4-DOOR SALOON	PREPARE OFF VEHICLE

3 Days.

Impress repair.

After repair photos.

Guo Qiang - 82880282

17/1/19.

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**  
**Assessment number: SGW9751C**  
**Version: 1712**  
**Date calculated: 01/15/2019 02:09 PM**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 01/15/2019 2:09 PM**


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	9.00
514210 10)	R + R REAR BUMPER		4.0	18.00
514210 10)	REAR BUMPER (REMOVED) RENEW INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		3.0	13.50
NO NUMBER	R + R REAR BUMPER REINFORCEMENT (BUMPER REMOVED)		2.0	9.00
153510 10)	R + R MAIN EXHAUST SECTION		5.0	22.50
2711	REAR PANEL REPAIR ?		? 40.0*	180.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			5.60	56.0
<b>Total of Labour</b>				252.00

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: SGW9751C  
 Version: 1712  
 Date calculated: 01/15/2019 02:09 PM

Full Report  
 Registration: SGW9751C  
 Printed: 01/15/2019 2:09 PM

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	REAR COVER BUMPER NEW PART PAINT K1R	13.0
	REAR PANEL REPAIR PAINTING >50%	16.0
	BOOTLID SURFACE PAINT	8.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR COVER BUMPER NEW PART PAINT K1R	57.24
2711	REAR PANEL REPAIR PAINTING >50%	13.48
2931	BOOTLID SURFACE PAINT	16.72

**Labour Cost - Paint**

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			37.0	
Preparation Main Work Metal		1.90	19.0	85.50
Preparation Comp. Work Plastic		0.30	3.0	13.50
<b>Total</b>	<b>10 WU/h</b>	<b>5.90</b>	<b>59.0</b>	<b>265.50</b>

**Material Cost - Paint**

Description	Price SGD
New Part Painting - Plastic K1R	57.24
Repair Painting	13.48
Surface-/Blend Paint	16.72
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>125.04</b>

*Guo Qiang*  
*UK*  
*25/7/19*

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR COVER BUMPER	6410B220WA	- ae.		300.00 ✓
<del>2641</del>	<del>L/R BUMPER REINF</del>	<del>6410G543</del>	<del>X</del>		<del>10.00</del>
<del>2642</del>	<del>R/R BUMPER REINF</del>	<del>6410G544</del>	<del>X</del>		<del>10.00</del>
2644	REAR BUMPER SUPPORT	6410B929	BT		120.00 ✓
<del>2672</del>	<del>R/R REFLECTOR</del>	<del>8355A040</del>	<del>X</del>		<del>15.00</del>
8834	EXH PIPE ORNAMENTAL	1570A700	- cut		70.00 ✓

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: SGW9751C  
 Version: 1712  
 Date calculated: 01/15/2019 02:09 PM

Full Report  
 Registration: SGW9751C  
 Printed: 01/15/2019 2:09 PM

Code	Description	Part Number	Supplier	Price SGD
1000	RR BUMPER TOW CVR	1 / P/S		15.00 ✓
1001	RR BUMPER CLIPS (20)	1 / ACC.		30.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			570.00
u: Used parts	Addition(+15.00%)			85.50
	<b>Total</b>			<b>655.50</b>

535

**Extras**

Code	Description	Price SGD
1002	CHECK WIRING	40.00*
<del>1003</del>	<del>REVERSE-SENSOR (2)</del>	<del>200.00*</del>
	<b>Total Extras</b>	<b>240.00</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	570.00	
Addition(+15.00%)	85.50	
<b>Total Parts</b>		<b>655.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 56.0 WU X 45.00 SGD/h	252.00	
<b>Total of Labour</b>		<b>252.00</b>
<b>Total Of Extras</b>		<b>240.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 59.0 WU X 45.00 SGD/h	265.50	
Material Cost	125.04	
<b>Total Paint Including Material</b>		<b>390.54</b>
<b>Repair Cost Excludes GST</b>		<b>1,538.04</b>
GST (+7.0%)		107.66
<b>Repair Cost Included GST</b>		<b>1,645.70</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang Mo Kio**  
**Ind. Park 2A**  
**568047**

**Insurer Reference:**  
**Repairer Reference: SGW9751C**  
**Date calculated: 29/08/2019 3:04 PM**  
**Summary Information**

**Full Report**  
**Registration: SGW9751C**  
**Printed: 29/08/2019 3:04 PM**

#### Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	11/01/19
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

#### Vehicle Details

##### Vehicle

Manufacturer:	MITSUBISHI
Model:	LANCER (CY,CX)
Sub Model:	GLS
Model Sheet Number:	32 39 09
Registration:	SGW9751C
VIN number:	JMYSTCY4A8U000563
Odometer:	

##### Model Specs

2.0 LTR 110-118KW	4-DOOR SALOON	TWO COAT METALLIC	PREPARE OFF VEHICLE
-------------------	---------------	-------------------	---------------------


#### Vehicle Condition

##### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

##### Damage Areas

All   
Underbody



#### Labour

Time Base 10 WU/h

Price = 45.00 SGD/h

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: SGW9751C  
 Version: 1712  
 Date calculated: 01/15/2019 02:09 PM

**Full Report**  
**Registration: SGW9751C**  
**Printed: 01/15/2019 2:09 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-11
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	MITSUBISHI
Model:	LANCER (CY,CX)
Sub Model:	GLS
Model Sheet Number:	32 39 09
Registration:	SGW9751C
VIN number:	JMYSTCY4A8U000563
Odometer:	

**Model Specs**

2.0 LTR 110-118KW	4-DOOR SALOON	PREPARE OFF VEHICLE
-------------------	---------------	---------------------

*3 Days.*  
*Impsun repair.*  
*After repair photos.*  
*Guo Qiang - 82880282*  
*17/1/19.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: SGW9751C  
 Version: 1712  
 Date calculated: 01/15/2019 02:09 PM

Full Report  
 Registration: SGW9751C  
 Printed: 01/15/2019 2:09 PM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	9.00
514210 10)	R + R REAR BUMPER		4.0	18.00
514210 10)	REAR BUMPER (REMOVED) RENEW INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		3.0	13.50 4.50
NO NUMBER	R + R REAR BUMPER REINFORCEMENT (BUMPER REMOVED)		2.0	9.00
153510 10)	R + R MAIN EXHAUST SECTION		5.0	22.50
2711	REAR PANEL REPAIR		40.0*	180.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			5.60	56.0
<b>Total of Labour</b>				<b>252.00</b>

256.50

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: **SGW9751C**  
 Version: **1712**  
 Date calculated: **01/15/2019 02:09 PM**

Full Report  
 Registration: **SGW9751C**  
 Printed: **01/15/2019 2:09 PM**

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	REAR COVER BUMPER NEW PART PAINT K1R	13.0 16.0
	REAR PANEL REPAIR PAINTING >50%	16.0 17.0
	BOOTLID SURFACE PAINT	8.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR COVER BUMPER NEW PART PAINT K1R	80.69 57.24
2711	REAR PANEL REPAIR PAINTING >50%	16.57 13.48
2931	BOOTLID SURFACE PAINT	23.66 16.72

**Labour Cost - Paint**

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			37.0	112.50
Preparation Main Work Metal		1.90	19.0	85.50
Preparation Comp. Work Plastic		0.30	3.0	13.50
<b>Total</b>	<b>10 WU/h</b>	<b>5.90</b>	<b>59.0</b>	<b>265.50</b>

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1R	57.24
Repair Painting	13.48
Surface-/Blend Paint	16.72
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>125.04</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR COVER BUMPER	6410B220WA	re.	80.69	300.00 ✓
2641	L/R BUMPER REINF	6410C543	x		10.00
2642	R/R BUMPER REINF	6410C544	x		10.00
2644	REAR BUMPER SUPPORT	6410B929	x		120.00 ✓
2672	R/R REFLECTOR	8355A040	x		15.00
8834	EXH PIPE ORNAMENTAL	1570A700	cut.		70.00 ✓

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

Claim Reference:  
 Assessment number: SGW9751C  
 Version: 1712  
 Date calculated: 01/15/2019 02:09 PM

Full Report  
 Registration: SGW9751C  
 Printed: 01/15/2019 2:09 PM

Code	Description	Part Number	Supplier	Price SGD
1000	RR BUMPER TOW CVR	1 / <i>PLS</i>		15.00 ✓
1001	RR BUMPER CLIPS (20)	1 / <i>MLC</i>		30.00 ✓
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			570.00
u: Used parts	<b>Addition(+15.00%)</b>			85.50
	<b>Total</b>			655.50

**Extras**

Code	Description	Price SGD
1002	CHECK WIRING <i>X NN</i>	40.00*
1003	REVERSE SENSOR (2) <i>R NN</i>	200.00*
	<b>Total Extras</b>	240.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>	570.00	
Addition(+15.00%)	85.50	
<b>Total Parts</b>		655.50
<b>Labour Time Base 10 WU/h</b>		
Total 56.0 WU X 45.00 SGD/h	252.00	
<b>Total of Labour</b>		252.00
<b>Total Of Extras</b>		240.00
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 59.0 WU X 45.00 SGD/h	265.50	
Material Cost	125.04	
<b>Total Paint Including Material</b>		390.54
<b>Repair Cost Excludes GST</b>		1,538.04
GST (+7.0%)		107.66
<b>Repair Cost Included GST</b>		1,645.70

**AH LIM Motor Company  
#01-09, AMK Autopoint, 10 Ang  
Mo Kio Ind. Park 2A  
568047**

**Claim Reference:**

**Assessment number: SGW9751C**

**Version: 1712**

**Date calculated: 01/15/2019 02:09 PM**

**Full Report**

**Registration: SGW9751C**

**Printed: 01/15/2019 2:09 PM**

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 1962G

### Vehicle Details

Vehicle No.: SGW9751C  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 18 Jan 2019  
Vehicle Make: MITSUBISHI  
Vehicle Model: LANCER 2.0L MIVEC GLS 6-CVT  
Primary Colour: Black  
Manufacturing Year: 2007  
Engine No.: 4B11AM6598  
Chassis No.: JMYSTCY4ABU000563  
Maximum Power Output: 114.0 kW (152 bhp)  
Open Market Value: \$16,819.00  
Original Registration Date: 06 Aug 2007  
First Registration Date: 06 Aug 2007  
Transfer Count: 1  
Actual ARF Paid: \$18,501.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 05 Aug 2022  
COE Category: B - Car (1601cc & above)  
COE Period(Years): 5  
PQP Paid: \$25,486.00  
COE Rebate Amount: \$18,086.00  
**Total Rebate Amount: \$18,086.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jan 2019

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1962G
Vehicle Details	
Vehicle No.:	SGW9751C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 2.0L MIVEC GLS 6-CVT
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	4B11AM6598
Chassis No.:	JMYSTCY4A8U000563
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$16,819.00
Original Registration Date:	06 Aug 2007
First Registration Date:	06 Aug 2007
Transfer Count:	1
Actual ARF Paid:	\$18,501.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,486.00
COE Rebate Amount:	\$18,086.00
<b>Total Rebate Amount:</b>	<b>\$18,086.00</b>
Message	
<p>Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>	

The information contained herein is correct as at 18 Jan 2019

OK

## << Service Request Details

Claim

S9M01AHZ

Reference

None ✎

Loss Date

January 11, 2019

Request Date

January 16, 2019

Due Date

January 23, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

*16017019 @ 10:45am  
mail vch not in*

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SGW9751C

Make

TPVD MITSUBISHI

---

**Service Address**

---

...

---

**Primary Contact/Insured**

---

TOCK KENG HAN  
3 SIN MING WALK, #04-25, 575575, Singapore  
98269841

---

**Claim Handler**

---

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

---

[New Message](#)

**Catherine Chong (LKK Auto)**

---

**From:** meili@almsm.com.sg  
**Sent:** Tuesday, 15 January, 2019 4:03 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** Request to register TP Claim - Our client vehicle SGW 9751C insured under FWD Ins against yr insured Vehicle SDX8789G acc on : 11/01/2019  
**Attachments:** 9751-Docs.pdf; 9751-Audatex Estimate.pdf; 9751-FWD.PDF  
**Categories:** Mateen

Dear Motor Claims Team,

We refer to the attachment.

Kindly assist to register our client's TP claim & arrange appointment for survey on our client's vehicle.

Regards,

Meili Tan - (Sin Ming)  
176 Sin Ming Drive  
#05-12 Sin Ming Autocare  
Singapore 575721  
Tel : 6456 3637 Fax: 6456 3686  
email : meili@almsm.com.sg



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 24/01/2020

### Survey Details:

Date of loss	11-Jan-19
Date of appointment	16-Jan-19
Date of survey	17-Jan-19
Location of survey	AH LIM MOTOR COMPANY

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SGW 9751C
Make and Model	MITSUBISHI LANCER
Date of registration	6/8/2007
Excess	
Market Value	\$22,000
Parf Rebate	\$18,086
Nett Loss	\$3,914

### Repair details:

Initial Estimate	\$	1,349.79
------------------	----	----------

### Proposed/Revised repair cost:

Parts	\$	615.25
Check items (estimate)	\$	-
Labour	\$	734.54
<b>Total</b>	<b>\$</b>	<b>1,349.79</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>1,050.00</b>

Number of days for repair	3
---------------------------	---



**Remarks:**

BOLA S28 (OI 2ND)

**Mandate:**

Liability(TP)		100%	
Proposed repair cost (W/GST)	\$	1,123.50	
Loss of use	\$	-	
Loss of rental	\$	300.00	3days x \$100
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others (AUDATEX FEE)	\$	42.00	
<b>Proposed Total</b>	<b>\$</b>	<b>1,467.50</b>	



## <MANDATE IA> - S9M01AHZ {ACCIDENT INVOLVING SDX 8789G (OI) & SGW 9751C (TP) ON 11/01/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S28 (OI 2ND) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1467.50 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL  
24/01/2020

Reply

# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : XIE YAO QUAN  
11 SIN MIN WALK  
#05-02 THOMSON GRAND  
SINGAPORE 575579

Final No: ALS1900564  
Claim No: MCS1900004  
Date: 06 Jan 2020  
Policy No: PNPV2017-00005683-01  
Veh Reg No: SGW9751C  
Make/Model: MITSUBISHI LANCER  
2.0L

ATTN:

Your Ref No: SGW9751C  
Claim Type: Third Party  
Accident Date: 11/01/2019  
TP Veh Reg No: SDX8789G

Chassis No:  
TP Ins Co: AXA

## Tax Invoice-Final Repair Cost to Vehicle No :SGW9751C

PAGE:1

Description	Quantity	List Price	Amount
-------------	----------	------------	--------

SS

SS

As agreed to proceed repair at Lump Sum Repair	S\$ 1,050.00
Add GST @ 7%	73.50
Total Amount payable	<u>S\$ 1,123.50</u>

TOTAL: SINGAPORE DOLLAR ONE THOUSAND ONE HUNDRED TWENTY THREE AND CENTS FIFTY ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 17/01/2019

For AH LIM MOTOR COMPANY

E. & O. E.

AH LIM MOTOR COMPANY  
176 SIN MING DRIVE #05-12  
SIN MING AUTOCARE SINGAPORE 575721  
Tel: 6456 3637 Fax: 6456 3686  
AUTHORISED SIGNATURE



Re:<MANDATE IA> - S9M01AHZ {ACCIDENT INVOLVING SDX 8789G (OI) & SGW 9751C (TP) ON 11/01/2019}

Type

 Question

Message

Pls proceed with your proposed mandate.

Reply

# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg  
GST:M9-0009639-E RCB NO:06470300B

---

Our Ref : MCS1900004

Date : 06/01/2020

AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

Dear Sir/Madam,

**Request for Direct Settlement for Accident involving our client's vehicle SGW9751C and your Insured SDX8789G ON 11/01/2019 19:30 ALONG MARYMOUNT RD TURING ONTO SIN MING AVENUE**

---

We refer to the above matter.

Please assess through your Insured's (SDX8789G) report and our Client (SGW9751C) – XIE YAO QUAN's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search

The above vehicle was surveyed by GUO QIANG from LKK as appointed by AXA on 17/01/2019.

We would quantify our claim as below:-

Cost of Repair	: \$1,123.50
Rental	: \$300.00(3 Day X 100) Surveyor recommend 3 days
Audatex Fee	: \$42.00
LTA Search	: \$2.00
=====	
Total	: \$1,467.50

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY  
176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 Fax: 6456 3686

Kee Mui Hong

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000988/Gga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:PETER

Date : 10-02-2020



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SDX 8789G	Veh. Inspected	SGW 9751C
Policy No.	VPA/P1856130	Coverage (\$)	0.00
Claim No.	S9M01AHZ	Excess (\$)	0.00
Assign From		Assign Date	16/01/2019

**2. Vehicle Particulars & Condition**

Make & Model	MITSUBISHI LANCER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JMYSTCY4A8U000563	Colour	BLACK
Odometer	138611	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	225/40 R18	FALKEN	5 mm
L/H Front Tyre	225/40 R18	FALKEN	5 mm
R/H Rear Tyre	225/40 R18	FALKEN	5 mm
L/H Rear Tyre	225/40 R18	FALKEN	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	11/01/2019	Inspection Date	17/01/2019
Survey held at	176 SIN MING DRIVE #05-12		
Repairer	AH LIM MOTOR COMPANY		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 9751C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR COVER BUMPER (CONSISTENT) (WCP)	DEFORMED	300.00	300.00
1	L/R BUMPER REINF (CONSISTENT) (WCP)	NOT NECESSARY	10.00	-
1	R/R BUMPER REINF (CONSISTENT) (WCP)	NOT NECESSARY	10.00	-
1	REAR BUMPER SUPPORT (CONSISTENT) (WCP)	BENT	120.00	120.00
1	R/R REFLECTOR (CONSISTENT) (WCP)	NOT NECESSARY	15.00	-
1	EXH PIPE ORNAMENTAL (CONSISTENT) (WCP)	CUT	70.00	70.00
1	RR BUMPER TOW CVR (CONSISTENT) (WCP)	MISSING	15.00	15.00
20	RR BUMPER CLIPS (CONSISTENT) (WCP)	NECESSARY	30.00	30.00
	COST PLUS 15%		85.50	80.25
			655.50	615.25
<b>SPECIAL NETT ITEMS</b>				
2	REVERSE SENSOR (SN)(CONSISTENT)	NOT NECESSARY	200.00	-
			200.00	-
<b>LABOUR</b>				
	CHECK WIRING .	NOT NECESSARY	40.00	-
	56.0 WU X 45.00 SGD/H.		256.50	256.50
	LABOUR COST 59.0 WU X45.00 SGD/H.		319.50	319.50
	MATERIAL COST .		158.54	158.54
			774.54	734.54
<b>GRAND TOTAL</b>			<b>1,630.04</b>	<b>1,349.79</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,050.00</b>

Report Ref No. CC4/ASM19000988/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim	SPM01AHZ
Reference	CC4/ASM19000988/Gg2h2 
Loss Date	11 January 2019
Report Date	14 Jan 2019 8:44:00 AM
Request Date	30 May 2019
Due Date	
Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

**Actions**

Next Step Wait for Approve Invoice

<b>Vehicle Information</b>	
Incident Vehicle Registration #	SGW9751C
Make	TPVD MITSUBISHI
Model	LANCER 2.0L MIVEC GLS-4-CVT
Service Address	

...

<b>Primary Contact/Insured</b>	
TUCK KENG HAN	
3 SIN MING WALK, #04-25, S75575, Singapore	
98269841	

<b>Claim Handler</b>	
KHOR Saw Theng	
6588804754	
sawtheng.khor@axa.com.sg	

### Additional Instructions

3 [Messages](#) [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

Document Type

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LUKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LUK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LKK Inspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LKK Adjustment (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
MANDATE IA DD 24012020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020
TP MARKED EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Qi rear video.MP4	Evidence	Videos	WANG Peter	24 January 2019
 Qi video.MP4	Evidence	Videos	WANG Peter	24 January 2019
 GIA REPORT OF SGW8751C.PDF	Reports & Statement	GIA Report	KADRI Mateen	16 January 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRJ).img	Letters and Correspondence	Workshop	KADRI Mateen	16 January 2019
 GIA REPORT OF SDX8789G (INSO).PDF	Reports & Statement	GIA Report	KADRI Mateen	16 January 2019
 GIA REPORT OF SLH4598T.PDF	Reports & Statement	GIA Report	KADRI Mateen	16 January 2019