

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|                   |   |                    |
|-------------------|---|--------------------|
| <b>Estimate</b>   | : | Accident Repairs   |
| <b>Workshop</b>   | : | Ubi Road 1         |
| <b>Contact No</b> | : | 6366 2323          |
| <b>Fax No</b>     | : | 6841 1183          |
| <b>Reference</b>  | : | PA/TP/0067/2019/GW |
| <b>Date</b>       | : | 16-Jan-19          |

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no:SKK 6192 B

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax 6880 4838**

|                          |   |                                                        |
|--------------------------|---|--------------------------------------------------------|
| <b>Owner's Name</b>      | : | Ms. Joanne See Mui Kheng                               |
| <b>Address</b>           | : | 781 Upper Changi Rd East<br>#03-36<br>Singapore 486069 |
| <b>Telephone</b>         | : | (HP) 98301888                                          |
| <b>Type of Claim</b>     | : | Third Party Claims                                     |
| <b>Policy No.</b>        | : | 1800106939                                             |
| <b>Vehicle No</b>        | : | <b>SLB 5577 S</b>                                      |
| <b>Model Code</b>        | : | A5 SB 2.0 TFSI                                         |
| <b>Model / Year</b>      | : | Sep-18                                                 |
| <b>Engine No</b>         | : | CVK 063501                                             |
| <b>Chassis No</b>        | : | WAUZZZF53JA107430                                      |
| <b>Mileage</b>           | : |                                                        |
| <b>Date In</b>           | : |                                                        |
| <b>Liability</b>         | : | -                                                      |
| <b>Excess Cost</b>       | : | -                                                      |
| <b>Estimated By</b>      | : | Johnny Boo / Allan Wu                                  |
| <b>Accident Date</b>     | : | 14-Jan-19                                              |
| <b>Place of Accident</b> | : | Along Havelock Road ( infront & MOM BLDG)              |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SLB 5577 S

| S/n                  | Nature of Jobs                                                                                                                            | Estimated Charges           |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| 1                    | To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.                                                    | S/N \$ 360.00 ✓             |
| 2                    | To dismantle and renew rear bumper. To repair lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed. | \$ 1,750.00 <del>700</del>  |
| 3                    | To respray rear bumper and lhs rear fender.                                                                                               | \$ 1,600.00 <del>1400</del> |
| 4                    | To carry out diagnostic check.                                                                                                            | S/N \$ 192.00 ✓             |
| TOTAL LABOUR CHARGES |                                                                                                                                           | : \$ <u>3,902.00</u>        |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLB 5577 S

|                                  |                                           | <u>Damaged Parts &amp; Prices</u> |                     |
|----------------------------------|-------------------------------------------|-----------------------------------|---------------------|
| <u>S/N</u>                       | <u>Parts Description</u>                  |                                   | <u>S/Nett</u>       |
| 1                                | REAR BUMPER <i>Delud</i>                  | \$                                | 2,311.00 ✓          |
| 2                                | REAR BUMPER FIXING PARTS <i>3 new</i>     | \$                                | 150.00 ✗            |
| 3                                | REAR BUMPER SECURING STRIP <i>?</i>       | \$                                | 203.00 ✗            |
| 4                                | REAR BUMPER CHORME TRIM <i>?</i>          | \$                                | 928.00 ?            |
| 5                                | REAR BUMPER CLIP-INNER <i>?</i>           | 11 \$                             | 426.00 ?            |
| 6                                | REAR BUMPER CLIP-OUTER <i>?</i>           | 4 \$                              | 155.00 ?            |
| 7                                | REAR LIGHT REFLECTOR-LH <i>?</i>          | \$                                | 38.00 ?             |
| 8                                | REAR BUMPER GUIDE SECTION-LH <i>3 new</i> | \$                                | 40.00 ✗             |
| 9                                | REAR BUMPER UPPER GUIDE SECTION-LH        | \$                                | 20.00 ✗             |
| 10                               | REAR BUMPER CARRIER <i>?</i>              | \$                                | 819.00 ✗            |
| 11                               | REAR SENSOR                               | \$                                | 231.00 ✗            |
| 12                               | REAR SENSOR SEAL RING <i>new</i>          | 4 \$                              | 12.00 ✗             |
| 13                               | LED TAILLIGHT-LH                          | \$                                | 1,044.00 ✗          |
| 14                               | LED TAILLIGHT TRIM-LH                     | \$                                | 27.00 ✗             |
| 15                               | SUNDRIES <i>?</i>                         | \$                                | 500.00 ?            |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                           | <b>:</b>                          | <b>\$ 6,904.00</b>  |
| <b>TOTAL LABOUR CHARGES</b>      |                                           |                                   | <b>\$ 3,902.00</b>  |
| <b>GRAND TOTAL</b>               |                                           |                                   | <b>\$ 10,806.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 18/11/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 Days

**Please Note** : This estimate is based on visual inspection of the affected  
Should we require further labour charges and spare parts  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant