



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 16.01.2019

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2085B TOYOTA PRIUS ALPHA 1.8L (2014)

To Supply

1) 1pc	Front bumper <i>repair</i>	\$	585.00
2) 1set	Front bumper clip <i>new</i>	\$	30.00
3) 1pc	Left side mirror cover <i>repair</i>	\$	72.40

Sub total Parts	\$	687.40
Less: 25% discount	\$	171.85
	\$	515.55

L/charges

- 1) To knock/welding left front fender, remove & replace front bumper & left side mirror cover. Align & adjust front bumper & fender \$ ~~350~~ 500.00
- 2) To putty, respray painting front bumper, left front fender & left side mirror cover. To polish \$ ~~450~~ 550.00

Sub total L/charges	\$	1,050.00
Estimated Grand Total	\$	1,565.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hp 900 10068
3 days
43
30/01/19 @ 1200 hrs
Repair after repair