

# BEST AUTO K PTE LTD

Co. GST Reg. No.: 201211041G

2 KAKI BUKIT AVE 2 #01-11 AUTO HUB SINGAPORE 417921

Tel: 6604 9883

Fax: 6604 9823

Email: bestautokpl@gmail.com

## REPAIR ESTIMATED

L.K. ANG CONSTRUCTION PTE LTD  
459 TAGORE INDUSTRIAL AVENUE  
#04-08 SINGAPORE 787828

Our Ref : RS2019/1801  
Date : 18/01/2019  
Vehicle No : PC 7619 P  
Model : Toyota HiAceDX 2.8 Auto  
Accident Date : 12/01/2019

### INSURANCE CO :-

CHINA TAIPING INSURANCE (SINGAPORE) PTE .LTD.  
3 ANSON ROAD, #16-00  
SPRINGLEAF TOWER SINGAPORE 079909

TEL : 6389 6116 FAX : 6225 3592

Item	Description	Qty	U/Price	Amount
1.	RADIATOR	1	1,200.00	1,200.00 NN X
2.	RADIATOR SPARE TANK	1	285.00	285.00 NN X
3.	RADIATOR SUPPORT	1	380.00	380.00 ?
4.	FRONT LEFT HEAD LAMP	1	1,980.00	1,980.00 BR ✓
5.	FRONT BUMPER	1	450.00	450.00 BR ✓
6.	FRONT BORNET	1	580.00	580.00 DD ✓
7.	FRONT GRILLE	1	360.00	360.00 BR ✓
8.	BUMPER BRAKET (LEFT)	1	900.00	900.00 BR ✓
9.	PANEL BEATING FRONT BODY	1	600.00	600.00 ✓
10.	ADD BLUE SPARE TANK	1	450.00	450.00 CRU ✓
11.	AIRCOND CONDENSOR	1	960.00	960.00 ?
12.	WITH LABOUR TO REPLACE	1	650.00	650.00
	WIRING REPAIR			
	ALIGN BONET			
	FRONT BUMPER			
	HEAD LAMP			

- ALL ABOVE IS ORIGINAL PARTS.

The details and the estimate provided above are based on our first inspection and do not constitute a guarantee that no further work/parts will be required. The total bill of work will be as per the details available on completion of the work.

Other terms and conditions as applicable.

Sub Total 8,795.00

GST 7.0 % 615.65

Total 9,410.65

Yours faithfully,

Administrator

hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: