

ASS. REC. BY:

REF:

es/FCI19000999/Thd3^{SP}

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time: 2.01pm @ 16/1/19

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SS 888E

Insured:

SHC 1070E

at Workshop m/s:

Kah Motor

Tel:

9072 1769

of

255 Alexandra Road

Policy No:

Claim No:

D19000438 MP84

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3.26pm @ 16/1/19

Person Contacted:

Sin Hui

Vehicle IN:

OUT

Date/Time	Action/Instruction (✓) Estimate	
	ES 888E - CC4 / AXA 10025917 / Ry/bk2	DOA: 18/12/2010
	SHC 1070E - CS / FCI 18005760 / Brd3e2	DOA: 28/3/18
18/1/19	Email preli revised to FCI	

MOTOR SURVEY ASSIGNMENT

Date	15-01-2019	Our Ref No. D19000438MFSH
Accident Date	14-01-2019	Claim Type. Third Party
Insured Vehicle	SHC1070E	Third Party Vehicle. SS888E
Survey Location	255 ALEXANDRA ROAD BODY REPAIR & PAINT CENTRE	
Contact Person.	NG SIN HAI	
Contact No.	64715419/ 90721769	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 28 February 2019 9:25 AM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000438MFSH/1, SS 888E
Attachments: SS 888E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SS 888E
Date of survey: 26/2/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 16 January 2019 3:29 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000438MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 16 January 2019 2:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin

<maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000438MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000438MFSH

Our ref: CS/FCI19000999/T1vd3

Date: 28/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SS 888E


We thank you for your instruction on 16/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on
26/2/2019 at the premises of M/s KAH MOTOR CO SDN BHD
and have the following to report:-

Workshop Estimate Amount	: S\$8,421.60
Revised Estimate Amount	: S\$3,689.64
"Check" Items Amount	: S\$913.04
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 21:46
Date Of Accident	14/01/2019 09:40
Exact Location Of Accident	CLEMENTI AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SS888E
-----------------------------	--------

Insured/Policyholder

Name Of Registered Owner	CHIEW PENG CHOO
NRIC No	S0320879F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98183733
Alternative Phone No	OFFICE-98183733

Vehicle Particulars

Manufacturer	HONDA
Model	CR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHIEW PENG CHOO
NRIC No	S0320879F
Date Of Birth	27/06/1948
Occupation	INDOOR
Date Of Driving Pass	25/06/1979
Driving Experience	39 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98183733
Fax Number	
Contact Number	OFFICE-98183733
Email Address	NOEMAIL

Sketch Plan

Vehicle No _____

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to remediate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]


[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SS888E
 Chassis No : MRHRW1860JP000010
 Model : CRV 1.5L TURBO YM2018 (5 SEATER)
 Owner's Name : CHIEW PENG CHOO
 Ins Policy No. :
 Date of Accident : 14/1/2019

Document No. : SQT19000280
 Date : 15. Jan 2019
 Customer No. : WZF002
 Svc Advisor :
 Engine No : L15BG1106908
 Date | Time : 15. Jan 2019 8:41:59 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
71101-TMC-U00ZZ	FACE, FR. BUMPER <i>de</i>	1	548.30	25	411.22 ✓	28.79	440.01
71100-TMC-U10ZZ	FACE ASSY, FR. BUMPER <i>? X nn</i>	1	548.30	25	411.22	28.79	440.01
71130-TME-T12	BEAM COMP, FR. BUMPER <i>? X nn</i>	1	480.80	25	360.60	25.24	385.84
71102-TME-T00	FACE, FR. BUMPER LOWER <i>cut</i>	1	530.40	25	397.80 ✓	27.85	425.65
71190-TME-T01	BEAM, FR. BUMPER L. CORNER UPP <i>? X nn</i>	1	42.50	25	31.87	2.23	34.10
71193-TME-T01	SPACER, R. FR. BUMPER SIDE <i>X nn</i>	1	11.90	25	8.92	0.62	9.54
71198-TME-T01	SPACER, L. FR. BUMPER SIDE <i>new</i>	1	11.90	25	8.92 ✓	0.62	9.54
91505-TM8-003	CLIP, BUMPER <i>new</i>	14	2.30	25	24.15 ✓	1.69	25.84
71110-TME-T01	GARNISH, FR. BUMPER SKID <i>X nn</i>	1	29.90	25	22.42	1.57	23.99
33150-TLA-T11	HEADLIGHT ASSY, L. <i>X nn</i>	1	1836.50	25	1377.37	96.42	1473.79
33950-SLE-J51	LIGHT ASSYL, FR. FOG LIGHT <i>X</i>	1	239.70	25	179.77	12.58	192.35
71166-TME-T00	BRACKET, L. FR. FOG LIGHT <i>X } fan</i>	1	8.40	25	6.30	0.44	6.74
71156-TMC-T00	GARNISH, L. FR. FOG LIGHT <i>X</i>	1	29.40	25	22.05	1.54	23.59
39680-TEX-Y41ZT	SENSOR ASSY, PARKING <i>? X nn</i>	1	145.80	25	109.35	7.65	117.00
74165-TME-T01	PROTECTOR, L. FR. WHEEL ARCH <i>cut</i>	1	23.40	25	17.55 ✓	1.23	18.78
60261-TLA-A00ZZ	PANEL, L. FR. FENDER <i>RX</i>	1	631.10	25	473.32	33.13	506.45
74150-TME-T00	FENDER ASSY, L. FR. INNER <i>X nn</i>	1	145.50	25	109.12	7.64	116.76
74207-TLA-A00	GARNISH, L. FR. FENDER <i>X nn</i>	1	26.20	25	19.65	1.38	21.03
Sum Item					3991.60	279.41	4,271.01

Printed on 26/2/2019 9:55:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SS888E
 Chassis No : MRHRW1860JP000010
 Model : CRV 1.5L TURBO YM2018 (5 SEATER)
 Owner's Name : CHIEW PENG CHOO
 Ins Policy No. :
 Date of Accident : 14/1/2019

Document No. : SQT19000280
 Date : 15. Jan 2019
 Customer No. : WZF002
 Svc Advisor :
 Engine No : L15BG1106908
 Date | Time : 15. Jan 2019 8:41:59 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30. ✓	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	✓ ✓	180.00	12.60	192.60
BA01R	REMOVE & INSTALL SIDE CORNER SENSORS-2 PCS (N)	1	150.00	✓ ✓	150.00	10.50	160.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	2000.00	1120 ✓	2000.00	140.00	2140.00
BP02R	SPRAY PAINT ON REPAIRED/REPLACED AREAS. (2PX- \$450)	1	2000.00	1350 ✓	2000.00	140.00	2140.00
Sum Labor					4430.00	310.10	4,740.10

Survey By
 Date & Time
 Excess
 Status
 Signature

Tanpin 97495469
 26/2/19 1040
 wp.
 [Signature]

[Signature]
 28/1/19

Total Amount 8,421.60 589.51 9,011.11
 Total (Inclusive of GST) 9,011.11

8641.71

Surveyor's.com
 Resurvey before paint.
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Printed on 26/2/2019 9:55:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Acknowledged by Repairer
 Signature
 Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHRW1860JP000010
License No: SS888E
Mileage: 18524
Engine No: L15BG1106908

Document No: SVO19012583
Printed By: SHNG
Order Date: 26. February 2019
Order Time: 11:39:08 AM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CHIEW PENG CHOO OWNER INSURER:AVIVA ACC DATE:14/01/2019 SURVEYED BY:TAUFIKH DATE:26/02/2019 REF NO: TP INSURER:MS FIRST CAP TP VEH:SHC1070E SUPPLEMENTARY PART							
71101-TMC-U00ZZ	FACE, FR. BUMPER	1	548.30	25	411.22	28.79	440.01	
71102-TME-T00	FACE, FR. BUMPER LOWER	1	530.40	25	397.80	27.85	425.65	
71198-TME-T01	SPACER, L. FR. BUMPER SIDE	1	11.90	25	8.92	0.62	9.54	
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84	
74165-TME-T01	PROTECTOR, L. FR. WHEEL ARCH	1	23.40	25	17.55	1.23	18.78	
71121-TME-T00	BASE, FR. GRILLE (A)	1	154.00	25	115.50	8.09	123.59	
71123-TME-T00	MOLDING B, R. FR. GRILLE (A)	1	52.90	25	39.67	2.78	42.45	
71173-TME-T00	MOLDING B, L. FR. GRILLE (A)	1	52.90	25	39.67	2.78	42.45	
75700-SZW-000	EMBLEMH MARK (A)	1	29.50	25	22.12	1.55	23.67	
90301-ST0-003	NUTPUSH 3MM (A)	2	2.10	25	3.15	0.22	3.37	
	SUM PARTS:				1,079.75	75.60	1,155.35	
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10	
BML01I	0701 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	180.00		180.00	12.60	192.60	
BA01R	0669 REMOVE & INSTALL SIDE CORNER SENSORS-2 PCS (N)	1	150.00		150.00	10.50	160.50	
BKBH01S	0669 STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40	
BP02R	1610 SPRAY PAINT ON REPAIRED/REPLACED AREAS.(2PX\$450)	1	1,350.00		1,350.00	94.50	1,444.50	
	SUM LABOUR:				2,830.00	198.10	3,028.10	
	TOTAL SGD				3,909.75	273.70	4,183.45	
	Total Payable (SGD)						4,183.45	

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****0879F / CHIEW PENG CHOO
Chassis No: MRHRW1860JP000010
License No: SS888E
Mileage: 18524
Engine No: L15BG1106908

Document No: SVO19012583
Printed By: SHNG
Order Date: 26. February 2019
Order Time: 11:39:08 AM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
71121-TME-T00	BASE, FR. GRILLE	1	154.00	25	115.50	8.09	123.59
71123-TME-T00	MOLDING B, R. FR. GRILLE	1	52.90	25	39.67	2.78	42.45
71173-TME-T00	MOLDING B, L. FR. GRILLE	1	52.90	25	39.67	2.78	42.45
75700-SZW-000	EMBLEMH MARK	1	29.50	25	22.12	1.55	23.67
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
	SUM PARTS:				220.11	15.42	235.53
	TOTAL SGD				220.11	15.42	235.53

Total Payable (SGD)

235.53

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Taufikh (LKKAUTO)
Sent: Wednesday, 6 March 2019 3:29 PM
To: 'Ng Sin Hai'
Cc: Veron Chen (LKKAUTO)
Subject: RE: Submission Pre-Invoice for vehicle SS888E

Hi Sin Hai,

COR \$3909.75 , 5 days.

Regards
Taufikh
Lkk AUTO

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Tuesday, 5 March 2019 7:40 PM
To: Taufikh@lkkauto.com; SUR
Subject: RE: Submission Pre-Invoice for vehicle SS888E

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$3,909.75 (before GST)
No of working days : 05 days. (LOU)

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19000999/T1vd3s2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 07-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1070E	Veh. Inspected	SS 888E
Policy No.		Coverage (\$)	0.00
Claim No.	D19000438MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	16/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CRV	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHRW1860JP000010	Colour	WHITE
Odometer	027454	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/65R17	GOODYEAR	6 mm
L/H Front Tyre	235/65R17	GOODYEAR	6 mm
R/H Rear Tyre	235/65R17	GOODYEAR	6 mm
L/H Rear Tyre	235/65R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/01/2019	Inspection Date	26/02/2019
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SS 888E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE, FR. BUMPER (SN)	DEFORMED	411.22	411.22
1	FACE ASSY, FR. BUMPER (SN)	NOT NECESSARY	411.22	-
1	BEAM COMP, FR. BUMPER (SN)	NOT NECESSARY	360.60	-
1	FACE, FR. BUMPER LOWER (SN)	CUT	397.80	397.80
1	BEAM, FR. BUMPER L.CORNER UPP (SN)	NOT NECESSARY	31.87	-
1	SPACER, R. FR. BUMPER SIDE (SN)	NOT NECESSARY	8.92	-
1	SPACER, L. FR. BUMPER SIDE (SN)	NECESSARY	8.92	8.92
14	CLIP,BUMPER (SN)	NECESSARY	24.15	24.15
1	GARNISH, FR. BUMPER SKID (SN)	NOT NECESSARY	22.42	-
1	HEADLIGHT ASSY, L. (SN)	NOT NECESSARY	1,377.37	-
1	LIGHT ASSYL.FR.FOGLIGHT (SN)	NOT NECESSARY	179.77	-
1	BRACKET, L. FR. FOG LIGHT (SN)	NOT NECESSARY	6.30	-
1	GARNISH, L. FR. FOG LIGHT (SN)	NOT NECESSARY	22.05	-
1	SENSOR ASSY,PARKING (SN)	NOT NECESSARY	109.35	-
1	PROTECTOR, L. FR. WHEEL ARCH (SN)	CUT	17.55	17.55
1	PANEL, L. FR. FENDER (SN)	TO REPAIR SEE LABOUR	473.32	-
1	FENDER ASSY, L. FR. INNER (SN)	NOT NECESSARY	109.12	-
1	GARNISH, L. FR. FENDER (SN)	NOT NECESSARY	19.65	-
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	BASE, FR. GRILLE (SN) (ADDITIONAL)	CRACKED	115.50	115.50
1	MOLDING B, R. FR. GRILLE (SN) (ADDITIONAL)	CUT	39.67	39.67
1	MOLDING B, L. FR. GRILLE (SN) (ADDITIONAL)	CUT	39.67	39.67
1	EMBLEMH MARK (SN) (ADDITIONAL)	NECESSARY	22.12	22.12
2	NUTPUSH 3MM (SN) (ADDITIONAL)	NECESSARY	3.15	3.15
			4,311.71	1,109.75
LABOUR				
INSPECT FR LIGHTING MECHANISMS & FOCUS.			180.00	180.00
REMOVE & INSTALL SIDE CORNER SENSORS.			150.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	STRAIGHTEN ALIGN BIULKHEAD & RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF PANEL, L. FR. FENDER.		2,000.00	1,120.00
	SPRAY PAINT ON REPAIRED / REPLACED AREAS.		2,000.00	1,350.00
			4,330.00	2,800.00
GRAND TOTAL			8,641.71	3,909.75
RECOMMENDED COST OF REPAIRS				3,909.75

Report Ref No. CS/FCI19000999/T1vd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.