

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4007
Date Estimated : 18/01/2019
Prepared By : Chong Min Seng

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Raphael Nyoe Song Sue
Blk 753 Woodlands Circle
#11-548

Singapore 730753

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD2256R	WF05XXGCC5FE08246	28/08/2015	FOCUS 1.6 TITN 5DR	15

DESCRIPTION

VALUE

TO CONDUCT TP CLAIM - INDIA INTERNATIONAL

0.00

SUNDRIES

30- 150.00

LABOUR TO REMOVE, REALIGN, REPLACE REAR BUMPER, TAIL GATE AND ALL AFFECTED AREA

600- 2,400.00

TO REMOVE AND REFIX REAR BUMPER REVERSE SENSOR, CONDUCT DISTANCE SETTING (NETT)

✓ 150.00

LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAIL GATE AND ALL AFFECTED AREA.

600- 1,800.00

TO REMOVE AND REPLACE REAR WINDSHIELD, CONDUCT WATER LEAK TEST (NETT)

X 600.00

TO TRANSFER REAR TAIL GATE COMPONENTS, FIXING, TRIMS RETAINERS BOARDS, AND ALL OTHER NECESSARY COMPONENTS (NETT)

X 300.00

SEALANT FOR TAIL GATE (PER PANEL \$90 NETT)

X 180.00

INNER SEAL FOR REAR WINDSCREEN (NETT)

Y 60.00

SEALANT FOR REAR WINDSCREEN (NETT)

X 60.00

TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS. (PER PANEL \$60 NETT)

X 180.00

TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE. (NETT)

✓ 600.00

Total Labour 1:

6,480.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB17906ABX	REAR BUMPER - 5DR	1	1,314.00	10.00	de ✓ 1,182.60
WAA					
BM51A17B861A	CENTER BRACKET PLASTIC - ^{Per} FRONT BUMPER	1	125.00	10.00	? 112.50
E					
F1EB17F954AB	REAR BUMPER LWR EXTENSION	1	335.00	10.00	de ✓ 301.50
BM51A17B918A	RR BPR MOUNTING BRACKET	1	40.00	10.00	? 36.00
E					

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : **BG 4007**
Date Estimated : **18/01/2019**
Prepared By : **Chong Min Seng**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD2256R	WF05XXGCC5FE08246	28/08/2015	FOCUS 1.6 TITN 5DR	15

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
BM51A403C94A	RR BPR REINFORCEMENT - F11	1	626.00	10.00	? 563.40
F					
F1EB17E850DC	BRACKET - BUMPER MOUNTING, RH	1	75.00	10.00	? 67.50
F1EB17E851DC	RR BUMPER SIDE BRACKET LH	1	75.00	10.00	? 67.50
F1EB17A881AA	MOUNTING - SIDE BRACKET RHR BUMPER	1	63.00	10.00	? 56.70
F1EB17A882AA	MOUNTING - SIDE BRACKET LHR BUMPER	1	63.00	10.00	? 56.70
F1EB13B415AB	RR BUMPER REFLECTOR LH	1	70.00	10.00	? 63.00
F1CT15K859AA	PARKING SENSOR RR	1	87.00	10.00	? 78.30
5BRQ					
BM5T15K872AC	RR PARKING AID BRACKET CTR, UNPRIMED	4	58.00	10.00	? 208.80
XUAA					
F1ET15K868AD	RR PARKING AID, JUMPER WIRING	1	161.00	10.00	? 144.90
D					
PF1EBA40410A	TAILGATE	1	1,580.00	10.00	X 1,422.00
C					
BM51A404A06S	WEATHERSTRIP, TAILGATE - EC02.0 ST	1	350.00	10.00	X 315.00
B					

Total Parts : 4,676.40

Tanji 97495749
up
18/1/19 245pm
3 days
Resurvey. before painting
sure lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Service Officer

Contact

Labour 1	:	6,480.00
Parts	:	4,676.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	780.95
Grand Total	:	11,937.35

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.