



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 16.01.2019

China Taiping Insurance (S) Pte Ltd

2 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLT4750U MAZDA 2 (2017)

To Supply

1)	1pc	Left front fender <i>repair</i>	\$	323.10
2)	1pc	Left front door <i>repair</i>	\$	1,109.30
3)	1pc	Left side mirror cover <i>repair</i>	\$	122.00

Sub total Parts	\$	1,554.40
Less: 20% discount	\$	310.88
	\$	1,243.52

L/charges

1)	To tuff kote	\$	50.00 30
2)	To transfer left front door trim board, glass, handle & mechanism parts	\$	60.00 40
3)	To remove left front fender, left front door & left side mirror cover. Replace the above parts. Align & adjust door & fender.	\$	500.00 300
4)	To putty, respray painting left front fender, left front door inlet & outer, left rear door outer, left rear fender & left side mirror cover. To polish	\$	900.00 500

Sub total L/charges	\$	1,510.00
Estimated Grand Total	\$	2,753.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *after* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur

Ap 900/0068

4 days

P/R

17/01/19 @ 1250

Resurvy after repair