

Asher

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Page No. :

Estimate No. : b1 49784
Date Estimated : 16/01/2019
Prepared By : Chua Kee Sin

REPAIR FOR -
J Vijay
409B Fernvale Road
#08-54

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 792409

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE	ORIGINAL PRICE	DISC. %	NETT
SJF528U	NU32262	31/10/2016	318iA/4Dr	0			
DESCRIPTION					ORIGINAL PRICE	DISC. %	NETT
①	To replace rear bumper and attachments include knocking out dents caused by the accident				850.00		850.00
②	To spray paint rear bumper				934.20		934.20
③	To check electrical wiring systems and lightings at the rear section for proper function				150.00		150.00
④	Sundries				80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
⑤ REAR BUMPER PANEL PRIMED (LINES)	1,172.30	1.00		1,172.30
⑥ SET MOUNTING PDC/PMA SENSOR REAR	66.95	1.00		66.95
⑦ DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
⑧ # (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,014.20
Total Parts :	1,312.50
Total Labour & Parts :	3,326.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,326.70
GST @7%:	232.87
Grand Total :	3,559.57

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49784
Date Estimated : 16/01/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
J Vijay
409B Fernvale Road
#08-54
Singapore 792409

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SJF528U	NU32262	31/10/2016	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
⑧ # (DG/SL) ADHESIVE SET K6 * / NEC	53.05	1.00		53.05

Total Labour :	
Total Parts :	53.05
Total Labour & Parts :	53.05

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528
63190533/53
Fax. 64796601
64796624

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- Subject to final approval from Insurance Company

(AfterSales)
Approved by Repairer
Signature:
Date:

GST REG. NO : M2 - 0020081 - X

16 JAN 2019

ESTIMATE

Estimate No. : b1 49784		Page No. : 1 of 5	
Date Estimated : 16/01/2019			
Prepared By : Chua Kee Sin			
- ESTIMATE REPAIR FOR - J Vijay 409B Fernvale Road #08-54 Singapore 792409		- ACCOUNT - 40000 Cash Sales - Service Singapore	
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL
SJF528U	NU32262	31/10/2016	318iA/4Dr
			MILEAGE
			0

DESCRIPTION	VALUE
① Replace rear bumper and remove attachment etc include knock on accident dent	850 / 1,275.00
② Spray painting rear bumper	934.20 / 1,038.00
③ To check electrical wiring systems and lightings at the rear section for proper function.	150 / 177.00
④ Sundries.	50 / 40.00
Total Labour 1: 2,530.00	

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TIP BLACK CHROME X NN	1	118.65	118.65
REAR BUMPER CENTRE GUIDE	1	32.90	32.90
REAR BUMPER CARRIER (ECE)	1	467.95	467.95
REAR BUMPER BLACK TRIM STRIP	1	81.40	81.40
REAR BUMPER PANEL PRIMED (LINES) DO	1	1,172.30	1,172.30
(S/L) LH PROTECTION FOIL	1	7.90	7.90
(S/L) RH PROTECTION FOIL	1	7.90	7.90
SET MOUNTING PDC/PMA SENSOR REAR	1	66.95	66.95
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR MINERALWEISS (A96)	2	368.80	737.60
Total Parts :			2,713.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 49784	Page No. : 2 of 5
Date Estimated	: 16/01/2019	
Prepared By	: Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJF528U	NU32262	31/10/2016	318iA/4Dr	0

with private Resy before & Aft spray

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date&Time 20/2/19 11.50am	Excess S\$
Surveyor's Name Steve (LKK)	Sign
Surveyor's Tel 8329 8813	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail Steve@lkk.com	
No. of Working Days Recommend 3 days	

Labour 1	:	2,530.00
Parts	:	2,713.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	367.06
Grand Total	:	5,610.81

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **