

INS. CASE OWNER:

RA

CC 4, Asm 1900 1038

A ka352

LKK:

IDAC:

93752

Surveyor:

WNP

DOI:

17/1/2019

Date / Time:

16-01/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 9530 Y

Name of Insured:

Tlc svs pte

Insured Tel No.:

HP:

Excess Sec II :SS

5,000.00

D.O.A:

12/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLQ5066



INSRS:

WSP:

Tel:

Liability:

RMKS:

1st mbo



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

23/1/19

SLQ5066 - X.
SHB 9530 Y - 02/11/17 2481 / ka352; 008 18/1/19
02/11/17 2481 / ka352; 008 9/12/15
- MINUS

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 14/03/19 - suha

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: suha

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PR

SS 5748.80 (3 days) Reduction: 47 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

WNN

SS 5615.90

COLD LTR - ENDED TP

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

180.00 (s60 x 3 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee: 5750.10

Total:

SS

5803.35

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

5803.35

Name 1:

1st Autoworks Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or NoLum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLQ506B Yr Regn: 2017, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Mokka C.C. 1598Colour: Red A/C: Insured / Std / NI / NASp. Reading: 121289 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLJDTECSHB179333Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R18R: 215/55R8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Camdorses

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 17/01/19Survey held at: 1st AutoworkDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA.

P/B 25,248.50

CRW: 4,731.90 (47%)

MV: 75K.

PV: 51.7K.

Net: 23.3K.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

) S + RG \$4

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

6
01-27
Hire
In-Stock

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	3483E
Vehicle Details	
Vehicle No.:	SLQ506B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jan 2019
Vehicle Make:	OPEL
Vehicle Model:	MOKKA X 1.6 CDTI 6AT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	A1170165GU7X0137
Chassis No.:	W0LJD7EC5HB179333
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,376.00
Original Registration Date:	27 Jun 2017
First Registration Date:	27 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$15,527.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2027
PARF Rebate Amount:	\$11,645.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,526.00
COE Rebate Amount:	\$40,088.00
Total Rebate Amount:	\$51,733.00

The information contained herein is correct as at 17 Jan 2019

OK



ANNOUNCING BENEFIT AUTO

as sgCarMart Premium Dealer for the 5th Consecutive Year

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

1 Owner, Aug 2016 Volkswagen Passat 2.0A TSI R-Line.



Only 14400km! As Good As New
Car Condition! Agent Maintain &
Warranty!
Auto Zoom Enterprise StarAd



- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

2 vehicles

Search Opel Mokka

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Opel Mokka

Any

Any

2017

Any

Any

Any

Available



☐ Opel Mokka X Diesel 1.6A

\$72,800

\$8,060 /yr

20-Jan-2017

1,598 cc

23,031 km

SUV

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Arrange Call To Our Sales For Appointment!

Benefit Auto Enterprise Pte Ltd

Posted: 17-Jan-2019 Tags: 2017 Opel Mokka, 2017 opel mokka, Opel Mokka, opel mokka, Opel, Mokka, mokka, Used Opel



☐ Opel Mokka X Diesel 1.6A

\$78,388

\$8,560 /yr

28-Mar-2017

1,598 cc

58,000 km

SUV

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Up To 90% Loan! From \$1,130/Month. Single Lady Owner, Fully Maintained By Agent Coupled With Agent Warranty Till 2020. Rare Compact Suv On The Road, Well-Rounded Package That Proves Strong On Fuel Eco...

Cars 88 Pte Ltd

Posted: 10-Jan-2019 Tags: 2017 Opel Mokka, 2017 opel mokka, Opel Mokka, opel mokka, Opel, Mokka, mokka, Used Opel

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from van, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Opel Mokka, Opel Mokka Singapore, used Opel Mokka Singapore, used Opel Mokka, used vehicles Singapore or even buy used Opel Mokka Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



Download on the
App Store



GET IT ON
Google play

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 12/8/2013

Reference: SLQ506B
OPEL MOKKA X
Make: 1.6 CDTI 6AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLQ506B
CHASSIS NO.: W0LJD7EC5HB179333
ENGINE NO.: A1170165GU7X0137

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 12/01/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Bumper	\$ 1,800.00
2	1	Rear Bumper Lower	\$ 1,390.00
3	1	Rear Bumper Towing Cover	\$ 90.00
4	1	Rear Bumper Sill Plate	\$ 344.00
5	1	LHF Bumper Reflector	\$ 150.00
6	1	RHF Bumper Reflector	\$ 150.00
7	1	Rear Bumper Reinforcement Bar	\$ 671.00
8	1	Rear End Panel	\$ 1,217.00
9	1	Rear End Panel Trim	\$ 150.00
10	1	Rear Bumper Absorber - RH	\$ 82.00
11	1	Rear Bumper Absorber - LH	\$ 82.00
12	1	LHR Bumper Bracket, Guide	\$ 70.00
13	1	RHR Bumper Bracket, Guide	\$ 70.00
14	1	LHR Bumper Bracket	\$ 65.00
15	1	RHR Bumper Bracket	\$ 65.00
16	1	LHR Lower Bumper Bracket	\$ 80.00
17	1	RHR Lower Bumper Bracket	\$ 80.00

Parts Total: \$ 6,556.00
Less 10%: \$ 655.60

4565
4108.50

Total : \$ 5,900.40

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>	
Rear portion			
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 1,650.00	550
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 1,350.00	450
3	To conduct anti rust of under carriage tuff coat	\$ 200.00	x
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	To remove and refix reverse sensor and conduct test	\$ 80.00	50

1080

Labour Total : \$ 3,310.00

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>	
Rear portion				
1	10	Rear bumper upper clip <i>gan</i>	\$ 65.00	30
2	10	Rear bumper lower clip <i>gan</i>	\$ 65.00	30
3	1	Reverse sensor 1 set <i>nt m</i>	\$ 640.00	x

60

Other Total: \$ 770.00

GRAND TOTAL: \$ 9,980.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Suhaimi O

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

Adnan King
P/p 17/01/19

030 days.

total: 5248.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

A/m Advancing
fundraising

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AXA Insurance Pte Ltd
Cecil Street #01-01 GB Building
Singapore 069542

GST Ref. No: 20-0000274-Z

Vehicle No: SLQ506B
Chasis No: W0LJD7EC5HB179333
Engine No: A1170165GU7X0137

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	Rear Bumper	\$ 1,800.00
2	1	Rear Bumper Lower	\$ 1,390.00
3	1	Rear Bumper Towing Cover	\$ 90.00
4	1	Rear Bumper Sill Plate	\$ 344.00
5	1	Rear Bumper Reinforcement Bar	\$ 671.00
6	1	LHR Bumper Bracket, Guide	\$ 70.00
7	1	RHR Bumper Bracket, Guide	\$ 70.00
8	1	LHR Bumper Bracket	\$ 65.00
9	1	RHR Bumper Bracket	\$ 65.00

Total: S 4,565.00
Less 10%: S 456.50
Parts Total : S 4,108.50

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 550.00
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 450.00

<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00

Labour Total : \$ 1,080.00

Other

<u>No.</u>		<u>Other Description</u>	<u>Price (SGD)</u>
1	10	Rear bumper upper clip	\$ 30.00
2	10	Rear bumper lower clip	\$ 30.00

Other Total : \$ 60.00

Total : \$ 5,248.50

GST (7%) \$ 367.40

Grand Total: \$ 5,615.90

Yours Faithfully,




Suhaimi Ong

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.


Please check and finalize with me this invoice

Service Request Details

Claim

S9M01AH4

Reference

None 

Loss Date

January 12, 2019

Request Date

January 16, 2019

Due Date

January 23, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLQ506B

Make

TPVD OPEL

9189 2617
16/01/2019 @ 3:54pm
Subsidiary veh not in.

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

1/16/19 12:15 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

S9M01AH4

BODY

PLEASE SHARE DOCUMENTS



TYPE



SENT

1/16/19 10:53 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

BODY

Kindly assist provide us the workshop detail.



Catherine Chong (LKK Auto)

From: Suhaimi <suhaimi@firstautoworks.com.sg>
Sent: Tuesday, 15 January, 2019 6:36 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: fw: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019
Attachments: SLQ506B - 3 PARTY.PDF
Categories: Namrata

Dear Sirs,

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

- 1)
- 2)
- 3)

Take Notice : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Please note that this notification does not in any way prejudice our client(s) rights nor shall it be deemed as a waiver of any of their rights, as such our client(s) rights are expressly reserved.

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185



<TP - Mandate IA> - S9M01AH4 [ACCIDENT INVOLVING SHB 9530Y(OI) & SLQ 506B(TP) ON 12/01/2019]

Type

🔗 Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best. We seek your mandate at \$5,803.35(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong -28 July 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/07/2019

Survey Details:

Date of loss	12.01.2019
Date of appointment	16.01.2019
Date of survey	17.01.2019
Location of survey	1ST AUTOWORKS PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLQ506B
Make and Model	Opel Mokka (1598cc)
Date of registration	27.06.2017
Excess	
Market Value/ Book Value	\$ 75,000.00 (est)
Parf/COE Rebate	\$ 51,733.00 (est)
Nett Value/ ERV	\$ 23,267.00 (est)

Repair details:

Initial Estimate	\$ 9,980.40
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,168.50
Check items (estimate)	NIL
Labour	\$ 1,080.00
Supplementary	NIL
Total	\$ 5,248.50
Lump Sum(if applicable)	

Number of days for repair	<u>3</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 5,615.90	
Loss of use	\$ 180.00	(3days x \$60.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 5,803.35	

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 30 July 2019 9:08 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 93752, vehicle number SLQ506B

Message HI, pls proceed as per mandate. TY.

-----Original Message-----

From: richard.angbs@axa.com.sg [mailto:richard.angbs@axa.com.sg]
Sent: Tuesday, 30 July, 2019 3:59 PM
To: admin-d@lkkauto.com
Subject: New message for service request 93752, vehicle number SLQ506B

AXA Insurance has sent you a message for claim number S9M01AH4.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 7 August 2019 9:35 AM
To: suhaimi@firstautoworks.com.sg
Cc: Admin A
Subject: RE: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019 *** LKK REF: CC4/ASM19001038/Apa3
Attachments: EXPRESS SETTLEMENT FORM_SLQ506B.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 5,615.90
2. Loss of Use(3days x \$60.00)	\$ 180.00
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	<u>\$ 5,803.35</u>

If our offer is acceptable by your client, please duly sign the document enclosed and return to us for our necessary action.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Suhaimi <suhaimi@firstautoworks.com.sg>

Sent: Thursday, 25 July 2019 12:10 PM

To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019 *** LKK REF: CC4/ASM19001038/ha3

Hi Mei Kwan,

I passed the paperwork to Adrian 2 days back. I think you'll receive it in the next couple of days.

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)

S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

From: "Mei Kwan (LKKAUTO)" <Meikwan@lkkauto.com>
Sent: Wednesday, 24 July, 2019 6:03 PM
To: "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>
Cc: "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>, "Admin A" <admin-a@lkkauto.com>
Subject: RE: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019 *** LKK
REF: CC4/ASM19001038/ha3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Suhaimi,

We didn't receive your LOD. Please email us the soft copy.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Suhaimi <suhaimi@firstautoworks.com.sg>
Sent: Wednesday, 24 July, 2019 4:33 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Subject: RE: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019 *** LKK
REF: CC4/ASM19001038/ha3

Hi Mei Kwan

Have your side received all my documents such as my LOD and invoices for this accident case?

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

From: "Mei Kwan (LKKAUTO)" <Meikwan@lkkauto.com>
Sent: Wednesday, 16 January, 2019 7:58 PM
To: "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>
Cc: "CS A Team" <cs-a@lkkauto.com>, "Admin A" <admin-a@lkkauto.com>, "Vic (LKKAUTO)" <vicalph@lkkauto.com>, "assignments" <assignments@lkkauto.com>
Subject: RE: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019 *** LKK
REF: CC4/ASM19001038/ha3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

A: SHB9530Y
B: SL0506B

Bendenee Road

please see the attach CIA report

On 12.01.2019 at about 2000hours, I was travelling on the second lane along Bendemeer Road. When the traffic light turn red, vehicle B (SLQ506B) in front of me suddenly jammed brake. I immediately applied brake to avoid collision but to no avail my taxi skidded and moved forward and hit onto vehicle B rear portion.

To check availability of the case handler, you may contact the undersigned.

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Subject: fw: Accident vehicle between our insured SLQ506B and your insured SHB9530Y on 12/01/2019

3

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

- 1)
- 2)
- 3)

Take Notice : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Please note that this notification does not in any way prejudice our client(s) rights nor shall it be deemed as a waiver of any of their rights, as such our client(s) rights are expressly reserved.

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

Letter of Demand

To : AXA Insurance PTE LTD

Re : Accident involving my vehicle no. SLQ506B and vehicle no. SHB95301 on 12/01/2019 at 0806 HRS PM/AM along Bendermei Road

1) I/We, the owner of vehicle no. SLQ506B hereby appoint LT Automotive Pte Ltd ("the workshop") to act for me/us to recover damages sustained in the above accident from the third party driver and/or insurers. Claims are as follows :

Vehicle Repair cost / Excess	\$ 5615.90
Vehicle Rental Fee for _____ days @	
\$ _____ per day	\$
Loss of use/rental for <u>3</u> days @	
\$ <u>100</u> per day	\$ 300.00
Loss of income for _____ days @	
\$ _____ per day	\$
Police search fee/police report fee/LTA search fees	\$ 7.45
Others	\$
Total :	\$ 5923.35

Signature of vehicle owner

Name -

Address : 7 Lib Close, Alpine

Centre, Singapore 408604

Tel : 6511 3021

Witnessed by :

Shen



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001038/Apa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: RICHARD ANG

Date : 19-08-2019

Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 9530Y	Veh. Inspected	SLQ 506B
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01AH4	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	16/01/2019

2. Vehicle Particulars & Condition

Make & Model	OPEL MOKKA	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LJD7EC5HB179333	Colour	RED
Odometer	121289	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R18	COMFORSER	6 mm
L/H Front Tyre	215/55 R18	COMFORSER	6 mm
R/H Rear Tyre	215/55 R18	COMFORSER	6 mm
L/H Rear Tyre	215/55 R18	COMFORSER	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/01/2019	Inspection Date	17/01/2019
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 506B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,800.00	1,800.00
1	REAR BUMPER LOWER (CONSISTENT)	DEFORMED	1,390.00	1,390.00
1	REAR BUMPER TOWING COVER (CONSISTENT)	CUT	90.00	90.00
1	REAR BUMPER SILL PLATE (CONSISTENT)	CUT	344.00	344.00
1	LHF BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	150.00	-
1	RHF BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR BUMPER REINFORCEMENT BAR (CONSISTENT)	BENT	671.00	671.00
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	1,217.00	-
1	REAR END PANEL TRIM (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR BUMPER ABSORBER - RH (CONSISTENT)	NOT NECESSARY	82.00	-
1	REAR BUMPER ABSORBER - LH (CONSISTENT)	NOT NECESSARY	82.00	-
1	LHR BUMPER BRACKET, GUIDE (CONSISTENT)	NECESSARY	70.00	70.00
1	RHR BUMPER BRACKET, GUIDE (CONSISTENT)	NECESSARY	70.00	70.00
1	LHR BUMPER BRACKET (CONSISTENT)	NECESSARY	65.00	65.00
1	RHR BUMPER BRACKET (CONSISTENT)	NECESSARY	65.00	65.00
1	LHR LOWER BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	80.00	-
1	RHR LOWER BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	80.00	-
	LESS 10% DISCOUNT		-655.60	-456.50
			5,900.40	4,108.50
SPECIAL NETT ITEMS				
10	REAR BUMPER UPPER CLIP (SN) (CONSISTENT)	NECESSARY	65.00	30.00
10	REAR BUMPER LOWER CLIP (SN) (CONSISTENT)	NECESSARY	65.00	30.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	640.00	-
			770.00	60.00
LABOUR				
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		1,650.00	550.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,350.00	450.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	NOT NECESSARY	200.00	-
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
			3,310.00	1,080.00
GRAND TOTAL			9,980.40	5,248.50
RECOMMENDED COST OF REPAIRS				5,248.50

Report Ref No. CC4/ASM19001038/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.