

M/s India International Insurance Pte Ltd
64 Cecil Street #04-02
IOB Building
Singapore 049711

3RD PARTY CLAIM ESTIMATION

Vehicle number	SJG1617J
Make / Model	KIA OPTIMA
Chassis number	KNAGN412MF5611300
Accident date	07/01/2019
Reference	KM1901-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>new</i>	681.50 X
1	REAR BUMPER SIDE RETAINER <i>new</i>	76.50 X
1	REAR RH FENDER <i>new</i>	543.80 X
1	REAR RH SHOCK ABSORBER <i>distorted</i>	561.10 2 ✓
1	REAR RH KNUCKLE ARM <i>distorted</i>	463.30 2 ✓
1	REAR RH KNUCKLE ARM BEARING <i>Done</i>	150.88 2 ✓
1	REAR RH LOWER ARM <i>distorted</i>	335.90 2 ✓
		2812.98
	Less 10 %	281.30
	Subtotal	2513.68
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	2513.68
1	RIM <i>new</i>	1200.00 600/-
1	TYRE <i>new</i>	800.00 X
1 SET	REAR BUMPER CLIP <i>new</i>	50.00 X
	Subtotal	2050.00
	Balance C/F	4563.68
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	4563.68
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 new
2	CHECK REAR WHEEL ALIGNMENT	200.00 60/-
3	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	200.00 150/-
5	PANEL BEATING ON AFFECTED AREAS	800.00 500/-
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 400/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	2210.00
	Grand total	6773.68

17/01/2019 @ 1045w

WAT Auto

L/Smm

[Signature]

WAT Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer