

AUTOLUTION INDUSTRIAL PTE LTD
3 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0038/19
DATE : 16-JAN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR JOEL LEON NG (HUANG LIYONG)
ADDRESS : 530 EAST COAST ROAD
#17-04
S(458970)
TELEPHONE NO : 93801955

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100500076-01
VEHICLE NO : SFM1881C
MODEL CODE : TDBARVWE52ED7Y408Z
MODEL/YEAR : NISSAN ELGRAND 7 SEATER
ENGINE NO : QR25526352L
CHASSIS NO : JN1TBAE52Z0802476
MILEAGE : 24006 KM
DATE IN : 16/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 15/01/2019

9645 0084 elmer@tanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFM1881C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RENEW RR END PANEL & REAR BUMPER	1000.00	
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	800.00	
3 ZZ/003	RENEW BOTH RR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	48.00	
4 ZZ/004	RENEW REVERSE SENSOR 2 POINT	55.00	
	TOTAL LABOUR CHARGES	1903.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFM1881C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			50.00
2	RH SIDE SPACER RR BUMPER	85094-1JB0A	6.30		
3	LH SIDE SPACER RR BUMPER	85095-1JB0A	6.30		
4	SENSOR-REVERSE 2 POINT	SENSOR			250.00
5	LH SIGHT SHIELD REAR BUMPER	85235-1JB0A	134.40		
6	RH SIGHT SHIELD RR BUMPER	85234-1JB0A	134.40		
7	LH CORNER SIGHT SHIELD RR BUMPER	85237-1JB0A	42.00		
8	RH CORNER SIGHT SHIELD RR BUMPER	85236-1JB0A	42.00		
9	ENERGY ABSORBER LH RR BUMPER	85093-1JB0A	126.10		
10	REINFORCEMENT RR BUMPER	85030-1JB0A	661.90		
11	ENERGY ABSORBER RR BUMPER	85090-1JB0A	126.40		
12	RH SIDE BRACKET RR BUMPER	85220-1JA0A	33.00		
13	LH SIDE BRACKET RR BUMPER	85221-1JA0A	33.00		
14	CLIP RR BUMPER @ SGD \$ 1.30 EACH	01553-09321	7.80		
15	REAR BUMPER	85022-1JB1A	2462.40		
SUB TOTAL			3816.00	0.00	300.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			763.20	0.00	0.00
GRAND TOTAL			3052.80	0.00	300.00
OVERALL TOTAL			3352.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFM1881C

TOTAL LABOUR CHARGES	1903.00
TOTAL SPARE PARTS CHARGES	3352.80

GRAND TOTAL	5255.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.