

REPAIR ESTIMATE*

VEHICLE NO : SHA 7555U

MAKE :

MODEL : HYUNDAI IONIQ

DATE 16/1/2019 12:57

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 418.30
	Front Bumper Moulding Centre Upper			\$ 108.50
	Front Bumper Bracket Top (RH)			\$ 35.00
	Front Bumper Retainer Mounting			\$ 28.00
	Front Bumper Clips 10 pcs			\$ 22.00
	SUB TOTAL			\$ 611.80
	LESS 20%			\$ 122.36
	DISCOUNTED TOTAL			\$ 489.44
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Towing Fee			\$ 60.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,189.44

NAZ LK

- PIP

16/1/19 1600

2 Days

CHECK ITEMS PHOTO.

BEFORE & AFTER PHOTO

- LKK Auto Consult** hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party claims on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.