

2/03/2002

ASS. REC. BY:

REF

CS/FCI 19001097/Gg d3rd

Special Instruction:

Surveyor

AWS

ASSIGNMENT (Officer)

From (Person):

May chua

of

FCI

Date/Time: 8:40 am @ 17/1/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 7532M

Insured:

SHB 4280B

at Workshop m/s

Tip Top car Auto

Tel:

62501543

of

160 Sin Ming Drive # 03-15

Policy No:

Claim No:

D19000435MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/01/2019

CA / REV / REP. / REV 24 HRS

lup

21/1/19 @ Morning

H.O.D. Endorsement:

Date/Time:

9:23 am @ 17/1/19

Person Contacted:

Ricky

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 7532M-X
	SHB 4280B-003/1/01/5017322/H/na3g2 DOA: 9/10/15
27/1/19 @ 4:51pm	revised to May chua by email.
	Inv. \$ 16 kless; LTR: B 11823; NV: \$ 4177

DATE

REF: 2110112019

8633H

ASSIGNMENT

(-2021)

From:

Date: 2110112019

Veh No:

SLA7532M

Yr Regn:

19 Jul 2006

Estimated Cost:

Type: ☒ M/Cab / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No:

SLA 7632 M

Make:

Honda Edix

C.C.

1668

at Workshop m/s

Tip Top Car Auto

Colour:

Black

A/C:

Insured / Std / NI / NA

of

160 Sin Ming Drive # 03-15

Sp. Reading

177246

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

BE11102156

C.No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Policy No.

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Claims No.

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

Modi: ☒ Nil / ☐ S/Rim / ☐ STD / ☐ A/Rim or

Tyre Size:

F: 195/65 R15

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

☒ BS7 DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Bal. or Market Value:

\$16k - \$17k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

4

days

Res:

Yes or No

D.O.A.

D.O.I.

21-01-19

Lum Sum:

20

%

3 Val:

Yes or No

Survey held at

w/s

1pm

CA / REV / REP. / 24 HRS

(up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair limit not more than \$4000

chasing for finalization.

08/4 finalizd \$2400 with Alice. (led \$8400.60, 78%)

RECEIVED 09 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

11/09/4 trunk

☐

: Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee:

☐

: Site Insp (\$

) \$ + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

TR

Lump Sum / I.B. (\$

2400

TOTAL

170
50
50 + 50
59
329



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000435MFSH
Our Ref: CS/FCI19001097/Gqd3

Date: 22 January 2019

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 7532M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/01/2019 at the premises of M/s TIP TOP CAR AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 10,822.60 .
Revised Estimate Amount	: S\$ 2,751.36 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-01-2019	Our Ref No. D19000435MFSH
Accident Date	12-01-2019	Claim Type. Third Party
Insured Vehicle	SHB4280B	Third Party Vehicle. SLA7532M
Survey Location	160 SIN MING DRIVE #03-15 SIN MING AUTOCITY	
Contact Person.	MS ALICE LIM	
Contact No.	62501543/ 6250543	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TIP TOP CAR AUTO & ACCESSORIES CENTRE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 22 January 2019 4:51 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000435MFSH/1
Attachments: CSFCI19001097Gqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SLA 7532M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 17 January 2019 9:27 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000435MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 17 January 2019 8:24 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000435MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

▶ edix Used Vehicle List (5 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Honda Edix 1.7A (COE till 05/2021)	\$26,888	\$11,590 /yr	19-May-2006	1,668 cc	120,879 km	ABS Auto Capital Pte Ltd	Availabl

We Are The COE Specialist, No Gimmicks, Honest Dealing, Low Mileage Clock, Car In Good Condition, High Loan 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Show...

Office No. - 64753423

Ken - 91196006 | Kenny - 98259995 | Roy - 83158315 | Md Andry - 90503927

Honda Edix 1.7A (COE till 05/2021)	\$15,800	\$6,710 /yr	08-Jun-2006	1,668 cc	-	D&L Auto Trading	Availabl
---	-----------------	--------------------	--------------------	-----------------	----------	-----------------------------	-----------------

90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily.

Office No. - 62960188

Darren Low - 96236322

Honda Edix 1.7A (COE till 08/2021)	\$20,800	\$7,970 /yr	27-Sep-2006	1,668 cc	155,883 km	SQ Car Credit	Availabl
---	-----------------	--------------------	--------------------	-----------------	-------------------	----------------------	-----------------

Cool Black With Well Maintained Upholstery Condition By Owner. Great Family Car With Smooth And Reliable Engine. Worth Deal, Flexible Lo Package Available, With Attractive Interest Rate. Trade In We...

Office No. - 63390586

Ken - 91218186 | Justin - 91827511 | Rachel - 91126538 | Lester - 96192666

Honda Edix 1.7A (COE till 06/2021)	\$19,900	\$8,160 /yr	08-Dec-2006	1,668 cc	208,636 km	Prem Roy Motoring	Availabl
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	-----------------

Compressor,oil Change And Air Con Filter Just Changed On April 2018. Engine Overhaul Done Once. Great Family Car. Interior And Exterior Taken Care Of. Attractive Loan Package And Competitive Trad...

Office No. - 66028046

Kana - 96435365 | Mark - 98896985

Honda Edix 2.0A (New 5-yr COE)	\$32,800	\$6,560 /yr	22-Jan-2009	1,998 cc	112,000 km	Creative Auto	Availabl
---------------------------------------	-----------------	--------------------	--------------------	-----------------	-------------------	----------------------	-----------------

Full Loan Amount Stated Above. Pristine Exterior With Well Kept Interior. Warranty Provided With Extra Peace Of Mind. One Of The Most Popular Japanese Car Model With Low Maintenance, Low Fuel Consumpt...

Office No. - -

Alvin Chua - 84488354 | Alex Tan - 97556887 | Terence Leow - 90290899

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8633H
Vehicle Details	
Vehicle No.:	SLA7532M
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	EDIX 1.7 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	D17A4052437
Chassis No.:	BE11102156
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,568.00
Original Registration Date:	19 Jul 2006
First Registration Date:	19 Jul 2006
Transfer Count:	1
Actual ARF Paid:	\$21,525.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$11,823.00
Total Rebate Amount:	\$11,823.00
Message	
<p>Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>	

The information contained herein is correct as at 22 Jan 2019

OK

TIP TOP CAR AUDIO & ACC CENTRE

160 SIN MING DRIVE
 #03-15 SIN MING AUTO CITY
 SINGAPORE 575722
 REG NO: 52891930W
 TEL: 6250 1543

ESTIMATE

FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

DATE: 16.01.2019
 CLAIM NO:
 REF NUM: TP 0103/19
 YOUR REF: SHB 4280 B

ATTN: MOTOR CLAIM DEPT

RE: THE VEHICLE NO: SLA 7532 M HONDA EDIX

TO SUPPLY:**SS**

1PC	REAR BUMPER	/ TN	1,172.00	988.9
2PCS	REAR BUMPER SIDE RETAINERS	@46.00 LH - Re	92.00	38.1
1PC	REAR BUMPER REINFORCEMENT	X NN	470.00	X
2PCS	TAIL LAMP ASSY L/R	@482.00 & LH - CHA, RH X NN	964.00	338.4
1PC	REAR END PANEL	X Repair	762.00	X
1PC	REAR END PANEL TOP GARNISH	R / Re	261.00	148.6
1PC	TAIL GATE	X Repair	1,425.00	X
1PC	TAIL GATE LOCK	X NN	168.00	X
1PC	TAIL GATE LOGO	/	67.00	48.9
1PC	TAIL GATE "EDIX" BADGE	/	64.00	56.8
1PC	TAIL GATE "3X2" BADGE	/	56.00	51
1PC	TAIL GATE CHROME GARNISH	X NN	286.00	X
1PC	TAIL GATE RUBBER	R / Tru	156.00	/
1PC	REAR FENDER INNER TRIM LH	X	410.00	X
1PC	REAR EXHAUST SILENCER	X	916.00	X
2PCS	REAR EXHAUST MOUNTINGS	@37.00 X NN	74.00	X
1PC	SPARE TYRE PANEL	X	1,657.00	X
1PC	SPARE TYRE COVER	X	522.00	X
Total:			SS 9,522.00	1826.7
Less 20% :			1,904.40	
SUB TOTAL:			SS 7,617.60	1467.36

TIP TOP CAR AUDIO & ACC CENTRE

160 SIN MING DRIVE
#03-15 SIN MING AUTO CITY
SINGAPORE 575722
REG NO: 52891930W
TEL: 6250 1543

ESTIMATE

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

DATE: 16.01.2019
CLAIM NO:
REF NUM: TP 0103/19
YOUR REF: SHB 4280 B

ATTN: MOTOR CLAIM DEPT

RE: THE VEHICLE NO: SLA 7532 M HONDA EDIX

TO SUPPLY:

1SET REAR REVERSE SENSOR *8/9M*
1PC REVERSE CAMERA *X NN*
1SET REAR BUMPER CLIPS *1 pc.*
1PC REAR WINDSCREEN SEALANT *X NN*

Total:
Less 0% :

SUB TOTAL:

S\$

270.00 SN *200*
580.00 *X*
45.00 SN *20*
60.00 SN *X*

S\$ 955.00 *220*
0.00

S\$ 955.00

LABOUR CHARGE:

TO STRAIGHTEN AND PANEL BEATING REAR CHASSIS
REMOVE & REFIX THE REAR END PANEL, REAR TAIL
GATE COMPARTMENT & ALL THE ABOVE PARTS

850
600 500
900.00 *200 400*

TO REMOVE & REFIX REAR EXHAUST

100.00 *X NN*

TO REMOVE & REFIX REVERSE SENSOR

90.00 *40*

TO REMOVE & REFIX REVERSE CAMERA

90.00 *X NN*

TO CHECK AND RECTIFY WIRING SYSTEM

80.00 *30*

TIP TOP CAR AUDIO & ACC CENTRE

160 SIN MING DRIVE
#03-15 SIN MING AUTO CITY
SINGAPORE 575722
REG NO: 52891930W
TEL: 6250 1543

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIM DEPT

RE: THE VEHICLE NO: SLA 7532 M HONDA EDIX

ESTIMATE

DATE: 16.01.2019
CLAIM NO:
REF NUM: TP 0103/19
YOUR REF: SHB 4280 B

LABOUR CHARGE

S\$

TO PUTTY, RE-SPRAY AND POLISH AFFECTED AREAS

890.00 ~~890~~ 700

TO RUST PROOF AFFECT AREAS

100.00 X . 21/19

Grand Total:

S\$ 10,822.60



TIP TOP CAR AUDIO & ACC CENTRE

4 Days.

lumpsum repair.

After repair photos.

Guo Qiang - 82880282

THIS IS ONLY AN ESTIMATE BASED ON OUR PRELIMINARY INSPECTION AND DOES NOT COVER ADDITIONAL PARTS LABOUR TIME OR WHICH MAY BE REQUIRED AFTER THE WORK BEGUN.

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21/1/19.

3091.36

20%: 2400




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19001097/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4280B	Veh. Inspected	SLA 7532M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000435MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	17/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA EDIX	c.c	1668	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	BE11102156	Colour	BLACK	
Odometer	177246	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2019	Inspection Date	21/01/2019	
Survey held at	160 SIN MING DRIVE# 03-15			
Repairer	TIP TOP CAR AUDIO & ACC. CENTRE			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7532M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TORN	1,172.00	988.90
2	REAR BUMPER SIDE RETAINERS @\$46.00	N/S DEFORMED / O/S NOT NECESSARY	92.00	38.10
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	470.00	-
2	TAIL LAMP ASSY L/R @\$482.00	N/S CRACKED / O/S NOT NECESSARY	964.00	338.40
1	REAR END PANEL	TO REPAIR SEE LABOUR	762.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	261.00	148.60
1	TAIL GATE	TO REPAIR SEE LABOUR	1,425.00	-
1	TAIL GATE LOCK	NOT NECESSARY	168.00	-
1	TAIL GATE LOGO	NECESSARY	67.00	48.90
1	TAIL GATE "EDIX" BADGE	NECESSARY	64.00	56.80
1	TAIL GATE "3X2" BADGE	NECESSARY	56.00	51.00
1	TAIL GATE CHROME GARNISH	NOT NECESSARY	286.00	-
1	TAIL GATE RUBBER	TWISTED	156.00	156.00
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	410.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	916.00	-
2	REAR EXHAUST MOUNTINGS @\$37.00	NOT NECESSARY	74.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	1,657.00	-
1	SPARE TYRE COVER	NOT NECESSARY	522.00	-
	LESS 20% DISCOUNT		-1,904.40	-365.34
			7,617.60	1,461.36
SPECIAL NETT ITEMS				
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	270.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	580.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			955.00	220.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING REAR CHASSIS REMOVE & REFIX THE REAR END PANEL, REAR TAIL GATE COMPARTMENT & ALL THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND TAIL GATE.		900.00	550.00
	TO REMOVE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		90.00	40.00
	TO REMOVE & REFIX REVERSE CAMERA.	NOT NECESSARY	90.00	-
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO PUTTY, RE-SPRAY AND POLISH AFFECTED AREAS.		890.00	700.00
	TO RUST PROOF AFFECT AREAS.	NOT NECESSARY	100.00	-
			2,250.00	1,320.00
	GRAND TOTAL		10,822.60	3,001.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/FCI19001097/Gqd3n2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,823.00=NETT VALUE: \$4,177.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.