

INSURANCE

INS. CASE OWNER:

CC3 /AIG1900

1107, Kkh63

LKK:

IDAC:

Surveyor:

KASUL

DOI:

ASSIGNMENT

11/02/19

Date / Time:

15/1/19

Registered in Merimen:

15/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMG 76727

Name of Insured:

BURGHEON BRICKS P/L

Insured Tel No.:

HP:

15/1/19

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Pamy Thun Nham

Driver Tel No.:

(V/L YES / NO)

Claim No.:

508888888888

Policy No.:

18000 56780

Make / Model:

Lexus

Place of Accident:

Oprie ko Tuss Etp

OI GIA REPORT

(YES / NO)

TP GIA REPORT

(YES / NO)

Insured Liability:

%

Final ? Yes / No

5/1 2770



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

28/1/19
NC
28/1/19

5/1 2770 - x

5/1 2770 - x

STAGE

DATE / PIC

Non-Reporting In (1st):

Non-Reporting In (2nd):

Non-Reporting In (Final):

Notification In (if non-pickup):

Call OI:

After call In to OI: 28/01/19 - 010

Documentation Check List: Handler Typist

Notification In (if non-pickup)

After call In to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/ GIA:

Medical Bill:

POL:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PP

SS 3,887.70

(3 days) Reduction:

33

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/03/19

Confirm with

CAROLINE

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

01

Repair Cost:

(w/gst)

SS

3,624.84

(B 28, C.C. 01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100)

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

180.00

(3 days)

Loss of Income (LOI):

SS

-

(3 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

Total:

SS

3,812.29

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

3,632.29

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

180.00

Name 2:

DAS ANIRUDDHA

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

Pace

REF:

h

9
43859

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: **SLT 9270**

at Workshop no/s: **PERFORMANCE**

of: **303, ALEXANDRA RD**

Insured: **AN**

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **Joseph**

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No


Est. Repairs: **5** days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Vehicle: **SLT 9270** V Reg: **2017 04**

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **B.M.W 318I** CC: **1499**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp Reading: **16092** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: **WBABE36640N480802**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modl: **Nil** / ☒ STD A/Rim or

Tyre Size: F: **225/56R17**

R: _____

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: **6** mm R/Bal: **6** mm

L/Bal: **6** mm L/Bal: **6** mm

D.O.A: **12/01/19** D.O.I: **11/02/19**

Survey held at: **PERFORMANCE**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

P/P \$3,587.30
CRAB: \$1,662.30 (53%)

Date/Time: File Pass to: ☐ : Preli. Report

3) ☐ : Final Report

Date/Time: File Return to: _____

2) _____

Report Format: _____

Lump Sum / LB: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3) _____

4) _____

5) _____

6) _____

7) _____

8) _____

9) _____

10) _____

11) _____

12) _____

13) _____

14) _____

15) _____

16) _____

17) _____

18) _____

19) _____

20) _____

21) _____

22) _____

23) _____

24) _____

25) _____

26) _____

27) _____

28) _____

29) _____

30) _____

31) _____

32) _____

33) _____

34) _____

35) _____

36) _____

37) _____

38) _____

39) _____

40) _____

41) _____

42) _____

43) _____

44) _____

45) _____

46) _____

47) _____

48) _____

49) _____

50) _____

51) _____

52) _____

53) _____

54) _____

55) _____

56) _____

57) _____

58) _____

59) _____

60) _____

61) _____

62) _____

63) _____

64) _____

65) _____

66) _____

67) _____

68) _____

69) _____

70) _____

71) _____

72) _____

73) _____

74) _____

75) _____

76) _____

77) _____

78) _____

79) _____

80) _____

81) _____

82) _____

83) _____

84) _____

85) _____

86) _____

87) _____

88) _____

89) _____

90) _____

91) _____

92) _____

93) _____

94) _____

95) _____

96) _____

97) _____

98) _____

99) _____

100) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG19001107/hb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 7672Z	Veh. Inspected	SLT 927D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2019	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

11, Alexsandra Road,
Singapore 119944



11, Alexsandra Road,
Singapore 119944
Tel: 67796621 (AfterSales)
Fax: 67796624 (Motorrad)

240, Kampong Arong Road,
Singapore 478180
Tel: 67796621 (AfterSales)
Fax: 67796624 (Motorrad)

11, Alexsandra Road,
Singapore 119944
Tel: 67796621 (AfterSales)
Fax: 67796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

17 JAN 2019

ESTIMATE

Estimate No. : b1 49796	Page No. : 1 of 4
Date Est. : 17/01/2019	
Prepared by : Joseph Yaguel	

- ESTIMATE REPAIR FOR - Das Aniradham Blk 11 Kampong Arong Street 86 Q Bay Road Singapore 119944	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLY9278	17/10/2017	318iA/4Dr	0

- DESCRIPTION**
- Repairing rear bumper panel and attachments, etc to knock damage caused by the accident
 - Repair rear bumper
 - Check electrical wiring systems and lightings at the rear section for proper function.

VALUE
850.00
934.00
150.00
80.00

Total Labour 1: 2,995.00

- DESCRIPTION**
- BUMPER CENTRE GUIDE ?
 - BUMPER CARRIER (ECE) ?
 - BUMPER TOWING EYE COVER PRIMED X
 - BUMPER LH SIDE GUIDE ?
 - BUMPER RH SIDE GUIDE ?
 - BUMPER BLACK TRIM STRIP cut
 - BUMPER PANEL PRIMED (LINES) DE
 - COUPLING RING PDC TORQUE CONVERTER ?

QTY	PRIC	VALUE
1	32.90	32.90
1	467.95	467.95
1	43.25	43.25
1	58.50	58.50
1	58.50	58.50
1	81.40	81.40
1	1,172.30	1,172.30
4	5.05	20.20

Total Parts : 1,935.00

Some OD / Third Party / Uninsured losses / Direct Settlement

Claim No.

Excess \$5

Surveyor's Name Rave

Surveyor's Tel 90010068

Authorized Date Time

SURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail

Not Working Days Replacement 3 days

Labour 1	2,995.00
Parts	1,935.00
Labour 2	0.00
Excess	0.00
Total GST @ 7%	345.10
Grand Total	5,275.10



THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY
PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

5,050.00

[illegible]

SUPPLEMENTARY

Page No. :

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#1001 MOUNTING PDC/PMA SENSOR REAR *	66.95	1.00		66.95
#1002 ADHESIVE SET K6 *	53.05	1.00		53.05

NEK
NEK

Total Labour :	
Total Parts :	120.00
Total Labour & Parts :	120.00

Performance Motors Limited

A member of the BMW Group
Co. Reg. No. 198740001, GST Reg. No. M3-002081-X



FINAL REPORT

Estimate No. **b1 49796**
Date Estimated **17/01/2019**
Prepared By **Joseph Yaguel**

Page No. :

REPAIR FOR -
Owner: Aniruddha
81A 11 Tampines Street 86 #13-32
Q Bay Residence
Singapore 528588

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLT927D	NU80802	17/10/2017	318iA/4Dr	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking and dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TO REPAIR BUMPER BLACK TRIM STRIP	81.40	1.00		81.40
REPAIR BUMPER PANEL PRIMED (LINES)	1,172.30	1.00		1,172.30
# S11 MOUNTING PDC/PA SENSOR REAR *	66.95	1.00		66.95
# (DX1SL) ADHESIVE SET K6 *	53.05	1.00		53.05

Supplementary Items

Total Labour :	2,014.00
Total Parts :	1,373.70
Total Labour & Parts :	3,387.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,387.70
GST @7%:	237.14
Grand Total :	3,624.84

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

17 JAN 2019

ESTIMATE

Estimate No. : b1 49796
Date Estimated : 17/01/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Das Aniruddha
Blk 11 Tampines Street 86
Q Bay Residence

Singapore 528588

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT927D	NU80802	17/10/2017	3181A/4Dr	0

DESCRIPTION

Replacing rear bumper panel and attachments, etc to knock out dents caused by the accident

VALUE
850 1,700.00

Spray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries

? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER CENTRE GUIDE ?
REAR BUMPER CARRIER (ECE) ?
REAR BUMPER TOWING EYE COVER PRIMED X
REAR BUMPER LH SIDE GUIDE ?
REAR BUMPER RH SIDE GUIDE ?
REAR BUMPER BLACK TRIM STRIP cut ✓
REAR BUMPER PANEL PRIMED (LINES) DE ✓
DECOUPLING RING PDC TORQUE CONVERTE ?

QTY	PRIC	VALUE
1	32.90	32.90
1	467.95	467.95
1	43.25	43.25
1	58.50	58.50
1	58.50	58.50
1	81.40	81.40
1	1,172.30	1,172.30
4	5.05	20.20

Total Parts : 1,935.00

Claims GD / () / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 11/02/19 01:45 Excess \$

Surveyor's Name Rame Sign

Surveyor's Tel 90010068 Authorized Yes / No

Authorized Date Time

REBURY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommended 3 days

Labour 1	:	2,995.00
Parts	:	1,935.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	345.10
Grand Total	:	5,275.10



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLT 9270	Model:	BMW
Date of Accident:	12.1.2019		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	5275.10	
Final Repair Cost	: \$	3624.84	
Loss of Use	: \$	300.00	3 days at \$ 100. per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	7.45	
Others	: \$		
	: \$		
Final Settlement Sum	: \$	3932.29	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Application: Yes / No			
BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	3624.84
2)	Performance Motors Ltd	: \$	7.45
3)	Das Aniruddha	: \$	300.00

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;

Survey Report; Medical Report / Bill (if any)



Contact us at
 Hotline: (65) 6532 2888
 E-mail: CustomerService@DirectAsia.com

Premium Quote (Ref. MT/00479168)

This quotation will be valid until 29/07/2018. To purchase this policy you can simply go online or give us a call at 6532 2888. We look forward to welcoming you to **DirectAsia**!

Car Insurance

Name	: Das, Aniruddha
Period of cover	: 02/05/2018 - 01/05/2019
Premium	: S\$ 1,781.78 (inclusive of GST)
Own Damage Excess	: S\$ 800.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)

Vehicle Details	
Make and model	: BMW 318i (A) Saloon
Year of registration	: 2017
Car usage	: Private Use + Commuting to work
No. of accidents/claims in the last 36 months	: 0
Is your car modified? (Modifications are according to LTA guidelines)	: No
Mileage per year	: 8,000 - 12,000 km

Policyholder	
Policyholder	: Das, Aniruddha
No Claims Discount (NCD)	: 0%
Your NCD is 0% because	: you have never been insured before

Main Driver Details	
Main Driver	: Das, Aniruddha
Date of Birth	: XX/XX/1985
Gender	: Male
Certificate of Merit	: No
Years of valid driving licence	: 3
Marital Status	: Single
Occupation	: Private sector : management
No. of accidents or claims in the last 36 months	: 0

Named Driver Details	
Named Driver (1)	: Christine, Toh (Non-YIED)
Date of Birth	: XX/XX/1988
Gender	: Female
Certificate of Merit	: No
Years of valid driving licence	: 3
Marital Status	: Single
Occupation	: Private sector : management
No. of accidents or claims in the last 36 months	: 0

Important Note: This policy is on a named driver basis. Any unnamed drivers will not be covered.

Young and/ or Inexperienced Driver (YIED): refers to any driver who is below the age of 30 or holds a driving licence for less than 2 years.

**EMPLOYMENT PASS**Employment of Foreign Manpower Act (Chapter 91A)
Republic of SingaporeEmployer
CISCO SYSTEMS (USA) PTE. LTD.Name
DAS ANIRUDDHA
Occupation
BUSINESS DEVELOPMENT MANAGERFIN
G6344385PDate of Application
24-10-2017Date of Issue
24-11-2017Date of Expiry
18-12-2020

L5462731

REPUBLIC OF SINGAPORE DRIVING LICENCELicence Number
G6344385PName
DAS ANIRUDDHADate of Birth
08 Apr 1985Issue Date
07 Feb 2018Valid Till
06/02/2023**VISIT PASS**
Immigration RegulationsName
DAS ANIRUDDHADate of Birth
08-04-1985 Sex
M Nationality
INDIAN
FIN
G6344385P Date of Issue
24-11-2017 Date of Expiry
18-12-2020**MULTIPLE JOURNEY VISA ISSUED****YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.****YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)****EFFECTIVE DATE**

Class 2B	Motorcycles <= 200 cc	07 Feb 2018
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	07 Feb 2018

NP 428A





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG19001107/hb3

28 JANUARY 2019

**M/s BURGEON BRICKS PTE LTD
22 SIN MING LANE
#06-83 MIDVIEW CITY
SINGAPORE 573969
ATTN: THE MANAGEMENT**

Dear Sir/Madam,

ACCIDENT INVOLVING SMG 7672Z / SLT 927D / OTHERS ON 12/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh
Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, DAS ANIRUDDHA ("the third party claimant")
of 811 Tampines Street #13-32 @ Bay Residence (address),
owner of SLT927D (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLT 927D that was
damaged pursuant to the accident which occurred on 12.1.2019 (date) along
Raffles Hospital Traffic Light Junction (location)
involving vehicle no/s SM G76722 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 11 day of 02 (month) 20 19 (year)

Signed by "the third party claimant"

PERFORMANCE MOTORS LTD

Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. Mr Rasul from LKK Auto Consultants Pte (name of surveyor) with respect to the amount claimed for S\$ 3624.84 (repair costs), S\$ 180.00 (loss of use/~~rental~~) S\$ 7.45 (search fees) for vehicle no. SLT 927D that was damaged pursuant to the accident which occurred on 12.1.19 (date) along Raffles Hospital Traffic Light Junction (location) involving vehicle no/s SMG 76722 /

This is pursuant to the inspection conducted on 11.2.2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Das Anirudh ("third party claimant") of vehicle no. SLT 927D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLT 927D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 day of 05 (month) 20 19 (year)



MR

Signed by AIG appointed surveyor

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Daly Performance Centre
Singapore 150041
63190100 (Sales)
63190111 (After Sales)

Chopped & Signed by "the workshop"

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401339M GST Reg. No M2-0022081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1336259

Date IN : 11/02/2019

Cust. Svc. Advisor: Joseph Yaguel

Page No. : 1 of 2

Invoice Number : 2081925 / WSB

Invoice Date : 28/03/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Das Aniruddha
Blk 11 Tampines Street 86
Q Bay Residence

Singapore 528588

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT927D	NU80802	17/10/2017	318IA/4DR	16092

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 12.1.2019. 3RD PARTY CAR : SMG7672Z.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO
CONSULTANTS PTE LTD ON 11.2.2019 AT 2.15 PM.
AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK AUTO
CONSULTANTS PTE LTD ON 28.1.2019 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

LTA SEARCH FEE = \$7.45.

NETT

850.00

934.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 2,014.00

- - - - PARTS - - - -

REAR BUMPER BLACK TRIM STRIP

REAR BUMPER PANEL PRIMED (LINES)

(DG/SL) ADHESIVE SET K6

SET MOUNTING PDC/PMA SENSOR REAR

Qty	Retail Price
1	81.40
1	1,172.30
1	53.05
1	66.95

NETT

81.40

1,172.30

53.05

66.95

Total Parts : 1,373.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020881-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel: 63190668 (AfterSales)
Fax: 63445771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190838 (AfterSales)
63190813 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : **B1 1336259**

Date IN : **11/02/2019**

Cust. Svc. Advisor: **Joseph Yaguel**

Page No. : **2 of 2**

Invoice Number : **2081925 / WSB**

Invoice Date : **28/03/2019**

Payment Terms : **30 Days From Invoice**

Invoice By : **Sharon Heng**

Labour Charges : **1,934.00**
Parts Charges : **1,373.70**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges	: S\$	3,387.70
Less Insurance Excess	: S\$	0.00
Invoice Total Amount Exclude GST	: S\$	3,387.70
GST @ 7%	: S\$	237.14
Invoice Total Amount Include GST	: S\$	3,624.84

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,624.84**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 17 Jan 2019 / 11:33:59

Receipt Date/Time : 17 Jan 2019 / 11:33:59

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190117-001022

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SMG7672Z

As at 12 Jan 2019/16:25:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SMG7672Z

Enquiry Fee

20190117113240012692

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

xxxxxxxxxxxx9609 Credit Card:
Visa/MasterCard 7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019 Edit Reg		11 Jan 2019 00:00 Edit Adj Rpt	S\$3,387.70 Edit Estimates	S\$3,387.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BURGEON BRICKS PTE LTD , Co. Reg. No.: NA								
Main Claimant:	DAS ANIRUDDHA , ID: G6344385P								
Vehicle Reg. No.:	SLT927D	Date of Loss:	12/01/2019 16:00 - :59 [14 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5080803713SG	Policy/Cover Note No.:	1800056930 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMG7672Z	Policy No. (Claimant):	MT/00479168						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT927D (5080803713SG)
[SMG7672Z]
TP
DAS ANIRUDDHA
Jan 12 2019 4:00PM
[BURGEON BRICKS PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 14:19	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	28/03/19 14:19	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
27	28/03/19 14:19	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 17:11	TP EST & GIA REPORT	Load PDF	
2	28/01/19 14:09	LETTER TO OI	Load PDF	
3	12/02/19 18:42	TP ESTIMATE- MARKED	Load PDF	
4	06/06/19 10:47	WORKSHOP INVOICE	Load PDF	
5	06/06/19 10:47	AUTHORISATION TO ACT FORM	Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
6	06/06/19 10:47	LKK Auto Consultants Pte Ltd (HQ) Release Voucher	Load PDF	
7	06/06/19 10:47	LTA SEARCH	Load PDF	
No	Finalized On		Thumbnail	Print
1	18/01/19 10:44	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMG7672Z (Insd veh)	Model:	BMW 318I 1.5 SEDAN LED
	SLT927D (TP veh)		NAV (A)
Date of Accident:	12/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		5,403.50
Final Repair Cost	:	\$		3,624.84
Loss of Use	:	\$		180.00
				3.00 days at \$60.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		7.45
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		3,812.29

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: ____100____(%) Assessed Liability (*): ____0____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 3,632.29
2)	Das Aniruddha	:	\$ 180.00
3)		:	\$

JOANNE LEE KHANG MIN

06 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001107/R1HB3Q2

Date: 06/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056930
Claimant Vehicle No : SLT927D **Insured Vehicle No :** SMG7672Z
 Date of Loss: 12/01/2019 Nature of Claim: TP Claim No: 5080803713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT927D**
 Make & Model: BMW 318i, 1.5 SEDAN LED NAV (A) Engine No: F7351685B38B15A
 Reg. Date: 17/10/2017 (Man. Year: 2017) Chassis No: WBA8E36040NU80802
 Colour: Black Odometer: 16092 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,135.00	1,453.70	681.30	31.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,050.00	3,387.70	1,662.30	32.92
+ GST 7.00/7.00% (S\$)	353.50	237.14	116.36	32.92
Nett Amount (S\$)	5,403.50	3,624.84	1,778.66	32.92
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,812.29		

INSPECTION

Date of Assignment: 11/01/2019
 Date Inspected: 11/02/2019 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	32.90 FS	*- FS
3	1		*REAR BUMPER CARRIER (ECE)	Not Necessary	467.95 FS	*- FS
4	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	43.25 FS	*- FS
5	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	58.50 FS	*- FS
6	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	58.50 FS	*- FS
7	1		*REAR BUMPER BLACK TRIM STRIP	Cut	81.40 FS	*81.40 FS
8	1		*REAR BUMPER PANEL PRIMED (LINES)	Deformed	1,172.30 FS	*1,172.30 FS
9	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
10	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	66.95 FS	*66.95 FS
11	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (S\$)					2,135.00	1,453.70

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT	New	1,700.00	850.00
2	SPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >