

ASS. REC. BY:

REF CS

MSG19001137/Kvd3m2

Special Instructions:

Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person): Christina Wong

of

MS/G

Date/Time: 12/1/19

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE G088H

Insured:

WC 1037A

at Workshop m/s

Chew Goon Motor

Tel:

64841626

of

Blk 10, Amk Ind. Park 2A #01-15/16

Policy No:

B29088496MKF

Claim No:

582576

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

11/01/2019

CA / REV / REF. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

9:49am 12/1/19

Person Contacted:

Grace

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE G088H-X

WC 1037A-X

21/1/19

Send preli revised via merimen

23/5/19

LS \$19,650 Confirmed by email (Ref 10, 168-01, 341)

ASS. REC. BY:

REF: MS61

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8496

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE6088HYr Regn: 01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS NV350c.c. 2488Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 140593

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1M62E2680005721Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NIS/Rim / STD A/Rim orTyre Size: F: Raxus 195R15X8R: KaprenBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 5 mmL/Bal. 9 mmL/Bal. 5 mmD.O.A. 11/1/19D.O.I. 18/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/1 File pass to CA

RECEIVED 24 MAY 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 21Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

20010210

Report Format:

Lump Sum / I.B.I. (\$

merimen19,650/224/5 typist

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 21 Jan 2019

Preliminary Advice

Insured Vehicle No	: WC1037A		
TP Vehicle No	: GBE6088H	Accident Date	: 11/01/2019
Make	: NISSAN NV350	Assignment Date	: 18/01/2019
Date of Inspection	: 18/01/2019	Est. Duration of Repair	: 21.00
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,818.01
Revised Amount	:S\$	22,953.22
Check Items (Estimated)	:S\$	3,527.20
Total	:S\$	26,480.42

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019		18 Jan 2019 09:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by Insurer]						
Insured:	SAY WAH WELDING & CONSTRN P L , Co. Reg. No.: 0								
Main Claimant:	RENTAL HYGIENE SERVICES PTE LTD , Co. Reg. No.: 200202717H								
Vehicle Reg. No.:	GBE6088H	Date of Loss:	11/01/2019 20:00 - :59 [35 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 582576	Policy/Cover Note No.:	B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019						
Vehicle Reg. No. (Insured):	WC1037A	Policy No. (Claimant):							
		Excess:							
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/01/2019]								
Driver/Custodian (Insured):	SELVAM ALEXPANDI (), NRIC: G3143368T, Tel: +6583033815								
Adj Asp. Remarks:	Liability is down subject to OI approval. TP want to use LKK as the SJE. Contact Person: Grace / 6484 1626.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Thursday, 23 May 2019 2:17 PM
To: Veron Chen (LKKAuto); chewgoon@singnet.com.sg; SUR
Subject: RE: GBE 6088H-DOA: 11/1/2019

Dear Veron,

We agreed to accept the lump sum repair @ \$19,650.00/-

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, May 22, 2019 1:28:34 PM
To: Chew Goon Motor(ad3); chewgoon@singnet.com.sg; SUR
Subject: GBE 6088H-DOA: 11/1/2019

Dear Kelly,

WITHOUT PREJUDICE

Offer Lump Sum \$19,650 @ 21 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	2717H

Vehicle Details

Vehicle No.:	GBE6088H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	YD25386870A
Chassis No.:	JN1MC2E26Z0005721
Maximum Power Output:	-
Open Market Value:	\$22,153.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,108.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	21 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,959.00
COE Rebate Amount:	\$3,483.00
Total Rebate Amount:	\$3,483.00

The information contained herein is correct as at 12 Jan 2019

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5097499392

Cover : Comprehensive

- | | |
|---|-----------------------------------|
| 1. Index mark and Registration Number of Vehicle | : GBE608BH |
| Chassis Number | : JN1MC2E262005721 |
| 2. Name of Policyholder | : RENTAL HYGIENE SERVICES PTE LTD |
| 3. Effective Date of Insurance | : 22 Jan 2018 |
| 4. Expiry Date of Insurance | : 21 Jan 2019 |
| 5. Persons or Classes of Persons entitled to drive | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: ABWIN PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ABWIN PTE LTD (00000614234)


Date of Issue : 17 Jan 2018 15:20 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7442760Z**

Name: **IBRAHIM BIN RAHIM**

Birth Date: **24 Dec 1974**

Issue Date: **21 Oct 2010**

0019020640




REPUBLIC OF SINGAPORE

IDENTITY CARD NO: **S7442760Z**

Name: **IBRAHIM BIN RAHIM**

Race: **MALAY**

Date of Birth: **24-12-1974**

Sex: **M**

Country of Birth: **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 21 Oct 2010

NP 426A

Licence No: **S7442760Z**



REPUBLIC OF SINGAPORE

NRIC No: **S7442760Z**

Address: **APT BLK 523 WOODLANDS DRIVE 14 #02-307 SINGAPORE 730523**

NRIC No: **S7442760Z**

Date: **26-05-2008**

No: **5411552**

17-12-1966




SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 09:53
Date Of Accident	11/01/2019 21:15
Exact Location Of Accident	SLIP ROAD FROM YIO CHU KANG RD TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE6088H
Insured/Policyholder	
Name Of Registered Owner	RENTAL HYGIENE SERVICES PTE LTD
Co Reg No	200202717H
Email Address	ZUL@RENTALHYGIENE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64811300
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097499392
Cover Note Number	

Driver

Name of Driver	IBRAHIM BIN RAHIM
NRIC No	S7442760Z
Date Of Birth	24/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	21/10/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90233255
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 523 WOODLANDS DRIVE 14 #02-397
Postcode	730523
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FADZYLAH
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING AT SLOW SPEED ALONG THE SLIP ROAD FROM YIO CHU KANG ROAD TOWARDS SLE, SUDDENLY REAR VEHICLE B (WC1037A) HIT ONTO MY VEHICLE A (GBE6088H) 'S REAR PORTION AND PUSHED MY VEHICLE FORWARD TOWARDS VEHICLE C (SGQ4426G), I CAME DOWN OF MY VEHICLE, I REALIZE THERE ARE A TOTAL OF 4 VEHICLES INVOLVED THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC1037A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SELVAM ALEXPANDI
NRIC/Passport Number	G3143368T
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGQ4426G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MUHAMMAD AMIRUL FAHMI BIN MOHAMED MOKHTAR

NRIC/Passport Number

S9729743F

Contact Number

97355871

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLK4098S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TEO JWEE POR

NRIC/Passport Number

S0071237Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

FADZYLAH

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBE6088H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling at slow speed along the G3p Road from Yie chu
Kang Road towards SE suddenly rear veh B (WC1037A) hit onto
my veh A (GBE6088H)'S rear portion and pushed my vehicle
forward towards vehicle C (SGR4426G), I came down of my
vehicle, I realize there are a total of 4 vehicles involved this
accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notarise
L12ny &?
Resurvey After Paint 2/1/19
21 days

To: **MSIG Insurance (S) Pte Ltd**

Policy No: **THIRD PARTY**

Date: **15.01.2019**

Accident Date : 11.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Nissan NV350" Reg. No. GBE6088H Claiming Against Your Insured Veh. No. WC1037A			
1pc	Tailgate		R 1,820.00 N
2pcs	Tailgate Hinges	51.60	DIT 103.20 N
1pc	Tailgate Center Emblem		M 75.00 N
1pc	Tailgate Badge "NV350"		M 73.00 N
1pc	Tailgate Badge "Urvan"		M 95.70 N
1pc	Tailgate Outer Moulding		CM 562.00 N
1pc	Tailgate 3rd Brake Lamp		CM 287.00 N
1pc	Tailgate Wiper Motor		JM 305.00 N
1pc	Tailgate Wiring Harness		Tailgate 635.00 N
1pc	Tailgate Trim Board		CM 245.00 N
16pcs	Tailgate Trim Board Clips	3.50	M 56.00 N
1pc	Tailgate Side Stopper RH		Ad 10.00 N
2pcs	Tailgate Dampers	199.00	Ad 398.00 N
1pc	Tailgate Lock Cover		Ad 51.20 N
1pc	Tailgate Lock Catch		DIT 62.80 N
1pc	Tailgate Weatherstrip		To T 140.00 N
1pc	Tailgate Weatherstrip Top Protective Plate		B 96.00 N
1pc	Tailgate Central Locking Device		Ad 345.00 N
1pc	Tailgate Wiper Motor Cover		Ad 102.00 N
1pc	Rear Bumper		R 776.00 N
10pcs	Rear Bumper Clips	2.60	M 26.00 N
1pc	Rear Bumper Center Step Panel		R 162.60 N
2pcs	Rear Bumper Top Retainers	14.50	CLSA 29.00 N
2pcs	Rear Bumper Corner Holders	110.00	CLSA 220.00 N
1pc	End Panel		B 297.00 N
1pc	End Panel Inner Panel		R 490.00 N
1pc	End Panel Side Ext Panel RH		R 237.00 N
2pcs	Taillamps Assy	1,230.70	← 2,461.40 N
2pcs	Taillamp Gaskets	25.00	M 50.00 N
1pc	Taillamp Panel RH		R 705.00 N
1pc	Taillamp Panel Inner Panel		R 305.00 N
1pc	Taillamp Panel Lower Ext Panel		R 315.00 N
1pc	Taillamp Panel Upper Ext		R 315.00 N
1pc	Fuel Lid		R 135.00 N
1pc	Fuel Lid Lock		CM 163.00 N
1pc	Fuel Lid Inner Panel		B 130.00 N
1pc	Rear Fender RH		← Ad 1,872.00 N
		C/F	14,150.90

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey bodywork after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary work(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 15.01.2019

Accident Date : 11.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Nissan NV350" Reg. No. GBE6088H Claiming Against Your Insured Veh. No. WC1037A			
		B/F	14,150.90
1pc	Rear Fender Inner Panel Top Horizontal Panel		Ry 465.00 N 2
1pc	Rear Fender Top Blind Panel		Bu 270.00 N 2
1pc	Rear Fender Inner Panel		Bu 1,136.00 N 1
1pc	Rear Fender Inner Panel Side Inspection Cover		Ry 203.00 N 1
1pc	Rear Fender Inner Pillar		Ry 499.00 N 2
1pc	Rear Fender Inner Trim Board		CM 397.00 N 1
10pcs	Rear Fender Inner Trim Board Clips	3.50	2 35.00 N 1
1pc	Rear Fender Inner Lower Panel		Ry 301.00 N 2
1pc	Rear Fender Wheel House		R 432.00 N 1
1pc	Rear Fender Wheel House Inner Panel		R 396.00 N 1
1pc	Sliding Door Roller Rail		CM 512.00 N 1
1pc	Sliding Door Roller Rail End Cover		MIT 112.00 N 1
1pc	Roof Panel Lower Side Cover RH		RYCM 203.00 N 1
1pc	Roof Panel Lower Reinforce Panel		B 495.00 N 1
1pc	Grille		MSM 487.00 N 1
1pc	Grille Emblem		2 70.00 N 1
1pc	Front Bumper		Bu 535.00 N 1
10pcs	Front Bumper Clips	5.00	2 50.00 N 1
1pc	Front Bumper Beam		Bu 630.00 N 2
1pc	Front Bumper Fog Lamp Cover		CM 162.00 N 1
1pc	Headlamp Assy LH		Ry 525.00 N 1
			22,065.90
	Less 10%		2,206.59
			19,859.31
1pc	Tailgate Glass Sealant		2 50.00 SN 400
1pc	Tailgate Glass Sealer		2 30.00 SN 1
1pc	Tailgate Glass Fastener		2 50.00 SN 300
1pc	Tailgate Glass Solar Film		2 180.00 SN X
1pc	Tailgate Sticker "70KM"		2 18.00 SN 120
1pc	Tailgate Sticker "8 Pax"		2 18.00 SN 120
1pc	Tailgate Co Logo and Lettering	(Bill)	2 500.00 SN 1
1pc	Tailgate Wiper Nozzle		2 21.50 SN 1
3pcs	Tailgate Accessories Stickers	60.00	2 180.00 SN 900
1pc	Tailgate Lock		2 355.00 SN 1
1pc	Tailgate Inner Inspection Cover		2 185.00 SN 1
1pc	Rear Bumper Reverse Sensor		CM 280.00 SN 2000
		C/F	21,726.81

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 15.01.2019

Accident Date : 11.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Nissan NV350" Reg. No. GBE6088H Claiming Against Your Insured Veh. No. WC1037A			
		B/F	21,726.81
1pc	Rear Bumper Side Blue Sticker		180.00 SN
1pc	Rear Bumper Sticker		20.00 SN
1pc	Fuel Filler Neck Pipe		167.20 SN
1pc	Rear Fender Top Blind Panel Sealant		50.00 SN
1pc	Rear Fender Co Ad Sticker		600.00 SN
1pc	Rear Floor Panel Top Board		850.00 SN
1pc	Front Number Plate		45.00 SN
1pc	Front Bumper Fog Lamp LH		389.00 SN
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00
	To Dismantle / Refit Rear Windscreen Glass		160.00
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00
	To Dismantle / Refit Roof Upholstery		150.00
	To Dismantle / Refit Fuel Tank Inlet Hose and Piping		100.00
	To Supply Rear Panel Joint Sealant		80.00
	To Provide Transportation (Towing)		100.00
	To Mount Vehicle on Car "O" Liner Chassis Alignment Equipment/ Workbench for Chassis Alignment to Facilitate Repair		350.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00
	Labour Charge - Panel Beating , Repairing Of Rear Chassis Member, Inner Panel, Floor Panel, Roof Panel etc. Cnt, Weld End Panel, Rear Fender, Inner Panel and Parts Replacement		2,800.00
	To Spray Painting Affected Areas		1,600.00
Total :			29,818.01

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001137/KVD3N2

Date: 27/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29088496MKF
Claimant Vehicle No :	GBE6088H	Insured Vehicle No :	WC1037A
Date of Loss:	11/01/2019	Nature of Claim:	TP
		Claim No:	582576

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6088H	Engine No:	YD25386870A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0005721
Reg. Date:	22/01/2016 (Man. Year: 2015)	Odometer:	140593 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Raxus 9 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	Raxus 9 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,028.01	20,047.17	3,980.84	16.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,790.00	4,550.00	1,240.00	21.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,818.01	24,597.17	5,220.84	17.51
Approved Total (Overridden) (S\$)		19,650.00		
(S\$)	29,818.01	19,650.00	10,168.01	34.10
+ GST 7.00/7.00% (S\$)	2,087.26	1,375.50	711.76	34.10
Nett Amount (S\$)	31,905.27	21,025.50	10,879.77	34.10

INSPECTION

Date of Assignment:	18/01/2019	
Date Inspected:	18/01/2019	Inspected At:
		Chew Goon Motor (AMK)
		Blk 10 Ang Mo Kio Industrial Park 2A,
		#01-15/16 & 17, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	21.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 May 2019)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE6088H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,820.00 FN	*1,820.00 FN
2	2		*TAILGATE HINGES	Distorted	103.20 FN	*103.20 FN
3	1		*TAILGATE CENTER EMBLEM	Necessary	75.00 FN	*75.00 FN
4	1		*TAILGATE BADGE NV350	Necessary	73.00 FN	*73.00 FN
5	1		*TAILGATE BADGE URVAN	Necessary	95.70 FN	*95.70 FN
6	1		*TAILGATE OUTER MOULDING	Cracked	562.00 FN	*562.00 FN
7	1		*TAILGATE 3RD BRAKE LAMP	Cracked	287.00 FN	*287.00 FN
8	1		*TAILGATE WIPER MOTOR	Jammed	305.00 FN	*305.00 FN
9	1		*TAILGATE WIRING HARNESS	Torn/Cut	635.00 FN	*635.00 FN
10	1		*TAILGATE TRIM BOARD	Cracked	245.00 FN	*245.00 FN
11	16		*TAILGATE TRIM BOARD CLIPS	Necessary	56.00 FN	*56.00 FN
12	1		*TAILGATE SIDE STOPPER RH	Dented	10.00 FN	*10.00 FN
13	2		*TAILGATE DAMPERS	Bent/Punctured	398.00 FN	*398.00 FN
14	1		*TAILGATE LOCK COVER	Dented	51.20 FN	*51.20 FN
15	1		*TAILGATE LOCK CATCH	Distorted	62.80 FN	*62.80 FN
16	1		*TAILGATE WEATHERSTRIP TOP PROTECTIVE PLATE	Bent	96.00 FN	*96.00 FN
17	1		*TAILGATE CENTRAL LOCKING DEVICE	Dented	345.00 FN	*345.00 FN
18	1		*TAILGATE SIPER MOTOR COVER	Dented	102.00 FN	*102.00 FN
19	1		*REAR BUMPER	Bent	776.00 FN	*696.00 FN
20	10		*REAR BUMPER CLIPS	Necessary	26.00 FN	*26.00 FN
21	1		*REAR BUMPER CENTER STEP PANEL	Repair	162.60 FN	*- FN
22	1		*REAR BUMPER TOP RETAINERS	O/s Bent	29.00 FN	*14.50 FN
23	1		*REAR BUMPER CORNER HOLDERS	O/s Cracked	220.00 FN	*110.00 FN
24	1		*END PANEL	Bent	297.00 FN	*297.00 FN
25	1		*END PANEL INNER PANEL	Repair	490.00 FN	*- FN
26	1		*END PANEL SIDE EXT PANEL RH	Bent	237.00 FN	*237.00 FN
27	2		*TAILLAMPS ASSY	N/s Cracked/O/s Broken	2,461.40 FN	*834.80 FN
28	2		*TAILLAMP GASKETS	Necessary	50.00 FN	*50.00 FN
29	1		*TAILLAMP PANEL RH	Bent	705.00 FN	*705.00 FN
30	1		*TAILLAMP PANEL INNER PANEL	Bent	305.00 FN	*305.00 FN
31	1		*TAILLAMP PANEL LOWER EXT PANEL	Bent	315.00 FN	*315.00 FN
32	1		*TAILLAMP PANEL UPPER EXT	Bent	315.00 FN	*315.00 FN
33	1		*FUEL LID	Bent	135.00 FN	*135.00 FN
34	1		*FUEL LID LOCK	Cracked	163.00 FN	*163.00 FN
35	1		*FUEL LID INNER PANEL	Bent	130.00 FN	*130.00 FN
36	1		*REAR FENDER RH	Buckled	1,872.00 FN	*1,786.10 FN
37	1		*REAR FENDER INNER PANEL TOP HORIZONTAL PANEL	Bent	465.00 FN	*465.00 FN
38	1		*REAR FENDER TOP BLIND PANEL	Buckled	270.00 FN	*270.00 FN
39	1		*REAR FENDER INNER PANEL	Buckled	1,136.00 FN	*1,136.00 FN
40	1		*REAR FENDER INNER PANEL SIDE INSPECTION COVER	Bent	203.00 FN	*203.00 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR FENDER INNER PILLAR	Bent	499.00 FN	*499.00 FN
42	1		*REAR FENDER INNER TRIM BOARD	Cracked	397.00 FN	*397.00 FN
43	10		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	35.00 FN	*35.00 FN
44	1		*REAR FENDER INNER LOWER PANEL	Bent	301.00 FN	*301.00 FN
45	1		*REAR FENDER WHEEL HOUSE	Repair	432.00 FN	*- FN
46	1		*REAR FENDER WHEEL HOUSE INNER PANEL	Repair	396.00 FN	*- FN
47	1		*SLIDING DOOR ROLLER RAIL	Cracked	512.00 FN	*512.00 FN
48	1		*SLIDING DOOR ROLLER RAIL END COVER	Missing	112.00 FN	*112.00 FN
49	1		*ROOF PANEL LOWER SIDE COVER RH	Mtg Cracked	203.00 FN	*203.00 FN
50	1		*ROOF PANEL LOWER REINFORCE PANEL	Bent	495.00 FN	*495.00 FN
51	1		*GRILLE	Mtg Cracked	487.00 FN	*487.00 FN
52	1		*GRILLE EMBLEM	Necessary	70.00 FN	*70.00 FN
53	1		*FRONT BUMPER	Buckled	535.00 FN	*535.00 FN
54	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
55	1		*FRONT BUMPER BEAM	Buckled	630.00 FN	*630.00 FN
56	1		*FRONT BUMPER FOG LAMP COVER	Cut	162.00 FN	*162.00 FN
57	1		*HEADLAMP ASSY LH	Cut	525.00 FN	*525.00 FN
58	1		*TAILGATE WEATHERSTRIP (50%)	Torn	126.00 FS	*70.00 FS
59	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
60	1		*TAILGATE GLASS SEALER	Necessary	30.00 FS	*30.00 FS
61	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
62	1		*TAILGATE GLASS SOLAR FILM	Not Necessary	180.00 FS	*- FS
63	1		*TAILGATE STICKER 70KM	Necessary	18.00 FS	*12.00 FS
64	1		*TAILGATE STICKER 8PAX	Necessary	18.00 FS	*12.00 FS
65	1		*TAILGATE CO LOGO AND LETTEING	Necessary	500.00 FS	*500.00 FS
66	1		*TAILGATE WIPER NOZZLE	Dented	21.50 FS	*21.50 FS
67	3		*TAILGATE ACCESSORIES STICKERS	Necessary	180.00 FS	*90.00 FS
68	1		*TAILGATE LOCK	Jammed	355.00 FS	*355.00 FS
69	1		*TAILGATE INNER INSPECTION COVER	Bent	185.00 FS	*185.00 FS
70	1		*REAR BUMPER REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
71	1		*REAR BUMPER SIDE BLUE STICKER	Not Necessary	180.00 FS	*- FS
72	1		*REAR BUMPER STICKER	Necessary	20.00 FS	*5.00 FS
73	1		*FUEL FILLER NECK PIPE	Dented	167.20 FS	*167.20 FS
74	1		*REAR FENDER TOP BLIND PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
75	1		*REAR FENDER CO AD STICKER	Necessary	600.00 FS	*600.00 FS
76	1		*REAR FLOOR PANEL TOP BOARD	Cracked	850.00 FS	*600.00 FS
77	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*25.00 FS
78	1		*FRONT BUMPER FOG LAMP LH	Mtg Cracked	389.00 FS	*389.00 FS

F=Franchise part. S=SpcNett, N=NettItemDisc

Sub Total (\$\$)	26,220.60	21,900.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	2,192.59	1,852.83
Total Parts (\$\$)	24,028.01	20,047.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT FRONT ELECTRICAL CHECK,LOCKING SYSTEM,ADJUST,FOCUS HEADLAMP ETC	New	30.00	30.00
2	TO DISMANTLE/REFIT REAR WINDSCREEN GLASS	New	160.00	120.00
3	TO DISMANTLE/REFIT TAILGATE FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
4	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE,REWIRING ETC	New	120.00	50.00
5	TO DISMANTLE/REFIT RPPF UPHOLSTERY	New	150.00	120.00
6	TO DISMANTLE/REFIT FUEL TANK INLET HOSE AND PIPING	New	100.00	60.00
7	TO SUPPLY REAR PANEL JOINT SEALANT	New	80.00	60.00
8	TO PROVIDE TRANSPORTATION (TOWING)	New	100.00	80.00
9	TO MOUNT VEHICLE ON CAR O LINER CHASSIS ALIGNMENT EQUIPMENT/WORKBENCH FOR CHASSIS ALIGNMENT TO FACILITATE REPAIR	New	350.00	250.00
10	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	150.00	120.00
11	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL,FLOOR PANEL,ROOF PANEL ETC.CNT,WELD END PANEL,REAR FENDER,INNER PANEL AND PARTS REPLACEMENT	New	2,800.00	2,200.00
12	TO SPRAY PAINTING AFFECTED AREAS	New	1,600.00	1,400.00
Gross Labour Cost (S\$)			5,790.00	4,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >