

Surveyor:

PHJ

DOI:

ASSIGNMENT

28/1/19

Date / Time:

18/01/19

Registered in Merimen.

Pre-assign / CCU / FTE



Insured Vehicle No. : SPH 2584X

Name of Insured : Su Dan

Insured Tel No. : HP:

Excess Sec II : SS

D.O.A : 8/1/19

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SDY 8278J



INSRS:

WSP:

Tel :

Liability :

RMKS:

Automotive
Repair Centre

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

24/1

Aghu

1/3/19

Huei Jie

SDY 8278J - X; SPH 2584X - X

Confirmed C/S \$3,000/-
with 5 days of repair.

06-03-19 06:30pm

FILED OI CONFIRMED ACCIDENT. OI REPAIR ENDED TP. INFORM TP
CLAIM AGREED TO SETTLE AND AWARE ABOUT NCD ISSUE.

06-3-19

FILE PAGES TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

YEMAL 06-03-19.

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: PHJ

Repair Cost:

45

\$3,000

(5 days)

Reduction:

50 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 15-04-19

Confirm with: RAYMOND

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 21

If NO or B 28, Ass. Lia :

Repair Cost:

W/LGSI

\$3,210.00

OI REPAIR ENDED TP.

Loss of Rental (LOR):

\$ -

(days)

Loss of Use (LOU):

\$ 300.00

(\$ 50 x 6 days)

Loss of Income (LOI):

\$ -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$ 2.00

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost

\$ -

Total:

\$3,512.00

Global Sum \$:

FINAL PAYMENT

Date/Time: 15-04-19

Confirm with: RAYMOND

Email ☒Call ☐

Payee 1:

\$3,512.00

Name 1:

AUTOMOTIVE REPAIR CENTRE PTE LTD

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$400

COPY SENT 24/4/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI19001138/Jea3

Date: 27/02/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SDY 8278J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.01.2019 at the premises of M/s Automotive Repair Centre Pte Ltd - Woodlands and have the following to report:-

Workshop Estimate Amount	: S\$	6,000.00
Revised Estimate Amount	: S\$	4,110.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	4,110.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1901-001
DATE : 9-Jan-2019
POLICY NO. : FWD PNPV2017-00001714-01
VEHICLE REG. NO. : SDY8278J

VEHICLE MAKE : MITSUBISHI LANCER 1.6 GLX AUTO

LKK Auto Consultants hence notify

the Repairer of the following:

FOR SURVEYOR before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

ESTIMATE REPAIR COST

Acknowledged by Repairer

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>		Date:		
1	Rear Bumper BUL	1	\$ 700.00	\$ 700.00 ✓
2	Rear Bumper Clips NEL	10	\$ 5.00	\$ 50.00 ✓
3	Rear Bumper Retainer RH NN	1	\$ 40.00	\$ 40.00 X
4	Rear Bumper Retainer LH DEF	1	\$ 40.00	\$ 40.00 ✓
5	Rear Tail Lamp RH NN	1	\$ 420.00	\$ 420.00 X
6	Rear Tail Lamp LH NN	1	\$ 420.00	\$ 420.00 X
7	Rear Tail Lamp Grommet Upper NEL	2	\$ 10.00	\$ 20.00 ✓
8	Rear Tail Lamp Grommet Lower NEL	2	\$ 5.00	\$ 10.00 ✓
9	Rear Bootlid DEF	1	\$ 700.00	\$ 700.00 ✓
10	Rear Bootlid Lock SUL	1	\$ 80.00	\$ 80.00 X
11	Rear Bootlid Seal CUT	1	\$ 180.00	\$ 180.00 ✓
12	Rear Bootlid Hinge RH NN	1	\$ 50.00	\$ 50.00 X
13	Rear Bootlid Hinge LH NN	1	\$ 50.00	\$ 50.00 X
14	Rear / End Panel Garnish DEF	1	\$ 180.00	\$ 180.00 ✓
15	End Panel BUL	1	\$ 420.00	\$ 420.00 ✓
16	Rear Mitsubishi Emblem NEL	1	\$ 60.00	\$ 60.00 ✓
17	Rear Lancer Emblem NEL	1	\$ 60.00	\$ 60.00 ✓
18	Rear GLX Emblem NN	1	\$ 60.00	\$ 60.00 X
19	Rear MR Emblem NEL	1	\$ 60.00	\$ 60.00 ✓
10% Parts Discount			Total Spare Parts	\$ 3,600.00
<u>SPECIAL NETT</u>				
20	Reverse Sensor Shorted	1	\$ 200.00	\$ 200.00 ✓
			Total Special Nett	\$ 200.00
<u>LABOUR</u>				
21	Spray Painting Whole Rear Include Inner Panel	1	\$ 1,000.00	\$ 550 1,000.00 ✓
22	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 800 1,000.00 ✓
23	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 30 80.00 ✓
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 30 100.00 ✓
25	Check and rectify electrical wiring	1	\$ 20.00	\$ 20.00 ✓

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,200.00
Amount Before Excess	\$ 6,000.00
Add GST @ 7%	420.00
Total Amount Payable	\$ 6,420.00

Total - \$3000.7
Hwee Jie - LKK
28/1/19
1/15 Sdruv

Mei Kwan (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 25 January, 2019 1:52 PM
To: Mei Kwan (LKKAUTO)
Cc: CS A Team; Admin A; Asher Sng (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SKH2584X (OI : CTI - TBA) AND SDY8278J (TP : LKK REF - CC6/CTI19001138/ea3) on 08/01/2019
Attachments: INSURED REPORT.PDF
Categories: HMK

Dear Mei Kwan,

Pls find insured accident report.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 25 January, 2019 11:18 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving SKH2584X (OI : CTI - TBA) AND SDY8278J (TP : LKK REF - CC6/CTI19001138/ea3) on 08/01/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to your below email.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Enclosed for your perusal is:

- TP GIA report
- estimated cost of repair

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19001138/Jea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 25-04-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 2584X	Veh. Inspected	SDY 8278J	
Policy No.	DMPCSN3027051803	Coverage (\$)	0.00	
Claim No.	SNM19D200163C02/4	Excess (\$)	0.00	
Assign From		Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI GLX	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JMYSRCS3AAU000320	Colour	SILVER	
Odometer	152387	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	FALKEN	6 mm	
L/H Front Tyre	195/60 R15	FALKEN	6 mm	
R/H Rear Tyre	195/60 R15	FALKEN	6 mm	
L/H Rear Tyre	195/60 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2019	Inspection Date	28/01/2019	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDY 8278J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	700.00	700.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	40.00	-
1	REAR BUMPER RETAINER LH	DEFORMED	40.00	40.00
1	REAR TAIL LAMP RH	NOT NECESSARY	420.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	420.00	-
2	REAR TAIL LAMP GROMMET UPPER @\$10.00	NECESSARY	20.00	20.00
2	REAR TAIL LAMP GROMMET LOWER @\$5.00	NECESSARY	10.00	10.00
1	REAR BOOTLID	DEFORMED	700.00	700.00
1	REAR BOOTLID LOCK	SERVICEABLE	80.00	-
1	REAR BOOTLID SEAL	CUT	180.00	180.00
1	REAR BOOTLID HINGE RH	NOT NECESSARY	50.00	-
1	REAR BOOTLID HINGE LH	NOT NECESSARY	50.00	-
1	REAR /END PANEL GARNISH	DEFORMED	180.00	180.00
1	END PANEL	BUCKLED	420.00	420.00
1	REAR MITSUBISHI EMBLEM	NECESSARY	60.00	60.00
1	REAR LANCER EMBLEM	NECESSARY	60.00	60.00
1	REAR GLX EMBLEM	NOT NECESSARY	60.00	-
1	REAR MR EMBLEM	NECESSARY	60.00	60.00
	LESS 10% DISCOUNT		-	-248.00
			3,600.00	2,232.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	SPRAY PAINTING WHOLE REAR INCLUDE INNER PANEL.		1,000.00	550.00
	REPLACE REAR INCLUDING FITTING ,CUT,WELD AND RE-ALIGN		1,000.00	800.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR.		80.00	30.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	30.00

Report Ref No. CC6/CTI19001138/Jea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK AND RECTIFY ELECTRICAL WIRING.		20.00	20.00
			2,200.00	1,430.00
GRAND TOTAL			6,000.00	3,862.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC6/CT119001138/Jea3n2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.