



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1901-001
DATE : 9-Jan-2019
POLICY NO. : FWD PNPV2017-00001714-01
VEHICLE REG. NO. : SDY8278J

VEHICLE MAKE : MITSUBISHI LANCER 1.6 GLX AUTO

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

LKK Auto Consultants hence notify
the Repairer of the following:
FOR SURVEYOR
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE REPAIR COST

Acknowledged by Repairer

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>BUC</i>	1	\$ 700.00	\$ 700.00 ✓
2	Rear Bumper Clips <i>NEC</i>	10	\$ 5.00	\$ 50.00 ✓
3	Rear Bumper Retainer RH <i>NN</i>	1	\$ 40.00	\$ 40.00 X
4	Rear Bumper Retainer LH <i>DEF</i>	1	\$ 40.00	\$ 40.00 ✓
5	Rear Tail Lamp RH <i>NN</i>	1	\$ 420.00	\$ 420.00 X
6	Rear Tail Lamp LH <i>NN</i>	1	\$ 420.00	\$ 420.00 X
7	Rear Tail Lamp Grommet Upper <i>NEC</i>	2	\$ 10.00	\$ 20.00 ✓
8	Rear Tail Lamp Grommet Lower <i>NEC</i>	2	\$ 5.00	\$ 10.00 ✓
9	Rear Bootlid <i>DEF</i>	1	\$ 700.00	\$ 700.00 ✓
10	Rear Bootlid Lock <i>SVC</i>	1	\$ 80.00	\$ 80.00 X
11	Rear Bootlid Seal <i>CUT</i>	1	\$ 180.00	\$ 180.00 ✓
12	Rear Bootlid Hinge RH <i>NN</i>	1	\$ 50.00	\$ 50.00 X
13	Rear Bootlid Hinge LH <i>NN</i>	1	\$ 50.00	\$ 50.00 X
14	Rear / End Panel Garnish <i>DEF</i>	1	\$ 180.00	\$ 180.00 ✓
15	End Panel <i>BUC</i>	1	\$ 420.00	\$ 420.00 ✓
16	Rear Mitsubishi Emblem <i>NEC</i>	1	\$ 60.00	\$ 60.00 ✓
17	Rear Lancer Emblem <i>NEC</i>	1	\$ 60.00	\$ 60.00 ✓
18	Rear GLX Emblem <i>NN</i>	1	\$ 60.00	\$ 60.00 X
19	Rear MR Emblem <i>NEC</i>	1	\$ 60.00	\$ 60.00 ✓
Total Spare Parts				\$ 3,600.00
SPECIAL NETT				
20	Reverse Sensor <i>Shorted</i>	1	\$ 200.00	\$ 200.00 ✓
Total Special Nett				\$ 200.00
LABOUR				
21	Spray Painting Whole Rear Include Inner Panel	1	\$ 1,000.00	\$ 550 1,000.00 ✓
22	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 800 1,000.00 ✓
23	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 30 80.00 ✓
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 30 100.00 ✓
25	Check and rectify electrical wiring	1	\$ 20.00	\$ 20.00 ✓
Total Labour				\$ 2,200.00
Amount Before Excess				\$ 6,000.00
Add GST @ 7%				420.00
Total Amount Payable				\$ 6,420.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Hwee Jie - LKK
28/1/19
L/S Sdave