

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 21 Jan 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------|
| Vehicle No | : SDR3733G | Accident Date | : 16/01/2019 |
| Make | : MERCEDES-BENZ B180 | Policy No. | : D18MTPV01017834 |
| Assignment Date | : 18/01/2019 | Excess | : S\$500.00 |
| Date of Inspection | : 18/01/2019 | Est. Duration of Repair | : 7 days |
| Inspection At | : Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

| | |
|-----------------------------|----------------|
| Repairer's Estimate (Gross) | :S\$ 14,170.31 |
| Revised Amount | :S\$ 10,914.74 |
| Check Items (Estimated) | :S\$ 480.00 |
| Total | :S\$ 11,394.74 |
| Lump Sum Repair :S\$ | |

Total Loss Consideration

| | |
|--------------------|----------------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ 83,000.00 |
| COE / PARF Rebate | :S\$ 54,718.00 |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ 28,282.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :