

ASS. REC. BY:

REF

CS/SMO19001143/TIS d3er

Special Instruction:

Surveyor
Merimen

Tau fiah

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong

of SMO

Date/Time: 18/1/19 @ 11:50am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SDR 3733G

Insured:

at Workshop m/s

Cycle & Carriage Ltd.

Tel:

9186 5109

of

188 pendan loop

Policy No:

D18MTPV 01017834

Claim No:

CMTD1900406

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A. 16/01/2019

CA / REX

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:17pm @ 18/1/19

Person Contacted:

Yik chen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDR 3733G - X

21/01/19

@ 14:53 p.m. revised IA to Gnoh Pau Loong
via merimen.

21/01/19

@ 15:01 p.m. ^{requested} mandate authority repair to Gnoh Pau
Loong via merimen.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: thq.
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$83K.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Yuh Vehicle: IN / OUT

Veh No: SDR 3733 G. Yr Regn: 2015 / Oct.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Mercedes Benz. B180 C.C. 1595.
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 84932 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD-24624 22 J356139.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / 2Rim / STD A/Rim or
 Tyre Size: F: 205 / 55 R16.
 R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 18/1/19 @ 3pm
 Survey held at CRC Pankar Long
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/5 Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/01/19 @ 15:25 p.m.	mandate approved by Ansh Pas Looy via merime.
22/01/19 @ 10:52 a.m.	revert authorize repair to Yik (Gepaw) via email.
12/03/19	Confirmed P/P \$ 11,354.77 @ 7 days with Taufik (\$ 3,255.57 Red - 22%)

RECEIVED 12 MAR 2019

12/3/2019

Date/Time, File Pass to? 12/03/19
 1) Typist ☐ : Preli. Report
☒ : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 7
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:	<u>350</u>
Transportation	_____
Photos	_____
Others	_____
TOTAL	<u>360</u>

Report Format : _____
 Lump Sum / I.B.I: (\$ 11,354.77 P/P)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		18 Jan 2019 11:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEONG CHEE ONN, ID: S1610093E, Tel: +6590120823, Email: fleong3733@gmail.com		
Vehicle Reg. No.:	SDR3733G	Date of Loss:	16/01/2019 08:00 - :59
Claim Type:	OD / CMTD1900406	Policy/Cover Note No.:	D18MTPV01017834 (Comprehensive)
		Excess:	
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2019]		
Driver/Custodian:	LEONG CHEE ONN (55 / Male), NRIC: S1610093E, Tel: +6590120823		
Adj Asg. Remarks:	PIC: YIK CHAN HOE / 9186 5109 DID: 6771 4353 FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0093E
Vehicle Details	
Vehicle No.:	SDR3733G
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 STYLE (R16 LED)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	27091030764628
Chassis No.:	WDD2462422J356139
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,384.00
Original Registration Date:	28 Oct 2015
First Registration Date:	28 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$22,538.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2025
PARF Rebate Amount:	\$16,903.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,889.00
COE Rebate Amount:	\$37,815.00
Total Rebate Amount:	\$54,718.00

The information contained herein is correct as at 21 Jan 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 12 March 2019 3:58 PM
To: 'Yik Chan Hoe'
Cc: SUR; Taufikh (LKKAuto)
Subject: RE: SDR3733G final bill

Dear Chan Hoe,

Confirmed final fig of \$ 11,354.77 (part by part) @ 7 days of repairs before excess \$500/- & GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Saturday, 9 March 2019 10:59 AM

To: Taufikh (LKK Auto) <taufikh@lkkauto.com> (taufikh@lkkauto.com) <taufikh@lkkauto.com>

Cc: 'sur@lkkauto.com' <sur@lkkauto.com>

Subject: SDR3733G final bill

Hi Taufikh,

Fyna.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

-----Original Message-----

From: ApeosPort-IV 3070 [mailto:AP3070@cyclecarriage.com.sg]

Sent: Saturday, 9 March, 2019 10:55 AM

To: Yik Chan Hoe

Subject: Scan Data from FX-C5A1F4

Number of Images: 2

Attachment File Type: PDF

Device Name: ApeosPort-IV 3070

Device Location:

DISCLAIMER:-

This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message.

Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 22 January 2019 10:52 AM
To: 'Yik Chan Hoe'
Cc: 'Dennis Yap Kian Meng'; 'chinleong.cheong@cyclecarriage.com.sg'
Subject: SDR 3733G OD (SOMPO)

Dear Mr. Yik,

As instructed by our client, please proceed to repair the insured vehicle **SDR 3733G (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Sent Message

This mail is associated with :

***SDR3733G (CMTD1900406)**

OD

Jan 16 2019 8:00AM

[LEONG CHEE ONN]

Cycle & Carriage Industries Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/03/2019 11:48 AM.

To PauLoong.Gnoh@sompo.com.sg

CC sur@lkkauto.com

Subject SDR3733G (CMTD1900406) OD

Dear Pau Loong,

We have received supplementary of \$440.03 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair, within authorize limit.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SDR3733G (CMTD1900406)**

OD

Jan 16 2019 8:00AM

[LEONG CHEE ONN]

Cycle & Carriage Industries Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 21/01/2019 15:25 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11394.74) - SDR3733G - Claim Handler: GNOH PAU LOONG

Approved:11394.74.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 21 Jan 2019

Preliminary Advice

Vehicle No	: SDR3733G	Accident Date	: 16/01/2019
Make	: MERCEDES-BENZ B180	Policy No.	: D18MTPV01017834
Assignment Date	: 18/01/2019	Excess	: S\$500.00
Date of Inspection	: 18/01/2019	Est. Duration of Repair	: 7 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,170.31
Revised Amount	:S\$	10,914.74
Check Items (Estimated)	:S\$	480.00
Total	:S\$	11,394.74

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	54,718.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,282.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2019 18:57
Date Of Accident	16/01/2019 08:20
Exact Location Of Accident	ALG JUNC OF UPPER PICKERING ST & SOUTH BRIDGE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDR3733G
Insured/Policyholder	
Name Of Registered Owner	LEONG CHEE ONN
NRIC No	S1610093E
Email Address	FLEONG3733@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90120823
Alternative Phone No	OFFICE-90120823

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B180 STYLE (R16 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01017834
Cover Note Number	

Driver

Name of Driver	LEONG CHEE ONN
NRIC No	S1610093E
Date Of Birth	29/10/1963
Occupation	INDOOR
Date Of Driving Pass	14/11/1990
Driving Experience	28 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90120823
Fax Number	
Contact Number	OFFICE-90120823
EMail Address	FLEONG3733@GMAIL.COM

Address	37 SPRINGSIDE CRESCENT SINGAPORE 786180
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : LEE SONG LENG GENDER: : FEMALE
Passenger 2	NAME: : JAMIE LEONG WEI YI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was turning right on lane 2 into South Bridge Rd. Car B (motorbike) went straight on lane 1 instead of turning right while was a right turn lane only. And knocked into the right front side of my car. Please note that my right turn signals were on. Damages of my car right side position. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM7825Z
Vehicle Make/Model/Colour	SUZUKI/GSX1300RAL4 (HAYABUSA ABS)/WHITE
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	THEEBAN S/O SANDERAN
NRIC/Passport Number	S9244362J
Contact Number	94276032

Address	APT BLK 813 TAMPINES STREET 81 #06-536
Postcode	520813
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

meeting.

Sketch Plan

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GfA Records Management Centre established by the General Insurance Association of Singapore (GfA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if required.
8. Consent under the Personal Data Protection Act (PDPA):
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GfA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or processed by me, insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) and have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"; the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (ii) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) investigating the accident and/or my claims;
 - (iv) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (v) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (vi) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/also be disclosed by any of the insurers and/or GfA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


VERIFIED BY AJAX MARS
REPORTING OFFICER
Johnny
Voo Cheon Yee
Witnessed by Reporting Centre
Personnel

Sketch Plan



SKETCH PLAN

South Bridge Rd.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was turning right on lane 2 into South Bridge Rd. Car B (motor bike) went straight on lane 1 instead of turning right which was a right turn lane only. and knocked into the right front side of my car. Please note that my right turn signals were on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1610093E



Name

LEONG CHEE ONN



梁志安

Race

CHINESE

Date of Birth

Sex

29-10-1963

M

Country of Birth

SINGAPORE

S1610093E

Identification Card

0882097



NRIC No. S1610093E

Blood Group Date of issue

B+ 08-04-1993

37 SPRINGSIDE CRESCENT
SINGAPORE 786180

NRIC No: S1610093E

Date: 20/12/2015

Driving License


REPUBLIC OF SINGAPORE **DRIVING LICENCE**


License Number **S1610093E**

Name
LEONG CHEE ONN

Birth Date **29 Oct 1963**

Issue Date **25 Oct 2003**



 000948245D

Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms


14 Nov 1990



Licence No: S1610093E

NP 428A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9244362J



Name
THEEBAN S/O SANDERAN

தீபன்
Race
INDIAN

Date of birth
23-11-1992

Sex
M

Country of birth
SINGAPORE

S9244362J

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S9244362J

Name
THEEBAN S/O SANDERAN

Birth Date: 23 Nov 1992

Issue Date: 10 Mar 2011



1001945057K

PICS BY INSURED

4142629




NRIC No. S9244362J

Date of issue
10-12-2007

Address
APT BLK 813 TAMPINES STREET 81
#06-536
SINGAPORE 520813

PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING CATEGORIES


Class 2B	Motorcycles <= 200 CC	16 Mar 2011
Class 2A	Motorcycles between 201 CC and 400 CC	16 Sep 2012
Class 2	Motorcycles > 400 CC	22 Apr 2011
Class 3	Motor cars <= 2000 kg with <= 7 passengers, exclusive of the driver, and motor tractor/vehicles <= 2500 kg	16 Feb 2012

S9244362J

S/No. 9000204430

NP 425A

License No. S9244362J





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDR3733G

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information

WIP No **30209**
Reg No/Reg Date **SDR3733G / 28/10/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2462422J356139**
Engine No **27091030764628**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **026-650-Calcit White/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	17/01/2019/ 14:28	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE : D18MTPV01017834 // 16/01/2019 DRIVE IN/EXCESS : 17/01/2019 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
S BPNSUB TRANSFER TYRE OVER TO NEW RIM				60.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				2880 3000.00
A BPIRES RESPRAY RIGHT FRONT DOOR, RIGHT FRONT FENDER AND FRONT BUMPER				1800 2400.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DQOR.NETT				an x 480.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
M RIGHT FRONT DOOR	1.00	1615.97	00.00	R 1615.97
M RIGHT FRONT DOOR INSULATION	1.00	63.93	00.00	x 63.93
M RIGHT FRONT DOOR WEATHERSTRIP	1.00	290.54	00.00	x 290.54
M RIGHT FRONT WINDOW GUIDE RAIL	1.00	75.78	00.00	x 75.78
M RIGHT FRONT FENDER	1.00	659.41	00.00	659.41
M RIGHT FRONT DOOR INTERMEDIATE LAYER	1.00	9.35	00.00	an x 9.35
M FRONT BUMPER	1.00	1387.61	00.00	de 1387.61
M RIGHT HEADLAMP UNIT	1.00	2578.52	00.00	cut 2578.52
M RIGHT FRONT DISK WHEEL	1.00	509.20	00.00	cut 509.20

Confirmed & accepted by

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Nett **14,170.31**
7% GST on **14170.31** **991.92**
Total Payable 15,162.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDR3733G

SUPPLEMENTARY

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information
WIP No 30209
Reg No/Reg Date SDR3733G / 28/10/2015
Date In/Mileage 22/01/2019/ 84932
Chassis No WDD2462422J356139
Engine No 27091030764628
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 026 650 Calcit Whit/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	24/01/2019/ 15:50	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X COMPANY SIGN	1.00	61.80	00.00	61.80 A
X MOUNTING RAIL	1.00	30.48	00.00	30.48 A
X STIFFENING	1.00	27.27	00.00	27.27 A
X WHEEL HOUSE COVERING	1.00	188.53	00.00	188.53 A
X IMPACT ABSORBER	1.00	131.95	00.00	131.95 A

ESTIMATE

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 440.03
7% GST on 440.03 30.80
Total Payable 470.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SDR3733G

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

WIP No

30209

Reg No/Reg Date

SDR3733G / 28/10/2015

Date In/Mileage

22/01/2019 / 84932

Chassis No

WDD2462422J856139

Engine No

27091030764628

Make/Model

MB/B 180 SEDAN (W246) "STYLE

Colour/Trim

026 650 Calcit Whit/ 041 111 Black

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	09/03/2019/ 10:52		395 / Yik Chan Hoe

Description of Goods / Services

Qty Unit Price Disc% Amount

Z REQUEST

Customer Request

M BPNSUB

POLICY NO/ACC DATE : D18MTPV01017834 // 16/01/2019

DRIVE IN/EXCESS : 17/01/2019 // \$500.00

DATE IN/DATE SURVEY: 18/01/2019 // TAUFIKH LKK

BY/AUTHORIZED ON : 22/01/2019 // SHIRLEY HIEW LKK

S BPNSUB

LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)

WHEEL BALANCE AND INSTALL NEW VALVE HEAD

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY RIGHT FRONT DOOR, RIGHT FRONT FENDER AND FRONT BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

X RIGHT FRONT FENDER

1.00 659.41 00.00 659.41

X FRONT BUMPER

1.00 1387.61 00.00 1387.61

X RIGHT HEADLAMP UNIT

1.00 2578.52 00.00 2578.52

X RIGHT FRONT DISK WHEEL

1.00 509.20 00.00 509.20

X BPNEXC

INSURANCE EXCESS

-500.00

X FRONT BUMPER MB EMBLEM

1.00 61.80 00.00 61.80

X RIGHT FRONT BUMPER MOUNTING RAIL

1.00 30.48 00.00 30.48

X RIGHT FRONT BUMPER STIFFENING

1.00 27.27 00.00 27.27

X RIGHT FRONT FENDER LINER

1.00 188.53 00.00 188.53

X FRONT IMPACT ABSORBER

1.00 131.95 00.00 131.95

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Nett

10,854.77

7% GST on 10854.77

759.83

Total Payable

11,614.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDR3733G

SUPPLEMENTARY

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information
WIP No 30209
Reg No/Reg Date SDR3733G / 28/10/2015
Date In/Mileage 22/01/2019/ 84982
Chassis No WDD246242J356139
Engine No 27091030764628
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 026 650 Calcit Whit/ 041 111 Black

SDR3733G

Account No	Terms	Date/Time Printed	CSE	Operator			
WT009122	Credit	09/03/2019/ 10:53		395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	FRONT BUMPER MB EMBLEM			1.00	61.80	00.00	61.80
X	RIGHT FRONT BUMPER MOUNTING RAIL			1.00	30.48	00.00	30.48
X	RIGHT FRONT BUMPER STIFFENING			1.00	27.27	00.00	27.27
X	RIGHT FRONT FENDER LINER			1.00	188.53	00.00	188.53
X	FRONT IMPACT ABSORBER			1.00	131.95	00.00	131.95

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on	440.03	30.80
Total Payable	440.03	470.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2019		18 Jan 2019 11:50 Edit Adj Rpt	S\$11,354.77 Edit Estimates	S\$11,354.77 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEONG CHEE ONN , ID: S1610093E, Tel: +6590120823, Email: fleong3733@gmail.com									
Vehicle Reg. No.: SDR3733G		Date of Loss: 16/01/2019 08:00 - :59 [38 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / CMTD1900406		Policy/Cover Note No.: D18MTPV01017834 (Comprehensive)							
		Excess: S\$500.00							
Repairer: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/01/2019]									
Driver/Custodian: LEONG CHEE ONN (55 / Male) , NRIC: S1610093E, Tel: +6590120823 Email: fleong3733@gmail.com									
Adj Asg. Remarks: PIC: YIK CHAN HOE / 9186 5109 DID: 6771 4353 FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• SOMPO_SG (21/01/2019): Alert - Adj Mandate Approved (S\$11394.74) - SDR3733G - Claim Handler: GNOH PAU L...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


















*SDR3733G (CMTD1900406)
OD
Jan 16 2019 8:00AM
[LEONG CHEE ONN]
Cycle & Carriage Industries Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)								Thumbnail	Print	
1	16/01/19 19:01	Accident Statement								Load HTM	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	21/01/19 14:53	Adjuster Immediate Advice								Load HTM	<input checked="" type="checkbox"/>	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	21/01/19 14:55	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>	
2	21/01/19 14:55	Chassis Number								Load JPG	<input checked="" type="checkbox"/>	
3	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
4	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
5	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
6	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
7	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
8	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
9	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
10	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
11	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
12	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
13	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
14	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
15	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
16	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
17	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
18	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
19	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
20	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
21	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
22	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
23	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
24	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
25	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
26	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
27	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
28	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
29	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
30	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
31	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
32	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
33	21/01/19 14:56	General View								Load JPG	<input checked="" type="checkbox"/>	
34	12/03/19 11:50	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	12/03/19 11:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/19 16:57	OD Survey - Cycle & Carriage Industries Pte Ltd	Load PDF	
2	17/01/19 17:13	OD - ESTIMATE	Load JPG	<input checked="" type="checkbox"/>
3	18/01/19 11:55	OD - REASSIGN TO LKK	Load PDF	
4	21/01/19 14:18	EMAIL REPLY FRM C & C THAT OI NO FOOTAGE	Load PDF	
5	21/01/19 14:18	SO10 LTR	Load PDF	
6	24/01/19 14:02	AGENT FWD 5 SCENE PIC	Load PDF	
7	24/01/19 14:02	EMAIL REPLY ACK TO AGENT ON 5 SCENE PIC	Load PDF	
8	30/01/19 14:33	MOTOR ALERT POINTS	Load PDF	
9	08/03/19 10:29	EMAIL REPLY TO AGENT & TO C & C TO FWD OD DOC FOR RECOVERY	Load PDF	
10	11/03/19 09:01	EMAIL CHASER TO LKK TO FINALISE OD REPAIR'	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 14:54	ESTIMATE.pdf	Load PDF	
2	12/03/19 11:50	SUPPLEMENTARY.pdf	Load PDF	
3	12/03/19 16:04	ESTIMATE & SUPPLEMENTARY MARKED.pdf	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	16/01/19 19:01	Accident Statement	Load HTM	
2	16/01/19 19:47	Accident Statement Addm. #1	Load HTM	
3	17/01/19 12:15	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
4	17/01/19 12:17	Accident Statement Addm. #2	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	16/01/19 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
12	16/01/19 19:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	16/01/19 19:01	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
14	16/01/19 19:01	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
15	16/01/19 19:01	Driving License	 Load JPG	<input checked="" type="checkbox"/>
16	16/01/19 19:01	Driving License	 Load JPG	<input checked="" type="checkbox"/>
17	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
18	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
19	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
20	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
21	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
22	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
23	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
24	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
25	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
26	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
27	16/01/19 19:46	PICS BY INSURED	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	17/01/19 12:15	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19001143/T1SD3E2

Date: 14/03/2019

REFERENCE

Insured/Claimant: LEONG CHEE ONN Policy No: D18MTPV01017834
Date of Loss: 16/01/2019 Nature of Claim: OD Claim No: CMTD1900406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDR3733G**
Make & Model: MERCEDES-BENZ B180, 1.6 STYLE (R16 LED) (A) Engine No: 27091030764628
Reg. Date: 28/10/2015 (Man. Year: 2015) Chassis No: WDD2462422J356139
Colour: White Odometer: 84932 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,630.34	5,574.77	2,055.57	26.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,980.00	5,780.00	1,200.00	17.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,610.34	11,354.77	3,255.57	22.28
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,110.34	10,854.77	3,255.57	23.07
+ GST 7.00/7.00% (S\$)	987.72	759.83	227.89	23.07
Nett Amount (S\$)	15,098.06	11,614.60	3,483.46	23.07

INSPECTION

Date of Assignment: 18/01/2019

Date Inspected: 18/01/2019 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2019)
Parts:	144	MERCEDES-BENZ B180 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDR3733G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR	Repair	1,615.97 FS	*- FS
2	1		*RIGHT FRONT DOOR INSULATION	Not Necessary	63.93 FS	*- FS
3	1		*RIGHT FRONT DOOR WEATHERSTRIP	Not Necessary	290.54 FS	*- FS
4	1		*RIGHT FRONT WINDOW GUIDE RAIL	Not Necessary	75.78 FS	*- FS
5	1		*RIGHT FRONT FENDER	Bent	659.41 FS	*659.41 FS
6	1		*RIGHT FRONT DOOR INTERMEDIATE LAYER	Not Necessary	9.35 FS	*- FS
7	1		*FRONT BUMPER	Deformed	1,387.61 FS	*1,387.61 FS
8	1		*RIGHT HEADLAMP UNIT	Cut	2,578.52 FS	*2,578.52 FS
9	1		*RIGHT FRONT DISK WHEEL	Cut	509.20 FS	*509.20 FS
10	1		*COMPANY SIGN	Deformed	61.80 FS	*61.80 FS
11	1		*MOUNTING RAIL	Deformed	30.48 FS	*30.48 FS
12	1		*STIFFENING	Bent	27.27 FS	*27.27 FS
13	1		*WHEEL HOUSE COVERING	Deformed	188.53 FS	*188.53 FS
14	1		*IMPACT ABSORBER	Deformed	131.95 FS	*131.95 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,630.34	5,574.77
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TYRE OVER TO NEW RIM	New	60.00	60.00
2	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	3,000.00	2,880.00
3	RESPRAY RIGHT FRONT DOOR, RIGHT FRONT FENDER AND FRONT BUMPER	New	2,400.00	1,800.00
4	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
5	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
6	INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
7	TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR	New	480.00	0.00
Gross Labour Cost (S\$)			6,980.00	5,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >