

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G**AAD1901-092***Man**Not Ashanid**11 Sep @ 4100h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9911G

VF1ABL15AUC273472

RENAULT

LATITUDE

9.1.2019

AIG

30/8/2013

PART**LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	HEADLAMP LH
20	1	HEADLAMP RH
21	1	HEADLAMP PANEL FRT LH
22	1	HEADLAMP PANEL FRT RH
23	1	BONNET
24	1	BONNET INSULATOR
25	1	BONNET STRUT LH
26	1	BONNET STRUT RH
27	1	BONNET HINGE LH
28	1	BONNET HINGE RH

\$	<i>Bumper</i>	<i>RH</i>	1,259.42	✓
\$		<i>SL</i>	181.75	
\$		<i>SL</i>	394.68	
\$		<i>SL</i>	151.41	
\$		<i>SL</i>	123.88	
\$		<i>SL</i>	150.77	
\$		<i>SL</i>	123.88	
\$		<i>SL</i>	472.83	
\$		<i>EM</i>	266.80	✓
\$		<i>SL</i>	207.21	X
\$		<i>SL</i>	207.21	X
\$		<i>R</i>	914.08	X
\$		<i>SL</i>	28.61	X
\$	<i>inj</i>	<i>RH</i>	1,707.78	—
\$		<i>RH</i>	225.36	—
\$	<i>CRT</i>		1,353.75	—
\$		<i>SL</i>	615.90	
\$		<i>R</i>	89.79	
\$		<i>SL</i>	1,184.43	
\$		<i>SL</i>	1,184.43	
\$		<i>R</i>	152.15	
\$		<i>R</i>	152.15	
\$		<i>R</i>	1,941.63	
\$		<i>SL</i>	405.73	
\$		<i>SL</i>	88.61	
\$		<i>SL</i>	88.61	
\$		<i>R</i>	348.31	
\$		<i>R</i>	348.31	

Trans-cab Auto Services Pte Ltd**AAD1901-092**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

29	1	BONNET CABLE COVER	\$	Sh	161.03	X
30	1	BONNET SEAL OUTER	\$	Sh	92.36	X
31	1	BONNET SEAL INNER	\$	Sh	157.28	X

TOTAL	\$	14,780.15
10%	\$	1,478.01
	\$	13,302.13

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	Sh	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	Sh	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	Sh	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	Sh	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	Sh	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	Sh	10.50	
7	1	TOW COVER FRT	\$	Sh	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	Sh	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	Sh	69.00	} X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Sh	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	Sh	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	Sh	30.00	} X
21	1	Windscreen moulding	\$	Sh	100.00	
22	1SET	Front licence plate with holder	\$	Sh	80.00	255a

TOTAL	\$	562.50
TOTAL PARTS	\$	13,864.63

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 2,450.00 ⁴⁰⁰¹

To apply paint protection system (PPS) maintain
and enhancement

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1901-092**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9911G

Putty and spray painting of the affected portion.	\$	2,200.00	220/
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	15/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X

TOTAL \$ 7,790.00**Over All Total \$ 21,654.63****(LUMP SUM) Repair Days****2-DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: