

15/5/2010

INS. CASE OWNER:

KC

CC 4 / AXA1900

1154

J P 6302

LKK:  
IDAC:

Surveyor:

VLS

DOI:

ASSIGNMENT

18/1/19

Date / Time:

8/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5039X

Name of Insured:

TRANS-LAB SERVICES P/L

Insured Tel No.:

HP:

Excess Sec II : \$S

D.O.A:

16/1/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

TAN MUN KUAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SANDIARK 14227

Policy No.:

UPX 1680510

Make / Model:

PERMANT

Place of Accident:

off Trans City

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHC 5039X

SHC 477AA

SDR 719

SJV 823R

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

01

INSRS:  
WSP: SMT  
Tel:  
Liability:  
RMKS: TPINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:Hi Su Li,  
Pls send BS  
form & ATA  
TA.

Date/ Time

21/1/19  
VLC

SHC 477AA - X

SHC 5039X - (W) / Trans City / (E) / 16/1/19

STA:

Non-

Non-

Non-

Notifi

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

14/1/19 - KC Y Su Li to send DCR on ATA  
19/1/19 - File pass to LSP to close.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

( days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia: 100%.

Repair Cost:

\$S

6000.00

Loss of Rental (LOR):

\$S

868.88

( 8 days)

&gt; \$108.61

Loss of Use (LOU):

\$S

-

(S x days)

Loss of Income (LOI):

\$S

400.00

(S x 8 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

Total:

\$S

7268.88

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$S

7268.88

Name 1:

SMRT TAXIS Pte Ltd

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

⊙ AA Wap

COPY SENT  
20/8/19





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001154/Jhb3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 18-01-2019



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SHC 5039X | Veh. Inspected | SHC 4727A  |
| Policy No.   |           | Coverage (\$)  | 0.00       |
| Claim No.    |           | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 18/01/2019 |

### 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |                                                                                      |                 |            |
|----------------|--------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 16/01/2019                                                                           | Inspection Date | 18/01/2019 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |            |



### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

Vic

Section A - Accident Details

|                                    |                     |
|------------------------------------|---------------------|
| Registration Number                | SHC4727A            |
| Case Reference Number              | TAX/01/19/2078      |
| Registration Date                  | 10/12/2014          |
| Company Type                       | SMRT Taxis Pte Ltd  |
| Make                               | TOYOTA              |
| Model                              | PRIUS               |
| Name of Driver                     | IRENE WONG YAN LING |
| Type of Accident                   | Head to Rear        |
| Accident Date and Time             | 16/1/2019 8:00 AM   |
| Accident Reported Date and Time    | 16/1/2019 12:43 PM  |
| Is Surveyor Required?              | No                  |
| Survey by                          |                     |
| Vehicle is Towed Back?             | No                  |
| Towed Back Date and Time           |                     |
| Replacement Vehicle issued?        | No                  |
| Job Card Number                    | 24099708            |
| Special Instruction to ARC, if any | TP /AXA             |
| Prepared Date and Time             | 17/1/2019 3:14 PM   |
| Chassis Number                     |                     |
| Mileage                            |                     |
| Work Shop                          |                     |
| Repair Completion Date and Time    |                     |



Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$2,059.00                                                                          | \$900.00                                                                            |
| Total Spray Cost             | \$2,970.00                                                                          | \$900.00                                                                            |
| Total Spare Part Cost        | \$14,890.71                                                                         | \$3,985.94                                                                          |
| Total Other Cost             | \$1,085.00                                                                          | \$215.00                                                                            |
| <b>TOTAL COST</b>            | <b>\$21,004.71</b>                                                                  | <b>\$6,003.94</b>                                                                   |
| Lump Sum Total               | \$21,000.00                                                                         | \$6,000.00 (L/S)                                                                    |
| Number of Repair Days        | 12.0                                                                                | 6.0                                                                                 |
| Prepared / Adjusted By       | Zhi Yang Phua                                                                       | Hwee Jie (LKK) / AXA                                                                |
| ARC / Surveyor Sign Off Date | 23/01/2019 11:31 AM                                                                 |                                                                                     |
| Signature                    |  |  |
| Remarks                      | SUP = 2 DAYS                                                                        | L/S repair, photo after paint.                                                      |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1904-0007 | Invoice Number |  |
| Quotation Date   | 02.04.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope                     | Quotation from AR | Adjusted by Surveyor, if applicable |
|-------------------------------|-------------------|-------------------------------------|
| TO REPAIR RR END PANEL (SUPP) | \$200.00          | \$100.00 ✓                          |
| TO REPAIR FRONT PORTION       | \$845.00          | \$200.00 ✓                          |
| TO REPAIR REAR PORTION        | \$1,014.00        | \$800.00 ✓                          |
| <b>Total Labour</b>           | <b>\$2,059.00</b> | <b>\$900.00</b>                     |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR PANEL (SUPP)                    | \$180.00           | \$100.00 ✓                          |
| TO REPSRAY FRONT BUMPER                         | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY FRONT BUMPER LOWER GRILLE            | \$180.00           | \$0.00 ✗                            |
| TO REPSRAY FRONT HOOD                           | \$378.00           | \$0.00 ✗                            |
| TO RESPRAY FRONT SUPPORT PANEL                  | \$180.00           | \$0.00 ✗                            |
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY BUMPER BEAM                          | \$180.00           | \$0.00 ✗                            |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$0.00 ✗                            |
| TO RESPRAY TAIL GATE                            | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY REAR FENDER LH                       | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY TROUGH BACK DOOR LH                  | \$180.00           | \$0.00 ✗                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$2,970.00</b>  | <b>\$900.00</b>                     |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------------------------------------------------------|--------------------|-------------------------------------|
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                               | \$125.00 SN 1766   | \$125.00 ✓                          |
| TO CHECK WIRING AND SYSTEM FUNCTION                                             | \$80.00            | \$20.00 ✓                           |
| TO CONDUCT RADIATOR PRESSURE CHECK                                              | \$120.00           | \$0.00 ✗                            |
| TO TOP UP A/C GAS                                                               | \$120.00           | \$0.00 ✗                            |
| TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | \$120.00           | \$0.00 ✗                            |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                                         | \$120.00           | \$30.00 ✓                           |
| TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE         | \$120.00           | \$0.00 ✗                            |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.            | \$120.00           | \$40.00 ✓                           |
| TO WASH AND VACUUM                                                              | \$60.00            | \$0.00 ✗                            |
| TO REPLACE SUNDRY PARTS                                                         | \$100.00           | \$0.00 ✗                            |
| <b>Total Other Costs</b>                                                        | <b>\$1,085.00</b>  | <b>\$215.00</b>                     |

## Part 4 - Spare Parts / Material Usage





# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
Fax Number : 63665592  
Estimator Telephone Number : 6862023  
Accident Reporting Number : 6862672

Date Generated : 12/04/2019

User ID : PehSuan

|               |                                 |       |            |        |          |         |           |   |         |
|---------------|---------------------------------|-------|------------|--------|----------|---------|-----------|---|---------|
| 16571-37140   | RADIATOR TOP HOSE NO 1          | 0.00  | \$42.40    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 16572-37120   | RADIATOR HOSE LOWER             | 0.00  | \$42.40    | 25.00  | \$0.00   | Replace | Check     | X |         |
|               | COOLANT                         | 0.00  | \$12.32    | 0.00   | \$0.00   | Replace | Check     | X |         |
| 16363-37010   | FAN MOTOR NO 1                  | 0.00  | \$538.30   | 25.00  | \$0.00   | Replace | Not Given | X | nn      |
| 16363-37020   | FAN MOTOR NO 2                  | 0.00  | \$538.30   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 16711-37040   | FAN SHROUD                      | 0.00  | \$244.50   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 16712-37030   | FAN SHROUD TOP                  | 0.00  | \$99.60    | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 52159-47905   | BUMPER REAR                     | 1.00  | \$458.60   | 25.00  | \$343.95 | Replace | Replace   | X | DEF     |
| 52161-16010   | BUMPER CLIPS                    | 10.00 | \$1.61     | 25.00  | \$12.08  | Replace | Replace   | X | NEC     |
|               | PIXEL STICKER                   | 2.00  | \$60.00    | 0.00   | \$120.00 | Replace | Replace   | X | NEC     |
| 52023-12240   | BUMPER REINFORCEMENT REAR       | 0.00  | \$205.70   | 25.00  | \$0.00   | Replace | Check     | X | nn      |
| 52016-47030   | ARM SUB-ASSY, RR BUMPER LH      | 0.00  | \$139.60   | 25.00  | \$0.00   | Replace | Check     | X | nn      |
| 52015-47050   | ARM SUB-ASSY, RR BUMPER RH      | 0.00  | \$139.60   | 25.00  | \$0.00   | Replace | Check     | X | nn      |
| 89997-30070   | ANTENNA, ELECTRICAL LOWER REAR  | 0.00  | \$157.40   | 10.00  | \$0.00   | Replace | Check     | X | nn      |
|               | SENSOR REVERSE                  | 1.00  | \$180.00   | 0.00   | \$180.00 | Replace | Replace   | X | Shorted |
| 52576-47020   | BUMPER SIDE RETAINER RR/LH      | 0.00  | \$94.80    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 52575-47020   | BUMPER SIDE RETAINER RR/RH      | 0.00  | \$94.80    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 52592-47021   | BUMPER SEAL, RR LH              | 0.00  | \$88.90    | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 52591-47021   | BUMPER SEAL, RR RH              | 0.00  | \$85.70    | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 76088-47020   | BUMPER LIP COVER RR/LH          | 0.00  | \$72.20    | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 76087-47020   | BUMPER LIP COVER RR/RH          | 0.00  | \$118.10   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 76891-47020   | BUMPER LIP REAR                 | 0.00  | \$228.90   | 25.00  | \$0.00   | Replace | Not Given | X | nn      |
| 58308-47011   | UNDER COVER CENTER REAR         | 0.00  | \$514.50   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 58307-47060   | END PANEL                       | 0.00  | \$602.10   | 25.00  | \$0.00   | Replace | Check     | X |         |
| 64718-47031B0 | SEALANT SIKAFLEX                | 0.00  | \$37.00    | 0.00   | \$0.00   | Replace | Not Given | X |         |
| 64718-47031B0 | END PANEL COVER, DECK TRIM HOLE | 0.00  | \$46.10    | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 64716-47031B0 | END PANEL COVER, DECK TRIM, RR  | 0.00  | \$121.10   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 58336-12090   | REINFORCEMENT, RR               | 0.00  | \$34.60    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 67005-47241   | TAILGATE ASY                    | 1.00  | \$1,007.90 | 100.00 | \$0.00   | Replace | Repair    | X | RX      |
| 75374-47051   | NAME PLATE (HYBRID)             | 1.00  | \$51.90    | 25.00  | \$38.93  | Replace | Replace   | X | NEC     |
| 61602-47091   | FENDER RR/LH                    | 1.00  | \$766.80   | 100.00 | \$0.00   | Replace | Repair    | X | RX      |
|               | STICKER DECAL SMRT              | 1.00  | \$7.80     | 0.00   | \$7.80   | Replace | Replace   | X | NEC     |
|               | STICKER DECAL 6555 8888         | 1.00  | \$21.60    | 0.00   | \$21.60  | Replace | Replace   | X | NEC     |
| 62720-47031   | QUARTER GLASS RR/LH             | 0.00  | \$168.10   | 25.00  | \$0.00   | Replace | Not Given | X |         |
|               | SEALANT W/SCREEN                | 0.00  | \$37.00    | 0.00   | \$0.00   | Replace | Not Given | X |         |
| 65638-47021   | FENDER LINER RR/LH              | 0.00  | \$141.30   | 25.00  | \$0.00   | Replace | Not Given | X |         |
| 61622-47030   | TROUGH, BACK DOOR LH            | 0.00  | \$110.90   | 25.00  | \$0.00   | Replace | Check     | X | nn      |
| 52563-47010   | TAIL LAMP BRACKET, LH           | 0.00  | \$30.70    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 52562-47010   | TAIL LAMP BRACKET, RH           | 0.00  | \$30.70    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 62940-16060   | DUCT ASSY, QUARTER              | 0.00  | \$70.40    | 25.00  | \$0.00   | Replace | Check     | X |         |
| 69350-47030   | TAILGATE DOOR LOCK              | 0.00  | \$444.10   | 25.00  | \$0.00   | Replace | Not Given | X |         |

|       |             |                             |      |             |       |            |         |       |   |
|-------|-------------|-----------------------------|------|-------------|-------|------------|---------|-------|---|
|       | 67881-47022 | TAILGATE DOOR WEATHER STRIP | 0.00 | \$353.40    | 25.00 | \$0.00     | Replace | Check | X |
| Total |             |                             |      | \$20,541.44 |       | \$2,638.58 |         |       |   |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name                   | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | 52611-47080  | BUMPER ENERGY ABSORBER FRT  | 1.00     | \$78.80       | 25.00        | \$59.10          | Replace   | Replace        |
|             |         | 52021-47023  | BUMPER REINFORCEMENT FRT    | 1.00     | \$498.40      | 25.00        | \$373.80         | Replace   | Replace        |
|             |         | 57014-47030  | ARM SUB-ASSY, FR BUMPER LH  | 1.00     | \$250.40      | 25.00        | \$187.80         | Replace   | Replace        |
|             |         | 57013-47030  | ARM SUB-ASSY, FR BUMPER RH  | 1.00     | \$250.40      | 25.00        | \$187.80         | Replace   | Replace        |
|             |         | 81130-47500  | HEAD LAMP RH                | 1.00     | \$945.20      | 10.00        | \$850.68         | Replace   | Replace        |
|             |         | 52023-12240  | BUMPER REINFORCEMENT REAR   | 1.00     | \$205.70      | 25.00        | \$154.28         | Replace   | Replace        |
|             |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH  | 1.00     | \$139.60      | 25.00        | \$104.70         | Replace   | Replace        |
|             |         | 52015-47050  | ARM SUB-ASSY, RR BUMPER RH  | 1.00     | \$139.60      | 25.00        | \$104.70         | Replace   | Replace        |
|             |         | 52576-47020  | BUMPER SIDE RETAINER RR/LH  | 1.00     | \$94.80       | 25.00        | \$71.10          | Replace   | Replace        |
|             |         | 76087-47020  | BUMPER LIP COVER RR/RH      | 1.00     | \$118.10      | 25.00        | \$88.58          | Replace   | Replace        |
|             |         | 67881-47022  | TAILGATE DOOR WEATHER STRIP | 1.00     | \$353.40      | 25.00        | \$265.05         | Replace   | Replace        |
| Total       |         |              |                             |          | 3,074.40      |              | \$2,447.59       |           |                |

TN  
DD  
DD  
DD  
CRA  
DD  
DD  
DD  
CRA  
TN  
CUT

3428.80  
4986.17  
-20%  
3988.94  
+ 900.00  
+ 1115.00  
6003.94  
45 \$6000/-

2981P.82



# REQUEST FOR SUPPLEMENT PARTS

|                      |                |                                   |            |
|----------------------|----------------|-----------------------------------|------------|
| Contractor:          |                |                                   |            |
| Accident Case Number | TAX 01/19/2018 | Date of Collection:               | 1 / 1      |
| Vehicle No           | 84C 4727 A     | Date of Request                   | 22 10/2019 |
| Vehicle Model        | TOYOTA PRIUS   | Number of Days to Extend (if any) | \$ 2       |

| S/N | Part Number | Part Description              | Quantity | Unit Price |
|-----|-------------|-------------------------------|----------|------------|
|     |             | FRONT BUMPER FOAM             | 1pc      | TN ✓       |
|     |             | FRONT BUMPER REINFORCEMENT    | 1pc      | DD ✓       |
|     |             | ARM SUB ASSY, FRONT BUMPER LH | 1pc      | DD ✓       |
|     |             | ARM SUB ASSY, FRONT BUMPER RH | 1pc      | DD ✓       |
|     |             | HEAD LAMP RH                  | 1pc      | CRA ✓      |
|     |             | REAR BUMPER REINFORCEMENT     | 1pc      | DD ✓       |

<<Please submit photographs for damaged parts>>>

23/1/17

I, (Name) \_\_\_\_\_

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are used for replacement for the aforesaid vehicle.

.....  
Signature of person making this declaration  
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARCExecutive / Supervisor / SA                 |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO:                                      | Date of submission                        |

19/3

# REQUEST FOR SUPPLEMENTARY PARTS

|                      |                |                                   |            |
|----------------------|----------------|-----------------------------------|------------|
| Contractor:          |                |                                   |            |
| Accident Case Number | TAX/01/19/2018 | Date of Collection:               | / /        |
| Vehicle No           | SHL 4777 A     | Date of Request                   | 22/01/2019 |
| Vehicle Model        | TOYOTA PRIUS   | Number of Days to Extend (If any) | 32         |

| S/N | Part Number | Part Description             | Quantity | Unit Price |
|-----|-------------|------------------------------|----------|------------|
|     |             | ARM SUB ASSY, REAR BUMPER LH | 1pc      | DD ✓       |
|     |             | ARM SUB ASSY, REAR BUMPER RH | 1pc      | DD ✓       |
|     |             | REAR BUMPER RETAINER LH      | 1pc      | CRA ✓      |
|     |             | REAR BUMPER LIP RH           | 1pc      | TN ✓       |
|     |             | REAR WEATHERSTRIP            | 1pc      | CUT ✓      |
|     | Labour      | to REPAIR REAR END PANEL     |          | \$500 ✓    |

<<Please submit photographs for damaged parts>>

23/1/19

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration  
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |

pg 2/3

# REQUEST FOR SUPPLEMENTARY PARTS

|                      |                |                                   |             |
|----------------------|----------------|-----------------------------------|-------------|
| Contractor:          |                |                                   |             |
| Accident Case Number | Tax/01/19/2078 | Date of Collection:               | 1 / 1       |
| Vehicle No           | SIC 4777 A     | Date of Request                   | 22 101 2019 |
| Vehicle Model        | TOYOTA PRIUS   | Number of Days to Extend (if any) | \$ 2        |

| S/N | Part Number | Part Description                  | Quantity | Unit Price |
|-----|-------------|-----------------------------------|----------|------------|
|     |             | Labour to spray REAR END PANEL    |          | \$ 200     |
|     |             | TO REQUEST ADDITIONAL REPAIR DAYS |          |            |
|     |             |                                   |          |            |
|     |             |                                   |          |            |
|     |             |                                   |          |            |
|     |             |                                   |          |            |

\$105 ✓

<<Please submit photographs for damaged parts>>

23/1/19

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration  
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |

Pg 3/3



## Case Details

Case Reference Number : TAX/01/19/2078  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4727A

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5392-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd  
 Accident Date and Time : 16/01/2019 12:00 AM  
 Vehicle Age(In Months) : 49

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type              | Costing Type | Portion | Material Number | SMRT Recommendation        |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |
|-----------------------|--------------|---------|-----------------|----------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|
|                       |              |         |                 | Part Name                  | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |
| One Time Key In       | Main         |         |                 | BUMPER FRT                 | 1   | 482.00                  | 482.00         | 25.00  | 361.50          | Replace         | 1                 | 361.50                   | Replace ▾ DEF  |
| One Time Key In       | Main         |         |                 | BUMPER CLIPS               | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace         | 10                | 12.08                    | Replace ▾ NEC  |
| One Time Key In       | Main         |         |                 | BUMPER SUPPORT F/RH        | 1   | 76.40                   | 76.40          | 25.00  | 57.30           | Replace         | 0                 | 0                        | Not Give ▾     |
| One Time Key In       | Main         |         |                 | BUMPER SUPPORT F/LH        | 1   | 76.40                   | 76.40          | 25.00  | 57.30           | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | BUMPER ENERGY ABSORBER FRT | 1   | 78.80                   | 78.80          | 25.00  | 59.10           | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | BUMPER REINFORCEMENT FRT   | 1   | 498.40                  | 498.40         | 25.00  | 373.80          | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | ARM SUB-ASSY, FR BUMPER LH | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | ARM SUB-ASSY, FR BUMPER RH | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace         | 0                 | 0                        | Not Give ▾     |
| One Time Key In       | Main         |         |                 | DEFLECTOR, RADIATOR LH     | 1   | 77.00                   | 77.00          | 25.00  | 57.75           | Replace         | 0                 | 0                        | Check ▾        |
| Total Spare Part Cost |              |         |                 |                            |     |                         |                |        | 16,165.82       |                 | Surveyor Total    | 2,538.57                 |                |
| Lump Sum Discount (%) |              |         |                 |                            |     |                         |                |        | 0.00            |                 | Lump Sum Dis (%)  | 20                       |                |
| Final Spare Part Cost |              |         |                 |                            |     |                         |                |        | 12,932.66       |                 | Final Sur Total   | 2,030.86                 |                |

| BOM Type              | Costing Type | Portion | Material Number | SMRT Recommendation           |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |
|-----------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|
|                       |              |         |                 | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |
| One Time Key In       | Main         |         |                 | DEFLECTOR, RADIATOR RH        | 1   | 83.50                   | 83.50          | 25.00  | 62.63           | Replace           | 0                 | 0                        | check *        |
| One Time Key In       | Main         |         |                 | BRACKET, FR BUMPER            | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace           | 1                 | 82.80                    | Replace * BUL  |
| One Time Key In       | Main         |         |                 | NUMBER PLATE                  | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace           | 1                 | 15.00                    | Replace * DEF  |
| One Time Key In       | Main         |         |                 | NUMBER PLATE FRAME            | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace           | 1                 | 12.00                    | Replace * CRA  |
| One Time Key In       | Main         |         |                 | COVER, FR BUMPER HOLE LH      | 1   | 18.50                   | 18.50          | 25.00  | 13.88           | Replace           | 1                 | 13.88                    | Replace * MIS  |
| One Time Key In       | Main         |         |                 | COVER, FR BUMPER HOLE RH      | 1   | 18.50                   | 18.50          | 25.00  | 13.88           | Replace           | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | BUMPER GRILLE SUB-ASSY, LOWER | 1   | 311.10                  | 311.10         | 25.00  | 233.33          | Replace           | 1                 | 233.33                   | Replace * CRA  |
| One Time Key In       | Main         |         |                 | WIRE, ENGINE ROOM, NO.3       | 1   | 242.00                  | 242.00         | 10.00  | 217.80          | Replace           | 0                 | 0                        | Check *        |
| One Time Key In       | Main         |         |                 | LENS & BODY, FR TURN RH       | 1   | 511.80                  | 511.80         | 10.00  | 460.62          | Replace           | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | LENS & BODY, FR TURN LH       | 1   | 511.80                  | 511.80         | 10.00  | 460.62          | Replace           | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | EMBLEM FRONT                  | 1   | 86.50                   | 86.50          | 25.00  | 64.88           | Replace           | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | HOOD END PANEL SEAL           | 1   | 35.50                   | 35.50          | 25.00  | 26.63           | Replace           | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | GRILLE RADIATOR               | 1   | 310.60                  | 310.60         | 25.00  | 232.95          | Replace           | 1                 | 232.95                   | Replace * DEF  |
| One Time Key In       | Main         |         |                 | GRILLE RADIATOR LOWER NO.2    | 1   | 94.60                   | 94.60          | 25.00  | 70.95           | Replace           | 0                 | 0                        | Check *        |
| Total Spare Part Cost |              |         |                 |                               |     |                         |                |        | 16,165.82       | Surveyor Total    | 2,538.57          |                          |                |
| Lump Sum Discount (%) |              |         |                 |                               |     |                         |                |        | 0.00            | Lump Sum Dis (%)  | 20                |                          |                |
| Final Spare Part Cost |              |         |                 |                               |     |                         |                |        | 12,932.66       | Final Sur Total   | 2,030.86          |                          |                |



| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation         |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |              |
|-----------------|--------------|---------|-----------------|-----------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|--------------|
|                 |              |         |                 | Part Name                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |              |
| One Time Key In | Main         |         |                 | HOOD PANEL                  | 1   | 748.10                  | 748.10         | 25.00  | 561.08          | Replace         | 0                 | 0                        | Not Give       | ▼            |
| One Time Key In | Main         |         |                 | HOOD LOCK                   | 1   | 128.90                  | 128.90         | 25.00  | 96.68           | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | CABLE ASSY, HOOD            | 1   | 52.20                   | 52.20          | 25.00  | 39.15           | Replace         | 0                 | 0                        | Not Give       | ▼            |
| One Time Key In | Main         |         |                 | HORN ASSY, HIGH             | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | HORN ASSY, LOW              | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | SUPPORT SUB-ASSY            | 1   | 1,460.40                | 1,460.40       | 25.00  | 1,095.30        | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | HEAD LAMP LH                | 1   | 945.20                  | 945.20         | 10.00  | 850.68          | Replace         | 1                 | 850.68                   | Replace        | ▼ <i>SCR</i> |
| One Time Key In | Main         |         |                 | HEAD LAMP RH                | 1   | 945.20                  | 945.20         | 10.00  | 850.68          | Replace         | 0                 | 0                        | Not Give       | ▼            |
| One Time Key In | Main         |         |                 | A/C CONDENSER               | 1   | 1,181.90                | 1,181.90       | 25.00  | 886.43          | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | RADIATOR ASSY, UPPER        | 1   | 679.60                  | 679.60         | 25.00  | 509.70          | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | HOSE, INVERTER NO.1         | 1   | 80.00                   | 80.00          | 25.00  | 60.00           | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | HOSE, INVERTER COOLING NO.5 | 1   | 125.30                  | 125.30         | 25.00  | 93.97           | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | RADIATOR ASSY               | 1   | 1,496.90                | 1,496.90       | 25.00  | 1,122.68        | Replace         | 0                 | 0                        | Check          | ▼            |
| One Time Key In | Main         |         |                 | CUSHION, RADIATOR           | 2   | 11.30                   | 22.60          | 25.00  | 16.95           | Replace         | 0                 | 0                        | Check          | ▼            |

Total Spare Part Cost 16,165.82

Surveyor Total 2,538.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

Final Spare Part Cost 12,932.66

Final Sur Total 2,030.86

| SMRT Recommendation   |              |         |                 |                           |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |        |
|-----------------------|--------------|---------|-----------------|---------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|--------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                 | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |        |
| One Time Key In       | Main         |         |                 | SUPPORT, RADIATOR, LH     | 1   | 17.70                   | 17.70          | 25.00  | 13.27           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | SUPPORT, RADIATOR, RH     | 1   | 54.50                   | 54.50          | 25.00  | 40.88           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | SUPPORT, RADIATOR,        | 2   | 18.50                   | 37.00          | 25.00  | 27.75           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | RADIATOR TOP HOSE NO 1    | 1   | 42.40                   | 42.40          | 25.00  | 31.80           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | RADIATOR HOSE LOWER       | 1   | 42.40                   | 42.40          | 25.00  | 31.80           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | COOLANT                   | 4   | 12.32                   | 49.28          | 0.00   | 49.28           | Replace         | 0                 | 0                        | Check          | ▼      |
| One Time Key In       | Main         |         |                 | FAN MOTOR NO 1            | 1   | 538.30                  | 538.30         | 25.00  | 403.72          | Replace         | 0                 | 0                        | Not Give       | ▼      |
| One Time Key In       | Main         |         |                 | FAN MOTOR NO 2            | 1   | 538.30                  | 538.30         | 25.00  | 403.72          | Replace         | 0                 | 0                        | Not Give       | ▼      |
| One Time Key In       | Main         |         |                 | FAN SHROUD                | 1   | 244.50                  | 244.50         | 25.00  | 183.38          | Replace         | 0                 | 0                        | Not Give       | ▼      |
| One Time Key In       | Main         |         |                 | FAN SHROUD TOP            | 1   | 99.60                   | 99.60          | 25.00  | 74.70           | Replace         | 0                 | 0                        | Not Give       | ▼      |
| One Time Key In       | Main         |         |                 | BUMPER REAR               | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace         | 1                 | 343.95                   | Replace        | ▼ DEF  |
| One Time Key In       | Main         |         |                 | BUMPER CLIPS              | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace         | 10                | 12.08                    | Replace        | ▼ NEC  |
| One Time Key In       | Main         |         |                 | PIXEL STICKER             | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace         | 2                 | 120.00                   | Replace        | ▼ NIKL |
| One Time Key In       | Main         |         |                 | BUMPER REINFORCEMENT REAR | 1   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace         | 0                 | 0                        | Check          | ▼      |
| Total Spare Part Cost |              |         |                 |                           |     |                         |                |        | 16,165.82       |                 | Surveyor Total    | 2,538.57                 |                |        |
| Lump Sum Discount (%) |              |         |                 |                           |     |                         |                |        | 0.00            |                 | Lump Sum Dis (%)  | 20                       |                |        |
| Final Spare Part Cost |              |         |                 |                           |     |                         |                |        | 12,932.66       |                 | Final Sur Total   | 2,030.86                 |                |        |

## SMRT Recommendation

## Surveyor Approval

| BOM Type        | Costing Type | Portion | Material Number | Part Name                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace         |
|-----------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|------------------------|
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER LH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER RH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | ANTENNA, ELECTRICAL LOWER REAR | 1   | 157.40                  | 157.40         | 10.00  | 141.66          | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | SENSOR REVERSE                 | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace         | 1                 | 180.00                   | Replace <i>shorted</i> |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/LH     | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/RH     | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | BUMPER SEAL, RR LH             | 1   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | BUMPER SEAL, RR RH             | 1   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/LH         | 1   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/RH         | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | BUMPER LIP REAR                | 1   | 228.90                  | 228.90         | 25.00  | 171.68          | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | UNDER COVER CENTER REAR        | 1   | 514.50                  | 514.50         | 25.00  | 385.88          | Replace         | 0                 | 0                        | Not Give               |
| One Time Key In | Main         |         |                 | END PANEL                      | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace         | 0                 | 0                        | Check                  |
| One Time Key In | Main         |         |                 | SEALANT SIKAFLEX               | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace         | 0                 | 0                        | Not Give               |

Total Spare Part Cost

16,165.82

Surveyor Total

2,538.57

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

20

Final Spare Part Cost

12,932.66

Final Sur Total

2,030.86

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation             |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |       |
|-----------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|-------|
|                 |              |         |                 | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |       |
| One Time Key In | Main         |         |                 | END PANEL COVER, DECK TRIM HOLE | 1   | 46.10                   | 46.10          | 25.00  | 34.58           | Replace         | 0                 | 0                        | Not Give       | ▼     |
| One Time Key In | Main         |         |                 | END PANEL COVER, DECK TRIM, RR  | 1   | 121.10                  | 121.10         | 25.00  | 90.82           | Replace         | 0                 | 0                        | Not Give       | ▼     |
| One Time Key In | Main         |         |                 | REINFORCEMENT, RR               | 2   | 34.60                   | 69.20          | 25.00  | 51.90           | Replace         | 0                 | 0                        | Check          | ▼     |
| One Time Key In | Main         |         |                 | TAILGATE ASY                    | 1   | 1,007.90                | 1,007.90       | 25.00  | 755.92          | Replace         | 1                 | 0                        | Repair         | ▼     |
| One Time Key In | Main         |         |                 | NAME PLATE (HYBRID)             | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace         | 1                 | 38.92                    | Replace        | ▼ NEC |
| One Time Key In | Main         |         |                 | FENDER RR/LH                    | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace         | 1                 | 0                        | Repair         | ▼     |
| One Time Key In | Main         |         |                 | STICKER DECAL SMRT              | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 1                 | 7.80                     | Replace        | ▼ NEC |
| One Time Key In | Main         |         |                 | STICKER DECAL 6555 8888         | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 1                 | 21.60                    | Replace        | ▼ NEC |
| One Time Key In | Main         |         |                 | QUARTER GLASS RR/LH             | 1   | 168.10                  | 168.10         | 25.00  | 126.07          | Replace         | 0                 | 0                        | Not Give       | ▼     |
| One Time Key In | Main         |         |                 | SEALANT W/SCREEN                | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace         | 0                 | 0                        | Not Give       | ▼     |
| One Time Key In | Main         |         |                 | FENDER LINER RR/LH              | 1   | 141.30                  | 141.30         | 25.00  | 105.98          | Replace         | 0                 | 0                        | Not Give       | ▼     |
| One Time Key In | Main         |         |                 | TROUGH, BACK DOOR LH            | 1   | 110.90                  | 110.90         | 25.00  | 83.18           | Replace         | 0                 | 0                        | Check          | ▼     |
| One Time Key In | Main         |         |                 | TAIL LAMP BRACKET, LH           | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace         | 0                 | 0                        | Check          | ▼     |
| One Time Key In | Main         |         |                 | TAIL LAMP BRACKET, RH           | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace         | 0                 | 0                        | Check          | ▼     |

Total Spare Part Cost 16,165.82

Surveyor Total 2,538.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

Final Spare Part Cost 12,932.86

Final Sur Total 2,030.86

## SMRT Recommendation

## Surveyor Approval

| BOM Type              | Costing Type | Portion | Material Number | Part Name                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |
|-----------------------|--------------|---------|-----------------|-----------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|
| One Time Key In       | Main         |         |                 | DUCT ASSY, QUARTER          | 1   | 70.40                   | 70.40          | 25.00  | 52.80           | Replace         | 0                 | 0                        | Check *        |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR LOCK          | 1   | 444.10                  | 444.10         | 25.00  | 333.08          | Replace         | 0                 | 0                        | Not Give *     |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR WEATHER STRIP | 1   | 353.40                  | 353.40         | 25.00  | 265.05          | Replace         | 0                 | 0                        | Check *        |
| Total Spare Part Cost |              |         |                 |                             |     |                         |                |        | 16,165.82       |                 | Surveyor Total    | 2,538.57                 |                |
| Lump Sum Discount (%) |              |         |                 |                             |     |                         |                |        | 0.00            |                 | Lump Sum Dis (%)  | 20                       |                |
| Final Spare Part Cost |              |         |                 |                             |     |                         |                |        | 12,932.66       |                 | Final Sur Total   | 2,030.86                 |                |

## Labour's Cost Detail

| S.No.  | Job Scope               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|-------------------------|-------------------------|-------------------------|---------|
| 1      | TO REPAIR FRONT PORTION | 845.00                  | 200                     |         |
| 2      | TO REPAIR REAR PORTION  | 1,014.00                | 600                     |         |
| Total: |                         | 1,859.00                | 800.00                  |         |

## Spray Cost Detail

| S.No.  | Job Scope                            | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------------------------------|-------------------------|-------------------------|---------|
| 1      | TO REPSRAY FRONT BUMPER              | 378.00                  | 200                     |         |
| 2      | TO RESPRAY FRONT BUMPER LOWER GRILLE | 180.00                  | 0                       |         |
| 3      | TO REPSRAY FRONT HOOD                | 378.00                  | 0                       |         |
| 4      | TO RESPRAY FRONT SUPPORT PANEL       | 180.00                  | 0                       |         |
| 5      | TO REPSRAY REAR BUMPER               | 378.00                  | 200                     |         |
| 6      | TO RESPRAY BUMPER BEAM               | 180.00                  | 0                       |         |
| 7      | TO RESPRAY REAR PANEL                | 180.00                  | 0                       |         |
| 8      | TO RESPRAY TAIL GATE                 | 378.00                  | 200                     |         |
| Total: |                                      | 2,790.00                | 800.00                  |         |



| S.No.         | Job Scope                      | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------------------------|-------------------------|-------------------------|---------|
| 9             | TO RESPRAY REAR FENDER LH      | 378.00                  | 200                     |         |
| 10            | TO RESPRAY TROUGH BACK DOOR LH | 180.00                  | 0                       |         |
| <b>Total:</b> |                                | <b>2,790.00</b>         | <b>800.00</b>           |         |

**Other Cost Detail**

| S.No.         | Job Scope                                                                       | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|---------------------------------------------------------------------------------|-------------------------|-------------------------|---------|
| 1             | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                               | 125.00                  | 125.00                  |         |
| 2             | TO CHECK WIRING AND SYSTEM FUNCTION                                             | 80.00                   | 20                      |         |
| 3             | TO CONDUCT RADIATOR PRESSURE CHECK                                              | 120.00                  | 0                       |         |
| 4             | TO TOP UP A/C GAS                                                               | 120.00                  | 0                       |         |
| 5             | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | 120.00                  | 0                       |         |
| 6             | TO TEST AND REFIX REVERSE SENSOR SYSTEM                                         | 120.00                  | 30                      |         |
| 7             | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE         | 120.00                  | 0                       |         |
| 8             | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.            | 120.00                  | 40                      |         |
| 9             | TO WASH AND VACUUM                                                              | 60.00                   | 0                       |         |
| 10            | TO REPLACE SUNDRY PARTS                                                         | 100.00                  | 0                       |         |
| <b>Total:</b> |                                                                                 | <b>1,085.00</b>         | <b>215.00</b>           |         |

**Summary**

|                         | Estimator Assessment(\$) | Surveyor Assessment(\$) |
|-------------------------|--------------------------|-------------------------|
| Total Spare Part Detail | 12,932.66                | 2,030.86                |
| Total Labour Cost       | 1,859.00                 | 800.00                  |
| Total Spray Painting    | 2,790.00                 | 800.00                  |
| Other                   | 1,085.00                 | 215.00                  |
| Overall Total           | 18,666.66                | 3,845.86                |
| Lump Sum Repair Option  |                          |                         |

## Estimator Assessment(\$)

## Surveyor Assessment(\$)

Lump Sum Total

18,650.00

3,850.00

Surveyor Approved Amount

3,850.00

No of Repair Days\*

12

5

Remarks

L/S repair, photo after paint.

Surveyor Name

Hwee Jie

Signature



Save

Clear

Survey Date

18/01/2019

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ◀ Service Request Details

Claim

S9M01ARK

Reference

None ✎

Loss Date

January 16, 2019

Request Date

January 18, 2019

Hwa Jie

Due Date

January 25, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SHC4727A

Make

TPVD TOYOTA