

ASS. REC. BY:

REF:

es/smo19001160/ Ut d302

Special Instruction:

Surveyor

Maimen

Maimen

ASSIGNMENT (Office)

From (Person)

Chan shu hui agnes

of

SMO

Date/Time:

18/1/19 @ 1.45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6707K

Insured:

GBB 9088D

at Workshop m/s

Kai Liang Motor

Tel:

67474189

of

Blk 1, Kaki Bukit Ave 6 # 01-101

Policy No:

D18MTPCVE003322

Claim No:

CMTD1900422

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/01/2019

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

2.22pm @ 18/1/19

Person Contacted:

Mr. Liang

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
18/1/19-	Repairer (Mr. Liang) arrange survey on 21/01/19 as he wants Maimen to survey.
	GBD 6707K - x
	GBB 9088D - x
28/1-	Report pending estimate from repairer

Marcus

REF: 8MD

ASSIGNMENT

From: Date: 21/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 6707K
at Workshop m/s Kai Liang Motor
of 1 Kaki Bukit Ave 6 #01-101

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

40

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

33986

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: G3D6707K Yr Regn: 215

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make: Toyota Dyna C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp Reading: 118470 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDY2318018344

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/12R15

R: 15-5-12R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1850

Front

Rear

R/Bal: 6 mm

R/Bal: 0.6 mm

L/Bal: 6 mm

L/Bal: 0.6 mm

D.O.A.

D.O.I.

21/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21A15243 andy return

21/2/19 4/5 4000 confirmed with Kai Liang - Cred: 5153.50, 56%

RECEIVED 22 FEB 2019

Date/Time, File Pass to?

1) 21/2 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.V. (\$)

TP

4000

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

250

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019		18 Jan 2019 13:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	KEE BENG FILTERS (S) PTE LTD, Co. Reg. No.: 199508356E			[Created by insurer]
Main Claimant:	LEONG FAT CONSTRUCTION PTE LTD, Co. Reg. No.: 198903398E			
Vehicle Reg. No.:	GBD6707K	Date of Loss:	16/01/2019 17:00 - :59	
Claim Type:	TP / CMTD1900422	Policy/Cover Note No.:	D18MTPCVE003322 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBB9088D	Policy No. (Claimant):		
		Excess:		
Repairer:	Kai Liang Motor Service - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY, 417883 Kaki Bukit - Tel: 67474189			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2019]			
Driver/Custodian (Insured):	PEH HOCK KEE (), NRIC: S1426457D, Tel: +6596890097			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2019 10:46
Date Of Accident	16/01/2019 17:20
Exact Location Of Accident	AT WEST COAST HIGHWAY TOWARDS TAMPINES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD6707K
Insured/Policyholder	
Name Of Registered Owner	LEONG FAT CONSTRUCTION PTE LTD
Co Reg No	198903398E
Email Address	FELICITYENGRG.CONTRACTS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-86430208
Alternative Phone No	OFFICE-65430281

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA-3.0 D TURBO M/T 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-000600
Cover Note Number	26/02/2018 - 25/02/2019

Driver

Name of Driver	BELAL MD SHAHABUDDIN
Passport No/FIN	G8274094K
Date Of Birth	20/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	02/11/2016
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86430208
Fax Number	
Contact Number	OFFICE-65430281
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured -
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : AMIN MOHAMMAD AL
 GENDER: : MALE
 Passenger 2 NAME: : RABBANI MOHAMMAD GOLAM
 GENDER: : MALE
 Passenger 3 NAME: : DALI MD RUBAEL
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB9088D
 Vehicle Make/Model/Colour NA
 Details Of Properties NA
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver PEH HOCK KEE
 NRIC/Passport Number S1426457D
 Contact Number 96890097

Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

A: GBD 6707K
B: GBB 9088D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/01/2019 at 5:20pm I was driving on the West Coast Highway towards Tampines.
At the traffic light junction, the traffic light turned red and a few cars in front already stopped.
So I stopped my vehicle for a while, but vehicle B came from behind and hit into the rear of
my vehicle.

DECLARATION

I HEREBY DECLARE that:

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.

IND. SHAKHBUDDIN BELM

Name, Signature & Company
Stamp (if applicable)

<input checked="" type="checkbox"/>	Third Party Claim
<input type="checkbox"/>	Own Damage Claim
<input type="checkbox"/>	Reporting Time
<input type="checkbox"/>	Date of Accident
<input type="checkbox"/>	Police No.
<input type="checkbox"/>	Police Station

LEONG FAT CONSTRUCTION PTE LTD

DECLARATION

NO. 35 ABINGDON ROAD

(We declare the foregoing particulars are true in every respect.)

SINGAPORE 499941

TEL: 65430281 FAX: 65430520

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3398E
Vehicle Details	
Vehicle No.:	GBD6707K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2472350
Chassis No.:	KDY2318018344
Maximum Power Output:	-
Open Market Value:	\$30,371.00
Original Registration Date:	26 Feb 2015
First Registration Date:	26 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$1,519.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,844.00
COE Rebate Amount:	\$15,143.00
Total Rebate Amount:	\$15,143.00

The information contained herein is correct as at 21 Jan 2019

OK

New Car's

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Jun 2018 Opel Grandland X 1.2A Turbo @ \$109,800 Only



In House Financing Available!
Low Downpayment Available!
Price Nego! Call Now!
[Speedo Motoring](#) [StarAd](#)

HIN LUNG A
HoBee Group
One Stop Ca
Finance, Insurance
New and Used Car

[Browse by Category](#)
[Sort by Date Posted](#)

8 vehicles

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

Search Selection

toyota dyna

Any

Any

2015

Any

Any



Toyota Dyna 150

\$44,800

\$7,170 /yr

20-Apr-2015

2,982 cc

91,000 km

Fuel Type: Diesel

The Most Reliable And Popular Lorry For Your Commercial Needs. Engine, Gearbox & Interior In Perfect Condition. Low Diesel Consumpt Maintenance. Only 1 Owner With Low Mileage Clocked. Flexible Lo...

Tan Wei Auto Pte Ltd

Posted: 20-Jan-2019

Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150

\$47,800

\$7,160 /yr

23-Sep-2015

2,982 cc

-

Fuel Type: Diesel

One Of The Best Selling And Reliable 10ft Lorry In Town. 1 Careful Owner. Servicing Done, Wear And Tear Replaced. No Repairs Needed Loan/High Trade Available. Call Us For Appointment To View The...

ABWIN (1994) Pte Ltd

Posted: 18-Jan-2019

Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150

\$48,800

\$7,300 /yr

28-Sep-2015

2,982 cc

46,407 km

Fuel Type: Diesel

1 Owner! Low Mileage Of 46,407km Clocked! Under Utilised Lorry! Comes With Full Canopy & Chequered Plate. Stock Condition. Original Many Freebies To Go For This Unit. Please Call Now To Vie...

Car (S) Pte Ltd

Posted: 17-Jan-2019

Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150

\$49,800

\$7,270 /yr

27-Nov-2015

2,982 cc

-

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 15-Jan-2019

Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Kaizen Autowerke Pte Ltd - Repair & Servicing

Kaizen Autowerke Pte Ltd is a collaborative of automotive professionals with more than 6 decades worth of combined experience in the industry.

[More info about this shop](#)

[Compare](#)

toyota Dyna 150

\$45,800

\$7,300 /yr

30-Apr-2015

2,982 cc

-

Fuel Type: Diesel

KAI LIANG MOTOR SERVICE
BLK1 KAKI BUKIT AVE 6
#01-101 AUTOBAY
SINGAPORE 417883

VEHICLE NO:GBD 6707K

QTY	PARTICULAR
1 PCS	TAILGATE
1 PCS	TAILGATE LOWER MEMBER
2 PCS	TAILGATE LOCK LATCHES @\$169.10
2 PCS	TAILGATE LOWER 'L' PANELS @\$101.50
2 PCS	TAILGATE BRACKETS @\$241.1
2 PCS	TAILGATE BRACKETS @\$109.10
1 PCS	REAR SPARE TYRE BRACKET & CHAIN
1 PCS	REAR EXHAUST
1 PCS	DROPSIDE GATE LOWER MEMBER O/S

	S.NETT
1 PCS	REAR LICENCE PLATE
1 SET	REAR REVERSE SENSOR
1 SET	REAR BUMPER
1 PCS	TAILGATE REFLECTOR STICKER
1 PCS	TAILGATE '70 KM/H' STICKER
1 PCS	TAILGATE '13PAX' STICKER

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REFIX REAR EXHAUST
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

10/201	\$1,455.10	—
3rd	\$545.10	—
3rd	\$338.20	—
3rd	\$203.00	—
one	\$482.20	—
one	\$218.20	x
one	\$366.50	x
2	\$677.10	x
2	\$878.10	x
	\$5,163.50	

one	\$20.00	14
slab	\$280.00	200
set	\$850.00	800
11	\$80.00	x
one	\$20.00	10
one	\$20.00	10

	\$80.00	20
	\$80.00	50
11	\$80.00	x
	\$80.00	60
	\$1,200.00	800
	\$1,200.00	800
TO	\$9,153.50	

When the repairer is notified of the following:

- To ensure the vehicle is properly painted
- To ensure the vehicle is properly repaired
- To ensure the vehicle is properly inspected
- To ensure the vehicle is properly approved
- To ensure the vehicle is properly documented
- To ensure the vehicle is properly insured
- To ensure the vehicle is properly maintained
- To ensure the vehicle is properly stored
- To ensure the vehicle is properly transported
- To ensure the vehicle is properly disposed of

Acknowledged by Repairer:

Signature:

Date:

9-3023-6
252
2267-70
5031-7
4024-76

...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2019		18 Jan 2019 13:45 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KEE BENG FILTERS (S) PTE LTD , Co. Reg. No.: 199508356E								
Main Claimant:	LEONG FAT CONSTRUCTION PTE LTD , Co. Reg. No.: 198903398E								
Vehicle Reg. No.:	GBD6707K	Date of Loss:	16/01/2019 17:00 - :59 [46 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1900422	Policy/Cover Note No.:	D18MTPCVE003322 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBB9088D	Policy No. (Claimant):							
		Excess:							
Repairer:	Kai Liang Motor Service - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY, 417883 Kaki Bukit - Tel: 67474189								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/01/2019]								
Driver/Custodian (Insured):	PEH HOCK KEE (), NRIC: S1426457D, Tel: +6596890097 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD6707K (CMTD1900422)
[GBB9088D]
TP
LEONG FAT CONSTRUCTION PTE LTD
Jan 16 2019 5:00PM
[KEE BENG FILTERS (S) PTE LTD]
Kai Liang Motor Service - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
2	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
3	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
4	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
5	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
6	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
7	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
8	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
9	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
10	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
11	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
12	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
13	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
14	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
15	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
16	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
17	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
18	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
19	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
20	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
21	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
22	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
23	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
24	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
25	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
26	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
27	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
28	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
29	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
30	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
31	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
32	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
33	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
34	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
35	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
36	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>
37	22/02/19 10:48	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
57	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
58	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
59	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
60	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
61	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
62	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
63	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
64	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
65	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
66	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
67	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
68	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
69	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
70	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
71	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
72	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
73	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
74	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
75	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
76	22/02/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
77	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	22/02/19 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/19 18:07	Pre-Repair Survey+SAS		Load PDF
2	18/01/19 13:40	Pre-Repair Survey - AGREED LKK		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19001160/UTD3E2

Date: 22/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE003322
Claimant Vehicle No :	GBD6707K	Insured Vehicle No :	GBB9088D
Date of Loss:	16/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900422

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6707K		
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Engine No:	1KD2472350
Reg. Date:	26/02/2015 (Man. Year: 2014)	Chassis No:	KDY2318018344
Colour:	White	Odometer:	118470 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	LEAO 6 mm	Rear Left Side:	LEAO 6/6 mm
Front Right Side:	LEAO 6 mm	Rear Right Side:	LEAO 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,433.50	3,301.70	3,131.80	48.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,730.00	990.00	36.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,153.50	5,031.70	4,121.80	45.03
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	9,153.50	4,000.00	5,153.50	56.30

INSPECTION

Date of Assignment:	18/01/2019	
Date Inspected:	21/01/2019 Inspected At:	Kai Liang Motor Service - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Feb 2019)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD6707K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,455.10 F	*1,455.10 FL
2	1		*TAILGATE LOWER MEMBER	Bent	545.10 F	*545.10 FL
3	2		*TAILGATE LOCK LATCHS	Bent	338.20 F	*338.20 FL
4	2		*TAILGATE LOCK L PANELS	Bent	203.00 F	*203.00 FL
5	2		*TAILLAMP	Cracked	482.20 F	*482.20 FL
6	2		*TAILLAMP BRACKETS	Repair	218.20 F	*- FL
7	1		*REAR SPARE TYRE BRACKET & CHAIN	Serviceable	366.50 F	*- FL
8	1		*REAR EXHAUST	Repair	677.10 F	*- FL
9	1		*DROPSIDE GATE LOWER MEMBER O/S	Repair	878.10 F	*- FL
10	1		*REAR LICENCE PLATE	Cracked	20.00 FS	*14.00 FS
11	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
12	1		*SET REAR BUMPER	Bent	850.00 FS	*800.00 FS
13	1		*TAILGATE REFLECTOR STICKER	Not Necessary	80.00 FS	*- FS
14	1		*TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
15	1		*TAILGATE 13PAX STICKER	Necessary	20.00 FS	*10.00 FS
Sub Total (\$\$)					6,433.50	4,057.60
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	755.90
Total Parts (\$\$)					6,433.50	3,301.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	0.00
4	TO SPRAY RUST-PROOFING	New	80.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,200.00	800.00
6	TO PUTTY & SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,720.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >