

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05909

Vehicle Insured : SKV8914P
Accident Date : 14-Jan-2019

Date : 17-Jan-2019

Our Ref : 219009 (AXA) / CHAN

PAGE : 1

TRIO DZIGN CONSTRUCTION PTE LTD
7 TOA PAYOH INDUSTRIAL PARK
#01-1259
Singapore 319059

Not Authorised
El Long & ?
Resurvey After Paint
6 days

ESTIMATED COST OF REPAIR FOR HONDA CIVIC 1.8L SDQ1868U
=====

1 pc Boot lid
1 pc Boot lid inner lock
1 pc Boot lid rubber
1 pc Boot lid logo
1 pc Rear bumper fascia
2 pcs Rear bumper bracket
2 pcs Rear bumper side retainer
4 pcs Rear bumper clip
1 pc End panel
1 pc End panel top garnish
1 pc Rear spare tyre panel
1 pc Rear spare tyre board
1 pc Spare tyre panel lower member

	Bu	650.70	✓
	Re	85.10	✓
	Adm	97.60	50%
	Re	25.70	✓
	Bu	688.00	✓
@ S\$ 13.90	Re	27.80	X
@ S\$ 14.60	Adm	29.20	X
@ S\$ 3.90	Re	15.60	✓
	Bu	380.50	✓
	Re	86.10	✓
	Re	992.20	X
	cmf	175.00	✓
	Re	229.70	X
		3,483.20	
Less 20% :		696.64	

1 pc Rear bumper reverse sensor(set
1 pc Rear no.plate with box

2,786.56 200%
Re 300.00 sn
Sn 50.00 sn X

To apply undersealing

80.00 60%

To remove and refix exhaust
silencer box

60.00 ✓

To putty and spray replaced parts

1,000.00 80%

Date: _____
Signature: _____
Acknowledged by Repairer _____
The Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
Subject to final approval from Insurance Company

Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKV8914P

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

8001
1,200.00

Total : S\$ 5,476.56
=====

Singapore Dollars Five Thousand Four Hundred
and Seventy Six and Cents Fifty Six Only