

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05909

Vehicle Insured : SKV8914P
Accident Date : 14-Jan-2019

Date : 17-Jan-2019

Our Ref : 219009 (AXA) / CHAN

PAGE : 1

TRIO DZIGN CONSTRUCTION PTE LTD
7 TOA PAYOH INDUSTRIAL PARK
#01-1259
Singapore 319059

*Not Authorized
C/Ling @ ?*

Resuming After Paint

6dat

ESTIMATED COST OF REPAIR FOR HONDA CIVIC 1.8L SDQ1868U

- 1 pc Boot lid
- 1 pc Boot lid inner lock
- 1 pc Boot lid rubber
- 1 pc Boot lid logo
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper bracket
- 2 pcs Rear bumper side retainer
- 4 pcs Rear bumper clip
- 1 pc End panel
- 1 pc End panel top garnish
- 1 pc Rear spare tyre panel
- 1 pc Rear spare tyre board
- 1 pc Spare tyre panel lower member

	Ru	650.70	✓
	M	85.10	✓
	Del 17/1	97.60	<i>50/100 68.80 SN</i>
	M	25.70	✓
	Bu	688.00	✓
	R	27.80	✓
@ S\$ 13.90	10/1	29.20	✓
@ S\$ 14.60	M	15.60	✓
@ S\$ 3.90	Bu	380.50	✓
	M	86.10	✓
	R	992.20	X
	CM	175.00	✓
	R	229.70	X

3,483.20
Less 20% : 696.64

*2121.30
424.26
1697.04
2,786.56 2001m
Ret 300.00 sn
Sn 50.00 sn X*

- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear no.plate with box

To apply undersealing

80.00 601

To remove and refix exhaust
silencer box

60.00 ✓

To putty and spray replaced parts

1,000.00 800

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKV8914P

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800/

1,200.00

Total : S\$ 5,476.56

=====

Singapore Dollars Five Thousand Four Hundred
and Seventy Six and Cents Fifty Six Only

4/Sum
2900 ✓ ok
↑
Kennard pls confirm
TKS.

P 1697.04
SN 248.80
L 1720.00

3665.84
733.17

2932.67