



FINAL REPORT

Estimate No. : **b1 49671**
Date Estimated : **08/01/2019**
Prepared By : **Joseph Yaguel**

Page No. :

REPAIR FOR -
Kemral Durgadas Shetty
2B HONG SAN WALK
#12-02

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

SINGAPORE 689048

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEASE
SFM7739S	NS37629	30/07/2014	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00
To spray paint rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED BASIS	1,172.30	1.00		1,172.30
# REAR PDC HOLDER SET *	24.60	1.00		24.60
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,249.95
Total Labour & Parts :	3,263.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,263.95
GST @7%:	228.48
Grand Total :	3,492.43