

ASS. REC. BY

REF

03/CTI19001167/TVd3m

Special Instruction

Surveyor

## ASSIGNMENT (Office)

From (Person) Chong Boon Sen

of

CTI

Date/Time 17/1/19 @ 5:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFM 7739S

Insured:

GBF3307R

at Workshop m/s

performance

Tel:

of

303 Alexandra Road

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/1/19

CA / REV / REP. / REV 24 HRS <sup>up</sup>

H.O.D. Endorsement:

Date/Time: 9:44am 08/1/19

Person Contacted:

caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFM 7739S - CS / GAT 18069486 / R / vb02
	GBF 3307R - X
20/2/19	Final fig \$ 3363.95 confirmed by email (Ref 1656.15, 349)
20/2/19	No claim number.

Dm: 22/5/2018

Signature

Taylor

REF:

CTL

# ASSIGNMENT

From:

Date:

28/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SFM 77395

at Workshop m/s

Performance

of

305 Alexandra Rd

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Yaguel

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SFM 77395

Yr Regn

2014 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 316i

C.C

1598

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

80195

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

WNS193A16040NS37629

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

^ ^

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal

6

mm

L/Bal.

6

mm

L/Bal

6

mm

D.O.A.

D.O.I.

28/1/17ellan

Survey held at

PHH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

job- typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

)

TOTAL

Report Format :

merimen

Lump Sum / I.B.I: (\$

3263.95

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

220

## Veron Chen (LKKAUTO)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 19 February 2019 3:25 PM  
**To:** Veron Chen (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: sfm7739s and gbf3307r on 7.1.19

Dear Veron,

Merimen created.

No claim number as of now.

Thank you.

Regards,

**Chong Boon Sen**

Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 19 February, 2019 2:40 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: sfm7739s and gbf3307r on 7.1.19

Dear Boon Sen,

Kindly create claim in merimen and provide us claim number.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 18 January 2019 2:41 PM  
**To:** 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: sfm7739s and gbf3307r on 7.1.19

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 17 January 2019 5:35 PM  
**To:** PBSP <pml-pbsp@sirmedarby.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: sfm7739s and gbf3307r on 7.1.19

Dear Caroline,

We will proceed.

Dear LKK,

Kindly pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Thursday, 17 January, 2019 5:29 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: sfm7739s and gbf3307r on 7.1.19

Dear Sirs

We are agreeable to use the following surveyor as the SJE.

XING QUO QIANG

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 15 January 2019 5:37:21 PM  
**To:** PBSP  
**Subject:** sfm7739s and gbf3307r on 7.1.19

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.  
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.  
Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



---

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Thursday, 17 January 2019 5:38 PM  
**To:** assignments  
**Subject:** FW: sfm7739s and gbf3307r on 7.1.19

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 17 January 2019 5:35 PM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: sfm7739s and gbf3307r on 7.1.19

Dear Caroline,

We will proceed.

Dear LKK,

Kindly pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** PBSP [mailto:[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)]  
**Sent:** Thursday, 17 January, 2019 5:29 PM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Subject:** Re: sfm7739s and gbf3307r on 7.1.19

Dear Sirs

We are agreeable to use the following surveyor as the SJE.

XING QUO QIANG

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Tuesday, 15 January 2019 5:37:21 PM

**To:** PBSP

**Subject:** sfm7739s and gbf3307r on 7.1.19

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,  
**Chong Boon Sen**



Claims Executive  
Claims.

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/01/2019 11:22
Date Of Accident	07/01/2019 07:45
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFM7739S
Insured/Policyholder	
Name Of Registered Owner	KEMRAL DURGADAS SHETTY
NRIC No	S2665119J
Email Address	SHETTYKD@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98317802
Alternative Phone No	OTHERS-98317802
Vehicle Particulars	
Manufacturer	BMW
Model	316
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1427011804
Cover Note Number	
Driver	
Name of Driver	KEMRAL DURGADAS SHETTY
NRIC No	S2665119J
Date Of Birth	01/05/1966
Occupation	INDOOR
Date Of Driving Pass	30/01/2004
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98317802
Fax Number	
Contact Number	OTHERS-98317802
Email Address	SHETTYKD@YAHOO.COM

Address	2B HONG SAN WALK #12-02
Postcode	689048
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3307R
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	THYE TICK ANN
NRIC/Passport Number	G2545691U
Contact Number	83428907 (DRIVER)
Address	91699786 (OWNER)
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1


**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 8/1/2019

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am travelling to office through Upper Bukit Timah Road passing through Rail mall. The road condition was dry & had heavy traffic. My car was stationary in the traffic suddenly the Van behind my vehicle hit my rear bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 8/1/2019

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 JAN 2019

## ESTIMATE

Estimate No. : b1 49671	Page No. : 1 of 4
Date Estimated : 08/01/2019	
Prepared By : Joseph Yaguel	

<b>- ESTIMATE REPAIR FOR -</b> Kemral Durgadas Shetty Blk 305 Bukit Batok Street 31 #08-89 Singapore 650305	<b>- ACCOUNT - 135</b> China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909
---	--

REGN. NO. SFM7739S	CHASSIS NO. NS37629	REGN. DATE 30/07/2014	MODEL 3161A/4	MILEAGE 0
--------------------	---------------------	-----------------------	---------------	-----------

### DESCRIPTION

Replacing rear bumper panel and attachments

Spray rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries

- LKR Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
  - No display damaged part(s) during resurvey
  - Prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### VALUE

1,770.00

1,038.00

177.00

80.00

Total Labour 1: 3,065.00

### DESCRIPTION

REAR BUMPER CARRIER (ECE)  
 REAR BUMPER PANEL PRIMED BASIS  
 REAR BUMPER LH SIDE GUIDE  
 REAR BUMPER RH SIDE GUIDE  
 DECOUPLING RING PDC TORQUE CONVERTE

### QTY PRIC

1 467.95  
 1 1,172.30  
 1 58.50  
 1 58.50  
 4 5.05

### VALUE

467.95  
 1,172.30  
 58.50  
 58.50  
 20.20

Total Parts : 1,777.45

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 28/1/19 P.M. Excess S\$ \_\_\_\_\_

Surveyor's Name Tanjhir Sign \_\_\_\_\_

Surveyor's Tel 97495249 Authorised Yes / No \_\_\_\_\_

Authorised Person \_\_\_\_\_

4920.10

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjhir@pharbit.com

No. of Working Days Recommend 03 days

205/50R11

Conti



Labour 1	:	3,065.00
Parts	:	1,777.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	338.97
Grand Total	:	5,181.42

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 49671  
Date Estimated : 08/01/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Kemral Durgadas Shetty  
2B HONG SAN WALK  
#12-02

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

SINGAPORE 689048

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED BASIS	1,172.30	1.00		1,172.30
# REAR PDC HOLDER SET *	24.60	1.00		24.60
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,249.95
Total Labour & Parts :	3,263.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,263.95
GST @7%:	228.48
Grand Total :	3,492.43

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 49671  
Date Estimated : 08/01/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Kemral Durgadas Shetty  
2B HONG SAN WALK  
#12-02

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

SINGAPORE 689048

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR PDC HOLDER SET * <i>nil</i>	24.60	1.00		24.60
# (DG/SL) ADHESIVE SET K6 * <i>nil</i>	53.05	1.00		53.05

Total Labour :	
Total Parts :	77.65
Total Labour & Parts :	77.65



## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 20 February 2019 10:01 AM  
**To:** 'PBSP'; Taufikh (LKKAUTO); SUR  
**Subject:** RE: FINAL REPORT / SFM7739S

Dear Caroline,

WITHOUT PREJUDICE

Confirmed final amount \$3,263.95 before GST

Repair days: 3 days

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 15 February 2019 6:33 PM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SFM7739S

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,249.95

Total Labour & Parts : 3,263.95

Repair days: 3

Thank you.

Regards,  
Caroline

C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2019 16:12		19 Feb 2019 15:22 <a href="#">Edit Adj Rpt</a>	<b>\$3,263.95</b> <a href="#">Edit Estimates</a>	<b>\$3,263.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>KEMRAL DURGADAS SHETTY</b> , ID: S2665119J								
Vehicle Reg. No.:	<b>SFM7739S</b>	Date of Loss:	07/01/2019 07:00 - :59 [53 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>GBF3307R</b>	Policy No. (Claimant):	DMPCSN1427011804						
		Excess:	S\$0.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 28/02/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFM7739S  
[GBF3307R]  
TP  
KEMRAL DURGADAS SHETTY  
Jan 7 2019 7:00AM  
[-]  
Performance Motors Limited

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:30	Accident Statement	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	08/01/19 11:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 10:53	General View	Load PDF	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/02/19 15:24	REPAIR ESTIMATE	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:28	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 16:23	Supplementary	Load PDF	

## Linked Accident Report Documents

			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:30	Accident Statement	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
2	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	08/01/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	08/01/19 11:28	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001167/T1VD3E2

Date: 20/02/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle  
No : SFM7739S

Insured Vehicle No : GBF3307R

Date of Loss: 07/01/2019

Nature of Claim: TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SFM7739S</b>	Engine No:	B016J723N13B16A
Make & Model:	BMW 316I, 1.6 F30 (A)	Chassis No:	WBA3A16040NS37629
Reg. Date:	30/07/2014 (Man. Year: 2014)	Odometer:	80195 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,935.10	1,329.95	605.15	31.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,985.00	1,934.00	1,051.00	35.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,920.10</b>	<b>3,263.95</b>	<b>1,656.15</b>	<b>33.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>344.41</b>	<b>228.48</b>	<b>115.93</b>	<b>33.66</b>
<b>Nett Amount (S\$)</b>	<b>5,264.51</b>	<b>3,492.43</b>	<b>1,772.08</b>	<b>33.66</b>

## INSPECTION

Date of Assignment: 19/02/2019

Date Inspected: 28/01/2019 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2019)
<b>Parts:</b> 143	BMW 316I 1.6 F30 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFM7739S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER (ECE)	Not Necessary	467.95 FS	*- FS
3	1		*REAR BUMPER PANEL PRIMED BASIS	Deformed	1,172.30 FS	*1,172.30 FS
4	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	58.50 FS	*- FS
5	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	58.50 FS	*- FS
6	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
7	1		*SET REAR PDC HOLDER	Necessary	24.60 FS	*24.60 FS
8	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
					<b>Total Parts (S\$)</b>	<b>1,935.10      1,329.95</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS	New	1,770.00	850.00
2	SPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			<b>2,985.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >