



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 16/01/2019

Attn: The Motor Claims Department

Your Insured veh no: GBD 4385 T

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

WITHOUT PREJUDICE

(By Email Only)

Steve.

68299199

Xiao Tony.

Dear Sir / Madam

Estimate Cost repair Bill To Subaru SLS 8084 M & GBD 4385 T on 15/01/2019 @08:00:00

To Supply :-

1pc	Front bonnet <i>dent</i>	\$ 882.00	nett ✓
1pc	Front bonnet moulding <i>hit</i>	\$ 160.00	nett ✓
1pc	Front bonnet lock <i>new</i>	\$ 60.00	nett ✓
1pc	Front bonnet hinge <i>new</i>	\$ 48.00	nett ✓
1pc	Front bonnet S/A <i>new</i>	\$ 105.00	nett ✓
1pc	Front bonnet cable <i>new</i>	\$ 50.40	nett ✓
1pc	Front bonnet side gransih <i>new</i>	\$ 24.40	nett ✓
5pcs	Front bonnet stopper <i>new</i>	\$ 30.00	nett ✓
1pc	Front bonnet striker	\$ 40.00	nett ✓
1pc	Front grille lower <i>new cracked</i>	\$ 316.80	nett ✓
1pc	Front grille moulding cte <i>new</i>	\$ 180.00	nett ✓
1pc	Front fender LH <i>Bent</i>	\$ 300.00	nett ✓
1pc	Front fender cowling <i>new</i>	\$ 86.00	nett ✓
1pc	Front Head lamp LH <i>cracked</i>	\$ 2,400.00	nett ✓
1pc	Front head lamp lower bracket LH <i>Bent</i>	\$ 45.00	nett ✓
1pc	Front bumper <i>new</i>	\$ 600.00	nett ✓
1pc	Front bumper rin <i>new</i>	\$ 850.00	nett ✓
1pc	Front bumper SD bracket <i>new</i>	\$ 24.00	nett ✓
1pc	Front bumper spong <i>new</i>	\$ 136.00	nett ✓
1pc	Front bumper reformant <i>new</i>	\$ 288.00	nett ✓
1pc	Front tow cap <i>new</i>	\$ 14.00	nett ✓
1pc	Front fox lamp <i>new</i>	\$ 272.00	nett ✓
1pc	Front fox lamp rubber <i>new</i>	\$ 85.00	nett ✓
10pcs	Front bumper <i>chips</i>	\$ 41.00	nett ✓
1pc	Front noz cover <i>new</i>	\$ 55.00	nett ✓
1pc	Front nozzle washer <i>new</i>	\$ 88.00	nett ✓

5324.80

4259.84

Less

10%

\$7,180.60

\$ 718.06

\$6,462.54

30%



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 16/01/2019

Attn: The Motor Claims Department

Your Insured veh no: GBD 4385 T

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Page .2

Estimate Cost repair Bill To Subaru SLS 8084 M & GBD 4385 T on 15/01/2019 @08:00:00

To Supply :-

\$6,462.54

To dismanlte & replace damage parts,panel beat where necessaey \$ ~~900.00~~ 600

To putty,apply primer & spray paint on the affecte portion.

\$1,200.00 ~~800~~

1430

To check wiring functions.

\$ ~~80.00~~ 30

To wheel alignment

\$ ~~100.00~~ X.
\$8,742.54

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Adrian Ling

18/01/19

P/P 06 Days.

total 5689.84 (P/P)

5689.84