

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : CHINA TAIPING
ATTENTION : MOTOR CLAIMS DEPT
ESTIMATE REPORT :
DATE : 17-Jan-19
JOB TYPE : T/P CLAIM

VEHICLE DETAILS

VEHICLE NO : SJT2778C
MODEL : CHEVROLET CRUZE 1.6
CHASSIS NO

ACCIDENT DETAILS
DATE : 16-Jan-19
TIME : 11:55HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 833.50	\$ 833.50
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 72.50	\$ 72.50
3	FRONT FENDER LH <i>Replaced</i>	1	\$ 533.50	\$ 533.50
4	FRONT FENDER SIGNAL LAMP LH <i>changed</i>	1	\$ 60.20	\$ 60.20
5	FRONT FENDER INNER COWLING LH <i>Replaced</i>	1	\$ 170.20	\$ 170.20
6	FRONT SIDE MIRROR ASSEMBLY LH <i>Miss. y.</i>	1	\$ 455.30	\$ 455.30
7	FRONT SIDE MIRROR COVER LH <i>changed</i>	1	\$ 90.50	\$ 90.50
8	FRONT DOOR LH <i>Replaced</i>	1	\$ 987.00	\$ 987.00
9	FRONT DOOR HINGE(UPPER) <i>3 Best</i>	1	\$ 63.20	\$ 63.20
10	FRONT DOOR HINGE(LOWER)	1	\$ 63.00	\$ 63.00
11	FRONT DOOR CHECKER <i>Best</i>	1	\$ 128.00	\$ 128.00
12	FRONT DOOR LOCK <i>Sum d</i>	1	\$ 230.00	\$ 230.00
13	FRONT DOOR CATCH <i>new</i>	1	\$ 80.00	\$ 80.00
14	FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$ 188.20	\$ 188.20
15	FRONT DOOR OUTER HANDLE <i>Repair</i>	1	\$ 98.00	\$ 98.00
16	FRONT DOOR OUTER PILLAR <i>Repair cut</i>	1	\$ 140.00	\$ 140.00
17	FRONT DOOR OUTER GARNISH <i>Replaced</i>	1	\$ 166.70	\$ 166.70

18	FRONT DOOR POWER WINDOR MOTOR <i>PM</i>	1	\$	433.50	\$	433.50	+
19	FRONT DOOR POWER REGUALTION	1	\$	280.50	\$	280.50	+
20	FRONT DOOR GLASS <i>Cut</i>	1	\$	380.00	\$	380.00	-
21	FRONT DOOR GLASS CHANNEL <i>new</i>	1	\$	188.90	\$	188.90	+
22	REAR DOOR LH <i>Repr</i>	1	\$	987.00	\$	987.00	+
23	REAR DOOR OUTER HANDLE <i>Repr</i>	1	\$	98.00	\$	98.00	+
24	REAR DOOR OUTER PILLAR <i>Repr</i>	1	\$	140.00	\$	140.00	+
25	REAR FENDER LH <i>Repr</i>	1	\$	933.50	\$	933.50	+

TOTAL PRICE \$ 7,801.20

LESS 10% \$ 780.12

SUB TOTAL PRICE \$ 7,021.08

4513.60
4062.24

4062.24

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$2,000.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$2,000.00	<i>1200.</i>	
3	TUFF COAT	\$250.00	<i>x</i>	
4	WIRING CHECK	\$120.00	<i>30.</i>	
5	TO TRANSFER FRONT DOOR MECHANISM	\$120.00	<i>80</i>	
6	TO TRANSFER REAR DOOR MECHANISM	\$120.00	<i>x.</i>	

TOTAL

\$4,610.00

2110

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,061.08

TOTAL LABOUR COST : \$ 4,610.00

TOTAL REPAIR COST : \$ 11,671.08

APPROVED DETAILS
SURVEYOR :

total: 6212.24
2/5: 3.7K (Nett Value)

07 Days.

Lump Sum \$4950 + 70

Adrian Lij
2/3 17/01/19

4062.24
+ 40.00
+ 2110.00

6212.24
- 304.1242
4969.79

2110