

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 17-Jan-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJT2778C	Tp China.	
MODEL	: CHEVROLET CRUZE 1.6	Asker.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 16-Jan-19
		TIME	: 11:55HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 833.50	\$ 833.50
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 72.50	\$ 72.50
3	FRONT FENDER LH <i>Rehd</i>	1	\$ 533.50	\$ 533.50
4	FRONT FENDER SIGNAL LAMP LH <i>cancel</i>	1	\$ 60.20	\$ 60.20
5	FRONT FENDER INNER COWLING LH <i>Rehd</i>	1	\$ 170.20	\$ 170.20
6	FRONT SIDE MIRROR ASSEMBLY LH <i>Miss. y</i>	1	\$ 455.30	\$ 455.30
7	FRONT SIDE MIRROR COVER LH <i>cancel</i>	1	\$ 90.50	\$ 90.50
8	FRONT DOOR LH <i>Rehd</i>	1	\$ 987.00	\$ 987.00
9	FRONT DOOR HINGE(UPPER) <i>3 Bent</i>	1	\$ 63.20	\$ 63.20
10	FRONT DOOR HINGE(LOWER)	1	\$ 63.00	\$ 63.00
11	FRONT DOOR CHECKER <i>Rehd</i>	1	\$ 128.00	\$ 128.00
12	FRONT DOOR LOCK <i>Sum d</i>	1	\$ 230.00	\$ 230.00
13	FRONT DOOR CATCH <i>new</i>	1	\$ 80.00	\$ 80.00
14	FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$ 188.20	\$ 188.20
15	FRONT DOOR OUTER HANDLE <i>Repair</i>	1	\$ 98.00	\$ 98.00
16	FRONT DOOR OUTER PILLAR <i>Repair cut</i>	1	\$ 140.00	\$ 140.00
17	FRONT DOOR OUTER GARNISH <i>Rehd</i>	1	\$ 166.70	\$ 166.70

18	FRONT DOOR POWER WINDOW MOTOR <i>9M</i>	1	\$ 433.50	\$ 433.50	+
19	FRONT DOOR POWER REGULATION <i>9M</i>	1	\$ 280.50	\$ 280.50	+
20	FRONT DOOR GLASS <i>Cut</i>	1	\$ 380.00	\$ 380.00	-
21	FRONT DOOR GLASS CHANNEL <i>new</i>	1	\$ 188.90	\$ 188.90	+
22	REAR DOOR LH <i>Regr</i>	1	\$ 987.00	\$ 987.00	+
23	REAR DOOR OUTER HANDLE <i>Regr</i>	1	\$ 98.00	\$ 98.00	+
24	REAR DOOR OUTER PILLAR <i>Regr</i>	1	\$ 140.00	\$ 140.00	✓
25	REAR FENDER LH <i>Regr</i>	1	\$ 933.50	\$ 933.50	+

4513.60

4062.24

TOTAL PRICE \$ 7,801.20

LESS 10% \$ 780.12

SUB TOTAL PRICE \$ 7,021.08

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$2,000.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$2,000.00	<i>1200</i>	
3	TUFF COAT	\$250.00	<i>x</i>	
4	WIRING CHECK	\$120.00	<i>30</i>	
5	TO TRANSFER FRONT DOOR MECHANISM	\$120.00	<i>80</i>	
6	TO TRANSFER REAR DOOR MECHANISM	\$120.00	<i>x</i>	

TOTAL

\$4,610.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before repair.
- To display damaged part(s) during resurvey.
- Parts price to be agreed.
- Third party survey is on a "Without Prejudice" basis.
- No illegal or unlicensed work is allowed.
- Supplementary item(s) must be resurveyed and is subject to the insurance Company.

APPROVED DETAILS

SURVEYOR

Acknowledged by Repairer

Signature:

Date:

7,061.08

4,610.00

11,671.08

Adrian Li

h/s 17/01/19

07 Days.

Nett: 3.7K

total 6212.24

h/s: 3.7K

(Nett Value)