

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Feb 2019)
Parts: N/A NISSAN NV200 1.5 L (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBB9088D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*INTERCOOLER	0.00	0.00	*1,600.00 F
2	1		*AIRCON COOLING PIPE	0.00	0.00	*230.00 F
3	1		*AIRCON DISCHARGE PIPE	0.00	0.00	*190.00 F
Sub Total (S\$)						2,020.00
+ Margin on L,N Items 10.00% (S\$)						202.00
Total Parts (S\$)						2,222.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Parts 12,030

f10h 13,233

SN 60

lc 2030

15,323

Us 12000

Limit 11k

20/02/2019

AIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2019)	
Parts:	N/A	NISSAN NV200 1.5 L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	SME Motor Pte Ltd/GBB9088D/18/01/2019 12:01	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Disltd</i>	0.00	0.00	*360.00 P✓
2	2		*FRT BONNET HINGE <i>Best</i>	0.00	0.00	*76.00 F✓
3	1		*FRT BONNET INSULATOR <i>compd</i>	0.00	0.00	*75.00 F✓
4	6		*FRT BONNET INSULATOR CLIP <i>in</i>	0.00	0.00	*27.00 F✓
5	1		*FRT GRILLE <i>Disltd</i>	0.00	0.00	*210.00 F✓
6	6		*FRT GRILLE CLIP <i>in</i>	0.00	0.00	*27.00 F✓
7	1		*FRT GRILLE CENTER LOGO <i>in</i>	0.00	0.00	*60.00 F✓
8	1		*FRT BUMPER <i>Disltd</i>	0.00	0.00	*280.00 F✓
9	10		*FRT BUMPER CLIP <i>in</i>	0.00	0.00	*35.00 F✓
10	2		*FRT BUMPER RETAINER <i>in</i>	0.00	0.00	*36.00 F✓
11	1		*FRT TOWING COVER <i>Disltd</i>	0.00	0.00	*18.00 F✓
12	1		*FRT BUMPER INNER SPONGE ?	0.00	0.00	*160.00 F?
13	1		*FRT BUMPER REINFORCEMENT ?	0.00	0.00	*290.00 F?
14	1		*AIRCON CONDENSER <i>Disltd</i>	0.00	0.00	*350.00 F✓
15	1		*RADIATOR ?	0.00	0.00	*520.00 F?
16	2		*FRT APRON PANEL <i>Disltd</i>	0.00	0.00	*360.00 F✓
17	6		*FRT APRON PANEL CLIP <i>in</i>	0.00	0.00	*21.00 F✓
18	2		*FRT FENDER <i>Braked</i>	0.00	0.00	*520.00 F✓
19	1		*FRT LH FENDER INNER COWLING <i>new</i>	0.00	0.00	*90.00 F+
20	10		*FRT LH FENDER INNER COWLING CLIP <i>new</i>	0.00	0.00	*35.00 F+
21	1		*RADIATOR FAN MOTOR ASSY ?	0.00	0.00	*420.00 F?
22	1		*INTERCOOLER HOSE (SMALL) ? <i>in</i>	0.00	0.00	*90.00 F+
23	1		*INTERCOOLER HOSE (BIG) ? <i>in</i>	0.00	0.00	*220.00 F+
24	1		*FUSE BOX TOP COVER <i>new</i>	0.00	0.00	*100.00 F+
25	1		*RELAY BOX <i>new</i>	0.00	0.00	*80.00 F+
26	1		*AIR CLEANER BOX ?	0.00	0.00	*550.00 F?
27	1		*RADIATOR SPARE TANK <i>Disltd</i>	0.00	0.00	*85.00 F✓
28	1		*WASHER TANK <i>Disltd</i>	0.00	0.00	*160.00 F✓
29	1		*AIR HOSE <i>Disltd</i>	0.00	0.00	*115.00 F✓
30	1		*FRT BONNET LOCK <i>Disltd</i>	0.00	0.00	*45.00 F✓
31	2		*HEADLAMP <i>Disltd</i>	0.00	0.00	*520.00 F✓
32	1		*HEADLAMP SUPPORT PANEL <i>Disltd</i>	0.00	0.00	*180.00 F✓
33	2		*HEADLAMP PANEL <i>Best</i>	0.00	0.00	*90.00 F✓
34	1		*STEERING AIRBAG <i>Activated</i>	0.00	0.00	*2,800.00 F✓
35	1		*AIRBAG CONTROL UNIT ? <i>Activated</i>	0.00	0.00	*600.00 F✓
36	1		*CLOCK SENSOR	0.00	0.00	*180.00 F✓
37	2		*SEAT BELT	0.00	0.00	*1,160.00 F✓
38	1		*INTERCOOLER HOSE JOINT <i>new</i>	0.00	0.00	*160.00 F+

F=Franchise part.

Sub Total (\$\$)
+ Margin on L,N Items 10.00% (\$\$)

11,105.00
1,110.50

10,010

SME Motor Pte Ltd/GBB9088D/18/01/2019 12:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 BATTERY ?	160.00 ✓
2	1 NUMBER PLATE Bent	40.00 ✓
3	1 RADIATOR COOLANT New	20.00 ✓
Sub Total (S\$)		60 220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	REMOVE & REFIX FUSE BOX AND RELAY BOX	New	150.00 ?
4	REPAIR WIRE HARNESS	New	100.00 ?
5	REMOVE & REFIX 2PCS SAFETY BELT AND AIRBAG SYSTEM	New	300.00 250
6	REPROGRAMME AIRBAG SYSTEM	New	250.00 200
7	LABOUR CHARGE	New	700.00 650
8	SPRAY PAINTING	New	1,000.00 800
Gross Labour Cost (S\$)			2,630.00 2020

SME Motor Pte Ltd/GBB9088D/18/01/2019 12:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Intercooler - \$1600

A/cn body p/p \$230

A/cn discharge p/p \$190

Adrian L
P/P 18/01/18

08 days

NE Authorised

Excm : TBA.