

22/03/2009

ASS. REC. BY:

REF:

es/FCI/19001179/GSD3

12

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

AWS

From (Person):

Sanne for

of

FCI

Date/Time: 3:00pm @ 18/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 9333E

Insured:

SHC 8159M

at Workshop m/s

cycle &amp; Carriage Pulco

Tel:

91792566

of

330 Ubi Road 3

Policy No:

Claim No:

DI9 000 443MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/01/2019

CA / REV / REP. / REV 24 HRS 105'

21/1/19 @ morning

H.O.D. Endorsement:

Date/Time:

3:39pm @ 18/1/18

Person Contacted:

Mars

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH 9333E - X

SHC 8159M - NA / MSG 12000116/K

DUA 30/12/2011

23/1/19

Email preli revised to FCI

REF: FCI

1899C

# ASSIGNMENT

From: Date: 21/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH 9333E  
at Workshop n/s: Cycle & Carriage Fulco  
of 330 ubi Road 3

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh.

Morning  
Max

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

\$600k

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH 9333E

Yr Regn. 28 Jun 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitlander

C.C.

1590

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading

34616

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRC Y1AGU004101

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-01-19

Survey held at

MS

11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

05/04/19 Continued PIP \$11,458/- @ 8 days with XGA  
(\$4,612/- Red - 29%)

RECEIVED 05 APR 2019

Date/Time, File Pass to?

05/04/19

1) Typist

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 11,453/- P/P

Survey Fee:

Transportation:

S + RS, SI

Photos

Other

TOTAL

6x15-90

170+90

50

50+50

72

482



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000443MFSH

Our ref: CS/FCI19001179/Gsd3

Date: 23/1/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SGH 9333E**


We thank you for your instruction on 18/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/1/2019 at the premises of M/s CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$15,790.00
Revised Estimate Amount	:S\$10,323.00
"Check" Items Amount	:S\$ 983.00
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAI, AMSAE-A

Automotive Assessor

### MOTOR SURVEY ASSIGNMENT

<b>Date</b>	15-01-2019	<b>Our Ref No.</b> D19000443MFSH
<b>Accident Date</b>	12-01-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8159M	<b>Third Party Vehicle.</b> SGH9333E
<b>Survey Location</b>	330 UBI ROAD 3	
<b>Contact Person.</b>	MARS LER	
<b>Contact No.</b>	65949163/ 91792566	<b>Fax No.</b> 0
<b>Survey Type</b>	DIRECT SETTLEMENT: EST. COR - \$15,790.00	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	CYCLE & CARRIAGE - FULCO MOTOR DEALER PTE LTD - (SERVICE)	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 5 April 2019 1:57 PM  
**To:** 'Mars Ler'; 'Chris Bulaclac'; Guo Qiang (LKKAuto); Admin A  
**Cc:** 'Renemer Bagang'  
**Subject:** RE: SURVEYOR APPOINTED; OUR REF : D19000443MFSH ; YOUR REF: SGH9333E

Dear Mars,

Confirmed final fig \$11,458.00 @ 8 days of repairs.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chris Bulaclac [<mailto:chris.bulaclac@ccfulco.com.sg>]  
**Sent:** Wednesday, 27 March 2019 9:10 AM  
**To:** 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>; Admin A (admin-a@lkkauto.com) <admin-a@lkkauto.com>  
**Cc:** Mars Ler <mars.ler@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>  
**Subject:** Re : SURVEYOR APPOINTED; OUR REF : D19000443MFSH ; YOUR REF: SGH9333E

Hi Guoqiang,

Please see attach file for your reference & finalization.

Thank You,

Best regards

Mars Ler  
B & P Service Advisor  
Cycle & Carriage Fulco Motor Dealer Pte Ltd  
330 Ubi Road 3 Singapore 408650  
D/D 65949163 H/P 91792566

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 18 January, 2019 3:00 PM  
**To:** Mars Ler  
**Cc:** CWS Motor Claims; Serene Ler  
**Subject:** SURVEYOR APPOINTED; OUR REF : D19000443MFSH ; YOUR REF: SGH9333E

Dear Sir/Madam

PRI Request For **SGH9333E** Accident Involving **SHC8159M** On 12-01-2019 AT 20:15:00HRS.

Please find below details for your reference

- **Claim number** : D19000443MFSH
- **Insured vehicle number** : SHC8159M
- **Accident date** : 12-01-2019
- **Third-party vehicle number** : SGH9333E
- **Assignment type** : DIRECT SETTLEMENT
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : SERENE

**PS: This is a system generated mail. Please do not reply to this mail.**

Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 23 January 2019 12:20 PM  
**To:** 'CWS Motor Claims'  
**Cc:** 'Serene Ler'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19000443MFSH/1, SGH 9333E  
**Attachments:** SGH 9333E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGH 9333E  
Date of survey: 21/1/2019  
Number of days : 8 days

Best Regards,

**Veron Chen** | Case Handler **on behalf of Shirley**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 18 January 2019 3:45 PM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Serene Ler' <SereneLer@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19000443MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 21/01/2019.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 18 January 2019 3:00 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <SereneLer@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19000443MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



**AVG**

This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1899C
Vehicle Details	
Vehicle No.:	SGH9333E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	4A92CG8072
Chassis No.:	JMYSRCY1AGU004101
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,037.00
Original Registration Date:	28 Jun 2016
First Registration Date:	28 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$14,037.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2026
PARF Rebate Amount:	\$10,527.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$39,897.00
<b>Total Rebate Amount:</b>	<b>\$50,424.00</b>

The information contained herein is correct as at 22 Jan 2019

OK

**LONPAC INSURANCE BHD (S98FC5635C)**

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555.

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: [www.lonpac.com.sg](http://www.lonpac.com.sg)

GST Reg No.: F0-0005635-C

Class of Policy : MOTOR CAREPLUS

Policy No. : Z18VP05018899

Named Drivers : 1. THE INSURED

Age: 63

2. NG KIM LUK

Age: 27

This Policy is subject to the following endorsements, clauses, warranties, and/or Special Exclusion(s) as printed in this Policy or added thereon or attached thereto and forming part of this Policy.

**AUTHORISED WORKSHOP WARRANTY / DISTRIBUTOR-OWNED MOTOR WORKSHOP**

IT IS HEREBY WARRANTED THAT IT SHALL BE A CONDITION PRECEDENT TO LIABILITY THAT ALL REPAIRS TO THE INSURED VEHICLE WOULD BE CARRIED OUT BY AN AUTHORISED WORKSHOP OF LONPAC INSURANCE BHD OR DISTRIBUTOR-OWNED MOTOR WORKSHOP OTHERWISE THERE WILL BE NO PAYMENT UNDER SECTION 1.

- 1) ACCESSORIES
- 2) AIR-CONDITIONING UNIT & CAR RADIO/CASSETTE/C.D PLAYER
- 3) CLAIMS OPTION
- 4) ENDORSEMENT NO. 30 - REPLACEMENT PARTS
- 5) ENDORSEMENT NO. 72 - LEGAL LIABILITY OF PASSENGERS FOR ACTS NEGLIGENCE
- 6) EXCESS CLAUSE (OWN DAMAGE CLAIMS)
- 7) ACCIDENTS TO PASSENGERS AND AUTHORISED DRIVER (OTHER THAN THE INSURED)
- 8) BREAKAGE OF GLASS IN WINDSCREEN OR WINDOWS
- 9) EXCESS CLAUSE - ELDERLY OR YOUNG &/OR INEXPERIENCED DRIVERS
- 10) INCENTIVE DISCOUNT SCHEME FOR OFFENCE FREE DRIVERS
- 11) NO CLAIM DISCOUNT PROTECTION

LONPAC INSURANCE BHD

CHIEF EXECUTIVE  
(Singapore Branch)

User ID : SINGCHEW1

Date Issued : 2018-06-07 17:13:15.813

**PRIVACY POLICY**

For information on our privacy policy, please visit our website [www.lonpac.com.sg](http://www.lonpac.com.sg)

5378473



NRIC No. S0201899C



Date of issue

05-11-2014

FOR C&C USE ONLY

Address

APT BLK 241 SERANGOON AVENUE 3  
#02-168  
SINGAPORE 550241

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0201899C



Name

TAN CHOR KHENG JENNY

陳楚卿

Race

CHINESE

Date of birth

20-12-1954

Sex

F

Country/Place of birth

SINGAPORE



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S9149465E



Name  
NG KIM LUK

黄 金 力

Race  
CHINESE


Date of birth  
29-05-1991

Sex  
M

Country of birth  
CHINA



REPUBLIC OF SINGAPORE DRIVING LICENCE





Licence Number  
S9149465E

NG KIM LUK

Birth Date  
29 May 1991

Issue Date  
15 Oct 2015

000248 3603K


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg


EFFECTIVE DATE  
15 Oct 2015

NP 426A


Licence No: S9149465E



APR 06 2006



Licence No. S9149465E



Date of Issue  
03-06-2006

Address  
APT BLK 241 SERANGOON AVENUE 3  
#02-168  
SINGAPORE 550241



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Ms Tan Chor Kheng Jenny Reg No/Reg Date SGH9333E*1F / 28/06/2016 Date In/Mileage 15/01/2019/ 0 Chassis No JMYSRCY1AGU004101 Engine No 4A92CG8072 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000034	Credit	16/01/2019/ 19:28	DS	218 / MarsLer	17184			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK LIGHTNING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						80.00
S	MIPNT88088	TO REMOVE & RE-INSTALL CARPETING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						600.00
S	MIPNT88088	TO APPLY SEALANT ON NEW PANELS						300.00
S	MIPNT88088	TO TRANSFER REAR BOOT COMPONENTS AND MECHANISM						600.00
S	MIPNT88088	TO REPLACE REAR BOOT, REAR BUMPER, REINFORCEMENT, ETC. -TO CUT AND WELD REAR END PANEL AND FLOOR PANEL -TO REPAIR LHR OUTER FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						5400.00
S	MIPNT88088	TO APPLY SOUND PROOF SEALANT KIT						480.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						2940.00
M	JJ6410B832	FACE, RR BUMPER	1.00	852.00	0.00	852.00		
M	JJ6410C544	RH, BRKT, R/BMPR FACE	1.00	17.00	0.00	17.00		
M	JJ6410C543	LH, BRKT, R/BMPR FACE	1.00	17.00	0.00	17.00		
M	JJ6410B929	REINFORCEMENT, RR BUM	1.00	231.00	0.00	231.00		
M	JJ6410B028	REINFORCEMENT, UPR, RR	1.00	90.00	0.00	90.00		
M	JJ5281A179	PANEL, RR END	1.00	556.00	0.00	556.00		
M	JJ5251A837	FLOOR, RR	1.00	572.00	0.00	572.00		
M	JJ5920A061	PANEL, TRUNK LID	1.00	760.00	0.00	760.00		
M	JJ5925A042	GAS SPRING, TRUNK LID	2.00	66.00	0.00	132.00		
M	JJ5921A003	WEATHERSTRIP, TRUNK L	1.00	182.00	0.00	182.00		
M	JJ5927A012	LATCH, TRUNK LID	1.00	74.00	0.00	74.00		
M	JJ5927A010	STRIKER, TRUNK LID LA	1.00	24.00	0.00	24.00		

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Ms Tan Chor Kheng Jenny Reg No/Reg Date SGH9333E*1F / 28/06/2016 Date In/Mileage 15/01/2019/ 0 Chassis No JMYSRCY1AGU004101 Engine No 4A92CG8072 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	16/01/2019/ 19:28	DS	218 / MarsLer	17184

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ7240A032 TRIM,TRUNK ROOM RR E	1.00	164.00	0.00	164.00
M W8330A001LED LED TAILLAMP KIT	1.00	855.00	0.00	855.00
M JJ8355A039 REFLECTOR,LH	1.00	36.00	0.00	36.00
M JJ8355A040 REFLECTOR,RH	1.00	36.00	0.00	36.00
M JJ6410A436WA COVER,RR BUMPER	1.00	22.00	0.00	22.00
M JJ8341A099 LAMP ASSY,LICENSE PL	2.00	35.00	0.00	70.00
M JJ7415A111 MARK,THREE-DIA	1.00	51.00	0.00	51.00
M JJMR574899 MARK,LANCER	1.00	58.00	0.00	58.00
M JJMR200300 CLIP, BUMPER	10.00	2.00	0.00	20.00
M JJ6430A083 BRACKET,LICENSE PLAT	2.00	13.00	0.00	26.00
M JJ5370A289 LH,SHIELD,RR WHEELHO	1.00	32.00	0.00	32.00
M JJ8637A134 BUZZER,KEYLESS OPERA	1.00	170.00	0.00	170.00
M JJ8637A135 ANT,KEYLESS OPERATIO	1.00	93.00	0.00	93.00

Z NOTES

ACCIDENT ON 12/01/2019 ALONG UPPER BUKIT TIMAH ROAD

OWNER CLAIMING UNDER THIRD PARTY

REQUIRED REPLACEMENT CAR

TP #: SHC8159M

TP INS: MS FIRST CAPITAL

SDays.

before paint photos.

Gino Qiang - 82880282

21/1/19.

  
25/1/19

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts	5,140.00
Labour	0.00
Standard Menu	0.00
Specialist Job	10,650.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	16070 15,790.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Ms Tan Chor Kheng Jenny Reg No/Reg Date SGH9333E*1F / 28/06/2016 Date In/Mileage 15/01/2019/ 0 Chassis No JMYSRCY1AGU004101 Engine No 4A92CG8072 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000034	Credit	18/03/2019/ 11:24	DS	323 / ChrisBulaclac	17184		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
S	MIPNT88088						250.00
	DIAGNOSTIC/SCANNING						60.00
S	MIPNT88088						300.00
	TO CHECK LIGHTNING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						200.00
S	MIPNT88088						300.00
	TO REMOVE & RE-INSTALL CARPETING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						200.00
S	MIPNT88088						300.00
	TO APPLY SEALANT ON NEW PANELS						3000.00
S	MIPNT88088						300.00
	TO TRANSFER REAR BOOT COMPONENTS AND MECHANISM						300.00
S	MIPNT88088						300.00
	TO REPLACE REAR BOOT, REAR BUMPER, REINFORCEMENT, ETC.						300.00
	-TO CUT AND WELD REAR END PANEL AND FLOOR PANEL						300.00
	-TO REPAIR LHR OUTER FENDER						300.00
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						2520.00
S	MIPNT88088						280.00
	TO APPLY SOUND PROOF SEALANT KIT						280.00
S	MIPNT98088						280.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						280.00
S	MIPNT88088						280.00
	REVERSE SENSOR SET / DM						280.00
A	MI99000QC						280.00
	2ND TECH:NA						280.00
	COMPLAINT:NA						280.00
	REP:YEE						280.00
	REP DONE:YEE						280.00
X	JJ64108832	FACE, RR BUMPER	1.00	852.00	0.00	852.00	
X	JJ6410C544	RH, BRKT, R/BMPR FACE	1.00	17.00	0.00	17.00	
X	JJ6410C543	LH, BRKT, R/BMPR FACE	1.00	17.00	0.00	17.00	
X	JJ64108929	REINFORCEMENT, RR BUM	1.00	231.00	0.00	231.00	
X	JJ64108028	REINFORCEMENT, UPR, RR	1.00	90.00	0.00	90.00	

Confirm &amp; accepted by

Finalization  
27/03

Guo Qiang LKK

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Ms Tan Chor Kheng Jenny Reg No/Reg Date SGH9333E*1F / 28/06/2016 Date In/Mileage 15/01/2019/ 0 Chassis No JMYSRCY1AGU004101 Engine No 4A92CG8072 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000034	Credit	18/03/2019/ 11:24	DS	323 / ChrisBulaciac	17184	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X	JJ5281A179	PANEL,RR END	1.00	556.00	0.00	556.00
X	JJ5920A061	PANEL, TRUNK LID	1.00	760.00	0.00	760.00
X	JJ5921A003	WEATHERSTRIP,TRUNK L	1.00	182.00	0.00	182.00
X	JJ5927A012	LATCH,TRUNK LID	1.00	74.00	0.00	74.00
X	JJ7240A032	TRIM,TRUNK ROOM RR E	1.00	164.00	0.00	164.00
X	W8330A001LED	LED TAILLAMP KIT	1.00	855.00	0.00	855.00
X	JJ8355A039	REFLECTOR,LH	1.00	36.00	0.00	36.00
X	JJ6410A436WA	COVER,RR BUMPER	1.00	22.00	0.00	22.00
X	JJ7415A111	MARK,THREE-DIA	1.00	51.00	0.00	51.00
X	JJMR574899	MARK,LANCER	1.00	58.00	0.00	58.00
X	JJMU488006	CLIP,ENG ROOM COVER	10.00	2.00	0.00	20.00
X	JJ8637A134	BUZZER,KEYLESS OPERA	1.00	170.00	0.00	170.00
X	JJ8637A135	ANT,KEYLESS OPERATIO	1.00	93.00	0.00	93.00
Z	NOTES					
ACCIDENT ON 12/01/2019 ALONG UPPER BUKIT TIMAH ROAD						
OWNER CLAIMING UNDER THIRD PARTY						
REQUIRED REPLACEMENT CAR (R/A-22039)						
TP #: SHC8159M TP INS: MS FIRST CAPITAL						

Confirm &amp; accepted by

Parts	4,248.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,210.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	11,458.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19001179/Gsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8159M	Veh. Inspected	SGH 9333E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000443MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	18/01/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI LANCER	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JMYSRCY1AGU004101	Colour	SILVER	
Odometer	34616	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/01/2019	Inspection Date	21/01/2019	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 9333E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FACE,RR BUMPER (SN)	TORN	852.00	852.00
1	RH,BRKT,R/BMPR FACE (SN)	DEFORMED	17.00	17.00
1	LH,BRKT,R/BMPR FACE (SN)	DEFORMED	17.00	17.00
1	REINFORCEMENT,RR BUM (SN)	BENT	231.00	231.00
1	REINFORCEMENT,UPR,RR (SN)	BENT	90.00	90.00
1	PANEL,RR END (SN)	BENT	556.00	556.00
1	FLOOR,RR (SN)	TO REPAIR SEE LABOUR	572.00	-
1	PANEL,TRUNK LID (SN)	BENT	760.00	760.00
2	GAS SPRING,TRUNK LID (SN)	NOT NECESSARY	132.00	-
1	WEATHERSTRIP,TRUNK L (SN)	TWISTED	182.00	182.00
1	LATCH,TRUNK LID (SN)	BENT	74.00	74.00
1	STRIKER,TRUNK LID LA (SN)	NOT NECESSARY	24.00	-
1	TRIM,TRUNK ROOM RR E (SN)	DEFORMED	164.00	164.00
1	LED TAILLAMP KIT (SN)	DEFORMED	855.00	855.00
1	REFLECTOR,LH (SN)	CUT	36.00	36.00
1	REFLECTOR,RH (SN)	NOT NECESSARY	36.00	-
1	COVER,RR BUMPER (SN)	MISSING	22.00	22.00
2	LAMP ASSY,LICENSE PL (SN)	NOT NECESSARY	70.00	-
1	MARK,THREE-DIA (SN)	NECESSARY	51.00	51.00
1	MARK,LANCER (SN)	NECESSARY	58.00	58.00
10	CLIP,BUMPER (SN)	NECESSARY	20.00	20.00
2	BRACKET,LICENSE PLAT (SN)	NOT NECESSARY	26.00	-
1	LH,SHIELD,RR WHEEL HO (SN)	NOT NECESSARY	32.00	-
1	BUZZER,KEYLESS OPERA (SN)	DAMAGED	170.00	170.00
1	ANT,KEYLESS OPERATIO (SN)	DAMAGED	93.00	93.00
1	SET REVERSE SENSOR (ADDITIONAL)(SN)	DAMAGED	280.00	280.00
			5,420.00	4,528.00
<b>LABOUR</b>				
DIAGNOSTIC/SCANNING.			250.00	250.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK LIGHTNING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		80.00	60.00
	TO REMOVE & RE-INSTALL CARPETING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		600.00	300.00
	TO APPLY SEALANT ON NEW PANELS.		300.00	200.00
	TO TRANSFER REAR BOOT COMPONENTS AND MECHANISM.		600.00	300.00
	TO REPLACE REAR BOOT, REAR BUMPER, REINFORCEMENT, ETC. TO CUT AND WELD REAR END PANEL AND FLOOR PANEL-TO REPAIR LHR OUTER FENDER. STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FLOOR, RR.		5,400.00	3,000.00
	TO APPLY SOUND PROOF SEALANT KIT.		480.00	300.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,940.00	2,520.00
			10,650.00	6,930.00
<b>GRAND TOTAL</b>			<b>16,070.00</b>	<b>11,458.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>11,458.00</b>
------------------------------------	--	--	------------------

Report Ref No. CS/FC119001179/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.