



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	/Ms Tan Chor Kheng Jenny
	Reg No/Reg Date	SGH9333E*1F / 28/06/2016
	Date In/Mileage	15/01/2019/ 0
	Chassis No	JMYSRCY1AGU004101
	Engine No	4A92CG8072
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	A01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000034	Credit	18/03/2019/ 11:24	DS	323 / ChrisBulac	17184				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088								250.00
	DIAGNOSTIC/SCANNING								60.00
S	MIPNT88088	TO CHECK LIGHTNING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							300.00
S	MIPNT88088	TO REMOVE & RE-INSTALL CARPETING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							200.00
S	MIPNT88088	TO APPLY SEALANT ON NEW PANELS							300.00
S	MIPNT88088	TO TRANSFER REAR BOOT COMPONENTS AND MECHANISM							3000.00
S	MIPNT88088	TO REPLACE REAR BOOT, REAR BUMPER, REINFORCEMENT, ETC.							
	-TO CUT AND WELD REAR END PANEL AND FLOOR PANEL								
	-TO REPAIR LHR OUTER FENDER								
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS								300.00
S	MIPNT88088	TO APPLY SOUND PROOF SEALANT KIT							2520.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							280.00
S	MIPNT88088	REVERSE SENSOR SET / DM							
A	MI99000QC								
	2ND TECH:NA								
	COMPLAINT:NA								
	REP:YEE								
	REP DONE:YEE								
X	JJ6410B832	FACE, RR BUMPER			1.00	852.00	0.00	852.00	
X	JJ6410C544	RH, BRKT, R/BMPR FACE			1.00	17.00	0.00	17.00	
X	JJ6410C543	LH, BRKT, R/BMPR FACE			1.00	17.00	0.00	17.00	
X	JJ6410B929	REINFORCEMENT, RR BUM			1.00	231.00	0.00	231.00	
X	JJ6410B028	REINFORCEMENT, UPR, RR			1.00	90.00	0.00	90.00	

Confirm & accepted by

Finalization
27/03

Guo Qiang LKK

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.