

SERVICE ESTIMATE

0 - F00003 3L: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 26/06/2019
 SINGAPORE WIP No. : 48038
 Singapore 068877 Veh.In/Out: 20/06/2019 26/06/2019
 *Tel.No. :
 Reg.No. : SLR7991G
 Closed by : Michelle Ong Siew Be Reg.date : 29/08/2017
 Svc Consultant : ACC Mileage .. : 18,196
 Remarks : Mr Berghs Johan Piet Chassis No: VF1RFA00257485749

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER	0		450.00	0		450.00	S ✓
900	TO PUTTY AND SPRAY PAINT	0		400.00	0		400.00	S ✓
ON REAR BUMPER								
0031	TO REPLACE RH REAR RIM	0		50.00	0		50.00	S ✓
419	TO CONDUCT COMPUTERISED	0		280.00	0		280.00	S ✓
4 WHEEL ALIGNMENT								
280	TO CHECK WIRING INCLUDE	0		330.00	0		330.00	S ✓
RESETTING OF ALL ELECTRICAL								
MODULES								
①	ALLOY RIM 20" R983 S	1.0	EA	986.40	10		887.76	S
②	TYRE PRESSURE SENSOR	1.0	EA	119.10	10		107.19	S
③	BUMPER REAR PAD GS4	1.0	EA	392.30	10		353.07	S
④	ADHESIVE SEALER FL2	1.0	EA	669.10	10		602.19	S
⑤	BUMPER REAR GS4 BOSS	1.0	EA	1068.60	10		961.74	S
	MUDGUARD-RR RH GS4	1.0	EA	59.30	10		53.37	S <i>tn</i> ✓

Gross Total. 4,475.32 ✓

Labour Total 1,510.00
 Parts Total 2,965.32
 Package Total 0.00

Net..... 4,475.32
 GST @ 7.0% 313.27
 Total..... 4,788.59
 Paid..... 0.00
 Please Pay.. 4,788.59

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated