

ASS. REC. BY:

REF:

05/FCI19001189 / Agd3n2

Special Instruction:

Surveyor

Adnan

ASSIGNMENT (Office)

From (Person)

Karen Tan

of

FCI

Date/Time

3:55pm @ 18/1/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KQ 4527B

Insured:

8HA 7316T

at Workshop m/s

Lee Sheng Auto

Tel:

67477397

of

1 Kaki Bukit Ave 6 # 01-58

Policy No:

Claim No:

D19000507MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

4:40pm @ 18/1/19

Person Contacted:

Ms. Lee

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

8KQ 4527B-X

SHA 7316T-C03/C77/80/6/01/K1ha342

JWA: 3/9/18

7/1/19 @

2:44pm Informed Karen Tan, we are pending estimate from repairer.

13/1/19 @

2:56pm revised to Karen Tan by email.

US \$ 2300, 3 days (rel \$ 4700.78, 76%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK04527B Yr Regn: 2014, NovType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaruc.c. 1600

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

53347

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JF19?3KCSE6146629Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

225/55R17

R:

225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

18/01/19

Survey held at

Lee ShengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap

RECEIVED 14 AUG 2019

MV: 66K 56KPV: 46.3KNett: 9.7K

Date/Time, File Pass to?

Date/Time, File Return to?

1) 13/8 12:52

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

150

S + RS, SI

50

Photos

50

Others

23

TOTAL

273



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000507MFSH

Date: 13 August 2019

Our Ref: CS/FCI19001189/Aqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 4527B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/01/2019 at the premises of M/s LEE SHENG AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,305.18</u> .
Revised Estimate Amount	: S\$ <u>2,300.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-01-2019	Our Ref No. D19000507MFSH
Accident Date	16-01-2019	Claim Type. Third Party
Insured Vehicle	SHA7316T	Third Party Vehicle. SKQ4527B
Survey Location	1 KAKI BUKIT AVENUE 6 #01-58/60 AUTOBAY@KB	
Contact Person.	LEE EK CHEN	
Contact No.	67477397/ 0	Fax No. 67457138
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEE SHENG AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 13 August 2019 2:56 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000507MFSH/1
Attachments: CSFCI19001189Aqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKQ 4527B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 21 January 2019 2:44 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000507MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SKQ 4527B on 18/01/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 18 January 2019 4:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000507MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 21/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 21 January 2019 2:44 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000507MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SKQ 4527B on 18/01/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Friday, 18 January 2019 4:43 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000507MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 21/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 18 January 2019 3:55 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000507MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Inchcape
6303 6432
Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA
2019
Interest Rate 1.98% till 31 Jan 2019
Extended Warranty 1yr
Free Tyre & Service Credits up to \$3,000

FOR SALE BY OWNER
Post an Advertisement
Sell it yourself! Advertise it at just \$58 until it's SOLD!
Post an Ad Advertiser Login Ways of Selling

CNY SALES! 2018 Nissan NV200! @ \$54,800
No Hidden Cost! GST Inclusive!
Drive With 3A! Depre Only \$470/mth! Call Now!
Not Link Partners StarAd

Lake View Credit Pte Ltd
view our cars
> Low prices guaranteed
> Specialist in Japanese cars
> Easy loan approval
> All terms are negotiable

Browse by Category Save Search Print Sort by Date Posted 20 results/page

5 vehicles Search Advanced Search Search View All
Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Subaru XV Any Any 2015 Any Any Any Available



☐ Subaru XV 1.6A \$57,800 \$8,550 /yr 26-Feb-2015 1,600 cc 30,000 km SUV Available
1 Owner, Safe Buy As Selling Near Export Price, Flexible Loan Available, Agent Maintained And Warranty, Spacious Cabin And Boot Space, Low Road Tax, Low Depreciation, Classy White And High View SUV This...

Compare 18-Jan-2019 2015 Subaru XV, 2015 subaru xv, Subaru XV, subaru xv, Subaru, XV, xv, Used Subaru



☐ Subaru XV 1.6A \$57,000 \$8,380 /yr 06-Mar-2015 1,600 cc 52,000 km SUV Available
Agent Unit And Agent Maintained, Warranty And Free Servicing Till March 2020, Pristine Condition, Affordable Family SUV! Trade In And High Loan Assists Are Available, Consignment Unit, Make An Appointment...

Compare 17-Jun-2019 2015 Subaru XV, 2015 subaru xv, Subaru XV, subaru xv, Subaru, XV, xv, Used Subaru




☐ Subaru XV 1.6i-S \$63,800 \$8,080 /yr 21-Oct-2015 1,600 cc 28,000 km SUV Available
Cheapest Price Yet Still Able To Negotiable, Low Mileage & Well Maintained SUV By One Owner Only, Excellent Unit With Clean Interior And Original Paintwork, Call Us For An Appointment For Viewing Today...

Compare 10-Apr-2019 2015 Subaru XV, 2015 subaru xv, Subaru XV, subaru xv, Subaru, XV, xv, Used Subaru



☐ Subaru XV 1.6i-S \$65,800 \$8,370 /yr 23-Oct-2015 1,600 cc 40,333 km SUV Available
Classy Silver And High View SUV That's Suits Family And All, A New Face-lift Model, One Owner Unit With Well Maintained Interior And Exterior As Good As A New Car! Come Down And View This Beauty Before...

Compare 18-Jan-2019 2015 Subaru XV, 2015 subaru xv, Subaru XV, subaru xv, Subaru, XV, xv, Used Subaru



Magnetic Sun Shade
4 pcs Magnetic Sun Shade for Subaru XV. Made in Taiwan.
More info about this product



☐ Subaru XV 1.6i-S \$65,000 \$8,220 /yr 06-Nov-2015 1,600 cc 34,000 km SUV Available
Lady Owner, Pristine Condition.

Compare 18-Jan-2019 2015 Subaru XV, 2015 subaru xv, Subaru XV, subaru xv, Subaru, XV, xv, Used Subaru

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3497D

Vehicle Details

Vehicle No.:	SKQ4527B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU XV 1.6i AWD CVT
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	FB161479761
Chassis No.:	JF1GP3KC5EG146629
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$16,152.00
Original Registration Date:	28 Nov 2014
First Registration Date:	28 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$11,152.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2024
PARF Rebate Amount:	\$8,364.00

Intended COE Rebate Details

COE Expiry Date:	27 Nov 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,900.00
COE Rebate Amount:	\$37,966.00
Total Rebate Amount:	\$46,330.00

The information contained herein is correct as at 21 Jan 2019

OK

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. W.ATELIER PTE LTD

5 GUL AVE

S 629682

Attention : Motor Claim Department

Estimate : ES000828

Date : 17/01/2019

Vehicle Num. : SKQ 4527B

Make/Model : SUBARU XV-2014

Chassis/Eng# : JF1GP3KC5EG146629/FB161479701

Accident Date : 16/01/2019

Claim No. :

Reference :

Policy No. :

TP 1st Cap.

Xiao Chen.

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	REAR TRUNKLID <i>new</i>		910.80 +
2.	1 PC	REAR TRUNKLID OUTER GARNISH		162.80 +
3.	4 PCS	REAR TRUNKLID OUTER GARNISH CLIPS	1.60	6.40 +
4.	1 PC	REAR TRUNKLID LOGO		83.60 +
5.	2 PCS	REAR TRUNKLID EMBLEM	68.50	137.00 +
6.	2 PCS	REAR LAMPS	377.40	754.80 +
7.	1 PC	REAR TRUNKLID INNER LOCK		200.30 +
8.	1 PC	WIPER ARM		46.20 +
9.	1 PC	WIPER MOTOR		216.40 +
10.	1 PC	REAR WINDSCREEN MOULDING		44.20 +
11.	1 PC	REAR TRUNKLID WEATHERSTRIP		119.50 +
12.	2 PCS	REAR TRUNKLID DAMPER	14.20	28.40 +
13.	1 PC	REAR TRUNKLID TRIM BOARD		252.80 +
14.	1 PC	REAR BUMPER		894.20 +
15.	8 PCS	REAR BUMPER CLIPS	2.50	20.00 +
16.	2 PCS	REAR BUMPER RETAINER	36.20	72.40 +
17.	2 PCS	REAR BUMPER BRACKET	36.20	72.40 +
18.	1 PC	REAR BUMPER REINFORCEMENT <i>Best.</i>		187.20 +
19.	2 PCS	REAR BUMPER REFLECTOR	24.30	48.60 +
20.	1 PC	REAR BUMPER REFLECTOR CENTRE		102.80 +
21.	1 PC	REAR END PANEL		388.90 +
22.	1 PC	REAR END PANEL TOP GARNISH <i>new</i>		100.50 +
		<i>Exhaust Pipe</i>		
		<i>List Total S\$:</i>		4,850.20
		<i>10.00% Discount S\$:</i>		485.02
		<i>20%.</i>		4,365.18

1960.6

1568.48

684 ✓

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. WATELIER PTE LTD

5 GUL AVE

S 629682

Attention : Motor Claim Department

Estimate : ES000828

Date : 17/01/2019

Vehicle Num. : SKQ 4527B

Make/Model : SUBARU XV-2014

Chassis/Eng# : JF1GP3KC5EG146629/FB161479701

Accident Date : 16/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 SET			
2.	1 SET			

SPECIAL NETT ITEMS :REAR NUMBER PLATE & BASE *new*REAR BUMPER SENSOR *2nd*

50.00

250.00

300.00

Special Nett Total S\$:

LABOUR :

KNOCKING, CUTTING, JACKING WELDING ETC

SPRAY PAINTING

TO CHECK WIRING AND SYSTEM FUNCTION

TO APPLY RUST-PROOFING ON AFFECTED AREA

To remove exhaust pipe

Labour Total S\$:

700.00

700.00

120.00

120.00

1,640.00

Total S\$: 6,305.18

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7070.78



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19001189/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7316T	Veh. Inspected	SKQ 4527B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000507MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	18/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JF1GP3KC5EG146629	Colour	BLACK	
Odometer	53347	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2019	Inspection Date	18/01/2019	
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 4527B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TRUNKLID	NOT NECESSARY	910.80	-
1	REAR TRUNKLID OUTER GARNISH	NOT NECESSARY	162.80	-
4	REAR TRUNKLID OUTER GARNISH CLIPS @\$1.60	NOT NECESSARY	6.40	-
1	REAR TRUNKLID LOGO	NOT NECESSARY	83.60	-
2	REAR TRUNKLID EMBLEM @\$68.50	NOT NECESSARY	137.00	-
2	REAR LAMPS @\$377.40	NOT NECESSARY	754.80	-
1	REAR TRUNKLID INNER LOCK	NOT NECESSARY	200.30	-
1	WIPER ARM	NOT NECESSARY	46.20	-
1	WIPER MOTOR	NOT NECESSARY	216.40	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	44.20	-
1	REAR TRUNKLID WEATHERSTRIP	NOT NECESSARY	119.50	-
2	REAR TRUNKLID DAMPER @\$14.20	NOT NECESSARY	28.40	-
1	REAR TRUNKLID TRIM BOARD	NOT NECESSARY	252.80	-
1	REAR BUMPER	DEFORMED	894.20	894.20
8	REAR BUMPER CLIPS @\$2.50	NECESSARY	20.00	20.00
2	REAR BUMPER RETAINER @\$36.20	NECESSARY	72.40	72.40
2	REAR BUMPER BRACKET @\$36.20	NOT NECESSARY	72.40	-
1	REAR BUMPER REINFORCEMENT	BENT	187.20	187.20
2	REAR BUMPER REFLECTOR @\$24.30	NOT NECESSARY	48.60	-
1	REAR BUMPER REFLECTOR CENTRE	CUT	102.80	102.80
1	REAR END PANEL	TO REPAIR SEE LABOUR	388.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	100.50	-
1	EXHAUST PIPE	DENTED	684.00	684.00
	LESS 10% DISCOUNT		-553.42	-
	LESS 20% DISCOUNT		-	-392.12
			4,980.78	1,568.48
SPECIAL NETT ITEMS				
1	SET REAR NUMBER PLATE & BASE (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/FCI19001189/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER SENSOR (SN) LABOUR KNOCKING,CUTTING,JACKING WELDING ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL. SPRAY PAINTING. TO CHECK WIRING AND SYSTEM FUNCTION. TO APPLY RUST-PROOFING ON AFFECTED AREA. TO REMOVE EXHAUST PIPE.	DAMAGED	250.00	200.00
			300.00	200.00
		NOT NECESSARY	700.00	500.00
			700.00	500.00
			120.00	30.00
			120.00	-
			150.00	80.00
			1,790.00	1,110.00
GRAND TOTAL		7,070.78	2,878.48	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00	

Report Ref No. CS/FCI19001189/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.