

TEK SOON MOTOR REPAIR & SPRAY PAINTING

AUTOBAY @ KAKI BUKIT, 1 KAKI BUKIT AVENUE 6, #01-28,
SINGAPORE 417883

EMAIL: teksoonmotor@gmail.com

REG NO. 252083/00-L

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimated repair cost: **SKR 6768 D**

Date:

Signature: Li Gelin

Name :
Address : c/o No. 1 Kaki Bukit Ave 6
#01-93 AutoBay@Kaki Bukit
Singapore 417883
Model : Suzuki Vitara

TP FWD

Xiao Tong

Date :

Total 3364.97
H/S 2.712
04 Days

QTY	ITEM	AMT (\$)
-----	------	----------

List Items

1 pc	Rear tailgate <i>Dented</i>	\$ 773.60 ✓
1 pc	Rear tailgate damper <i>new</i>	\$ 109.90 ✓
1 pc	Rear tailgate inner board <i>could</i>	\$ 195.15 ✓
1 pc	Rear tailgate lock <i>3 new</i>	\$ 162.35 ✓
1 pc	Rear tailgate rubber	\$ 87.10 ✓
1 pc	Rear tailgate "VITARA" emblem <i>new</i>	\$ 30.25 ✓
1 pc	Rear taillamp <i>new</i>	\$ 186.15 ✓
1 pc	Rear end panel <i>new</i>	\$ 188.95 ✓
1 pc	Rear bumper <i>Dehond</i>	\$ 669.10 ✓
1 pc	Rear bumper reflector <i>new</i>	\$ 24.75 ✓
1 pc	Rear bumper side retainer <i>new</i>	\$ 18.15 ✓
1 pc	Rear spare tyre outer cover <i>Dehond</i>	\$ 456.85 ✓
1 pc	Rear spare tyre inner cover <i>new</i>	\$ 390.30 ✓
1 pc	Rear spare tyre cover "Suzuki" emblem <i>new</i>	\$ 98.05 ✓
1 pc	Rear spare wheel bracket <i>new</i>	\$ 196.50 ✓
		\$ 3,587.15
	Less 15.0%	\$ 538.07
		\$ 3,049.08

Special Nett Items

1 pc	Rear windscreen seal <i>new</i>	\$ 50.00 ✓
1 pc	Rear windscreen sealant <i>new</i>	\$ 80.00 ✓
1 pc	Rear number plate <i>200</i>	\$ 50.00 ✓
1 pc	Rear reverse sensor (1 set) <i>Damaged</i>	\$ 280.00 ✓
		\$ 460.00

S/N

Labour Charge

1	To check wiring.	\$ 50.00 ✓
2	To remove and refit inner garnishes.	\$ 120.00 ✓
3	To remove and refit reverse sensor.	\$ 150.00 ✓
4	To remove and refit windscreen glass.	\$ 180.00 ✓
5	Panel beating	\$ 750.00 ✓
6	Spray painting	\$ 750.00 ✓
7	To underseal	\$ 110.00 ✓
		\$ 2,110.00

Total : \$ 5,619.08