

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19001197/R1pa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH			Date: 06-05-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 2875Z	Veh. Inspected	SKW 4588T
	Policy No.	CV1/GA399113	Coverage (\$)	0.00
	Claim No.	S9M01ADJ	Excess (\$)	0.00
	Assign From		Assign Date	18/01/2019
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER 2.0I	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JF1SJ5KC5FG058723	Colour	BLUE
	Odometer	086815	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/60 R17	YOKOHAMA	6 mm
	L/H Front Tyre	275/60 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	275/60 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	275/60 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	11/01/2019	Inspection Date	21/01/2019
	Survey held at	eld at COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286		
5a.	. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			