

Case Details

Case Reference Number : TAX/01/19/2081
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4778C

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-5402-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
Accident Date and Time : 16/01/2019 11:45 AM
Vehicle Age(In Months) : 34

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	30.00	321.02	Replace	1	321.02	Replace ▾ DEF
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾ NEL
Total Spare Part Cost									441.02		Surveyor Total	441.02	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									441.02		Final Sur Total	441.02	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
Total:		378.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		240.00	20.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	TO WASH AND VACUUM	60.00	0	
3	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		240.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	441.02	441.02
Total Labour Cost	338.00	200.00
Total Spray Painting	378.00	200.00
Other	240.00	20.00
Overall Total	1,397.02	861.02
Lump Sum Repair Option		
Lump Sum Total	0.00	861.02
Surveyor Approved Amount		861.02
No of Repair Days*	3	2
Remarks		P/P repair, photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	18/01/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: