

Monster Motors Pte Ltd

Postad: 14-Jan-2019 Toys: 2006 Mitsubishi Lancer, 2006 mitsubishi lancer, mitsubishi Lanc

(COE till 07/2021)

Mitsubishi Lancer 1.6M GLX

\$16,500 \$6,570 /vr

28-Jul-2006

1.584 cc


195,000 km

Sedan

Available

Clean And Well Sorted Lancer For Hassle-free Motoring. Owner Has Replaced The AC Compressor, All 4 Suspension And Numerous Other Wear And Tear Items. An Elderly Owner Also Ensures That The Car Hasn't ...

Posted: 22-Dec-2018 Togo: 7006 Mesidish Lancer, 2006 mesidishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi Lancer, Immer, lancer, Line Mitsubishi



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Singapore NRIC
Owner ID:	0129Z
Vehicle Details	
Vehicle No.:	5GJ654C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	4G18HK2623
Chassis No.:	JMYSTCS3A6U011149
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,382.00
Original Registration Date:	29 Jun 2006
First Registration Date:	29 Jun 2006
Transfer Count:	3
Actual ARF Paid:	\$14,721.00
Intended PARE Robate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	•
PARF Rebate Amount:	\$0.00
Intended COE Repate Details	15000000000000000000000000000000000000
COE Expiry Date:	28 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$11,303.00
Total Rebate Amount:	\$11,303.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jan 2019





1 of 3

Report No. T/20190115/2003

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025

Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

TENDET OF A TRAFFIC ACCIDENT		
REPORT OF A TRAFFIC ACCIDENT	Law Const No.	Station Diary No.:
Date/Time Report Made:	Vide Report No.:	37
15/01/2019 01:24		THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAME

15/01/2019 01:24				37	
Informan	t's Particu	lars			
Name of Informant: ABDUL WAHID S/O KADER MAIDEEN			Address: APT BLK 436C FERNVALE ROAD #08-164 SINGAPORE 793436		
ID Type / ID No.: NRIC NO / S8270129Z			Contact No.: Home/Office: Mobile: 86841377		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age:	Date of Birth: 29/09/1982	Type of Informant: Driver		
Race: Indian Occupation: Self-Employed			Language: Institution / School Na English		
			Driving Licence Information: Class: 3A	Date of Expiry:	

Type of	Injury Foreign Vehicle	Drink Drive:	Date/Time of Accident: 14/01/2019 22:35	Type of Location Straight Road	
Accident:		No	14/01/2019 22:33		
	WEST WAY in front of Blk 432A Ser	gkang West Way Road Surface:		Road Speed Limit:	
Clear		Dry		Troffic Volume:	
Traffic Flow:		Traffic Control: Not Controlled	8	Traffic Volume: Light	
Type of Colli Between Mo	sion: ving Vehicles - Head To			Anyone conveyed by ambulance: No	

Details of V	ehicle invo		1.0.1.1	Color	Condition	No of Passenge
Vehicle No.	Type	Make	Model	Color		2
JQK7738	Lorry			White	No Damage	2
SGJ654C	Car	MITSUBISHI	LANCER 1.6	Black	Seriously Damaged	2

Details of Vo	ehicle Insurance	No.	Effective	Expiry Date
Vehicle No.	Insurance Company	Insurance No	12.11.0	
	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30127118	12/02/2018	11/02/2019



T/20190115/2003

2 of 3

Report No. T/20190115/2003

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025

Tel No: 1800-343 8999

CONTINUATION OF REPORT

Any Pedestrian Ir	volved: No					
No. of Pedestrian			Use of P	edestrian	Cross	ing: NA
Driver	以表现 增少罪 上兴。 唐明			Status level		ELECTRICAL ENGINEERS
Name	MUHAMMAD ZAKARI	A BIN MA	ASKAN	ID No.		A50076886
Related Vehicle	JQK7738 (Lorry)			Conta	ct No.	NIL
Hospital/Clinic	NIL		Lagrana Lagrana	Class Driving Licend Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Dis	scharge	NIL	
	ted Medical Leave	NIL	Degree	of Injury	NIL	
Driver						
Name	ABDUL WAHID S/O K	ADER M	AIDEEN	ID No		S8270129Z
Related Vehicle	SGJ654C (Car)			Conta	ct No.	86841377
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Di	scharge	NIL	Addisor
	ted Medical Leave	NIL	Deeree	of Injury	Sligh	t

Brief Details.

On 14/01/2019 at about 10.35 pm, I was driving my vehicle bearing registration plate no. SGJ654C when I entered the service road in front of Blk 432A Sengkang West Way. Thereafter, there was one Malaysia registered lorry bearing registration plate no. JQK7738 parking at the side of the service road blocking the way and my vehicle was unable to drive past. Subsequently, I sounded the horn but the lorry suddenly reversed and collided onto the front portion of my vehicle causing a big impact. Immediately, I alighted from my vehicle to make a check and the Malaysian driver also alighted. I observed that there is no damages to the lorry. Due to the accident, I felt some pain at my back area but I have not seek medical treatment.





3 of 3

Report No. T/20190115/2003

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025 Tel No: 1800-343 8999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt LEE SHAO WEI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 15/01/2019 01:24
Officer In Charge Of Case: TP / AEIT /	Classification Of Case:
Staff Sgt WONG SIEU LUI Contact No.: 65476151	SH 095
Authentication Stamp	W

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883 Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ABDUL WAHIB S/O KADER MAIDEEN BLK 436C FERNVALE ROAD #08-164 \$ 793436	Ye M	te hicle no ake/Model cident date	:19.02 :SGJ 65 :MITSU :14.01.	4 C BISHI LANCER 2019
No DESCRIPTION		Qty	1230	Amount (S\$)
List Items		24	ć	0630
1 Bonnet Dewter		1	\$	863.8
2 Bonnet hinges @ \$65.00		2	\$	130 /
3 Bonnet lock		1	\$	52
4 Bonnet lock bracket Best		1	\$	49
5 Bonnet inner rubber		1	\$	42.9 + ,
6 Fornt support panel Buckerd		1	s	739.7
7 Front grille rim caulo		1	\$	182
8 Front grille @ \$111.80 Cruled		2	\$	223.6
9 Front grille emblem		1	\$	46.8
10 Front grille clips (1set) Au		1	\$	50 20.
11 Front head lamp @ \$669.50		2	\$	1339
12 Front bumper Deland		1	\$	958.1
13 Front bumper side holder @ \$57.20 XLLV		2	\$	114.4
14 Front bumper reinforcement But		1	\$	170.3
15 Front bumper bracket @ \$65.00 >terev		2	\$	130 ×
16 Front bumper lower lip Ht rev		1	\$	869.7+
17 Front humper foe lamp @ \$764.40	15-8	2	\$	1528.8
18 Front bumper fog lamp cover @ \$39.00	ser	2	\$	78 🖈
19 Front bumper clips (1set)		1	\$	50-30:
20 Front number plate garnish	10	1	\$	46.8
21 Air con condenser Bent.	6 900	40 1	\$	1531.4
22 Radiator Best	6210:	36 1	\$	1078.9
23 Horn @ \$265.00 New	00,0	2	\$	530 ×
23 110111 @ \$203.000		10	\$	10805.2
		Less 20% Disc	\$	2161.04
		Total	\$	8644.16
21 0				
Special Nett Items		1	¢	50- 30
1 Front number plate (red &	480	1	\$	650-450 .
2 Bonnet sticker New	1105-2000	Total	- 4	700

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ABDUL WAHIB S/O KADER MAIDEEN **BLK 436C FERNVALE ROAD**

#08-164

5 793436

Date

:19.02.2019

Vehicle no

:SGJ 654 C

Make/Model

:MITSUBISHI LANCER

Accident date

:14.01.2019

No	DESCRIPTION	Qty		Amount (\$\$)
Labour C 1 Remove 2 Remove 3 Respray	& reinstall air con fill in gas replace & repair consistent to the accident	1970	\$ \$	200 123 2000 903 1500 900
4 Tuff kote		Total	\$	3850
		Grand Total	\$	-13194.16
				14274.68

tolal 8660.36 4/S 69K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Witnout Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

E _A g(Affiliated to Federation Interna	ationale Des Experts En Autom	obile
AUF	MENG SPRAY PA	INTING WORKSHOP	Ref : CS/TP1900125	3/Asd3n2
#01-6 ON B		APORE 417883 L WAHIB S/O KADER	Date: 27-05-2019 Code: TP127	
	EEN	Dalley Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	Policy Particula	Veh. Inspected	SGJ 654C
_	- cross statement from order		Coverage (\$)	0.00
_	Policy No.		Excess (\$)	0.00
_	Assign From		Assign Date	17/01/2019
	Assign From	Vahiala P	articulars & Condition	SANGELD MANAGER
2.	Banka 9 Bandal	MITSUBISHI LANCER	c.c	1584
-	Make & Model	HIDDEN	Year of Reg.	2006
-	Engine No. Chassis No.	JMYSTCS3A6U011149	Colour	BLACK
		213663	Steering	IN ORDER
	Odometer	IN ORDER	Modification	SPORTS RIM
	Brakes	GOOD	Wodification	
	General		nditions of Tyres	
3.		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
_	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4.	L/H Real Tyle		ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT PORTION.	
5.	DAWAGES SEE D		neral Information	THE RESERVE THE PARTY OF THE PA
J.	Accident Date	14/01/2019	Inspection Date	17/01/2019
_	Survey held at	HUA MENG SPRAY PAINT	ING WKSP	
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	IS, WE HAVE NOT AUTHOR	SIS. ISED REPAIRS.
5b.			nate Days of Repair	STATE OF THE PARTY
1	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Da	ays



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 654C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED	863.80	863.80
	BONNET HINGES @\$65.00	NOT NECESSARY	130.00	12
1	BONNET LOCK	DAMAGED	52.00	52.00
1	BONNET LOCK BRACKET	BENT	49.00	49.00
1	BONNET INNER RUBBER	NOT NECESSARY	42.90	-
1	FRONT SUPPORT PANEL	BUCKLED	739.70	739.70
1	FRONT GRILLE RIM	CRACKED	182.00	182.00
2	FRONT GRILLE @\$111.80	CRACKED	223.60	223.60
	FRONT GRILLE EMBLEM	NECESSARY	46.80	46.80
	SET FRONT GRILLE CLIPS	NECESSARY	50.00	20.00
	FRONT HEAD LAMP @\$669.50	CUT	1,339.00	1,339.00
1	FRONT BUMPER	DEFORMED	958.10	781.00
2	FRONT BUMPER SIDE HOLDER @\$57.20	NECESSARY	114.40	114.40
	FRONT BUMPER REINFORCEMENT	BENT	170.30	170.30
2	FRONT BUMPER BRACKET @\$65.00	NOT NECESSARY	130.00	
	FRONT BUMPER LOWER LIP	NOT NECESSARY	869.70	
2	FRONT BUMPER FOG LAMP @\$764.40	NOT NECESSARY	1,528.80	
	FRONT BUMPER FOG LAMP COVER @\$39.00	NOT NECESSARY	78.00)
	SET FRONT BUMPER CLIPS	NECESSARY	50.00	30.00
	FRONT NUMBER PLATE GARNISH	DEFORMED	46.80	46.80
	AIR CON CONDENSER	BENT	1,531.40	1,121.00
	RADIATOR	BENT	1,078.90	1,078.90
	HORN @\$265.00	NOT NECESSARY	530.00	o
	LESS 10% DISCOUNT		-1,080.5	
			9,724.6	6,172.47
	SPECIAL NETT ITEMS	1		
- 8	FRONT NUMBER PLATE (SN)	CRACKED	50.0	0 30.0
- 83	1 BONNET STICKER (SN)	NECESSARY	650.0	0 450.0
	The state of the s		700.0	0 480.0
	LABOUR			5
	REMOVE & REINSTALL AIR CON FILL IN GAS.		200.0	3
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		2,000.0	0 900.0

Report Ref No. CS/TP19001253/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY PAINTING.		1,500.00	900.00
	TUFF KOTE.		150.00	50.00
	TOT NOTE.		3,850.00	1,970.00
	GRAND TOTAL		14,274.68	8,622.47

	0 000 00
RECOMMENDED COST OF LUMP SUM REPAIRS	6,900.00
RECOMMENDED COST OF LOWIP SOM REPAIRS	
(TO ITS PRE-ACCIDENT CONDITION)	
(10113 FRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP19001253/Asd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.