

Surveyor:

REF:

C01/LPC19001256/Dqd3ez

Special Instruction:

From (Person): Gerald Poh of LPC ASSIGNMENT (Office)
 Estimated Cost: _____ Date/Time: 21012019
 Bill to: _____

4S: \$20000.00

Third Parties:

Claimant:

Surveyor: Prestige AppraiserWorkshop: Yee Auto

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SLC 3836C

Insured: _____

at Workshop m/s Yee Auto Service

Tel: _____

of 160 Sin Ming Drive #02-17

Policy No: _____

Claim No: 17/18/18/VP02/264906

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 08-08-2018

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 14 days)Date/Time: 08/2/19 Submit Final Fig 9200, 10 days (Red \$ 10800 / 54 %; Original 14 days)

Date/Time	Action/Instruction
	Market Value of the vehicle at the material time of accident
	SLC 3836C - X
	08/02/19 - Part Prices checked based on SLU 5288 surveyed by me with damages similar to this case.
	- To submit 2/5 9200/- with 10 days grace.
	- parts not altered either no photo to support or can be no damage seen from photo.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

MV 60K.
 LTA 43.7K
 NL 16.3K

RECEIVED 11 FEB 2019

Para(3) : Nett Value

Market Value : 60000
 LTA
 Salvage Value : 43740
 Nett Value : 16260

Inspected/
Evaluated by: _____

Fee Charged:

Date:

Basic & Add
 Transport
 Photos
 Others
 Total

1) Date/Time 11/2/19 File Pass to tyrist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 21 January, 2019 10:02 AM
To: GERALD POH WEE BIN; assignments
Cc: MT_Claim_SG; Admin A; Celine Fong (LKKAuto)
Subject: RE: Second opinion - SLC 3836 C; DOL : 08/08/2018; OUR REF : 17/18/18/VP02/264906
Attachments: 264906 ADJ REPORT.PDF; 264906 PHOTOS.PDF; 264906 PHOTOS1.pdf; 264906 RIMV1.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Part 1

Dear Gerald,

Thank you for your email.

By copy to Assignment team.

Please assign.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 21 January, 2019 9:14 AM
To: Admin A <admin-a@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: Second opinion - SLC 3836 C; DOL : 08/08/2018; OUR REF : 17/18/18/VP02/264906

Part 1


Dear Catherine,

Kindly assist our Head Office as per their request.

If you require further documents, kindly liaise with them.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: LILLIAN SIM BEE LIAN

Sent: Friday, 18 January, 2019 5:29 PM

To: GERALD POH WEE BIN

Subject: Second opinion - SLC 3836 C; DOL : 08/08/2018; OUR REF : 17/18/18/VP02/264906

Lonpac External Confidential

Dear Gerald,

Would appreciate if you could help to get a second opinion from your panel adjusters on the reasonability of cost of repairs to the claimant's vehicle vis a vis the circumstances of accident as well as the **market value of the vehicle at the material time of accident.**

Attached please find the following:-

- 1) Claimant's survey report.
- 2) Vehicle registration details.

Thanks and regards,

LILLIAN SIM

CLAIMS DEPARTMENT | LONPAC INSURANCE BHD

T : 03-27237716 F : 03-20342654 EMAIL : lilliansim@lonpac.com

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Mr Lim Wee Hiap
c/o 160 Sin Ming Drive
#02-17 Sin Ming Auto City
Singapore 575722

Date : 16th August 2018
Our Ref : PS/009/08/18
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : Mr Lim Wee Hiap
Assignment Date : 13th August 2018
Accident Date : 08th Auguts 2018
Inspection Date : 13th August 2018
Workshop Name : Yee Auto Service
Survey Conducted At : 160 Sin Ming Drive
#02-17 Sin Ming Auto City
Singapore 575722

PARTICULARS OF VEHICLE

Registration No	: SLC 3836 C	Mileage	: 037581km
Make/Model	: Honda Vezel	Engine No	: HIDDEN
Type Of Body	: Stationwagon	Chassis No	: RU1-1115309
Year Of Manu./Regn.	: 2016	Passenger Cap.	: 4 Passengers
Colour	: Met. Blue	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 6mm 215/60R16 Dunlop
Rear Tyre : 6mm 215/60R16 Dunlop

L/H SIDE

8mm 215/60R16 Dunlop
8mm 215/60R16 Dunlop

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the rear portion more to the L/H.

GENERAL DESCRIPTION OF DAMAGES

The rear end panel, bumper assy, floorboard panel, fenders, floorboard panel, tailgate, L/H door were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : SLC 3836 C

Our Ref : PS/009/08/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	rear bumper	dented	\$ 1,626.00	\$ 1,626.00 858.10 ✓
2	rear bumper side	dented	778.00	778.00 357.60 ✓
2	rear bumper bracket	dented	162.00	162.00 162.00 SVL ✓
2	rear bumper side retainer	dented	124.00	124.00 124.00 SVL ✓
1	L/H rear bumper reflector	broken	155.00	155.00 155.00 ✓
1	R/H rear bumper reflector	cracked	155.00	155.00 155.00 SVL ✓
10	rear bumper clip	necessary	50.00	50.00 50.00 ✓
1	rear end panel	dented	820.00	820.00 467.50 ✓
1	rear end panel top garnish	dented	535.00	535.00 86.80 ✓
6	rear end panel top garnish clip	necessary	42.00	42.00 42.00 ✓
1	L/H rear wheel house	dented - repair	798.00	- ✓
1	tailgate	dented/distorted	1,850.00	1,850.00 1072.50 ✓
2	tailgate absorber	warped	460.00	460.00 460.00 SVL ✓
2	tailgate hinge	dented - repair	220.00	- ✓
1	tailgate top lock	dented	380.00	380.00 221.40 ✓
1	tailgate lower lock	dented	198.00	198.00 198.00 ✓
1	tailgate weatherstrip	distorted	325.00	325.00 123.80 ✓
1	R/H tailgate reflector	stud damaged	490.00	490.00 490.00 NH ✓
1	L/H tailgate reflector	cracked	490.00	490.00 490.00 ✓
1	tailgate inner trimboard	dented/cracked	725.00	725.00 725.00 ✓
1	tailgate emblem ' LOGO '	necessary	79.00	79.00 79.00 ✓
1	tailgate emblem ' VEZEL '	necessary	85.00	85.00 85.00 ✓
1	tailgate outer garnish	dented/cracked	498.00	498.00 267.50 ✓
1	tailgate opening switch	damaged	298.00	298.00 298.00 NH ✓
1	rear number plate lamp	damaged	210.00	210.00 210.00 SVL ✓
1	rear wiper motor	damaged	525.00	525.00 525.00 NH ✓
1	R/H taillamp	stud damaged	750.00	750.00 750.00 NH ✓
1	L/H taillamp	cracked	750.00	750.00 503.30 ✓
1	R/H taillamp panel	dented	260.00	260.00 260.00 NH ✓
1	rear windscreen moulding	necessary	285.00	285.00 74.10 ✓
1	spare wheel panel	dented	1,420.00	1,420.00 863.50 ✓
1	spare wheel top cover	dented	398.00	398.00 398.00 ✓
1	spare wheel sponge	dented	268.00	268.00 268.00 SVL ✓
1	spare wheel panel lower dust cover	dented/distorted	485.00	485.00 157.30 ✓
1	L/H spare wheel side panel	dented	195.00	195.00 195.00 ✓
1	L/H rear fender	dented/distorted	1,565.00	1,565.00 770.00 ✓
1	L/H rear fender dust cover	torn	325.00	325.00 134.80 ✓
1	L/H rear fender inner garnish	dented/distorted	798.00	798.00 798.00 ✓
1	L/H rear fender arch garnish	holder fractured	584.00	584.00 220.20 ✓
1	L/H rear door	dented/distorted	1,568.00	1,568.00 900.10 ✓
1	L/H rear door lock	dented	498.00	498.00 498.00 NH ✓
1	L/H rear door weatherstrip	necessary	265.00	265.00 265.00 SVL ✓
1	reverse sensor buzzer	damaged	198.00	198.00 198.00 NH ✓
1	exhaust muffler	refit	1,050.00	- ✓
			23,740.00	21,672.00
		Less 20%	-	4,334.40
		Balance c/f	\$ 23,740.00	\$ 17,337.60

10293.50

8234.80

PRESTIGE APPRAISER SERVICES

Vehicle No : SLC 3836 C

Our Ref :

PS/009/08/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
		Balance b/d	\$ 23,740.00	\$ 17,337.60
	<u>S/NETT ITEMS</u>			
1set	reverse sensor	damaged	500.00	350.00 220/-
1	rear windscreen sealant	necessary	240.00	200.00 40/-
1	reverse camera	damaged	700.00	500.00 Nhl
		260-00		
	<u>Labour Charges & Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		2,800.00	2,400.00 1400/-
	To putty, apply primer & spray-paint on the affected portion.		2,100.00	1,800.00 1200/-
	To apply rust-proofing on repaired, replaced panel.		220.00	200.00 60/-
	To remove/refit rear windscreen glass to facilitate repairs.		240.00	220.00 120/-
	To remove/refit rear cushion seat, speaker board, roof upholstery to facilitate repairs.		240.00	220.00 120/-
	To remove/transfer tailgate mechanisms.		140.00	120.00 60/-
	To remove/transfer L/H rear door mechanisms.		100.00	80.00 60/-
	To check wiring functions.		120.00	100.00 30/-
			\$ <u>31,140.00</u>	\$ <u>23,527.60</u>

11544.80

2/S 9200/-

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$20,000.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FOURTEEN (14)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1294D
Vehicle Details	
Vehicle No.:	SLC3836C
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4035318
Chassis No.:	RU11115309
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,621.00
Original Registration Date:	12 May 2016
First Registration Date:	12 May 2016
Transfer Count:	0
Actual ARF Paid:	\$10,870.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2026
PARF Rebate Amount:	\$8,152.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$35,588.00
Total Rebate Amount:	\$43,740.00

The information contained herein is correct as at 16 Aug 2018

OK




Honda Vezel Price Range Depreciation 2016 Vehicle Type

Advanced Search

Home » Used Cars » Carro » Honda Vezel 1.5A X

Resources

Car Buying
Car Selling
Car Ownership
Car Aftermarket
On The Move
Lifestyle



Honda Vezel 1.5A X

Overview Financial Insurance Accessories Similar Research Photos Map

CONSIGNMENT



THE BETTER AUTOMOTIVE EXPERIENCE FOR EVERYBODY

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$63,500	?
Depreciation	\$8,030 /yr View models with similar depreciation	?
Reg Date	27-May-2016 (7yrs 3mths 18days COE left)	?
Manufactured	2016	?
Mileage	50,000 km (18.5k /yr)	?
Transmission	Auto	?
Engine Cap	1,496 cc	?
Road Tax	\$682 /yr	?
Power	96.0 kW (128 bhp) View specs of the Honda Vezel (2014)	?
Curb Weight	1,190 kg	?
Features	1.5L Earth Dreams I-VTEC Engine, Cruise Control, CTBA, Traction Control, Electric Park Button, Keyless Start And Entry Etc.	?
Accessories	Pioneer DVD Player, USB, Bluetooth, Reserve Sensors And Camera, Auto Headlights/LED, Fog Light, Electric Folding Side Mirror.	?
Description	Schedule A Test Drive Today, Viewing Is Strictly By Appointment Only.	?
COE	\$47,889	?
OMV	\$19,821	?
ARF	\$9,821	?
Dereg Value	\$42,318 as of today (change)	?
No. of Owners	2	?
Type of Veh	SUV	?
Category	PARF Car, Consignment Car	?
Availability	Available	?

Add to Shortlist Add to Compare Add a Note

Posted on: 03-Feb-2019 | Last Updated on: 03-Feb-2019

Tags: Honda Vezel, honda vezel, 2016 Honda Vezel, 2016 honda vezel, Honda, Vezel, vezel, Used Honda

Upfront Payment

» more Financial Info

Transfer Fee	\$25	?
Down Payment	\$19,050 (change)	Maximum 70% Loan ?
1st Instalment	\$640	?

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Seller Information

Company	Carro <ul style="list-style-type: none">» dealer's pricelist» 119 vehs sold 133 vehs available
Address	26 Sin Ming Lane #01-111 Search cars nearby this location
Location	Midview City
Office No	67146652
Contact Person(s)	Francis 87539539

Compare

Insurance
 Powered by

\$1,441 onwards
 Not at fault? No upfront payment required!
 (Get a quote)

Total Upfront Payment **\$21,156**

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Honda Vezel
» View All

Interior Leather Wrap
From \$550

Rear Trunk Trim
\$80

Reflector Chrome Light
\$50

Muffler Tip
\$68

Tonneau Covers
\$88

Bidded Carplate For Sale
\$31,888

Showing 6 out of 243 suitable items for Honda Vezel [View All](#)

Pro-Jex V2D Auto Pte Ltd is a specialist workshop for Honda cars.

USED CAR LIST | COMPANY PROFILE

Afraid of lemons? Request to have this car evaluated professionally.

Recommended for you

Impress relatives without owning a car

In a Nutshell: Uber's unhired fleet cars

SgGarage- The Leading Car Accessories Shop in S

Why you should never upsize your wheels

More privately-owned cars on the road

Uber leased fire-prone Hondas in Singapore

[Home](#) |
 [New Cars](#) |
 [Used Cars](#) |
 [Sell My Car](#) |
 [Directory](#) |
 [Products](#) |
 [Insurance](#) |
 [Article](#) |
 [Forum](#) |
 [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[About Us](#) |
 [Careers](#) |
 [Contact Us](#) |
 [Sitemap](#)
 [Terms of Service](#) |
 [Privacy Policy](#) |
 [Personal Data Protection Statement](#)
 ©2004-2019 sgCarMart. All rights reserved.

Compare



Your Ref: 17/18/18/VP02/264906

Date: 11th Feb 2019

Our Ref: CS1/LPC19001256/Dqd3e2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLC 3836C
ACCIDENT DATE: 08/08/2018**

We thank you for your instruction on 21/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 3836C from M/s Prestige Appraiser Services.
- b) Colour damaged vehicle photographs of SLC 3836C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLC 3836C
Make & Model	: Honda Vezel 1.5X A
Year of Registration	: 2016
Chassis Number	: RU11115309
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3836C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,626.00	858.10
2	REAR BUMPER SIDE	DENTED	778.00	357.60
2	REAR BUMPER BRACKET	SERVICEABLE	162.00	-
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	124.00	-
1	L/H REAR BUMPER REFLECTOR	BROKEN	155.00	155.00
1	R/H REAR BUMPER REFLECTOR	SERVICEABLE	155.00	-
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	820.00	467.50
1	REAR END PANEL TOP GARNISH	DENTED	535.00	86.80
6	REAR END PANEL TOP GARNISH CLIP	NECESSARY	42.00	42.00
1	L/H REAR WHEEL HOUSE	TO REPAIR SEE LABOUR	798.00	-
1	TAILGATE	DENTED / DISTORTED	1,850.00	1,072.50
2	TAILGATE ABSORBER	SERVICEABLE	460.00	-
2	TAILGATE HINGE	TO REPAIR SEE LABOUR	220.00	-
1	TAILGATE TOP LOCK	DENTED	380.00	221.40
1	TAILGATE LOWER LOCK	DENTED	198.00	198.00
1	TAILGATE WEATHERSTRIP	DISTORTED	325.00	123.80
1	R/H TAILGATE REFLECTOR	NOT NECESSARY	490.00	-
1	L/H TAILGATE REFLECTOR	CRACKED	490.00	490.00
1	TAILGATE INNER TRIMBOARD	DENTED / CRACKED	725.00	725.00
1	TAILGATE EMBLEM 'LOGO'	NECESSARY	79.00	79.00
1	TAILGATE EMBLEM 'VEZEL'	NECESSARY	85.00	85.00
1	TAILGATE OUTER GARNISH	DENTED / CRACKED	498.00	267.50
1	TAILGATE OPENING SWITCH	NOT NECESSARY	298.00	-
1	REAR NUMBER PLATE LAMP	SERVICEABLE	210.00	-
1	REAR WIPER MOTOR	NOT NECESSARY	525.00	-
1	R/H TAILLAMP	NOT NECESSARY	750.00	-

Report Ref No. CS1/LPC19001256/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	L/H TAILLAMP	CRACKED	750.00	503.30
1	R/H TAILLAMP PANEL	NOT NECESSARY	260.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	285.00	74.10
1	SPARE WHEEL PANEL	DENTED	1,420.00	863.50
1	SPARE WHEEL TOP COVER	DENTED	398.00	398.00
1	SPARE WHEEL SPONGE	SERVICEABLE	268.00	-
1	SPARE WHEEL PANEL LOWER DUST COVER	DENTED / DISTORTED	485.00	157.30
1	L/H SPARE WHEEL SIDE PANEL	DENTED	195.00	195.00
1	L/H REAR FENDER	DENTED / DISTORTED	1,565.00	770.00
1	L/H REAR FENDER DUST COVER	TORN	325.00	134.80
1	L/H REAR FENDER INNER GARNISH	DENTED / DISTORTED	798.00	798.00
1	L/H REAR FENDER ARCH GARNISH	HOLDER FRACTURED	584.00	220.20
1	L/H REAR DOOR	DENTED / DISTORTED	1,568.00	900.10
1	L/H REAR DOOR LOCK	NOT NECESSARY	498.00	-
1	L/H REAR DOOR WEATHERSTRIP	SERVICEABLE	265.00	-
1	REVERSE SENSOR BUZZER	NOT NECESSARY	198.00	-
1	EXHAUST MUFFLER	REFIT	1,050.00	-
	LESS 20% DISCOUNT		-	-2,058.70
			23,740.00	8,234.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	DAMAGED	500.00	220.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	240.00	40.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	700.00	-
			1,440.00	260.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF L/H REAR WHEEL HOUSE AND TAILGATE HINGE.		2,800.00	1,400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		2,100.00	1,200.00

Report Ref No. CS1/LPC19001256/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		220.00	60.00
	TO REMOVE / REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIRS.		240.00	120.00
	TO REMOVE / REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.		240.00	120.00
	TO REMOVE / TRANSFER TAILGATE MECHANISMS.		140.00	60.00
	TO REMOVE / TRANSFER L/H REAR DOOR MECHANISMS.		100.00	60.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
			5,960.00	3,050.00
GRAND TOTAL			31,140.00	11,544.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,200.00

Report Ref No. CS1/LPC19001256/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.