

ASS. REC. BY:

REF: CS/SM019001264/Mad362 Special Instruction:

Surveyor:

Mannan

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong of SMO Date/Time: 21/1/19 @ 11:09am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 9242X Insured:

at Workshop m/s SME Motor Tel: 67476106

of 1 Kaki Blot Ave 6 # 02-15

Policy No: DIEMTPV 01010426 Claim No: CMTD1900436

Sum Insured: Excess: TBA WAIVED

Make of Veh: D.O.A. 17/01/2019

(Client's Record)

CA / REX / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 11:41am @ 21/1/19 Person Contacted: Pei Ying Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLD 9242X - X

21/1/19 @ 1:59pm Sompb informed G/A if consistent & EXS WAIVED via Mannan.

22/1/19 @ 10:59am informed Pei Ying C/A & EXS WAIVED.

22/1/19 @ 10:58am revised to Gnoh Pau Loong via Mannan.

20/1/19 @ 3:34pm Informed Pau Loong, we have received supplementary \$382.60 and 75 constant & economical for repair.

(08/11/13) wif

ASS. REC. BY: MORCAY

REF:

SMD

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 9242Xat Workshop n/s Sme

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 626

IDAC Accident Report: _____ Consistent?: Yes or No

G/A / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 6 days Res.: Yes or NoLump Sum: 15.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD 9242X Yr Regn: 6.16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Honda Verde 1496Colour: white A/C: Insured / Std / Nil / NASp. Reading: 63986 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

Chassis: R411114857Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 17/1/19 D.O.I. 21/1/19

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop orSL 1/5

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 48886 Rep8

RECEIVED 25 FEB 2019.

Date/Time, File Pass to?

☐ : Preli. Report1) 24/2/2019☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: M&R-ODLump Sum / I.B.I. (\$) 4737.10Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 250

Transportation: _____

S - RS \$ _____

Photos _____

Others 10TOTAL 26022/2/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2019 Sendback Est	19 Jan 2019 11:49 S\$5,730.50	21 Jan 2019 11:09 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ASCEND COM PTE LTD, Co. Reg. No.: 199802692H		
Vehicle Reg. No.:	SLD9242X	Date of Loss:	17/01/2019 10:00 - :59 [30 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1900436	Policy/Cover Note No.:	D18MTPV01010426 (Comprehensive)
		Excess:	
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2019]		
Driver/Custodian:	CHONG HOCK LIANG NICHOLAS (29 / Male), NRIC: S8920508E, Tel: +6598320861		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	18 Jan 2019 16:21	Clim Veh Model Changed	(204586) HONDA VEZEL 1.5 X CVT (A).		[I] Merimen Administrator
2	18 Jan 2019 16:21	Clim Created	Reg No: SLD9242X. Policy No: D18MTPV01010426. Acct Date: 2019/01/17. Claim Type: SC. Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ). Ins.Status => Notification, Created from SAS:MSME19008708		[I] Merimen Administrator
3	18 Jan 2019 16:37	Clim Registration Modified	Acct Time:10:50:00->10:00:00.		[I] VIVIEN D/O GEORGE BONNIE D'SI
4	19 Jan 2019 11:34	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[I] Chia Pei Ying
5	19 Jan 2019 11:49	Clim Submitted	5730.50.		[R] Chia Pei Ying
6	21 Jan 2019 10:59	Adj Co Assigned	Raleigh Services (HQ):		[I] GRACE TEO
7	21 Jan 2019 10:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/30		[I] GRACE TEO
8	21 Jan 2019 10:59	Adj Mandate Set	Approved:0.00.		[I] GRACE TEO
9	21 Jan 2019 11:05	Adj Assignment Cancelled			[I] GRACE TEO
10	21 Jan 2019 11:05	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] GRACE TEO
11	21 Jan 2019 11:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		[I] GRACE TEO
12	21 Jan 2019 11:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/30		[I] GRACE TEO
13	21 Jan 2019 11:09	Adj Mandate Set	Approved:0.00.		[I] GRACE TEO
14	21 Jan 2019 11:39	Assignment 1st Accessed			[A] Nivitha Govindasamy
15	21 Jan 2019 12:14	Clim Registration Modified	Excess: -> 0.00. Excess Waived: -> 1000.00.		[I] GNOH PAU LOONG
16	21 Jan 2019 13:16	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] Nivitha Govindasamy
17	22 Jan 2019 10:55	Adj Rpt Initiated			[A] SHIAU CHAN
18	22 Jan 2019 10:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/01/30		[A] SHIAU CHAN
19	25 Jan 2019 09:48	Clim Supp Created (S:786542)			[R] Gary Seah
20	25 Jan 2019 09:50	Clim Submitted (S:786542)	380.60.		[R] Gary Seah
21	25 Jan 2019 09:50	Adj Co Assigned (S:786542)	LKK Auto Consultants Pte Ltd (HQ):		[I] Merimen Administrator
22	25 Jan 2019 10:28	Supp Combined (S:786542)			[A] SHIAU CHAN
23	30 Jan 2019 15:33	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/01/30		[A] SHIAU CHAN
24	30 Jan 2019 15:33	Adj Mandate Request	Cur,Req:5486.10:We have received supplementary of \$380.60 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical		[A] SHIAU CHAN
25	31 Jan 2019 08:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/30		[I] GNOH PAU LOONG
26	31 Jan 2019 08:34	Adj Mandate Set	Approved:5486.10.		[I] GNOH PAU LOONG

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2034133	18/01/2019 16:21	Motor	Sompo Insurance Singapore Pte. Ltd. (HQ)	Sompo Insurance Singapore Pte. Ltd. (HQ)	SLD9242X	ASCEND COM PTE LTD	xx.xx
2034530	19/01/2019 11:34	Motor	SME Motor Pte Ltd	SME Motor Pte Ltd (Kaki Bukit)	SLD9242X		xx.xx
2036790	22/01/2019 10:55	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLD9242X		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 30 Jan 2019

Preliminary Advice

Vehicle No	: SLD9242X	Accident Date	: 17/01/2019
Make	: HONDA VEZEL	Policy No.	: D18MTPV01010426
Assignment Date	: 21/01/2019	Excess	: S\$0.00
Date of Inspection	: 21/01/2019	Est. Duration of Repair	: 6.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,111.10	(ESTIMATE \$5,730.50 + SUPPLEMENTARY \$380.60)
Revised Amount	:S\$	4,495.10	
Check Items (Estimated)	:S\$	991.00	
Total	:S\$	5,486.10	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	48,886.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,114.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary of \$380.60 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 22 January 2019 11:08 AM
To: peiying@smemotor.com.sg
Cc: SUR
Subject: VEHICLE SLD 9242X (DOA: 17/01/2019)

Dear Pei Ying,

Please proceed to repair the insured vehicle **SLD 9242X (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 22 Jan 2019

Preliminary Advice

Vehicle No	: SLD9242X	Accident Date	: 17/01/2019
Make	: HONDA VEZEL	Policy No.	: D18MTPV01010426
Assignment Date	: 21/01/2019	Excess	: S\$0.00
Date of Inspection	: 21/01/2019	Est. Duration of Repair	: 6.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,730.50
Revised Amount	:S\$	3,834.00
Check Items (Estimated)	:S\$	1,271.50
Total	:S\$	5,105.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	48,886.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,114.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

SLD9242X (CMTD1900436)

OD

Jan 17 2019 10:00AM
[ASCEND COM PTE LTD]
SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on **21/01/2019 13:59 PM**.
To LKK_HQ
CC PauLoong; MelvinYe; IreneHenryJames
Subject **OD EXCESS & AUTHORISATION**

Hi LKK Auto,

Please be informed of the followings:-

- To authorise if consistent.
- Excess waived.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2692H
Vehicle Details	
Vehicle No.:	SLD9242X
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4034865
Chassis No.:	RU11114857
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,308.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$10,432.00 5216
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2026
PARF Rebate Amount:	\$7,824.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$41,062.00
Total Rebate Amount:	\$48,886.00

The information contained herein is correct as at 21 Jan 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2012 Fully Done Up BMW Z4.



Very Low Mileage, Superior
Condition. M2 Bodykit, Akrapovic
Xos, Only 1 In SG.
Direct Owner - StarAd



Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted

70 vehicles

vezel

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage V

Search Selection

vezel

Any

Any

2016

Any

Any



**Honda Vezel 1.5A X Honda
Sensing**

\$68,000**\$8,190 /yr****25-Aug-2016****1,496 cc****27,140 km**

Only Pay 1st Installment Plus Admin Fee Plus Transfer Fee. Insurance Can Pay By Giro x 12 Months (No Credit Cards Required).

Allmotoring.sg

Posted: 21-Jan-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X Honda
Sensing**

\$70,500**\$8,320 /yr****12-Oct-2016****1,496 cc****24,800 km**

Monthly \$1140. Insurance Can Be Paid By Credit Card Or By Giro x 12 Months Installments At 0% Interest. No Gimmicks, Call Us For View

Allmotoring.sg

Posted: 21-Jan-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$64,800****\$8,230 /yr****20-Apr-2016****1,496 cc****31,870 km**

Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry A
Our Sales For Appointment!

Benefit Auto Enterprise Pte Ltd

Posted: 21-Jan-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$75,000****\$9,520 /yr****02-Sep-2016****1,496 cc****35,000 km****Fuel Type:** Petrol-Electric

Tip Top Condition. Low Mileage And 1 Owner Only. Accident Free. High Loan Assists And Trade In Are Available. Consignment Unit, Mak
Appointment Now To View!

Posted: 20-Jan-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Transparent Spring Stiffeners**

Transparent Spring Stiffeners On Honda Vezel

More info about this product

Honda Vezel 1.5A X**\$67,800****\$8,470 /yr****02-Jun-2016****1,496 cc****48,789 km**

ent Unit! Low Monthly Installment! Fast Approval! 20KM/L Fuel Consumption On This Earth-dream Build Engine Using Direct In
finance! In A Very Good Condition To Drive Off! C...

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2019 16:12
Date Of Accident	17/01/2019 10:50
Exact Location Of Accident	LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD9242X
Insured/Policyholder	
Name Of Registered Owner	ASCEND COM PTE LTD
Co Reg No	199802692H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68460903

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01010426
Cover Note Number	

Driver

Name of Driver	CHONG HOCK LIANG NICHOLAS
NRIC No	S8920508E
Date Of Birth	24/06/1989
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98320861
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/01/19 / 11:30pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SALE

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/SP/OD-061 (01)
Policy No:	D18MTPV01010426	Date of Loss:	17/01/2019
Vehicle Reg. No.:	SLD9242X	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES <i>Not Approved</i>

Insured/Claimant: ASCEND COM PTE LTD
 Driver: CHONG HOCK LIANG
 NICHOLAS

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	30/06/2016
Vehicle Colour:	WHITE	Chassis No:	RU11114857
Engine No:	L15B4034865		
Odometer:	0 KM		

Paint Type:
 Total Loss? NO
 Est. Duration of Repair 7 (day)

Description of Accident/Loss: ON 17/01/2019 AT ABOUT 10.50PM, WHILST TRAVELLING ALONG LOYANG AVENUE ON THE EXTREME LEFT LANE, THERE WAS HEAVY TRAFFIC. SO, I SIGNALLLED CHECK ON MY RIGHT AND THERE WAS NO ONCOMING VEHICLE. THEN, I PROCEED TO MOVE TO THE RIGHT, BUT UNFORTUNATELY, I COULDN'T BRAKE IN TIME THUS COLLIDED INTO THE REAR OF VEHICLE B (SH6243J).

Remarks: VEHICLE IN.
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	3,910.50
Miscellaneous Items	0.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,730.50
+ GST 7.00% (\$\$)	401.14
Nett Amount (\$\$)	6,131.64

This claim is handled by: CHIA PEI YING

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLD9242X/19/01/2019 11:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Buf/3uc</i>	0.00	0.00	*450.00 F
2	1		*FRT BONNET RUBBER LH <i>To.1</i>	0.00	0.00	*25.00 F
3	1		*FRT GRILLE <i>one</i>	0.00	0.00	*185.00 F
4	2		*FRT GRILLE OUTER MOULDING <i>one</i>	0.00	0.00	*70.00 F
5	1		*FRT GRILLE OUTER GARNISH <i>one</i>	0.00	0.00	*150.00 F
6	4		*FRT GRILLE CLIP <i>one</i>	0.00	0.00	*10.00 F
7	1		*FRT BUMPER <i>Dis</i>	0.00	0.00	*220.00 F
8	1		*FRT BUMPER RETAINER LH <i>Buf</i>	0.00	0.00	*15.00 F
9	10		*FRT BUMPER CLIP <i>one</i>	0.00	0.00	*25.00 F
10	1		*FRT BUMPER BEAM (BELOW HEADLAMP) LH-TOP <i>Turn</i>	0.00	0.00	*25.00 F
11	1		*FOG LAMP LH <i>1.1</i>	0.00	0.00	*160.00 F
12	1		*FOG LAMP GARNISH LH <i>one</i>	0.00	0.00	*25.00 F
13	1		*HEADLAMP LH <i>one</i>	0.00	0.00	*850.00 F
14	1		*FRT FENDER LH <i>3uc</i>	0.00	0.00	*195.00 F
15	1		*FRT FENDER INNER COWLING LH <i>To.1</i>	0.00	0.00	*70.00 F
16	10		*FRT FENDER INNER COWLING CLIP <i>one</i>	0.00	0.00	*25.00 F
17	2		*FRT FENDER PROTECTOR <i>Turn</i>	0.00	0.00	*120.00 F
18	12		*FRT FENDER PROTECTOR CLIP <i>1.1</i>	0.00	0.00	*30.00 F
19	1		*FRT WHEEL HOUSING JOINT LH <i>Buf</i>	0.00	0.00	*95.00 F
20	1		*ENGINE UNDER COVER CENTER <i>1.1</i>	0.00	0.00	*90.00 F
21	12		*ENGINE UNDER COVER CLIP <i>1.1</i>	0.00	0.00	*30.00 F
22	1		*AIRCON SIDE DEFLECTOR LH <i>1.1</i>	0.00	0.00	*35.00 F
23	1		*FRT BUMPER BEAM (BELOW HEADLAMP) BTM-LH <i>one</i>	0.00	0.00	*30.00 F
24	1		*HEADLAMP SUPPORT PANEL <i>one</i>	0.00	0.00	*395.00 F
25	1		*FRT BONNET INSULATOR <i>To.1</i>	0.00	0.00	*110.00 F
26	8		*FRT BONNET INSULATOR CLIP <i>one</i>	0.00	0.00	*20.00 F
27	2		*ENGINE UNDER COVER SIDES <i>1.1</i>	0.00	0.00	*100.00 F

F=Franchise part.

Sub Total (S\$) 3,555.00
+ Margin on L,N Items 10.00% (S\$) 355.50
Total Parts (S\$) 3,910.50

SME Motor Pte Ltd/SLD9242X/19/01/2019 11:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	WIRE CHECKING	New	20.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✗
3	LABOUR CHARGE	New	800.00 600
4	SPRAY PAINTING	New	900.00 750

Gross Labour Cost (\$\$)	1,820.00
--------------------------	----------

SME Motor Pte Ltd/SLD9242X/19/01/2019 11:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/SP/OD-061 (01)
Policy No:	D18MTPV01010426	Date of Loss:	17/01/2019
Vehicle Reg. No.:	SLD9242X	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ASCEND COM PTE LTD		
Driver:	CHONG HOCK LIANG NICHOLAS		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	30/06/2016
Vehicle Colour:	WHITE	Chassis No:	RU11114857
Engine No:	L15B4034865		
Odometer:	63986 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss

ON 17/01/2019 AT ABOUT 10.50PM, WHILST TRAVELLING ALONG LOYANG AVENUE ON THE EXTREME LEFT LANE, THERE WAS HEAVY TRAFFIC. SO, I SIGNALLLED CHECK ON MY RIGHT AND THERE WAS NO ONCOMNG VEHICLE. THEN, I PROCEED TO MOVE TO THE RIGHT. BUT UNFORTUNATELY, I COULDN'T BRAKE IN TIME THUS COLLIDED INTO THE REAR OF VEHICLE B (SH6243J).

Present Location: **SME MOTOR PTE LTD (KAKI BUKIT)****COST OF CLAIMS**

	Amount
Parts	380.60
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	380.60
+ GST 7.00% (S\$)	26.64
Nett Amount (S\$)	407.24
+ Previous Estimates (S\$)	6,131.64
Claim Total (S\$)	6,538.88

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLD9242X/25/01/2019 09:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH CHASIS JOINT	0.00	0.00	*45.00 F
2	1		*FRONT LH CHASIS JOINT BRACKET	0.00	0.00	*35.00 F
3	1		*FRONT BONNET RUBBER LONG	0.00	0.00	*30.00 F
4	2	grilleside gornal	*HEADLAMP TOP BRACKET	0.00	0.00	*36.00 F
5	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*15.00 F
6	1		*FRONT BUMPER LOWER SPOILER	0.00	0.00	*130.00 F
7	1		*FRONT LH WHEEL HOUSING JOINT OUTER	0.00	0.00	*55.00 F

F=Franchise part.

Sub Total (S\$) 346.00

+ Margin on L,N Items 10.00% (S\$) 34.60

Total Parts (S\$) 380.60

SME Motor Pte Ltd/SLD9242X/25/01/2019 09:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

9-3061
102
3367.1
4737.10

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

SME Motor Pte Ltd/SLD9242X/25/01/2019 09:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6
#02-15/16/17/18 AUTOBAY @KAKI BUKIT
SINGAPORE 417883

NO: HLI9061236
PAGE: 1
DATE: 31/01/2019
A/C CODE: LDSM446
TERMS: CR
P/O NO: SLD 9242 X

Part No	Description	Location	Qty	Unit Price SIN	Amount SIN
Our D/O No: HDO9004640					
1	H60100-T8N-T00ZZ	BONNET	1	450.00	450.00
2	H71106-T7J-H00	FR.FOG LAMP GARNISH LH	1	25.00	25.00
3	H33150-T7A-J11	FRT.HEADLAMP LH	1	850.00	850.00
4	H60260-T8N-T00ZZ	FR.FENDER LH(T20ZZ)	1	195.00	195.00
5	H74150-T7A-000	FR.COWLING LH	1	70.00	70.00
6	H71101-T7J-H00ZZ	FR.BUMPER	1	220.00	220.00
7	H74157-T7M-H01	FR.W/H ARCH PROT.LH	1	60.00	60.00
8	H04684-T7A-300ZZ	FRT.W/H.EXTENSION LH	1	95.00	95.00
9	H74141-T7Y-T00	BONNET INSULATOR	1	110.00	110.00
10	H71190-T7A-000	FR.BPR BEAM LH(T7J)	1	30.00	30.00
11	H74194-T7B-000	BONNET CORNER RUB.LH	1	25.00	25.00
Our D/O No: HDO9004642					
1	H74192-T7A-000	BONNET SIDE RUB.LH	1	30.00	30.00
2	H71151-T7J-H00	FR.GRILLE SIDE GARNISH RH	1	18.00	18.00
3	H71152-T7A-000	FR.GRILLE GARNISH LH	1	18.00	18.00
4	H74107-T7M-H01	FR.W/H.Arch PROT.RH	1	60.00	60.00
5	H71193-T7A-000	FR.BPR.SIDE RETAINER RH	1	15.00	15.00
6	H71198-T7A-000	FR.BPR.SIDE RETAINER LH	1	15.00	15.00
7	H71102-T7W-A00	FR.BPR.CTR.SKIRT	1	130.00	130.00
8	H71121-T7A-000	FR.GRILLE	1	185.00	185.00
9	H60710-T7A-300ZZ	FR.W/H.UP MEMBER LH	1	55.00	55.00

Our D/O No: HDO9004643



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

NO: HLI9061236
PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 H60944-T7A-300ZZ	FR.CHASSIS GUSSET PLATE LH	H2A28	1	35.00	35.00 ✓
Our D/O No: HDO9004644					
1 H60945-T7A-300ZZ	FR.CHASSIS GUSSET LH	H2A28	1	45.00	45.00 ✓
Our D/O No: HDO9004645					
1 H71122-T7A-000	FR.GRILLE OUTER GARNISH	HU3-35	1	150.00	150.00 ✓
2 H71123-T7A-000	FR.GRIL LENS MLDG.RH	H1FT1	1	35.00	35.00 ✓
3 H71128-T7A-000	FR.GRIL LENS MLDG LH	H1FT1	1	35.00	35.00 ✓
4 H91505-TM8-003	CLIP	H1P5	14	2.50	35.00 ✓
5 H91501-TR0-003	COWLING CLIP	HDS	10	2.50	25.00 ✓
6 H91501-SWA-003	BNT.INSULATOR CLIP	HDS	8	2.50	20.00 ✓
7 H71150-T7J-H00	FR.GRILLE GARNISH.RR.CTR.	H2J3	1	25.00	25.00 ✓
TOTAL QUANTITY:			58	TOTAL	SIN 3,061.00
				ADD GST @ 7%	214.27
				GRAND TOTAL	SIN 3,275.27

#02-18
RU1

Print / MCNK / 31/01/2019 11:13:48 AM

SALESMAN: MCNK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

F & O. E.

GOODS RECEIVED BY



REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2019)
 Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/SLD9242X/25/01/2019 09:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH CHASIS JOINT	0.00	0.00	✓ *45.00 F
2	1		*FRONT LH CHASIS JOINT BRACKET	0.00	0.00	✓ *35.00 F
3	1		*FRONT BONNET RUBBER LONG	0.00	0.00	✓ *30.00 F
4	2		*HEADLAMP TOP BRACKET	0.00	0.00	✓ *15.00 F
5	1		*FRONT BUMPER RETAINER RH	0.00	0.00	✓ *130.00 F
6	1		*FRONT BUMPER LOWER SPOILER	0.00	0.00	✓ *55.00 F
7	1		*FRONT LH WHEEL HOUSING JOINT OUTER			
Sub Total (S\$)						346.00
+ Margin on L,N Items 10.00% (S\$)						34.60
Total Parts (S\$)						380.60

F=Franchise part.

SME Motor Pte Ltd/SLD9242X/25/01/2019 09:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Parts 3061
 +10% 3367.10

800

LC

1320

4737.10

2102/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2019	19 Jan 2019	21 Jan 2019	S\$4,737.10	S\$4,737.10		Pending for Survey Report
	Sendback Est	11:49 S\$5,730.50	11:09 Edit Adj Rpt	Edit Estimates	View Rpt		
Supp #1	25 Jan 2019 09:48	25 Jan 2019 09:50 S\$380.60	25 Jan 2019 09:50			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	ASCEND COM PTE LTD, Co. Reg. No.: 199802692H		
Vehicle Reg. No.:	SLD9242X	Date of Loss:	17/01/2019 10:00 - :59 [30 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1900436	Policy/Cover Note No.:	D18MTPV01010426 (Comprehensive)
		Excess:	S\$0.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/01/2019]		
Driver/Custodian:	CHONG HOCK LIANG NICHOLAS (29 / Male) , NRIC: S8920508E, Tel: +6598320861 Email: NOEMAIL		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- SOMPO_SG (31/01/2019): Alert - Adj Mandate Approved (S\$5486.10) - SLD9242X - Claim Handler: GNOH PAU LO...
- SOMPO_SG (21/01/2019): OD EXCESS & AUTHORISATION

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD9242X (CMTD1900436)

OD

Jan 17 2019 10:00AM

[ASCEND COM PTE LTD]

SME Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	18/01/19 16:21	Accident Statement	 Load HTM	☐
2	19/01/19 11:49	Repairer Estimates	 Load HTM	☐
3	25/01/19 09:50	Repairer Estimates Suppl. #1	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/19 10:58	Adjuster Immediate Advice	 Load HTM	☐
2	30/01/19 15:33	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/19 10:48	Chassis Number	 Load JPG ☒	☒
2	22/01/19 10:48	Odometer Reading	 Load JPG ☒	☒
3	22/01/19 10:48	General View	 Load JPG ☒	☒
4	22/01/19 10:48	General View	 Load JPG ☒	☒
5	22/01/19 10:48	General View	 Load JPG ☒	☒
6	22/01/19 10:48	General View	 Load JPG ☒	☒
7	22/01/19 10:48	General View	 Load JPG ☒	☒
8	22/01/19 10:48	General View	 Load JPG ☒	☒
9	22/01/19 10:48	General View	 Load JPG ☒	☒
10	22/01/19 10:48	General View	 Load JPG ☒	☒
11	22/01/19 10:48	General View	 Load JPG ☒	☒
12	22/01/19 10:48	General View	 Load JPG ☒	☒
13	22/01/19 10:48	General View	 Load JPG ☒	☒
14	22/01/19 10:48	General View	 Load JPG ☒	☒
15	22/01/19 10:48	General View	 Load JPG ☒	☒
16	22/01/19 10:48	General View	 Load JPG ☒	☒
17	22/01/19 10:48	General View	 Load JPG ☒	☒
18	22/01/19 10:48	General View	 Load JPG ☒	☒
19	22/01/19 10:48	General View	 Load JPG ☒	☒
20	22/01/19 10:48	General View	 Load JPG ☒	☒
21	22/01/19 10:48	General View	 Load JPG ☒	☒
22	22/01/19 10:48	General View	 Load JPG ☒	☒
23	22/01/19 10:48	General View	 Load JPG ☒	☒
24	22/01/19 10:48	General View	 Load JPG ☒	☒
25	22/01/19 10:48	General View	 Load JPG ☒	☒
26	22/01/19 10:48	General View	 Load JPG ☒	☒
27	22/01/19 10:48	General View	 Load JPG ☒	☒
28	22/01/19 10:48	General View	 Load JPG ☒	☒
29	22/01/19 10:48	General View	 Load JPG ☒	☒
30	22/01/19 10:48	General View	 Load JPG ☒	☒
31	22/01/19 10:48	General View	 Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
32	22/01/19 10:48	General View	 Load JPG	☒
33	22/01/19 10:48	General View	 Load JPG	☒
34	22/01/19 10:48	General View	 Load JPG	☒
35	22/01/19 10:48	General View	 Load JPG	☒
36	22/01/19 10:48	General View	 Load JPG	☒
37	22/01/19 10:48	General View	 Load JPG	☒
38	22/01/19 10:48	General View	 Load JPG	☒
39	22/01/19 10:48	General View	 Load JPG	☒
40	22/01/19 10:48	General View	 Load JPG	☒
41	22/01/19 10:48	General View	 Load JPG	☒
42	22/01/19 10:48	General View	 Load JPG	☒
43	22/01/19 10:48	General View	 Load JPG	☒
44	22/01/19 10:48	General View	 Load JPG	☒
45	22/01/19 10:48	General View	 Load JPG	☒
46	22/01/19 10:48	General View	 Load JPG	☒
47	22/01/19 10:48	General View	 Load JPG	☒
48	22/01/19 10:48	General View	 Load JPG	☒
49	22/01/19 10:48	General View	 Load JPG	☒
50	22/01/19 10:48	General View	 Load JPG	☒
51	22/01/19 10:48	General View	 Load JPG	☒
52	22/01/19 10:48	General View	 Load JPG	☒
53	22/01/19 10:48	General View	 Load JPG	☒
54	22/01/19 10:48	General View	 Load JPG	☒
55	22/01/19 10:48	General View	 Load JPG	☒
56	22/01/19 10:48	General View	 Load JPG	☒
57	22/01/19 10:48	General View	 Load JPG	☒
58	22/01/19 10:48	General View	 Load JPG	☒
59	22/01/19 10:48	General View	 Load JPG	☒
60	22/01/19 10:48	General View	 Load JPG	☒
61	22/01/19 10:48	General View	 Load JPG	☒
62	22/01/19 10:48	General View	 Load JPG	☒
63	22/01/19 10:48	General View	 Load JPG	☒
64	22/01/19 10:48	General View	 Load JPG	☒
65	22/01/19 10:48	General View	 Load JPG	☒
66	22/01/19 10:48	General View	 Load JPG	☒
67	22/01/19 10:48	General View	 Load JPG	☒
68	22/01/19 10:48	General View	 Load JPG	☒
69	22/01/19 10:48	General View	 Load JPG	☒
70	22/01/19 10:48	General View	 Load JPG	☒
71	22/01/19 10:48	General View	 Load JPG	☒
72	22/01/19 10:48	General View	 Load JPG	☒
73	22/01/19 10:48	General View	 Load JPG	☒
74	22/01/19 10:48	General View	 Load JPG	☒
75	22/01/19 10:48	General View	 Load JPG	☒
76	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
77	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
78	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
79	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
80	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
81	22/02/19 15:16	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
82	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
83	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
84	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
85	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
86	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
87	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
88	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
89	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
90	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
91	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
92	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
93	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
94	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
95	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
96	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
97	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
98	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
99	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
100	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
101	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
102	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
103	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
104	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
105	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
106	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
107	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
108	22/02/19 15:16	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/19 14:32	MOTOR ALERT POINTS	 Load PDF	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	21/02/19 10:33	LOU FORM	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 15:36	Parts Invoice	 Load PDF	
2	27/02/19 15:38	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	18/01/19 16:21	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	18/01/19 16:21	Accident Photo	 Load JPG	☒
2	18/01/19 16:21	Accident Photo	 Load JPG	☒
3	18/01/19 16:21	Accident Photo	 Load JPG	☒
4	18/01/19 16:21	Accident Photo	 Load JPG	☒
5	18/01/19 16:21	Accident Photo	 Load JPG	☒
6	18/01/19 16:21	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail Print
7	18/01/19 16:21	Accident Photo		Load JPG ☒
8	18/01/19 16:21	Accident Photo		Load JPG ☒
9	18/01/19 16:21	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No.	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail Print
1	18/01/19 16:20	Sketch Plan		Load TIF
2	18/01/19 16:20	Sketch Plan #2		Load TIF
3	18/01/19 16:20	Sketch Plan #3		Load TIF
4	18/01/19 16:20	Sketch Plan #4		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19001264/UQD3E2

Date: 27/02/2019

REFERENCE

Insured/Claimant: ASCEND COM PTE LTD Policy No: D18MTPV01010426
Date of Loss: 17/01/2019 Nature of Claim: OD Claim No: CMTD1900436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD9242X**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4034865
Reg. Date: 30/06/2016 (Man. Year: 2016) Chassis No: RU11114857
Colour: White Odometer: 63986 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,291.10	3,367.10	924.00	21.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,370.00	450.00	24.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,111.10	4,737.10	1,374.00	22.48
+ GST 7.00/7.00% (S\$)	427.78	331.60	96.18	22.48
Nett Amount (S\$)	6,538.88	5,068.70	1,470.18	22.48

INSPECTION

Date of Assignment: 21/01/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 21/01/2019 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLD9242X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Bent / Buckled	450.00 F	*450.00 F
2	1		*FRT BONNET RUBBER LH (WCP)	Torn	25.00 F	*25.00 F
3	1		*FRT GRILLE (WCP)	Cracked	185.00 F	*185.00 F
4	2		*FRT GRILLE OUTER MOULDING (WCP)	Cracked	70.00 F	*70.00 F
5	1		*FRT GRILLE OUTER GARNISH (WCP)	Cracked	150.00 F	*150.00 F
6	4		*FRT GRILLE CLIP (WCP)	Necessary	10.00 F	*10.00 F
7	1		*FRT BUMPER (WCP)	Distorted	220.00 F	*220.00 F
8	1		*FRT BUMPER RETAINER LH (WCP)	Bent	15.00 F	*15.00 F
9	10		*FRT BUMPER CLIP (WCP)	Necessary	25.00 F	*25.00 F
10	1		*FRT BUMPER BEAM (BELOW HEADLAMP) LH-TOP SHOULD BE BONNET RUBBER LH INSTEAD OF FRT BUMPER BEAM (BELOW HEADLAMP) LH-TOP (WCP)	Torn	25.00 F	*25.00 F
11	1		*FOG LAMP LH (WCP)	Not Necessary	160.00 F	*- F
12	1		*FOG LAMP GARNISH LH (WCP)	Twisted	25.00 F	*25.00 F
13	1		*HEADLAMP LH (WCP)	Cracked	850.00 F	*850.00 F
14	1		*FRT FENDER LH (WCP)	Buckled	195.00 F	*195.00 F
15	1		*FRT FENDER INNER COWLING LH (WCP)	Torn	70.00 F	*70.00 F
16	10		*FRT FENDER INNER COWLING CLIP (WCP)	Necessary	25.00 F	*25.00 F
17	2		*FRT FENDER PROTECTOR (WCP)	Torn	120.00 F	*120.00 F
18	12		*FRT FENDER PROTECTOR CLIP (WCP)	Not Necessary	30.00 F	*- F
19	1		*FRT WHEEL HOUSING JOINT LH (WCP)	Bent	95.00 F	*95.00 F
20	1		*ENGINE UNDER COVER CENTER (WCP)	Not Necessary	90.00 F	*- F
21	12		*ENGINE UNDER COVER CLIP (WCP)	Not Necessary	30.00 F	*- F
22	1		*AIRCON SIDE DEFLECTOR LH (WCP)	Not Necessary	35.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	1		*FRT BUMPER BEAM (BELOW HEADLAMP) BTM-LH (WCP)	Cracked	30.00 F	*30.00 F
24	1		*HEADLAMP SUPPORT PANEL (WCP)	Repair	395.00 F	*- F
25	1		*FRT BONNET INSULATOR (WCP)	Torn	110.00 F	*110.00 F
26	8		*FRT BONNET INSULATOR CLIP (WCP)	Necessary	20.00 F	*20.00 F
27	2		*ENGINE UNDER COVER SIDES (WCP)	Not Necessary	100.00 F	*- F
Supplementary #1						
28	1		*FRONT LH CHASIS JOINT (WCP)	Bent	45.00 F	*45.00 F
29	1		*FRONT LH CHASIS JOINT BRACKET (WCP)	Bent	35.00 F	*35.00 F
30	1		*FRONT BONNET RUBBER LONG (WCP)	Torn	30.00 F	*30.00 F
31	2		*HEADLAMP TOP BRACKET SHOULD BE GRILLE SIDE GARNISH INSTEAD OF HEADLAMP TOP BRACKET (WCP)	Cracked	36.00 F	*36.00 F
32	1		*FRONT BUMPER RETAINER RH (WCP)	Bent	15.00 F	*15.00 F
33	1		*FRONT BUMPER LOWER SPOILER (WCP)	Distorted	130.00 F	*130.00 F
34	1		*FRONT LH WHEEL HOUSING JOINT OUTER (WCP)	Bent	55.00 F	*55.00 F

F=Franchise part.

Sub Total (\$\$)	3,901.00	3,061.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	390.10	306.10

Total Parts (\$\$)	4,291.10	3,367.10
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	20.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	0.00
3	LABOUR CHARGE	New	800.00	600.00
4	SPRAY PAINTING	New	900.00	750.00
Gross Labour Cost (S\$)			1,820.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >