

INS. CASE OWNER: ACWN | CC 6/AIG1900 | 1279, G/H/29 | LKK: 18/1/19
 IDAC: 18/1/19

Surveyor: YGA | DOI: ASSIGNMENT 18/1/19 | Date / Time: 18/1/19
 Registered in Merimen: 18/1/19

Pre-assign / CCU / FTE
 Insured Vehicle N^o: SEP 1459P | Claim No.: 87MK HLP474054
 Name of Insured: WONG YIK SUM | Policy No.: 2100 862878-04
 Insured Tel No.: HP: 87674962 | Make / Model: TOYOTA
 Excess Sec II :SS | D.O.A.: 18/1/19 | Place of Accident: UP AVE 73V AVE AVE 2
 Is driver the owner? (YES / NO) | Nature of Accident:
 If NO, Driver Name / Age: | OI GIA REPORT: YES / NO: / NO:
 Driver Tel No.: | (VL: YES / NO) | Insured Liability: Final 7: Yes / No

SEP 7051A → → → →
 INSR: WSP: Tel: Liability: RMKS: NPH
 INSR: WSP: Tel: Liability: RMKS:
 INSR: WSP: Tel: Liability: RMKS:
 INSR: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
<u>18/1/19</u>	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: After call Itr to OI:	
<u>02/02/19</u>	Documentation Check List: Handler Typist Notification Itr (if non-pickup): After call Itr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: ETA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:	<u>18/06/19 - SUMMIT - 04</u>
<u>10-4-19</u>		<u>PEND. LOD.</u>
<u>18/5/19</u>		<u>Tried calling OI but was told contact no. wrong. Sent letter first.</u>
<u>18/6/19</u>		<u>OI called back, informed TP claim</u>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm by:

FINALIZATION Date/Time: Confirm with: Confirm by:
 Repair Cost: PIP \$5,116.20 (4 days) Reduction: 10 Email Call

FINAL SETTLEMENT Date/Time: 28/06/19 Confirm with: P/6607 Email Call
 Final Liability: % 100 (Assessed / Assessed) BOLA S/N No.: N/A
 Repair Cost: (w/loss) \$5,116.20
 Loss of Rental (LOR): \$5 (days)
 Loss of Use (LOU): \$5 200.00 x 5 days
 Loss of Income (LOI): \$5 (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: \$5 200
 Medical: \$5 -
 Disbursement: \$5 - (e.g. Tow/Independent)
 Legal Cost: \$5 -
 Total: \$5 3,684.19 Global Sum \$5: 3,600.00
 1) Claim status: N/Reject/Private Settle
 2) Report Format:
 3) Survey fee: \$310.00

FINAL PAYMENT Date/Time: Confirms with: Email Call
 Payee 1: \$5 3,600.00 Name 1: NPH AUTO SERVICE
 Payee 2: (Strike if N.A.) \$5 - Name 2: -
 Payee 3: (Strike if N.A.) \$5 - Name 3: -

COPY SENT
4/1/19 HIT
2 PARKED VEH.

Jay

REF: ALG 9928J

ASSIGNMENT

From: Date: Estimated Cost: OD (TP / WS / TP RES / OD RES / EVA / INV / MV) To inspect Vehicle No: at Workshop n/s NPH Auto of Insured: Policy No: Claims No: Sum Insured: Excess: (Client's Record) Make of Veh:

Veh No: SKE 7051A Yr Regn: 28 Mar 201 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: KIA Cerato Fortec 1591 Colour: Silver A/C: Insured / Std / NI / NA Sp. Reading: 106077 T/Radio: Insured / Std / NI / NA Eng/No: C/No: KNA FW 511 MC 560 6752 Gen. Cond: Good / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F: 245/45 R 17 R: 11

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: \$30k IDAC Accident Rpt. Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 4 days Res: Yes or No, Lum Sum: 1.5% 3 Val: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT

Table with 2 columns: N/S, O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Road Stone Front Rear R/Bal: 5 mm R/Bal: 5 mm L/Bal: 5 mm L/Bal: 5 mm D.O.A. D.O.I. 18-01-19 Survey held at w/s 3:30 pm Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/Tip or Rear o/s The UIC / Chassis frame / Body Structure affected due to collision.

Table with 2 columns: Date / Time, Action / Instruction. Handwritten notes: 4/4/19 No second hand parts, contents found by 3114-20 n/s Regy 1055 of use, CRAB: #2:BA-60 (40%)

Date/Time, File Pass to? []: Prel. Report []: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee: Transportation

Add Fee: [] Site Insp (\$), [] Interview (\$), [] Tech. Invs (\$), [] Weekend (\$)

Photos, Other

Report Format: Lump Sum / I.B.I: (\$)

TOTAL

Large empty box for final totals or notes.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG19001279/Gjb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-01-2019	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKP 1459P	Veh. Inspected	SKE 7051A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/01/2019	Inspection Date	18/01/2019
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS. WE HAVE NOT AUTHORISED REPAIRS.			



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
 Our Ref : TP0005/01/19 Date : 18/01/2019

THIRD PARTY CLAIM

M/S : TAN TAI CHEOW DARREN
 BLK 232 ANG MIO KIO AVE 3
 #12-1210
 SINGAPORE 560232

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKE7051A - KIA CERATO
 INSURED : TAN TAI CHEOW DARREN ENGINE# :
 DATE OF ACCIDENT : 17/1/2019 CHASSIS# :
 POLICY NO : DMPC18001674

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear boot lamp RH <i>SCR</i>	18	236.00	236.00	236.00
2 rear lamp RH <i>CRA</i>	18	269.00	269.00	269.00
3 rear bumper <i>TN</i>	18	601.00	601.00	601.00
4 rear bumper lower center spoiler <i>-cut</i>	18	108.00	108.00	108.00
5 rear bumper reflector lamp RH <i>-cut</i>	18	24.00	24.00	24.00
6 rear bumper side retainer RH <i>-re</i>	18	25.00	25.00	25.00
7 rear bumper sponge <i>✓ CRA</i>	18	147.00	147.00	147.00
8 rear bumper reinforcement <i>✓ CRA</i>	18	295.00	295.00	295.00
9 rear bumper parking sensor <i>-pm</i>	18	183.00	183.00	183.00
10 rear exhaust box with chrome pipe <i>X Set LR & R</i>	18	747.00	747.00	747.00
11 rear lamp center panel <i>X</i>	18	282.00	282.00	282.00
12 rear lamp panel RH <i>X</i>	18	265.00	265.00	265.00
				3,182.00
Less 10%				-318.20
Total Material				\$2,863.80

Labour & Misc

1 Remove & install r/boot lamp, r/lamp, r/bumper, knock r/boot, r/fender, cut out & renew center panel and restraighthen body & chassis.			500	980.00
2 Spray painting.			600	1,000.00
3 Check wiring system.				25.00
4 Remove & install rear boot carpet. <i>upholstery</i>			80	100.00
5 Remove & install rear exhaust box.			80	100.00
6 Remove & install rear parking sensor.			50	100.00
7 Remove & install rear exhaust box with chrome pipe			80	2,305.00
Total Labour				\$2,305.00

1335

4.7 hrs.

P/P \$3114.20



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0005/01/19

Page : 2/2
Date : 18/01/2019

THIRD PARTY CLAIM

Nett Total Before Gst

\$5,168.80

Your faithfully

NPH AUTO SERVICE
(Manager)

3-4 Days.

Umpson repair.

After repair photos.

Guo Qiang - 82880282

18/1/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
 Our Ref : TP0005/01/19 Date : 18/01/2019

THIRD PARTY CLAIM

M/S : TAN TAI CHEOW DARREN
 BLK 232 ANG MIO KIO AVE 3
 #12-1210
 SINGAPORE 560232

Attn :
 Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKE7051A - KIA CERATO
 INSURED : TAN TAI CHEOW DARREN ENGINE# :
 DATE OF ACCIDENT : 17/1/2019 CHASSIS# :
 POLICY NO : DMPG18001674

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear boot lamp RH <i>SCR</i>	10	236.00	236.00	236.00 ✓
2 rear lamp RH <i>-CMA</i>	10	269.00	269.00	269.00 ✓
3 rear bumper <i>-TN</i>	10	601.00	601.00	601.00 ✓
4 rear bumper lower center spoiler <i>-cut.</i>	10	108.00	108.00	108.00 ✓
5 rear bumper reflector lamp RH <i>-cut</i>	10	24.00	24.00	24.00 ✓
6 rear bumper side retainer RH <i>-el.</i>	10	25.00	25.00	25.00 ✓
7 rear bumper sponge ?	10	147.00	147.00	147.00 ✓
8 rear bumper reinforcement ?	10	295.00	295.00	295.00 ✓
9 rear bumper parking sensor <i>-pm</i>	10	183.00	183.00	183.00 ✓
10 rear exhaust box with chrome pipe ?x	10	747.00	747.00	747.00
11 rear lamp center panel x	10	282.00	282.00	282.00
12 rear lamp panel RH x <i>{ repair.</i>	10	265.00	265.00	265.00
				3,182.00
Less 10%				-318.20
Total Material				\$2,863.80

Labour & Misc

1 Remove & install r/boot lamp, r/lamp, r/bumper, knock r/boot, r/fender, cut out & renew center panel and restraigthen body & chassis.	<i>400-500 ?</i>	980.00
2 Spray painting.	<i>400-600 ?</i>	1,000.00
3 Check wiring system.	<i>25</i>	25.00
4 Remove & install rear boot carpet.	<i>60 x</i>	100.00
5 Remove & install rear exhaust box.	<i>?</i>	100.00
6 Remove & install rear parking sensor.	<i>40</i>	100.00
		2,305.00

Total Labour

\$2,305.00



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19001279/Gjb3

18 JUNE 2019

WONG YIK SUAN @ WONG AH HOI
17B JUBILEE ROAD
SINGAPORE 128551

Dear Sir/Madam,

ACCIDENT INVOLVING SKP1459P AND SKE7051A ON 17/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third-Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third-Party claim. However, if your policy has an NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jimmy
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT

I, Tan Tai cheow Darren ("the third party claimant") of _____

(address), owner of SKE 7051A (vehicle no.) hereby
authorize NAM AUTO SERVICE ("the workshop") to act for
me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my
vehicle no. SKE 7051A that was damaged pursuant to the accident which occurred on 12/01/19
(date) along AMK AVE 3 CARPARK AT BUK 232 (location) involving vehicle
no/s SKE 7051A + SKP 1459P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 18 (day) of JAN (month) 2019 (year)



Signed by "the third party claimant"
(with company stamp if applicable)

Paul

Signed by "the workshop"
(with company stamp)



**RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, NPH AUTO SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for SS 3,600.00 (REPAIR COSTS), SS --- (loss of use/rental) SS --- (SEARCH FEES) for vehicle no. SKE 7051A that was damaged pursuant to the accident which occurred on 17/01/19 (date) along AMK AVE 3 Carpark (location) involving vehicle no/s SKP 145AD.

This is pursuant to the inspection conducted on 18/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Darren Tan Tai chow ("third party claimant") of vehicle no. SKE 7051A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKE 7051A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 day of 06 (month) 20 19 (year)



Y6Q

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Registration No: QAC/180/10K

Our Ref : TP0005/01/19
Your Ref :

TAX INVOICE NO. : 06546
Date of
Accident Date : 17/01/2019
Policy Number : DMPG18001674
Model : KIA CERATO
Veh Reg No : SKE7051A
Date : 08/04/2019

TAN TAI CHEOW DARREN
BLK 232 ANG MIO KIO AVE 3
#12-1210
SINGAPORE 560232

Replacement of Parts

rear boot lamp RH	236.00
rear lamp RH	269.00
rear bumper	601.00
rear bumper lower center spoiler	108.00
rear bumper reflector lamp RH	24.00
rear bumper side retainer RH	25.00
rear bumper sponge	147.00
rear bumper reinforcement	295.00
rear bumper parking sensor	183.00
Total Material	\$1,888.00
Less 10%	-\$188.80
	\$1,699.20

Labour & Misc

Remove & install r/boot lamp, r/lamp, r/bumper, knock r/boot, r/fender, cut out & renew center panel and restraighthen body & chassis.	500.00
Spray painting.	600.00
Check wiring sysrtem.	25.00
Remove & install rear boot carpet.	80.00
Remove & install rear parking sensor.	50.00
Repari exhaust box with chrome pipe	80.00
Remove & install rear exhaust box.	80.00
Total Labour	\$1,415.00
Less 0%	\$0.00
	\$1,415.00

Nett Total Before GST	\$3,114.20
Add GST @ 7%	\$217.99
Nett Total After GST	\$3,332.19





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-010630
Date of Request: 18/01/2019

Your Ref No: Online Purchase

NPH Auto Service
Blk 9005 Tampines Steet 93
#01-246/254
Singapore 528839

Dear Sir/Madam,

Enquiry Date 18/01/2019
Enquiry By Peggy Foo
TP Vehicle No. SKP1459P
Accident Date 17/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKP1459P	AIG Asia Pacific Insurance Pte. Ltd.	20/08/2018-19/08/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2019 Edit Reg		18 Jan 2019 00:00 Edit Adj Rpt	S\$3,114.20 Edit Estimates	S\$3,114.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WONG YIK SUAN @ WONG AH HOI , ID: S1839227E								
Main Claimant:	DARREN TAN TAI CHEOW , ID: S0039928J								
Vehicle Reg. No.:	SKE7051A	Date of Loss:	17/01/2019 00:00 - :59 [81 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8736364340SG	Policy/Cover Note No.:	2100382878 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKP1459P	Policy No. (Claimant):	DMPG18001674						
		Excess:							
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Street 93, #01-246/254, 528839 Tampines - Tel: 6784 0663								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE7051A (8736364340SG)
[SKP1459P]
TP
DARREN TAN TAI CHEOW
Jan 17 2019 12:00AM
[WONG YIK SUAN @ WONG AH HOI]
NPH Auto Service

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	22/01/19 15:08	Accident Statement <small>From: DD - Reg. No: SKP1459P, Claimant: WONG YIK SUAN @ WONG AH HOI</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
2	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
3	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
4	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
5	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
6	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
7	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
8	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
9	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
10	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
11	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
12	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
13	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
14	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
15	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
16	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
17	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
18	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
19	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
20	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
21	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
22	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
23	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
24	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
25	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
26	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
27	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
28	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
29	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		
30	12/04/19 09:01	General View							Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	12/04/19 09:01	General View		Load JPG <input checked="" type="checkbox"/>
32	12/04/19 09:01	General View		Load JPG <input checked="" type="checkbox"/>
33	12/04/19 09:02	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
34	12/04/19 09:02	Chassis Number		Load JPG <input checked="" type="checkbox"/>
35	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
36	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
37	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
38	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
39	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
40	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
41	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
42	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
43	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
44	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
45	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
46	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
47	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
48	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
49	12/04/19 09:02	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
50	12/04/19 09:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	12/04/19 09:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	12/04/19 09:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	12/04/19 09:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
54	12/04/19 09:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
55	12/04/19 09:03	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/19 09:44	TP ESTIMATE- MARKED		Load PDF
2	22/01/19 09:44	TP GIA REPORT		Load PDF
3	18/06/19 10:50	Letter to OI		Load PDF
4	15/07/19 14:52	WORKSHOP INVOICE		Load PDF
5	15/07/19 14:52	AUTHORISATION TO ACT FORM		Load PDF
6	15/07/19 14:52	Release Voucher		Load PDF
7	15/07/19 14:52	GIA SEARCH		Load PDF
8	15/07/19 14:52	LETTER TO OI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKP1459P (Insd veh)	Model:	KIA CERATO FORTE 1.6 KROUP SX (M)
	SKE7051A (TP veh)		
Date of Accident:	17/01/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	5,530.62
Final Repair Cost	:	\$	3,600.00
Loss of Use	:	\$	5.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,600.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	NPH Auto Service	:	\$ 3,600.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 Jul
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001279/GHB3Q2
Date: 15/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100382878	
Claimant Vehicle No : SKE7051A	Insured Vehicle No : SKP1459P	
Date of Loss: 17/01/2019	Nature of Claim: TP	Claim No: 8736364340SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE7051A		
Make & Model:	KIA CERATO FORTE, 1.6 KOUP SX (M)	Engine No:	G4FCCH227797
Reg. Date:	28/03/2012 (Man. Year: 2012)	Chassis No:	KNAFW511MC5606752
Colour:	Silver	Odometer:	106077 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Rockstone 5 mm	Rear Left Side:	Rockstone 5 mm
Front Right Side:	Rockstone 5 mm	Rear Right Side:	Rockstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,863.80	1,779.20	1,084.60	37.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,305.00	1,335.00	970.00	42.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,168.80	3,114.20	2,054.60	39.75
+ GST 7.00/7.00% (S\$)	361.82	217.99	143.83	39.75
Nett Amount (S\$)	5,530.62	3,332.19	2,198.43	39.75
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,634.19		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment:	18/01/2019	
Date Inspected:	18/01/2019 Inspected At:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LAMP RH	Scratched	236.00 FL	*236.00 FL
2	1		*REAR LAMP RH	Cracked	269.00 FL	*269.00 FL
3	1		*REAR BUMPER	Torn	601.00 FL	*601.00 FL
4	1		*REAR BUMPER LOWER CENTER SPOILER	Cut	108.00 FL	*108.00 FL
5	1		*REAR BUMPER REFLECTOR LAMP RH	Cut	24.00 FL	*24.00 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Deformed	25.00 FL	*25.00 FL
7	1		*REAR BUMPER SPONGE	Cracked	147.00 FL	*147.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	295.00 FL	*295.00 FL
9	1		*REAR BUMPER PARKING SENSOR	Damaged	183.00 FL	*183.00 FL
10	1		*SET REAR EXHAUST BOX WITH CHROME PIPE (LOCAL REPAIR)	Bent	672.30 FS	*80.00 FS
11	1		*REAR LAMP CENTER PANEL	Repair	282.00 FL	*- FL
12	1		*REAR LAMP PANEL RH	Repair	265.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	3,107.30	1,968.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	243.50	188.80
Total Parts (\$\$)	2,863.80	1,779.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL R/BOOT LAMP ,R/LAMP ,R/BUMPER,KNOCK R/BOOT,R/FENDER ,CUT OUT & RENEW CENTER PANEL AND RESTRAIGHTEN BODY & CHASSIS	New	980.00	500.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	REMOVE & INSTALL REAR BOOT CARPET UPHOLSTERY	New	100.00	80.00
5	REMOVE & INSTALL REAR EXHAUST BOX	New	100.00	80.00
6	REMOVE & INSTALL REAR PARKING SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,305.00	1,335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >