



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0005/01/19 Date : 18/01/2019

THIRD PARTY CLAIM

M/S : TAN TAI CHEOW DARREN
BLK 232 ANG MIO KIO AVE 3
#12-1210
SINGAPORE 560232

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKE7051A - KIA CERATO
INSURED : TAN TAI CHEOW DARREN
DATE OF ACCIDENT : 17/1/2019
POLICY NO : DMPG18001674

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear boot lamp RH <i>SCR</i>	1@	236.00	236.00	236.00
2 rear lamp RH <i>CH</i>	1@	269.00	269.00	269.00
3 rear bumper <i>IN</i>	1@	601.00	601.00	601.00
4 rear bumper lower center spoiler <i>cut.</i>	1@	108.00	108.00	108.00
5 rear bumper reflector lamp RH <i>cut</i>	1@	24.00	24.00	24.00
6 rear bumper side retainer RH <i>de.</i>	1@	25.00	25.00	25.00
7 rear bumper sponge ?	1@	147.00	147.00	147.00
8 rear bumper reinforcement ?	1@	295.00	295.00	295.00
9 rear bumper parking sensor <i>DM</i>	1@	183.00	183.00	183.00
10 rear exhaust box with chrome pipe ?	1@	747.00	747.00	747.00
11 rear lamp center panel <i>X</i>	1@	282.00	282.00	282.00
12 rear lamp panel RH <i>X</i> <i>{ repair.</i>	1@	265.00	265.00	265.00
				3,182.00
Less 10%				-318.20
Total Material				\$2,863.80
Labour & Misc				

- 1 Remove & install r/boot lamp, r/lamp, r/bumper, knock r/boot, r/fender, cut out & renew center panel and restraigthen body & chassis.
- 2 Spray painting.
- 3 Check wiring sysrtem.
- 4 Remove & install rear boot carpet.
- 5 Remove & install rear exhaust box.
- 6 Remove & install rear parking sensor.

400-500 ? 980.00
400-600 ? 1,000.00
25.00
60 X 100.00
? 100.00
40 100.00
2,305.00

Total Labour **\$2,305.00**



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0005/01/19

Page : 2/2
Date : 18/01/2019

THIRD PARTY CLAIM

Nett Total Before Gst

\$5,168.80

Your faithfully

NPH AUTO SERVICE
(Manager)

3-4 Days.

Lumpsum repair.

After repair photos.

Guo Qiang - 82880282

18/1/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: