

ASS. REC. BY:

REF:

⑧/LCR19001289/Ktd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hor Yinnul

of

LER

Date/Time:

21/1/19 @ 11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9660Z

Insured:

SLG 2914X

at Workshop m/s

Insurance Auto

Tel:

90089959

of

Blk 5038, Amic Ave 3 # 01-405 Ind. park 2

Policy No:

0999994823

Claim No:

3194623566SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:20am @ 21/1/19

Person Contacted:

Mr. YEO

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 9660Z - X

SLG 2914X - X

31/1 L1Smp 841001 email

L1Smp 846501 Confirmed (Red: 10479.28: 69%)

ASS. REC. BY:

REF:

16/1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

23/1

File pass to Car

RECEIVED 25 FEB 2019.

Date/Time, File Pass to?

25p typst

Date/Time, File Return to?



: Prel. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Tp

Lump Sum / I.B.I. (\$

4650

Pre repair inspection request - SLR9660Z V5 SLG2914X (OI) DOA: 17/01/2019

From: Hor, Yiru
To: Admin A (admin-a@ikikauto.com), 'assignments@ikikauto.com'
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Marissa; Azlan, Syazirrina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur
Sent: 21/1/2019 11:00:41 AM
Attachments: <90061 (NOA).pdf> <90061 (NOA).pdf>

Hi,

Please refer to the enclosed request from Cheonghoh Law Corporation

Claim no : 3194623566SG003
Case Owner : MARICEL OLEA

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Yin Ru, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FIVOL, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Yinru.hor@aig.com | www.aig.sg

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]
Sent: Monday, January 21, 2019 10:33 AM
To: Abu Kassim, Noor Marissa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: Re: Notice of Accident - Traffic accident involving SLR 9660 Z and SLG 2914 X (your insured) on 17 January 2019 at/along airport Boulevard towards Terminal 3 ; Our ref: LCH.my/AMK07-80061.19

Dear Sir/ Madam,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong named in paragraph 2 of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SLR 9660 Z is currently laying at our client's workshop, Insurance's Auto at Blk 5038 Ang Mo Kio Ave 3 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541. Kindly contact the person in charge Mr Yeo at 9008 9959 before your surveyor attending at the said workshop.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Jan 18, 2019, at 6:11 PM, Cheong Hoh Lee <mail@cheonghoh.sg> wrote:

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

<90061 (NOA).pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul Hor@aiig.com

To: mail@cheonghoh.sg

Cc: Andy-SY.Fong@aiig.com, Lee-

Ying.Chen@aiig.com, Baljit.Kaur@aiig.com, NoorMarissa.AbuKassim@aiig.com, Syazairdina.Azlan@aiig.com, yokeeshi.chan@aiig.com, ShengYang.Lim@aiig.com, Imran.Ishak@aiig.com, Aashweenje

etiaur.Mithosasingh@aiig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG2914X AND SLR9660Z ON 17/01/2019

Date: Mon, 21 Jan 2019 01:59:00 +0000

Without Prejudice

Your Reference : LCH.my/AMK07-90061.19

Our Reference : 3194623566SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

| Name of Surveyor | Company Name |
|--------------------------|--|
| AIG In House Surveyor | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gury) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufik | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rut, Hor (Viviane)

AIG

Claim Adjuster II, Singapore PHOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]

Sent: Friday, January 18, 2019 6:12 PM

To: Abu Kassim, Noor Marissa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Notice of Accident - Traffic accident involving SLR 9660 Z and SLG 2914 X (your insured) on 17 January 2019 at/along airport Boulevard towards Terminal 3 ; Our ref: LCH.my/AMK07-80061.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,

Melody

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 6337 6700

Fax: 6337 3700

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------|
| Date Of Report | 18/01/2019 16:44 |
| Date Of Accident | 17/01/2019 19:05 |
| Exact Location Of Accident | AIRPORT BLVD TWDS T3 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | SLR9660Z |
| Insured/Policyholder | |
| Name Of Registered Owner | TITANIUM LIMOUSINES PTE LTD |
| Co Reg No | 201213055R |
| Email Address | TANCHRIS603@YAHOO.COM |
| Mobile Phone No | (LOCAL) +65-96790297 |
| Alternative Phone No | OFFICE-96790297 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | TOYOTA |
| Model | ALPHARD |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | 5089460350-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|---------------------------|
| Name of Driver | TAN TIONG HIN CHRISTOPHER |
| NRIC No | S6828067B |
| Date Of Birth | 31/07/1968 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 22/07/1983 |
| Driving Experience | 35 YEARS AND 5 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96790297 |
| Fax Number | |
| Contact Number | |
| Email Address | TANCHRIS603@YAHOO.COM |

| | |
|---|----------------------------------|
| Address | BLK 961 HOUGANG AVE 9 #12-574 |
| Postcode | 530961 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - - - |
| Insurance Company of Driver's Own Vehicle | - - - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------|
| Vehicle Registration Number | SLG2914X |
| Vehicle Make/Model/Colour | HONDA STREAM |
| Details Of Properties | |
| Vehicle Category | PRIVATE HIRE |
| Name of Driver | MR. TAN |
| NRIC/Passport Number | |
| Contact Number | 94899102 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Titanium
LIMOUSINES PTE LTD
CORPORATE NO. 201203014

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Airport Boulevard towards Terminal 3 on the 4th lane of 5 lanes road. In front of me a taxi stopped so I managed to slow down and stopped. About 5 seconds a ~~Vehicle~~ Vehicle SLG 2914X collided against the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Titanium
LIMOUSINES PTE LTD
GRAND RD. SINGAPORE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Insurance's Auto

Blk 5038 #01-405, Ang Mo Kio Ind. Park 2
Singapore 569541.
Fax: 64455393, Email: insurancesauto@hotmail.com
Tel: 90089959

Titanium Limousines Pte Ltd

Blk 5038 An Mo Kio Ind. Park2 #01-405
Singapore 569541.

Vehicle : SLR 9660 Z
Chassis No : AGH300040850
Make : Toyota ALPHARD
Year : 2016

Not Withheld
11 Sep 846501
Recovery After Paint
6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before reassembly painting
- To display damaged part in a recovery
- Parts prices are subject to confirmation
- Third party survey is on a "best effort" basis
- No illegal modifications is allowed
- Supplementary item(s) must be approved
in subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

| QTY | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

Estimate Cost Of Repair

| | | | |
|-------|----------------------------------|----------|--------------|
| 1 | Tailgate Assy | | \$1,834.30 ✓ |
| 1 | Tailgate Inner Lock | | \$465.00 X |
| 1 | Tailgate Lower Catch | | \$41.25 X |
| 1 | Tailgate Lock Actuator | | \$289.20 X |
| 1 | Tailgate Logo | | \$71.00 ✓ |
| 1 | Tailgate Emblem' ALPHARD' | | \$66.20 ✓ |
| 1 | Taigate Centre Ganish | | \$411.00 X |
| 1 | Tailgate Outer Chrome | | \$423.20 X |
| 1 | Tailgate Auto Close Motor | | \$487.00 X |
| 2 | Tailgate Lamp LH/RH | \$534.00 | \$1,068.00 X |
| 1 | Tailgate Weatherstrip | | \$387.00 X |
| 1 | Tailgate Innerboard | | \$552.00 ✓ |
| 1 set | Tailgate Innerboard Clips | | \$48.50 ✓ |
| 1 | Rear Bumper | | \$719.65 ✓ |
| 2 | Rear Bumper Reflector LH/RH | \$58.60 | \$117.20 X |
| 2 | Rear Bumper Side Retainer -Inner | \$85.20 | \$170.40 X |
| 2 | Rear Bumper Side Holder | \$62.00 | \$124.00 X |
| 2 | Rear Bumper Side Garnish LH/RH | 274.75 | \$389.20 ✓ |
| 1 | Rear Tow Cover | | \$72.00 ✓ |
| 1 | Rear End Panel | 685-10 | \$829.30 X |
| 1 | Rear End Panel Centre Garnish | | \$227.60 X |
| 1 | Rear Fender RH | | \$1,845.20 X |
| 1 | Rear Fender Inner Board RH | | \$889.30 X |
| 1 | Exhaust Silencer | | \$885.00 X |

| | | | |
|----------|-----------|-------------------|---|
| | <u>Sm</u> | \$68.00 | X |
| | | \$12,869.70 | |
| less 25% | | \$3,217.43 | |
| | | <u>\$9,652.28</u> | |

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$1,500.00 *500*

To putty and spray paint on front accident affected portion.

\$1,300.00 *800*

To Spray Anti Rust On Accident Affected Portion

\$120.00 *60*

To check electrical components for proper function.

\$75.00 *20*

Install rear bumper sensor and check for proper function.

\$80.00 *60*

Remove /replace Rear Exhaust Silencer

nn \$150.00 X

To remove /refix Boot compartment fittings and attachments to facilitate repair.

\$150.00 *60*

To remove and replace exhaust end pipe.

nn \$150.00 X

To remove/transfer tailgate glass. To conduct water Leak Test.

\$150.00 *120*

Special Nett Item

- 1 Rear bumper ultrasonic sensor-LH outer
- 1 Rear bumper ultrasonic sensor-RH outer *371.45*
- 2 Rear bumper ultrasonic sensor-inner *0371.45*
- 1 Rear Number Plate
- 1 Rear Windscreen Sealant

| | | |
|----------------|----------|-----------|
| <i>Sm</i> | \$428.00 | X |
| <i>Ref Sm</i> | \$428.00 | X |
| <i>ols cmf</i> | \$856.00 | X |
| <i>Sm</i> | \$30.00 | X |
| <i>nn</i> | \$60.00 | <i>40</i> |

Grand Total : \$15,129.28



























...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 18 Jan 2019 Edit Reg | | 21 Jan 2019 00:00 Edit Adj Rpt | S\$4,650.00 Edit Estimates | S\$4,650.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | LCRF PTE LTD, Co. Reg. No.: 201624597K | | | | | | | | |
| Main Claimant: | TITANIUM LIMOUSINES PTE LTD | | | | | | | | |
| Vehicle Reg. No.: | SLR9660Z | Date of Loss: | 17/01/2019 00:00 - :59 [16 Months and 17 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 3194623566SG | Policy/Cover Note No.: | 0999994823 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SLG2914X | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Insurance Auto (HQ) BLK 134 PASIR RIS ST 11 #04-253 (510134) MAILING ADDRESS, BLK S038 ANG MO KIO INDUSTRIAL PARK 2N#01-405 (569541), 569541 Ang Mo Kio - Tel: | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/01/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (22/01/2019): TP GIA REPORT | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SLR9660Z (3194623566SG)**
[SLG2914X]
TP
TITANIUM LIMOUSINES PTE LTD
Jan 17 2019 12:00AM
[LCRF PTE LTD]
Insurance Auto

| | | | | | | | | | |
|--------------------|-----------------|--|--------------------|--------------|--------------|---|-----------|-------------------------------------|-------------------------------------|
| Upload Documents | | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View | | View in Browser | |
| Assessment Reports | | | | | | 1 per page | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | Thumbnail | Print | |
| 1 | 22/01/19 14:31 | Accident Statement From: SC - Reg. No: SLG2914X, Claimant: LCRF PTE LTD | | | |  | Load HTML | | |
| | | | | | | | | | |
| Photos/Images | | | | | | 3 per page | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | Thumbnail | Print | |
| 1 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 25/02/19 09:47 | General View | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 25/02/19 09:48 | Reinspection Photo | | | |  | Load JPG | <input checked="" type="checkbox"/> | |

Documents Checklist

| | | | |
|--|-----------------------|----------------------|-----------------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR19001289/KTD3Q2

Date: 26/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994823
Claimant Vehicle No : SLR9660Z **Insured Vehicle No :** SLG2914X
 Date of Loss: 17/01/2019 Nature of Claim: TP Claim No: 3194623566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR9660Z**
 Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 2ARH637894
 Reg. Date: 31/08/2017 (Man. Year: 2015) Chassis No: AGH300040850
 Colour: Metallic Black Odometer: 102592 km
 Engine Capacity: 2493 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 11,454.27 | 4,196.22 | 7,258.05 | 63.37 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,675.00 | 1,620.00 | 2,055.00 | 55.92 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 15,129.27 | 5,816.22 | 9,313.05 | 61.56 |
| Approved Total (Overridden) (S\$) | | 4,650.00 | | |
| Nett Amount (S\$) | 15,129.27 | 4,650.00 | 10,479.27 | 69.26 |

INSPECTION

Date of Assignment: 21/01/2019
 Date Inspected: 22/01/2019 Inspected At: Insurance Auto (HQ)
 BLK 134 PASIR RIS ST 11 #04-253
 (510134) MAILING ADDRESS, BLK 5038
 ANG MO KIO INDUSTRIAL PARK 2N#01-405 (569541)
 Singapore 569541
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *TAILGATE ASSY | Bent | 1,834.30 FL | *1,834.30 FL |
| 2 | 1 | | *TAILGATE INNER LOCK | Repair | 465.00 FL | *- FL |
| 3 | 1 | | *TAILGATE LOWER CATCH | Repair | 41.25 FL | *- FL |
| 4 | 1 | | *TAILGATE LOCK ACTUATOR | Serviceable | 289.20 FL | *- FL |
| 5 | 1 | | *TAILGATE LOGO | Necessary | 71.00 FL | *71.00 FL |
| 6 | 1 | | *TAILGATE EMBLEM ALPHARD | Necessary | 66.20 FL | *66.20 FL |
| 7 | 1 | | *TAILGATE CENTRE GARNISH | Serviceable | 411.00 FL | *- FL |
| 8 | 1 | | *TAILGATE OUTER CHROME | Serviceable | 423.20 FL | *- FL |
| 9 | 1 | | *TAILGATE AUTO CLOSE MOTOR | Serviceable | 487.00 FL | *- FL |
| 10 | 2 | | *TAILGATE LAMP LH/RH | Serviceable | 1,068.00 FL | *- FL |
| 11 | 1 | | *TAILGATE WEATHERSTRIP | Serviceable | 387.00 FL | *- FL |
| 12 | 1 | | *TAILGATE INNERBOARD | Buckled | 552.00 FL | *552.00 FL |
| 13 | 1 | | *SET TAILGATE INNERBOARD CLIPS | Necessary | 48.50 FL | *48.50 FL |
| 14 | 1 | | *REAR BUMPER | Cracked | 719.65 FL | *719.65 FL |
| 15 | 2 | | *REAR BUMPER REFLECTOR LH/RH | Serviceable | 117.20 FL | *- FL |
| 16 | 2 | | *REAR BUMPER SIDE RETAINER -INNER | Serviceable | 170.40 FL | *- FL |
| 17 | 2 | | *REAR BUMPER SIDE HOLDER | Serviceable | 124.00 FL | *- FL |
| 18 | 1 | | *REAR BUMPER SIDE GARNISH LH/RH | O/S Buckled | 778.40 FL | *274.75 FL |
| 19 | 1 | | *REAR TOW COVER | Dented | 72.00 FL | *72.00 FL |
| 20 | 1 | | *REAR END PANEL | Bent | 829.30 FL | *685.10 FL |
| 21 | 1 | | *REAR END PANEL CENTRE GARNISH | Mtg Distorted | 227.60 FL | *227.60 FL |
| 22 | 1 | | *REAR FENDER RH | Repair | 1,845.20 FL | *- FL |
| 23 | 1 | | *REAR FENDER INNER BOARD RH | Serviceable | 889.30 FL | *- FL |
| 24 | 1 | | *EXHAUST SILENCER | Repair | 885.00 FL | *- FL |
| 25 | 2 | | *EXHAUST SILENCER HOLDER | Serviceable | 68.00 FL | *- FL |
| 26 | 1 | | *REAR BUMPER ULTRASONIC SENSOR -LH OUTER | Serviceable | 428.00 FS | *- FS |
| 27 | 1 | | *REAR BUMPER ULTRASONIC SENSOR-RH OUTER | Dented | 428.00 FS | *371.45 FS |
| 28 | 1 | | *REAR BUMPER ULTRASONIC SENSOR-INNER | O/S Cracked | 856.00 FS | *371.45 FS |
| 29 | 1 | | *REAR NUMBER PLATE | Serviceable | 30.00 FS | *- FS |
| 30 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 60.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 14,671.70 | 5,334.00 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 3,217.43 | 1,137.78 |
| Total Parts (\$\$) | 11,454.27 | 4,196.22 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS | New | 1,500.00 | 500.00 |
| 2 | TO PUTTY AND SPRAY PAINT ON FRONT ACCIDENT AFFECTED PORTION | New | 1,300.00 | 800.00 |
| 3 | TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION | New | 120.00 | 60.00 |
| 4 | TO CHECK ELECTRICAL COMPONENTS FOR PROPER FUNCTION | New | 75.00 | 20.00 |
| 5 | INSTALL REAR BUMPER SENSOR AND CHECK FOR PROPER FUNCTION | New | 80.00 | 60.00 |
| 6 | REMOVE /REPLACE REAR EXHAUST SILENCER | New | 150.00 | 0.00 |
| 7 | TO REMOVE /REFIX BOOT COMPARTMENT FITTINGS AND ATTACHMENTS TO FACILITATE REPAIR | New | 150.00 | 60.00 |
| 8 | TO REMOVE AND REPLACE EXHAUST END PIPE | New | 150.00 | 0.00 |
| 9 | TO REMOVE/TRANSFER TAILGATE GLASS .TO CONDUCT WATER LEAK TEST | New | 150.00 | 120.00 |
| Gross Labour Cost (S\$) | | | 3,675.00 | 1,620.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >